

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 11st December 2016

To : AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01, AXA Tower
Singapore 068811


Attn : Motor Claims Dept

Re : Vehicle Reg No: SKA8808Z
Model: MERCEDES BENZ C180 CGI
Chassis No: WDD2043312G086702
Engine No: 27491030042166

Upon inspection to the above-mentioned vehicle, we wish to advise you that the vehicle be severely damaged. The estimate cost of repair is approximately S\$60,000.00
Kindly arrange your adjuster to inspect the said vehicle at our premises 188 Pandan Loop Singapore 128378.

Kindly contact the undersigned should you need further clarifications.
Your early attention is greatly appreciated.

Yours truly,


Kerlyn Ong
Service Advisor

Remark: Should the above vehicle be subject to total loss towed from our premises
Prior to any repair 5 % of the total estimate price will be charged, plus towing charges if applicable.
A daily storage charge at the rate of \$50.00 per day will commence 7 days after estimate date. These charges will not apply if CYCLE & CARRIAGE PTE LTD undertakes repairs.

Rasul (LKK)
Raf
12/12/18 @ 1545

Recommended TOTAL LOSS