(W)			NT (Office)		mone han recover apparen
From (Person): _	yourne young	of	FCI	Date/	Time: 11/12/1805.49PM
Estimated Cost: _	,		Bill to:		
OD/HP)WS/T	PRES / OD RES / E				
To Inspect Vehicl	e No:	SLZ 253	359	Insured:	AFFOI AHS
at Workshop m/s	Cycl	e & Courricage	Ind.	Tel:9	1865113
of		88 pandan	toup		
Policy No:			Claim No:	018008	8747MFSH
Sum Insured:			Excess:		
Sum Insured: Make of Veh:			220	DO.	1 12 2018
(Client's Record)		- 2 19 10	Excess: _	D.O.A	8105   51150
Make of Veh: (Client's Record)	EP. / REV 24 HRS	9	Excess: _	fler lown	D. Endorsement:
Make of Veh: (Client's Record)		9	Excess: _	fler lown H.O	.D. Endorsement:
Make of Veh: (Client's Record)  CA / REV / R  Date/Time: 9,2	gamo islislis	Person Contacted:	Excess: _ 1.2018 @ 9 Kerylyn	fler loum, H.O	.D. Endorsement:
Make of Veh: (Client's Record)  CA / REV / R  Date/Time: 9,2	etion/instruction (	Person Contacted:	Excess: _ 1.2018 @ 9 Kerylyn	fler lown H.O	.D. Endorsement:
Make of Veh: (Client's Record)  CA / REV / R  Date/Time: 9,2	gamo islislis	Person Contacted:	Excess: _ 1.2018 @ 9 Kerylyn	fler lown H.O	.D. Endorsement:
Make of Veh: (Client's Record)  CA / REV / R  Date/Time: 9,2	ction/Instruction ( C	Person Contacted:	Excess: _ 1.2018 @ 9  Kerylyn	fler lown H.O	.D. Endorsement:
Make of Veh: (Client's Record)  CA / REV / R  Date/Time: 9,2	etion/instruction (	Person Contacted:	Excess: _ 1.2018 @ 9  Kerylyn	fler lown H.O	D. Endorsement: IN 1 6079

Lump Sum / I.B.I. (\$ 3.887.69 P/P)

Report Format:

211

Weekend 1\$

Tech Invs (\$

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D18008747MFSH

Date: 20 December 2018

Our Ref: CS/FCI18022342/R1sd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


# INITIAL INSPECTION REPORT OF VEHICLE NO. <u>SLZ 2535G</u>.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/12/2018 at the premises of M/s Cycle & Carriage Industries Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,392.54	
Revised Estimate Amount	: SS	3,887.69	
"Check" Items Amount	: S\$	184.85	2.
Market Value	: <u>S</u> \$		
LTA Reimbursement Value	: <u>S</u> \$		
Nett Value	: <u>S</u> \$		

### Description of Damage:

The vehicle sustained damages at the rear portion.



#### Comments/ Present Status:

Damages Consistent. Repair days: 3 Days

Yours faithfully, Mohammed Rasul Automotive Assessor



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims 8 Motor Underwilling Dept 36 Robinson Road #16-D1 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

#### MOTOR SURVEY ASSIGNMENT

Date

10-12-2018

Our Ref No. D18008747MFSH

Accident Date

07-12-2018

Claim Type. Third Party

Insured Vehicle

SHA1977A

Third Party Vehicle. SLZ2535G

Survey Location

PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP

Contact Person.

KERLYN ONG

Contact No.

67714420/ 91865113

Fax No. 68721272

Survey Type

DIRECT SETTLEMENT:

Appointed

LKK AUTO CONSULTANTS PTE LTD

Surveyor Contact Person

NA

Fax No. 68416315

Contact Number.

NA

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

CYCLE & CARRIAGE INDUSTRIES PTE LTD

Attention, NIL

Cc : TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

JOANNEY

#### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

### Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Thursday, 3 January 2019 11:30 AM

To:

'Kerlyn Ong'

Cc:

'Rasul (LKKAuto)'; 'Admin-D (LKKAuto)'

Subject:

RE: SLZ2535G

Dear Kerlyn,

Confirmed final fig of \$ 3,887.69 (part by part) @ 3 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25

| S(408933)

----Original Message-----

From: Kerlyn Ong [mailto:kerlyn.ong@cyclecarriage.com.sg]

Sent: Wednesday, 26 December 2018 3:12 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: SLZ2535G

Dear Rasul,

Please proceed to finalize.

Your Sincerely,

Kerlyn Ong Service Advisor - Body Care & Repair Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd 188 Pandan Loop Service Center

Mobile: 91865113 | DID: 67714420 | Fax: 68721272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

### Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Thursday, 20 December 2018 5:07 PM

To:

'Joanne Yong Lai fong'; 'CWS Motor Claims'

Cc:

assignments; SUR; Admin-D (LKKAuto) RE: SURVEY ASSESSMENT - D18008747MFSH/1

Subject: Attachments:

SLZ 2535G - Preli Advise.pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SLZ 2535G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, 12 December 2018 9:39 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18008747MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 11 December 2018 5:49 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong

<Joanneyong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18008747MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

This email has been checked for viruses by AVG antivirus software.
www.avg.com



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

## **ESTIMATE FOR SLZ2535G**

Micro-Fab Engineering Pte Ltd

280 Woodlands Industrial Park E5 #07-36 Harvest @ Woodlands Singapore 757322 Attn: Mr Cheng Ye

Vehicle & Document Information

29218 WIP No

/ 27/04/2018 **SLZ2535G** Reg No/Reg Date

Date In/Mileage

WDD2050402R352502 Chassis No

Engine No

27491031207512

Make/Model

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A 021 149 Polar White/ 041 101 Leather Bla

1 0

Colour/Trim Operator CSE Terms Date/Time Printed Account No 301 / Kerlyn Ong KO CRDVCH 10/12/2018/ 11:13 WCV35065 Unit Price Disc% Amount Qty Description of Goods / Services Z REQUEST Customer Request A BPILAB DISASSEMBLE AND REPAIR REAR BUMPER & REFINISH. A BPIRES RESPRAY REAR BUMPER M BPNSUN POLICY NO/ACC DATE : // 07/12/2018 : 07/12/2018 // SHA1977A - III DRIVE IN/EXCESS DATE IN/DATE SURVEY: BY/AUTHRIZED ON 0.10 380.00 A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY IDENTIFICATION STANDARD. NETT 120.00 A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT 1559.46 1559.46 00.00 1.00 REAR BUMPER DE 208.27 00.00 208.27 1.00 REAR BUMPER LOWER TRIM SOC 29.98 29.98 00.00 1.00 LH/ REAR BUMPER BRACKET No & 29.98 29.98 00.00 1.00 RH/ REAR BUMPER BRACKET 100.55 11 100.55 00.00 1.00

CTR/ BASIC MOUNTING FOR BUMPER Kerlyn One Kai Li DID: 6771 4420 HP: 9186 3113

Email: kerlyn.ong@cyclecarriage.com.sg Cycle & Carriage Industries Pre Ltd. Customer Service Centre - Pangan Loop

3 days 18/12/18 @ 1200hs Resur by paint

1.00

Confirmed & accepted by

COVER BUMPER AREA

Nett 5392.54 7% GST on

84.30

00.00

5,392.54 377.48

84.30 XA4

**Total Payable** 

5,770.02

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commonced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

## **ESTIMATE FOR SLZ2535G**

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 65073848 Venicle & Document Illiothauc

29218

Reg No/Reg Date S

Date In/Mileage

Chassis No

WIP No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

SLZ2535G / 27/04/2018

18/12/20/18/5 7253 WDD2050402R352502

27491031207512

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A 021 149 Polar White/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	3741263 U		Sta_88-75	
WF001862	Credit	21/12/2018/ 11:07	КО	301 / Kerlyn Ong		11 37 E 47 5 1		Aurent 4
		Description of Good	ls / Services		Qty	Unit Price	Disc%	Amount
Z REQUEST	- H	A TONA	NIC	FFICIAL	TA	VIA	IVIC	NCE
Customer	Request	NUIA	NO	FFICIAL	. 1 /~	11	ABE	950400
DISASSEM	BLE AND RE	PAIR REAR BUMPER & R						600.00
A BPIRES						7		000100
	REAR BUMPE	ER			210	3	- 1	
M BPNSUN	IO /ACC DATE	: D18MTPV01007785 /	/ 07/12/201	8	117			
DRIVE TO	W/FXCFSS	: 07/12/2018 // SHA	1977A - III		11 15			
DATE IN	DATE SURVE	FY: 18/12/2018 1200 /	/ LKK - KHS	OF 1111	11 -			
	SETTLEMENT		IRST CAPITA	L-JOANNEY 1	-		0.10	380.00
A BPILAB		HARTIO TO CUECK ON CO	TOUR HOUTE	pe de John Miller Ltd			39,742	
USING X	ENTRY DIAG	NOSTIC TO CHECK ON CO ANDARD. NETT	MIKOLONEI	J. Hiller Dr.			- 1	
A DOTLAD			2	11/1/2				120.00
CHECK R	EAR LIGHTI	NG SYSTEM AND WATER	EST FOR ANY	LEAKAGE. NETT	1 00	1559.46	00.00	1559.46
X REAR BUI	MPER		7) 4		1.00	208.27	00.00	208.27
X REAR BU	MPER LOWER	TRIM C	1)		1.00	29.98	00.00	29.98
X LH/ REA	R BUMPER B	PACKET \	<del>5</del> 713		1.00	29.98	00.00	29.98
A KH/ KEA	N DUNFER D	NACKE!					- 1	

Finalization

Confirmed & accepted by

Nett T on 3887.69 3,887.69

7% GST on 388

272.14

Total Payable

4,159.83

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required. Someonic of the work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, required after work has started and needed for repairs or replacement. However, should this occur, required after work has started and needed for repairs or replacement. However, should this occur, required after work has started and needed for repairs or replacement. However, has a commenced



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 9388 Fax: 6779 5383 www.mercedes-benz.com.sg



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internati	ionale Des Experts En Autom	obile	
MS FIRST CAPITAL		Ref : CS/FCI1802234		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 04-01-2019 Code: FCl2		
	Policy Particulars	s :- THIRD PARTY CLAI	M	
Insured Veh.	SHA 1977A	Veh. Inspected	SLZ 2535G	
Policy No.	***************************************	Coverage (\$)	0.00	
Claim No.	D18008747MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	11/12/2018	
2.	Vehicle Par	ticulars & Condition		
Make & Mode	MERCEDES BENZ C180 AV	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD2050402R352502	Colour	WHITE	
Odometer	7253	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3.	Cond	itions of Tyres		
	Size	Make	Balance	
R/H Front Ty	re 225/50 R17	BRIDGESTONE	6 mm	
L/H Front Ty	re 225/50 R17	BRIDGESTONE	6 mm	
R/H Rear Tyr	e 225/50 R17	BRIDGESTONE	6 mm	
L/H Rear Tyr	e 225/50 R17	BRIDGESTONE	6 mm	
4.		otion of Damages		
	SUSTAINED DAMAGES AT THE I	REAR PORTION.		
DAMAGES SE			The second second	
5.		eral Information	18/12/2018	
Accident Da		Inspection Date	16/12/2016	
Survey held	at CYCLE & CARRIAGE INDUS 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)	TRIES (1986) PL		
5a.		Remarks	A ME CONTRACTOR OF THE PARTY OF	
DITHE INCRE	CONSISTENT TO ACCIDENT REP CTION WAS CONDUCTED ON A"\ DANCE TO YOUR INSTRUCTIONS	WE HAVE NOT AUTHOR	ASIS. ISED REPAIRS.	
5b.	Estima	ate Days of Repair		

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 2535G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1 1 1 1	REPLACEMENT OF PARTS  REAR BUMPER (SN)  REAR BUMPER LOWER TRIM (SN)  LH/REAR BUMPER BRACKET (SN)  RH/REAR BUMPER BRACKET (SN)  COVER BUMPER AREA (SN)  CTR/BASIC MOUNTING FOR BUMPER (SN)  LABOUR  DISASSEMBLE AND REPAIR REAR BUMPER & REFINISH,  RESPRAY REAR BUMPER.  USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL  UNIT RESET MEMORY TO IDENTIFICATION STANDARD.	DEFORMED SCRATCHED NECESSARY NECESSARY NOT NECESSARY NOT NECESSARY	1,559.46 208.27 29.98 29.98 100.55 84.30 2,012.54 1,920.00 960.00 380.00	208.27 29.98 29.98 1,827.69 960.00 600.00 380.00
	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE.  GRAND TOTAL		3,380.00 5,392.54	2,060.0

RECOMMENDED COST OF REPAIRS	3,887.69
RECOMMENDED COST OF REPAIRS	

Report Ref No. CS/FCI18022342/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

N/S

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.