

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 21 Dec 2018

**Preliminary Advice**

|                    |                                                                                          |                         |              |
|--------------------|------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKW6369X                                                                               | Accident Date           | : 23/11/2018 |
| TP Vehicle No      | : FB3887G                                                                                | Assignment Date         | : 12/12/2018 |
| Make               | : VESPA PX20                                                                             | Est. Duration of Repair | : 6.00       |
| Date of Inspection | : 17/12/2018                                                                             |                         |              |
| Inspection At      | : HKL LIM TEAM MOTORSPORT (HQ)<br>BLK 1008 #01-24 BUKIT MERAH LANE 3<br>SINGAPORE 159722 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 2,680.00 |
| Revised Amount              | :S\$ | 1,330.00 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 1,330.00 |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |  |
|--------------------|------|--|
| New for Old Value  | :S\$ |  |
| Pre-Accident Value | :S\$ |  |
| COE / PARF Rebate  | :S\$ |  |
| Salvage Value      | :S\$ |  |
| Margin for Repair  | :S\$ |  |

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.