## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO: SH 7035L

MAKE

aluni pbyP 814:25 e CHINA

Qty	Parts Description/ Labour	Type	Un	it Price	I	Amount	
Qij	Rear Bumper	- J F -			\$	459.40	7
	Rear Bumper Reinforcement ?				\$	294.80	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$	138.10	\$	276.20	- 1
	Rear Bumper Lower Centre Moulding Assy		_		\$	270.10	- 1
	Rear Bumper Side Bracket (LH/RH) *		\$	33.10	\$	66.20	
	Rear Bumper Cover Clips —				\$	2.20	- 1
	Rear Bumper Under Centre .?				\$	53.85	
	Rear Bumper Side Under(LH/RH)		\$	27.50	\$	55.00	
	Rear Bumper Reflector Lamp (LH/RH) >		S	31.90	\$	63.80	- 1
	Real Bumper Reflector Lamp (Ell/Ref)		Ψ	31.50	Ψ	05.00	
	SUB TOTAL				\$	1,541.55	5
	LESS 20%				\$	308.31	
	DISCOUNTED TOTAL				\$	1,233.24	1
	Rear Bumper Advertisement Logo 🗶				\$	50.00	
	Rear Bumper Rubber Mat				\$	50.00	)
					\$	100.00	)
	Labour Charge Panel Beating				S	200 400.00	_
	Spray Painting Charge				\$	300.00	-
	Wiring Charge				\$	30.00	
	Remove/Refix Reverse Sensor				\$	120.00	- 1
					1		
	ESTIMATE TOTAL		in he is	ce notify	\$\	850.00	)
	ESTIMATE TOTAL	Auto Cons Repairer of	the following	ig:	-	2 192 24	Н
	ESTIMATE TOTAL	Repairer of o resurvey before display dam	relatter spray	painting uring resurvey onfirmation vithout Prejudice" by	\$	2,183.24	4
	\ •	O Too dam	aged heet to c	ontilling Prejudice D	sis	1	
	k / 1/1/1/4.	Parts prices a Third party si No illegal me	18 SUU) - n 3"	Althour.	d	\	
	Ca un 1000	Third party s	dification(s)	s allowed s allowed just be resurveyed and suit from Insurance Co lift from Insurance Co	mpany	\	
	1/ /	• No illegar	ary item(s)	al from Insure		1	
	11 11/12/18 1/cos	is subject	d Illian - i	70		1	
	11 11010 16019	Lanwled	ged by Repair				
	2 60	Signature	:				
	2100	Date:					
	PP						
	1 0 0 1	11					
	R. Sore Party 6	Co					
	Kabrilley  11/12/18 1600 A  2 PZ  PPP  Before Part p		1-				
	This is an initial estimate by the state of	h	histo Ti	final name in a	L .	veil1	$\dashv$
	This is an initial estimate based on a visual inspection of the	ne above ve	enicle. The	inai repair qu	uantu	III WIII	