

ASS. REC. BY:

REF:

C3/CTI18022106/R1sd361

Special Instruction:

Surveyor:

R1811

ASSIGNMENT (Office)

From (Person):

Eleine cheong

of

CTI

Date/Time:

12/12/18 @ 4:27pm

Estimated Cost:

Bill to:

OD / ~~TP~~

WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC173Z

Insured:

SLS 7365J

at Workshop m/s:

Ding Automotive

Tel:

83039588

of

31 Corporation Rd

Policy No:

DMPCSN 3065021800

Claim No:

8NM18D05730C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/12/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

13/12/18 @ 9:29am

Person Contacted:

Alex

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHC173Z-CS3/FCI18012976/G24/3s2

DUA: 13/07/18

SLS 7365J-X.

Refuse

REF: CTS

ASSIGNMENT

28324
COT 24/04/2020/11

From: Date: 13/12/2018

Veh No: SHC1732 Yr Began: 2012 Anh

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / ☒ / Prime Mover /

OD / ☒ / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SHC1732

Make: Hyundai Sonata 2.0 C.C. 1991

at Workshop no:

Ding Automotive
31 Corporation Road

Colour: yellow A/C Insured / Std / NI / NA

of:

Sp Reading: 699366 T/Reader: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: KMHET41VM C4824570

Claims No:

Gen. Cond: Good / ☒ / Poor / Burnt

Sum Insured

Excess:

Steering: ☒ / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ / Jammed / Leaked / Burnt or

Make of Veh:

Mod: ☒ / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 215/60R16
R:

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or TRIANGLE

Est. or Market Value:

Front

Rear

IDAC Accident Report Consistent? Yes or No

R/Bal. S mm R/Bal. S mm

GIA / PR Seen Consistent? Yes or No

L/Bal. S mm L/Bal. S mm

Est. Repairs: days Res: Yes or No

D.O.A. 08/12/18 D.O.I. 13/12/18

Lump Sum: % 3 Val: Yes or No

Survey held at DANK BUN

CA / REV / REP. / 24 HRS *lup*

Des. of Damages: ☒ / Rear / O/S / N/S / UIC / Rooftop or

Date: Person Contacted

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

refer to email repair / mit Sk only
08/01/19 Confirmed HS \$ 9,000/- @ 10 days with Result.
(\$13,301.21 - Red 60%)

RECEIVED 04 JAN 2019

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair: 10

01/01/19

☒ : Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to?

Survey Fee: 220

3

Add Fee: ☐ Site Insp (\$

Interpretation

Report Format :

☐ Interview (\$

1 Photos

Lump Sum / I.B.E (\$ 9,000/- HS

☐ Tech. Invs (\$

1 Other

☐ Weekend (\$

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2018		12 Dec 2018 16:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SITI RUGAYAH BINTE OSMAN, ID: S75377628		
Main Claimant:	CITYCAB PTE LTD		
Vehicle Reg. No.:	SHC173Z	Date of Loss:	08/12/2018 16:00 - :59
Claim Type:	TP / SNM18D05730C02	Policy/Cover Note No.:	DMPCSN3065021800 (Comprehensive)
Vehicle Reg. No. (Insured):	SLS7365J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/12/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2839G
Vehicle Details	
Vehicle No.:	SHC173Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Dec 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Yellow
Manufacturing Year:	2012
Engine No.:	D4EAC086306
Chassis No.:	KMHET41VMCA824570
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,552.00
Original Registration Date:	30 Apr 2012
First Registration Date:	30 Apr 2012
Transfer Count:	0
Actual ARF Paid:	\$14,552.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2020
PARF Rebate Amount:	\$9,458.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$42,384.00
COE Rebate Amount:	\$7,314.00
Total Rebate Amount:	\$16,772.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Dec 2018.

OK

Report ID : R2107222
DATE : 12.12.2018
TIME : 11:25:07

CityCops Pvt Ltd
Vehicle KM For Fleet Safety Division
AS AT 30.11.2018

Case ID : C2750203
PAGE : 1

Co. Code : C03
License Pl. No : SBC01732
Old Asset No :
Veh. Model : Hyundai Sonata
Reg. Date : 30.04.2012
Cap. Date : 30.04.2012
Accident Date : 09.12.2018
Veh. Age : 080

DATE OF ACCIDENT - 08/12/18

Asset No	SA No	Sal Dep Mths	Per Ach Dep	Sal Dep Value	Asset Description 1	Cost	Op. Acc. Dep	Cur. Year Dep	Accum. Dep	Net Book Value	Scrap Value/Estimated RNF Fatured
1000809	0	010	242.54	2,425.40	SBC01732 HST 30.04.2012 BASIC C2BT 218130 W ATRCOM	21,830.00	16,735.56	2,468.00	19,403.56	2,426.44	1.00
1000809	1	010	32.34	323.40	SBC01732 HST 30.04.2012 EXPORT DUTY	2,910.29	2,211.23	355.69	2,586.92	323.37	0.00
1000809	2	010	64.68	646.80	SBC01732 HST 30.04.2012 ASF 100600914552	34,552.00	4,462.76	711.46	5,174.22	9,377.78	8,731.00
1000809	3	010	470.93	4,709.30	SBC01732 HST 30.04.2012 CSE 80V	42,384.00	52,494.60	5,180.27	37,674.67	4,709.33	0.00
1000809	4	000	0.00	0.00	SBC01732 HST 30.04.2012 CSE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
1000809	5	010	0.00	0.00	SBC01732 HST 30.04.2012 AIR CONDITIONER	- 70	0.00	0.00	0.00	0.00	0.00
1000809	6	010	0.00	0.00	SBC01732 HST 30.04.2012 PRINTER DIGITAL THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
1000809	7	010	0.00	0.00	SBC01732 HST 30.04.2012 TAXIDETER DIGITAL F1	0.00	0.00	0.00	0.00	0.00	0.00
1000809	8	010	1.36	15.60	SBC01732 HST 30.04.2012 VEH REG FEE	140.00	167.34	17.11	124.45	15.55	0.00
			812.05	8,120.50		81,816.29	56,031.29	8,332.53	64,963.82	16,852.67	

COE	Vehicle
470.93	Vehicle : Without T/A & CSE
341.22	Vehicle : Without T/A, With COE
812.05	Taximeter

Cost. After - 81,816.29

ARE 60% - 8731.00

Depreciation - 81,816.29 - 8731.00 ÷ 96

= 761.30

(761.30 x 24) + 8731

= 27002.20

27,002.20 - 16,772 = 10,230.20 - 500
repair fund 9730.70
OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 4 January 2019 10:41 AM
To: 'Michelle'
Cc: taxiscs@stengg.com; Admin A; Asher Sng (LKKAuto); SUR; Thin Thin (LKKAuto); Vivian Lau (LKKAuto); CARLOR.CHAN@DINGAUTO.SG; KELLY.DING@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG; KENNETH.DING@DINGAUTO.SG; Rasul (LKKAuto)
Subject: RE: 50111195/SHC0173Z - FINALIZE AMOUNT AND AFTER PAINT PIC

Hi Michelle,

Confirmed final fig of \$9,000.00 (lump sum) @ 10 days of repairs.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you,

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michelle [mailto:accounts@dingauto.sg]
Sent: Friday, 4 January 2019 9:04 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: taxiscs@stengg.com; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; SUR <sur@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; CARLOR.CHAN@DINGAUTO.SG; KELLY.DING@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG; KENNETH.DING@DINGAUTO.SG; Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: Re: 50111195/SHC0173Z - FINALIZE AMOUNT AND AFTER PAINT PIC

Morning Shirley,

We confirm the finalize amount.

Thank you so much

Yours sincerely

Michelle Fang

92394128

Ding Automotive Pte Ltd

On 3/1/2019 5:11 PM, Shirley Hiew (LKK Auto) wrote:

Dear Michelle,

Please re-confirm the final figure.

Labour - \$3,390.00
Special Netts - \$580.00
Parts after discount 20% = \$8,477.82
Final Amount L+S+P = \$12,447.82

Finalize Amount After -20 % = \$9,958.26

Repair Limit \$9000.00 before GST

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michelle [<mailto:accounts@dingauto.sg>]

Sent: Thursday, 3 January 2019 12:04 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: taxiscs@stengg.com; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; SUR <sur@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; CARLOR.CHAN@DINGAUTO.SG; KELLY.DING@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG; KENNETH.DING@DINGAUTO.SG

Subject: Re: 50111195/SHC0173Z - FINALIZE AMOUNT AND AFTER PAINT PIC

Dear Rasul,

Good day to you.

We would like to check and follow up on our finalize amount for this case as we have not hear from you.

Kindly please provide us your finalize amount for us to close this case on our end.

We sincerely look forward to receive your finalize for our repair.

Thank you so much.

Yours sincerely

Michelle Fang

92394128

Ding Automotive Pte Ltd

On 21/12/2018 5:08 PM, taxiscs@stengg.com wrote:

Dear Rasul

Please see below for the finalize according to our conversion to finalize for

SHC173Z

Kindly check the attach after paint

Total Repair - 10 Days

L/S REPAIR

Labour - \$3590.00

Special Netts - \$580.00

Parts after discount 20% = \$7556.20

Final Amount L+S+P = \$11726.20

Finalize Amount After -20 % = \$9380.96

Repair Limit \$9000.00 before GST

Please confirm the finalize amount @9000.00 with 10days repair days

Please help to close this case ASAP

Thanks

Best Regards
Ding Automotive Pte Ltd
Jing Feng
Hp : 62657130

From: "Rasul (LKKAUTO)" <Rasul@lkkauto.com>
To: Taxis Customer Service/KAS/CBG/ST Kinetics@ST Engineering
Cc: "SUR" <sur@lkkauto.com>, "Asher Sng (LKKAUTO)" <AsherSng@lkkauto.com>, "Vivian Lau (LKKAUTO)" <vivianlau@lkkauto.com>, "T (LKKAUTO)" <thinthin@lkkauto.com>, "Admin A" <admin-a@lkkauto.com>
Date: Tue 18 Dec 2018 05:10 PM
Subject: RE: SHC0173Z DOA : 08/12/2018 (NAF case) - Serious Damaged at Front & Rear portion - Request Log Card / Book Value & Proje

***WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST
ENGINEERING.***

Hi Ding,

Repair limit to repair this vehicle is 9K only

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: taxiscs@stengg.com [<mailto:taxiscs@stengg.com>]

Sent: Saturday, 15 December, 2018 10:51 AM

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Tuesday, 18 December 2018 5:09 PM
To: taxiscs@stengg.com
Cc: SUR; Asher Sng (LKKAuto); Vivian Lau (LKKAuto); Thin Thin (LKKAuto); Admin A
Subject: RE: SHC0173Z DOA : 08/12/2018 (NAF case) - Serious Damaged at Front & Rear portion - Request Log Card / Book Value & Projection Value

Hi Ding,

Repair limit to repair this vehicle is 9K only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: taxiscs@stengg.com [mailto:taxiscs@stengg.com]
Sent: Saturday, 15 December, 2018 10:51 AM
To: Rasul (LKKAuto)
Cc: SUR; Asher Sng (LKKAuto); Vivian Lau (LKKAuto); Thin Thin (LKKAuto); Admin A
Subject: Fw: SHC0173Z DOA : 08/12/2018 (NAF case) - Serious Damaged at Front & Rear portion - Request Log Card / Book Value & Projection Value

Dear Rasul ,

Kindly provide us the taxis SHC173Z maximum repair cost .

Thanks

Best Regards

Ding Automotive Pte Ltd
Alex Khong
Hp : 62657130

----- Forwarded by Taxis Customer Service/KAS/CBG/ST Kinetics on Sat 15 Dec 2018 10:41 AM -----

From: "Doris Lim Puay Noi" <doris_lim@cdgtaxi.com.sg>
To: WONG Siew Keong/Snr SA-KAS/CBG/ST Kinetics@ST Engineering
Cc: Taxis Customer Service/KAS/CBG/ST Kinetics@ST Engineering
Date: Wed 12 Dec 2018 12:15 PM
Subject: Re: SHC0173Z DOA : 08/12/2018 (NAF case) - Serious Damaged at Front & Rear portion - Request Log Card / Book Value & Projection Value

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 10:35
Date Of Accident	08/12/2018 16:30
Exact Location Of Accident	ALONG LORNIE RAOD TOWRDS UPPER THOMSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC0173Z
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 CRDI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	CHIA YUE BOON
NRIC No	S0230738C
Date Of Birth	06/08/1954
Occupation	OUTDOOR
Date Of Driving Pass	21/08/1972
Driving Experience	46 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98554992
Fax Number	
Contact Number	

Address	BLK449 SIN MING AVE #03/519
Postcode	570449
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH STATEMENTS

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE NOT SUITABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ5180D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JOVITA
NRIC/Passport Number	S1809999C
Contact Number	
Address	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLS7365J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SITI RUGAYAH
NRIC/Passport Number	S7537762B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mailed packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Accident Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/12/18 around 1630HR, I was driving along Lornie Road towards upper Thomson Road, I was on first lane (from right) on that time, front got one motorcycle fall down himself and I change to lane two, After I have change lane I have feel Impact, and I hit front veh (SKZ 5180M) (SLS 7365J) and Rear veh hit my veh

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

11/12/2018 15:56

JOB-NO: 50111195

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC0173Z

TRANS: AUTO

CHASSIS: KMHET41VMCA824570

MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDi

ENGINE: D4EAC086306

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	2,500.00	0.00	2,500.00 1600		1500	Y
2 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00 60			Y
3 R&R SPARE TYRE BOARD, CARPET, TRIM AND ETC	1.00	250.00	0.00	250.00 60			Y
4 R&R REAR EXHAUST MUFFLER	1.00	180.00	0.00	180.00 X			Y
5 R&R REAR FUEL TANK	1.00	250.00	0.00	250.00 X			Y
6 R&R CONDENSOR AND RADIOTR AND REFILL AIRCON GAS	1.00	180.00	0.00	180.00 100			Y
7 R&R REVERSE SENSOR AND SPRAY REVERSE SENSOR	1.00	120.00	0.00	120.00 60			Y
8 CHECK WIRING	1.00	150.00	0.00	150.00 70 X 1111			Y
9 R&R BONNET COMPONENTS	1.00	80.00	0.00	80.00 X			Y
10 RUSH PROOFING	1.00	120.00	0.00	120.00 80			Y
11 ADJUST HEAD LAMP AIM	1.00	50.00	0.00	50.00 30			Y
12 SPRAY REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER LH, REAR FENDER RH, SPARE TYRE PANEL	1.00	1,200.00	0.00	1,200.00 900			Y
13 SPRAY FRONT BUMPER, FRONT FENDER LHS, FRONT FENDER RHS, BONNET	1.00	1,200.00	0.00	1,200.00 600			Y
14 MOUNT WORKBENCH TO ALIGNMENT CHASSIS	1.00	350.00	0.00	350.00 200 (photo)? Xin			Y
TOTAL:		6,780.00	0.00	6,780.00			

MATERIALS

1 REAR BUMPER DE / ? 220 /	1.00	523.93	104.79	419.14	L	Y	
2 REAR BUMPER REINF ? 32 /	1.00	462.30	92.46	369.84	L	Y	
3 REAR BUMPER REINF ARM LH ? 32 /	1.00	79.75	15.95	63.80	L	Y	
4 REAR BUMPER REINF ARM RH ? 32 /	1.00	79.75	15.95	63.80	L	Y	
5 REAR BUMPER RETAINER LH NE /	1.00	42.68	8.54	34.14	L	Y	
6 REAR BUMPER RETIANER RH NE /	1.00	42.68	8.54	34.14	L	Y	
7 REAR BUMPER SPONGE ? 120 /	1.00	113.52	22.70	90.82	L	Y	
8 REAR BUMPER PROTECTOR LH DE /	1.00	102.96	20.59	82.37	L	Y	
9 REAR BUMPER PROTECTOR RH DE /	1.00	102.96	20.59	82.37	L	Y	
10 BOOTLID 91 /	1.00	1,139.00	227.80	911.20	L	Y	
11 BOOTLID EMBLEM LOGO NE /	1.00	40.92	8.18	32.74	L	Y	
12 BOOTLID EMBLEM HYUNDAI NE /	1.00	40.92	8.18	32.74	L	Y	
13 BOOTLID EMBLEM SONATA NE /	1.00	40.92	8.18	32.74	L	Y	
14 BOOTLID EMBLEM CRDI NE /	1.00	40.92	8.18	32.74	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
15 BOOTLID LAMP LH	1.00	203.50	40.70	162.80	L	Y	
16 BOOTLID LAMP RH	1.00	203.50	40.70	162.80	L	Y	
17 BOOTLID PLATE LAMP LH	1.00	49.50	9.90	39.60	L	Y	
18 BOOTLID PLATE LAMP RH	1.00	49.50	9.90	39.60	L	Y	
19 BOOTLID LOCK	1.00	109.45	21.89	87.56	L	Y	
20 BOOTLID LOCK CATCH	1.00	108.90	21.78	87.12	L	Y	
21 BOOTLID INSULATOR	1.00	155.10	31.02	124.08	L	Y	
22 BOOTLID RUBBER BEADING	1.00	91.30	18.26	73.04	L	Y	
23 BOOTLID HINGE LH	1.00	140.80	28.16	112.64	L	Y	
24 BOOTLID HINGE RH	1.00	140.80	28.16	112.64	L	Y	
25 REAR END PANEL	1.00	323.29	64.66	258.63	L	Y	
26 REAR END PANEL TOP GARNISH	1.00	42.02	8.40	33.62	L	Y	
27 TAIL LAMP LH	1.00	323.40	64.68	258.72	L	Y	
28 TAIL LAMP RH	1.00	323.40	64.68	258.72	L	Y	
29 SPARETYRE PANEL	1.00	812.90	162.58	650.32	L	Y	
30 REAR FENDER LH	1.00	1,598.30	319.66	1,278.64	L	Y	
31 REAR FENDER RH	1.00	1,598.30	319.66	1,278.64	L	Y	
32 REAR WINDSCREEN MOULDING	1.00	23.10	4.62	18.48	L	Y	
33 BONNET	1.00	1,101.76	220.35	881.41	L	Y	
34 BONNET HINGE LH	1.00	79.20	15.84	63.36	L	Y	
35 BONNET HINGE RH	1.00	79.20	15.84	63.36	L	Y	
36 BONNET DAMPER LH	1.00	67.76	13.55	54.21	L	Y	
37 BONNET DAMPER RH	1.00	67.76	13.55	54.21	L	Y	
38 BONNET INSULATOR	1.00	222.75	44.55	178.20	L	Y	
39 BONNET CHROME	1.00	101.75	20.35	81.40	L	Y	
40 BONNET LOCK	1.00	108.90	21.78	87.12	L	Y	
41 FRONT BUMPER	1.00	515.68	103.14	412.54	L	Y	
42 FRONT BUMPER REINF	1.00	472.78	94.56	378.22	L	Y	
43 FRONT BUMPER RETAINER LH	1.00	29.98	6.00	23.98	L	Y	
44 FRONT BUMPER RETAINER RH	1.00	29.98	6.00	23.98	L	Y	
45 FRONT BUMPER CENTRE GRILLE	1.00	450.40	90.08	360.32	L	Y	
46 FRONT BUMPER CHROME MLDG	1.00	91.52	18.30	73.22	L	Y	
47 FRONT BUMPER SPONGE	1.00	130.35	26.07	104.28	L	Y	
48 FRONT BUMPER PROTECTOR LH	1.00	27.72	5.54	22.18	L	Y	
49 FRONT BUMPER PROTECTOR RH	1.00	27.72	5.54	22.18	L	Y	
50 SUPPORT PANEL	1.00	922.02	184.40	737.62	L	Y	
51 HEAD LAMP LH	1.00	763.18	152.64	610.54	L	Y	
52 HEAD LAMP RH	1.00	763.18	152.64	610.54	L	Y	
53 FRT FENDER LH	1.00	567.38	113.48	453.90	L	Y	
54 FRT FENDER RH	1.00	567.38	113.48	453.90	L	Y	
55 RADIATOR	1.00	764.06	152.81	611.25	L	Y	
56 CONDENSOR	1.00	1,042.58	208.52	834.06	L	Y	
57 REVERSE SENSOR	1.00	250.00	0.00	250.00	S	Y	
58 REAR BUMPER CLIPS	1.00	35.00	0.00	35.00	S	Y	
59 BOOTLID INSULATOR CLIPS	1.00	35.00	0.00	35.00	S	Y	
60 BOOTLID STICKER CAB BOOKING 65521111	1.00	120.00	0.00	120.00	S	Y	
61 BOOTLID STICKER CITYCAB	1.00	120.00	0.00	120.00	S	Y	
62 REAR NUMBER PLATE	1.00	35.00	0.00	35.00	S	Y	
63 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	
64 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	
65 SPARETYRE PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	
66 REAR WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	
67 REAR WINDSCREEN DAMPER	1.00	50.00	0.00	50.00	S	Y	
68 BONNET INSULATOR CLIPS	1.00	35.00	0.00	35.00	S	Y	
69 FRONT NUMBER PLATE&CASING	1.00	35.00	0.00	35.00	S	Y	
70 FRONT BUMPER CLIPS	1.00	35.00	0.00	35.00	S	Y	
71 FRONT FENDER INNERHSHIELD CLIP LH&RH	1.00	70.00	0.00	70.00	S	Y	
TOTAL		19,150.26	629.05	15,521.21			

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
TOTAL PARTS & LABOUR :		25,930.26	3,629.05	22,301.21			

EXCESS/LOADING: \$\$ 0.00

No. Of Day: 10 daysRE-SURVEY: BEFORE & AFTER PAINTING
PART-BY-PART OR LUMP SUM \$\$DATE OF SURVEY: 13 / 12 / 18 @ 1745SURVEYED BY: [Signature]CONTACT NO: 90010068

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

[Signature]
21/12/18

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

11/12/2018 15:56

OWNER'S PARTICULARS

JOB-NO: 50111195

NAME: CityCab PTE LTD (Fleet)

CONTACT: 85533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

84739522

VEHICLE DETAILS

LICENSE NO: SHC0173Z

TRANS: AUTO

CHASSIS: KMHET41VMCAR24570

MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDI

ENGINE: D4EAC086306

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	2,500.00	0.00	2,500.00		1500	Y
2 R&R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00		60	Y
3 R&R SPARE TYRE ,BOARD , CARPET,TRIM AND ETC	1.00	250.00	0.00	250.00		60	Y
4 R&R REAR EXHAUST MUFFLER	1.00	180.00	0.00	180.00		X	Y
5 R&R REAR FUEL TANK	1.00	250.00	0.00	250.00		X	Y
6 R&R CONDENSOR AND RADIATOR AND REFILL AIRCON GAS	1.00	180.00	0.00	180.00		100	Y
7 R&R REVERSE SENSOR AND SPRAY REVERSE SENSOR	1.00	120.00	0.00	120.00		60	Y
8 CHECK WIRING	1.00	150.00	0.00	150.00		70 X	Y
9 R&R BONNET COMPONENTS	1.00	80.00	0.00	80.00		X	Y
10 RUSH PROOFING	1.00	120.00	0.00	120.00		80	Y
11 ADJUST HEAD LAMP AIM	1.00	50.00	0.00	50.00		30	Y
12 SPRAY REAR BUMPER ,BOOTLID ,REAR END PANEL ,REAR FENDER LH,REAR FENDER RH , SPARE TYRE PANEL	1.00	1,200.00	0.00	1,200.00		900	Y
13 SPRAY FRONT BUMPER ,FRONT FENDER LHS ,FRONT FENDER RHS , BONNET	1.00	1,200.00	0.00	1,200.00		600	Y
14 MOUNT WORKBENCH TO ALIGNMENT CHASSIS	1.00	350.00	0.00	350.00		200 (photo)?	Y
TOTAL:		6,780.00	0.00	6,780.00			

MATERIALS

1 REAR BUMPER	1.00	523.93	104.79	419.14	L	Y
2 REAR BUMPER REINF	1.00	452.30	92.46	369.84	L	Y
3 REAR BUMPER REINF ARM LH	1.00	79.75	15.95	63.80	L	Y
4 REAR BUMPER REINF ARM RH	1.00	79.75	15.95	63.80	L	Y
5 REAR BUMPER RETAINER LH	1.00	42.68	8.54	34.14	L	Y
6 REAR BUMPER RETAINER RH	1.00	42.68	8.54	34.14	L	Y
7 REAR BUMPER SPONGE	1.00	113.52	22.70	90.82	L	Y
8 REAR BUMPER PROTECTOR LH	1.00	102.98	20.59	82.37	L	Y
9 REAR BUMPER PROTECTOR RH	1.00	102.98	20.59	82.37	L	Y
10 BOOTLID	1.00	1,139.00	227.80	911.20	L	Y
11 BOOTLID EMBLEM LOGO	1.00	40.92	8.18	32.74	L	Y
12 BOOTLID EMBLEM HYUNDAI	1.00	40.92	8.18	32.74	L	Y
13 BOOTLID EMBLEM SONATA	1.00	40.92	8.18	32.74	L	Y
14 BOOTLID EMBLEM CRDI	1.00	40.92	8.18	32.74	L	Y

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
15 BOOTLID LAMP LH	1.00	293.50	40.70	162.80	L	Y	
16 BOOTLID LAMP RH	1.00	293.50	40.70	162.80	L	Y	
17 BOOTLID PLATE LAMP LH	1.00	49.50	9.90	39.60	L	Y	
18 BOOTLID PLATE LAMP RH	1.00	49.50	9.90	39.60	L	Y	
19 BOOTLID LOCK	1.00	108.45	21.89	87.56	L	Y	
20 BOOTLID LOCK CATCH	1.00	108.90	21.78	87.12	L	Y	
21 BOOTLID INSULATOR	1.00	155.10	31.02	124.08	L	Y	
22 BOOTLID RUBBER BEADING	1.00	91.30	18.26	73.04	L	Y	
23 BOOTLID HINGE LH	1.00	140.80	28.16	112.64	L	Y	
24 BOOTLID HINGE RH	1.00	140.80	28.16	112.64	L	Y	
25 REAR END PANEL	1.00	323.29	64.66	258.63	L	Y	
26 REAR END PANEL TOP GARNISH	1.00	42.02	8.40	33.62	L	Y	
27 TAIL LAMP LH	1.00	323.40	64.68	258.72	L	Y	
28 TAIL LAMP RH	1.00	323.40	64.68	258.72	L	Y	
29 SPARETYRE PANEL	1.00	812.90	162.58	650.32	L	Y	
30 REAR FENDER LH	1.00	1,598.30	319.66	1,278.64	L	Y	
31 REAR FENDER RH	1.00	1,598.30	319.66	1,278.64	L	Y	
32 REAR WINDSCREEN MOULDING	1.00	23.10	4.62	18.48	L	Y	
33 BONNET	1.00	1,101.76	220.35	881.41	L	Y	
34 BONNET HINGE LH	1.00	79.20	15.84	63.36	L	Y	
35 BONNET HINGE RH	1.00	79.20	15.84	63.36	L	Y	
36 BONNET DAMPER LH	1.00	57.76	13.55	54.21	L	Y	
37 BONNET DAMPER RH	1.00	57.76	13.55	54.21	L	Y	
38 BONNET INSULATOR	1.00	222.75	44.55	178.20	L	Y	
39 BONNET CHROME	1.00	101.75	20.35	81.40	L	Y	
40 BONNET LOCK	1.00	108.90	21.78	87.12	L	Y	
41 FRONT BUMPER	1.00	515.88	103.14	412.54	L	Y	
42 FRONT BUMPER REINF	1.00	472.78	94.56	378.22	L	Y	
43 FRONT BUMPER RETAINER LH	1.00	29.98	6.00	23.98	L	Y	
44 FRONT BUMPER RETAINER RH	1.00	29.98	6.00	23.98	L	Y	
45 FRONT BUMPER CENTRE GRILLE	1.00	450.40	90.08	360.32	L	Y	
46 FRONT BUMPER CHROME MLDG	1.00	91.52	18.30	73.22	L	Y	
47 FRONT BUMPER SPONGE	1.00	130.35	26.07	104.28	L	Y	
48 FRONT BUMPER PROTECTOR LH	1.00	27.72	5.54	22.18	L	Y	
49 FRONT BUMPER PROTECTOR RH	1.00	27.72	5.54	22.18	L	Y	
50 SUPPORT PANEL	1.00	922.02	184.40	737.62	L	Y	
51 HEAD LAMP LH	1.00	763.16	152.64	610.54	L	Y	
52 HEAD LAMP RH	1.00	763.16	152.64	610.54	L	Y	
53 FRT FENDER LH	1.00	567.38	113.48	453.90	L	Y	
54 FRT FENDER RH	1.00	567.38	113.48	453.90	L	Y	
55 RADIATOR	1.00	764.06	152.81	611.25	L	Y	
56 CONDENSOR	1.00	1,042.58	208.52	834.06	L	Y	
57 REVERSE SENSOR	1.00	250.00	0.00	250.00	S	Y	
58 REAR BUMPER CLIPS	1.00	35.00	0.00	35.00	S	Y	
59 BOOTLID INSULATOR CLIPS	1.00	35.00	0.00	35.00	S	Y	
60 BOOTLID STICKER CAB BOOKING 65521111	1.00	120.00	0.00	120.00	S	Y	
61 BOOTLID STICKER CITYCAB	1.00	120.00	0.00	120.00	S	Y	
62 REAR NUMBER PLATE	1.00	35.00	0.00	35.00	S	Y	
63 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	
64 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	
65 SPARETYRE PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	
66 REAR WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	
67 REAR WINDSCREEN DAMPER	1.00	50.00	0.00	50.00	S	Y	
68 BONNET INSULATOR CLIPS	1.00	35.00	0.00	35.00	S	Y	
69 FRONT NUMBER PLATE&CASING	1.00	35.00	0.00	35.00	S	Y	
70 FRONT BUMPER CLIPS	1.00	35.00	0.00	35.00	S	Y	
71 FRONT FENDER INNERSHIELD CLIP LH&RH	1.00	70.00	0.00	70.00	S	Y	
TOTAL:		19,150.26	629.05	15,521.21			

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
TOTAL PARTS & LABOUR :		25,830.26	3,829.05	22,301.21			

EXCESS/LOADING:\$\$ 0.00

No. Of Day: 10 daysRE-SURVEY: BEFORE ~~AFTER~~ PAINTING
PART-BY-PART OR LUMP SUM \$\$DATE OF SURVEY: 13, 12, 18 @ 1745SURVEYED BY: PaulCONTACT NO: 90060068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2018		12 Dec 2018 16:27 Edit Adj Rpt	S\$9,000.00 Edit Estimates	S\$9,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SITI RUGAYAH BINTE OSMAN , ID: S7537762B									
Main Claimant: CITYCAB PTE LTD									
Vehicle Reg. No.: SHC173Z		Date of Loss: 08/12/2018 16:00 - :59 [79 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05730C02		Policy/Cover Note No.: DMPCSN3065021800 (Comprehensive)							
Vehicle Reg. No. (Insured): SL57365J		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/12/2018]									
Adj Asp. Remarks: NO EST, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC173Z (SNM18D05730C02)
[SLS7365J]
TP
CITYCAB PTE LTD
Dec 8 2018 4:00PM
[SITI RUGAYAH BINTE OSMAN]
Ding Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 13:57	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
8	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
9	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
10	10/12/18 13:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/01/19 10:48	Odometer Reading	 Load JPG	☒
2	04/01/19 10:48	Chassis Number	 Load JPG	☒
3	04/01/19 10:48	General View	 Load JPG	☒
4	04/01/19 10:48	General View	 Load JPG	☒
5	04/01/19 10:48	General View	 Load JPG	☒
6	04/01/19 10:48	General View	 Load JPG	☒
7	04/01/19 10:48	General View	 Load JPG	☒
8	04/01/19 10:48	General View	 Load JPG	☒
9	04/01/19 10:48	General View	 Load JPG	☒
10	04/01/19 10:48	General View	 Load JPG	☒
11	04/01/19 10:48	General View	 Load JPG	☒
12	04/01/19 10:48	General View	 Load JPG	☒
13	04/01/19 10:48	General View	 Load JPG	☒
14	04/01/19 10:48	General View	 Load JPG	☒
15	04/01/19 10:48	General View	 Load JPG	☒
16	04/01/19 10:48	General View	 Load JPG	☒
17	04/01/19 10:48	General View	 Load JPG	☒
18	04/01/19 10:48	General View	 Load JPG	☒
19	04/01/19 10:48	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
20	04/01/19 10:48	General View	 Load JPG	☒
21	04/01/19 10:48	General View	 Load JPG	☒
22	04/01/19 10:48	General View	 Load JPG	☒
23	04/01/19 10:48	General View	 Load JPG	☒
24	04/01/19 10:48	General View	 Load JPG	☒
25	04/01/19 10:48	General View	 Load JPG	☒
26	04/01/19 10:48	General View	 Load JPG	☒
27	04/01/19 10:48	General View	 Load JPG	☒
28	04/01/19 10:48	General View	 Load JPG	☒
29	04/01/19 10:48	General View	 Load JPG	☒
30	04/01/19 10:48	General View	 Load JPG	☒
31	04/01/19 10:48	General View	 Load JPG	☒
32	04/01/19 10:48	General View	 Load JPG	☒
33	04/01/19 10:48	General View	 Load JPG	☒
34	04/01/19 10:48	General View	 Load JPG	☒
35	04/01/19 10:48	General View	 Load JPG	☒
36	04/01/19 10:48	General View	 Load JPG	☒
37	04/01/19 10:48	General View	 Load JPG	☒
38	04/01/19 10:48	General View	 Load JPG	☒
39	04/01/19 10:48	General View	 Load JPG	☒
40	04/01/19 10:48	General View	 Load JPG	☒
41	04/01/19 10:48	General View	 Load JPG	☒
42	04/01/19 10:48	General View	 Load JPG	☒
43	04/01/19 10:48	General View	 Load JPG	☒
44	04/01/19 10:48	General View	 Load JPG	☒
45	04/01/19 10:48	General View	 Load JPG	☒
46	04/01/19 10:48	General View	 Load JPG	☒
47	04/01/19 10:48	General View	 Load JPG	☒
48	04/01/19 10:48	General View	 Load JPG	☒
49	04/01/19 10:48	General View	 Load JPG	☒
50	04/01/19 10:48	General View	 Load JPG	☒
51	04/01/19 10:48	General View	 Load JPG	☒
52	04/01/19 10:48	General View	 Load JPG	☒
53	04/01/19 10:48	General View	 Load JPG	☒
54	04/01/19 10:48	General View	 Load JPG	☒
55	04/01/19 10:48	General View	 Load JPG	☒
56	04/01/19 10:48	General View	 Load JPG	☒
57	04/01/19 10:48	General View	 Load JPG	☒
58	04/01/19 10:48	General View	 Load JPG	☒
59	04/01/19 10:48	General View	 Load JPG	☒
60	04/01/19 10:48	General View	 Load JPG	☒
61	04/01/19 10:48	General View	 Load JPG	☒
62	04/01/19 10:48	General View	 Load JPG	☒
63	04/01/19 10:48	General View	 Load JPG	☒
64	04/01/19 10:48	General View	 Load JPG	☒
65	04/01/19 10:48	General View	 Load JPG	☒
66	04/01/19 10:48	General View	 Load JPG	☒
67	04/01/19 10:48	Reinspection Photo	 Load JPG	☒
68	04/01/19 10:48	Reinspection Photo	 Load JPG	☒
69	04/01/19 10:48	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
70	04/01/19 10:48	Reinspection Photo	 Load JPG	☒
71	04/01/19 10:48	Reinspection Photo	 Load JPG	☒
72	04/01/19 10:48	Reinspection Photo	 Load JPG	☒
73	04/01/19 10:48	Reinspection Photo	 Load JPG	☒
74	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
75	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
76	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
77	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
78	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
79	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
80	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
81	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
82	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
83	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
84	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
85	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
86	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
87	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
88	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
89	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
90	04/01/19 10:49	Reinspection Photo	 Load JPG	☒
91	04/01/19 10:49	Reinspection Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/12/18 16:26	PRS	 Load PDF	
2	12/12/18 16:26	TP GIA	 Load PDF	
3	12/12/18 16:26	OT GIA	 Load PDF	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 13:39	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	10/12/18 13:39	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	10/12/18 13:39	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	☒
4	10/12/18 13:39	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	☒
5	10/12/18 13:39	Sketch Plan #5 [Linked Accident Report Documents]	 Load JPG	☒
6	10/12/18 13:39	Sketch Plan #6 [Linked Accident Report Documents]	 Load JPG	☒
7	10/12/18 13:40	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 13:57	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 13:46	Accident Photo	 Load JPG	☒
2	10/12/18 13:46	Accident Photo	 Load JPG	☒
3	10/12/18 13:46	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
4	10/12/18 13:46	Accident Photo	 Load JPG	☒
5	10/12/18 13:46	Accident Photo	 Load JPG	☒
6	10/12/18 13:46	Accident Photo	 Load JPG	☒
7	10/12/18 13:46	Accident Photo	 Load JPG	☒
8	10/12/18 13:46	Accident Photo	 Load JPG	☒
9	10/12/18 13:46	Accident Photo	 Load JPG	☒
10	10/12/18 13:46	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/12/18 13:39	Sketch Plan	 Load TIF	
2	10/12/18 13:39	Sketch Plan #2	 Load TIF	
3	10/12/18 13:39	Sketch Plan #3	 Load JPG	☒
4	10/12/18 13:39	Sketch Plan #4	 Load JPG	☒
5	10/12/18 13:39	Sketch Plan #5	 Load JPG	☒
6	10/12/18 13:39	Sketch Plan #6	 Load JPG	☒
7	10/12/18 13:40	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118022406/R1SD3E2

Date: 04/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3065021800

Claimant Vehicle
No: SHC173ZInsured Vehicle
No: SLS7365J

Date of Loss: 08/12/2018

Nature of Claim: TP

Claim
No: SNM18D05730C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC173Z

Make & Model: HYUNDAI SONATA, 2.0 (A)

Engine No: D4EAC086306

Reg. Date: 30/04/2012 (Man. Year: 2012)

Chassis No: KMHET41VMCA824570

Colour: Yellow

Odometer: 699366 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Triangle 5 mm	Rear Left Side:	Triangle 5 mm
Front Right Side:	Triangle 5 mm	Rear Right Side:	Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,521.21	9,057.82	6,463.39	41.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,780.00	3,390.00	3,390.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,301.21	12,447.82	9,853.39	44.18
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	22,301.21	9,000.00	13,301.21	59.64
+ GST 7.00/7.00% (S\$)	1,561.08	630.00	931.08	59.64
Nett Amount (S\$)	23,862.29	9,630.00	14,232.29	59.64

INSPECTION

Date of Assignment: 12/12/2018

Date Inspected: 13/12/2018 Inspected At:

Ding Automotive Pte Ltd (HQ)
31 CORPORATION ROAD
Singapore 649825

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2019)
Parts: 143	HYUNDAI SONATA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC173Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	523.93 FL	*523.93 FL
2	1		*REAR BUMPER REINF	Broken	462.30 FL	*462.30 FL
3	1		*REAR BUMPER REINF ARM LH	Bent	79.75 FL	*79.75 FL
4	1		*REAR BUMPER REINF ARM RH	Bent	79.75 FL	*79.75 FL
5	1		*REAR BUMPER RETAINER LH	Necessary	42.68 FL	*42.68 FL
6	1		*REAR BUMPER RETAINER RH	Necessary	42.68 FL	*42.68 FL
7	1		*REAR BUMPER SPONGE	Cracked	113.52 FL	*113.52 FL
8	1		*REAR BUMPER PROTECTOR LH	Deformed	102.96 FL	*102.96 FL
9	1		*REAR BUMPER PROTECTOR RH	Deformed	102.96 FL	*102.96 FL
10	1		*BOOTLID	Bent	1,139.00 FL	*1,139.00 FL
11	1		*BOOTLID EMBLEM LOGO	Necessary	40.92 FL	*40.92 FL
12	1		*BOOTLID EMBLEM HYUNDAI	Necessary	40.92 FL	*40.92 FL
13	1		*BOOTLID EMBLEM SONATA	Necessary	40.92 FL	*40.92 FL
14	1		*BOOTLID EMBLEM CRDI	Necessary	40.92 FL	*40.92 FL
15	1		*BOOTLID LAMP LH	Not Necessary	203.50 FL	*- FL
16	1		*BOOTLID LAMP RH	Not Necessary	203.50 FL	*- FL
17	1		*BOOTLID PLATE LAMP LH	Not Necessary	49.50 FL	*- FL
18	1		*BOOTLID PLATE LAMP RH	Not Necessary	49.50 FL	*- FL
19	1		*BOOTLID LOCK	Bent	109.45 FL	*109.45 FL
20	1		*BOOTLID LOCK CATCH	Bent	108.90 FL	*108.90 FL
21	1		*BOOTLID INSULATOR	Not Necessary	155.10 FL	*- FL
22	1		*BOOTLID RUBBER BEADING	Necessary	91.30 FL	*91.30 FL
23	1		*BOOTLID HINGE LH	Not Necessary	140.80 FL	*- FL
24	1		*BOOTLID HINGE RH	Not Necessary	140.80 FL	*- FL
25	1		*REAR END PANEL	Bent	323.29 FL	*323.29 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed	42.02 FL	*42.02 FL
27	1		*TAIL LAMP LH	Cracked	323.40 FL	*323.40 FL
28	1		*TAIL LAMP RH	Scratched	323.40 FL	*323.40 FL
29	1		*SPARE TYRE PANEL	Repair	812.90 FL	*- FL
30	1		*REAR FENDER LH	Not Necessary	1,598.30 FL	*- FL
31	1		*REAR FENDER RH	Repair	1,598.30 FL	*- FL
32	1		*REAR WINDSCREEN MOULDING	Not Necessary	23.10 FL	*- FL
33	1		*BONNET	Bent	1,101.76 FL	*1,101.76 FL
34	1		*BONNET HINGE LH	Not Necessary	79.20 FL	*- FL
35	1		*BONNET HINGE RH	Not Necessary	79.20 FL	*- FL
36	1		*BONNET DAMPER LH	Not Necessary	67.76 FL	*- FL
37	1		*BONNET DAMPER RH	Not Necessary	67.76 FL	*- FL
38	1		*BONNET INSULATOR	Not Necessary	222.75 FL	*- FL
39	1		*BONNET CHROME	Not Necessary	101.75 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*BONNET LOCK	Bent	108.90 FL	*108.90 FL
41	1		*FRONT BUMPER	Deformed	515.68 FL	*515.68 FL
42	1		*FRONT BUMPER REINF	Bent	472.78 FL	*472.78 FL
43	1		*FRONT BUMPER RETAINER LH	Necessary	29.98 FL	*29.98 FL
44	1		*FRONT BUMPER RETAINER RH	Necessary	29.98 FL	*29.98 FL
45	1		*FRONT BUMPER CENTRE GRILLE	Cracked	450.40 FL	*450.40 FL
46	1		*FRONT BUMPER CHROME MLDG	Cracked	91.52 FL	*91.52 FL
47	1		*FRONT BUMPER SPONGE	Cracked	130.35 FL	*130.35 FL
48	1		*FRONT BUMPER PROTECTOR LH	Repair	27.72 FL	*- FL
49	1		*FRONT BUMPER PROTECTOR RH	Repair	27.72 FL	*- FL
50	1		*SUPPORT PANEL	Deformed	922.02 FL	*922.02 FL
51	1		*HEAD LAMP LH	Cracked	763.18 FL	*763.18 FL
52	1		*HEAD LAMP RH	Cracked	763.18 FL	*763.18 FL
53	1		*FRT FENDER LH	Not Necessary	567.38 FL	*- FL
54	1		*FRT FENDER RH	Repair	567.38 FL	*- FL
55	1		*RADIATOR	Serviceable	764.06 FL	*- FL
56	1		*CONDENSOR	Bent	1,042.58 FL	*1,042.58 FL
57	1		*REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
58	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
59	1		*BOOTLID INSULATOR CLIPS	Necessary	35.00 FS	*35.00 FS
60	1		*BOOTLID STICKER CAB BOOKING 65521111	Necessary	120.00 FS	*60.00 FS
61	1		*BOOTLID STICKER CITYCAB	Necessary	120.00 FS	*60.00 FS
62	1		*REAR NUMBER PLATE	Serviceable	35.00 FS	*- FS
63	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	35.00 FS	*35.00 FS
64	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
65	1		*SPARE TYRE PANEL SEALANT	Not Necessary	50.00 FS	*- FS
66	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
67	1		*REAR WINDSCREEN DAMPER	Not Necessary	50.00 FS	*- FS
68	1		*BONNET INSULATOR CLIPS	Necessary	35.00 FS	*35.00 FS
69	1		*FRONT NUMBER PLATE & CASING	Cracked	35.00 FS	*35.00 FS
70	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
71	1		*FRONT FENDER INNERSHIELD CLIP LH & RH	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,150.26	11,177.28
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,629.05	2,119.46
Total Parts (\$\$)	15,521.21	9,057.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	2,500.00	1,500.00
2	R&R BOOTLID COMPONENTS	New	150.00	60.00
3	R&R SPARE TYRE, BOARD, CARPET, TRIM AND ETC	New	250.00	60.00
4	R&R REAR EXHAUST MUFFLER	New	180.00	0.00
5	R&R REAR FUEL TANK	New	250.00	0.00
6	R&R CONDENSOR AND RADIATOR AND REFILL AIRCON GAS	New	180.00	100.00
7	R&R REVERSE SENSOR AND SPRAY REVERSE SENSOR	New	120.00	60.00
8	CHECK WIRING	New	150.00	0.00
9	R&R BONNET COMPONENTS	New	80.00	0.00
10	RUSH PROOFING	New	120.00	80.00
11	ADJUST HEAD LAMP AIM	New	50.00	30.00
12	SPRAY REAR BUMPER, BOOTLID, REAR END PANEL, REAR FENDER LH, REAR FENDER RH, SPARE TYRE PANEL	New	1,200.00	900.00
13	SPRAY FRONT BUMPER, FRONT FENDER LHS, FRONT FENDER RHS, BONNET	New	1,200.00	600.00
14	MOUNT WORKBENCH TO ALIGNMENT CHASSIS	New	350.00	0.00
Gross Labour Cost (\$\$)			6,780.00	3,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >