

22/05/2017

ASS. REC. BY:

REF:

08/FCI18022417/Dad312

Special Instruction:

Surveyor:

CWS

Bryen

ASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time: 13/12/18 @ 9.04am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SH 6936T

Insured:

SHC 8390K

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMK Autopoint #01-05/06

Policy No:

Claim No:

D18008783MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/12/2018

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

9.12am @ 13/12/18

Person Contacted:

Lym

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SH 6936T - CC3/AIG/18011717/KIha392

DoA: 25/6/18

SHC8390K - 08/FCI18011836/Urbn2

DoA: 23/06/2018

18/12/18 @ 3.41pm revised to May chua by email.

REF:

ASSIGNMENT

COR 2022 Dec

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 6936T Yr Regn: Dec 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 637416 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDEU430048

C/No: KMHLB41UMBU061447

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16
R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wistake

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 10/12/2018 D.O.I. 13/12/2018

Survey held at Chummi AMIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

W/S Body y W/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SHC 8390 K

03/01/19 Juma 2/5 13 200/- with 8 days of rev
(Paid \$ 9188.80, 41%)

RECEIVED 04 JAN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 04/1/19 Juma

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

7P

Lump Sum / I.P. (\$) :

13200

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S-RS, GI

Photos 580

Others

OSR

4/1/19

12x15=180

170+180

50

50+50

134

634



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008783MFSH
Our Ref: CS/FCI18022417/Dqd3

Date: 18 December 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SH 6936T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/12/2018 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>22,388.80</u>
Revised Estimate Amount	: S\$ <u>16,554.56</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the n/s body & n/s rear portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	11-12-2018	Our Ref No. D18008783MFSH
Accident Date	10-12-2018	Claim Type. Third Party
Insured Vehicle	SHC8390K	Third Party Vehicle. SH6936T
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR,#01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 18 December 2018 3:41 PM
To: 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008783MFSH/1
Attachments: CSFCI18022417Dqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SH 6936T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Thursday, 13 December 2018 9:11 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18008783MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 13 December 2018 9:04 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18008783MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team

To survey by UAC

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper Cnt			\$ 553.00 ✓
	Rear Fender With Housing (LH) Bnc			\$ 4,736.80 ✓
	Rear Fender Inner Lining (LH) Svc			\$ 169.30 X
	Rear Windscreen Moulding Nw			\$ 28.30 ✓
	Rear Door (LH) Bnc			\$ 2,201.10 ✓
	Rear Door Rubber (LH) Huc			\$ 280.50 ✓
	Rear Door Gear/Regulator (LH) Nm			\$ 242.80 X
	Rear Door Power Motor (LH) Nm			\$ 158.60 X
	Front Door (LH) Bnc			\$ 2,256.40 ✓
	Front Door Rubber Huc			\$ 290.50 ✓
	Front Door Gear / Regulator (LH) & mounting crank			\$ 250.60 ✓
	Front Door Power Motor, LH Nm			\$ 172.70 X
	Door Centre Pillar Outer (LH) Dental			\$ 2,527.80 ✓
	Rocker Panel Outer Garnish (LH) & mounting crank			\$ 341.40 ✓
	Rocker Panel Outer Nm			\$ 1,310.60 X
	Rear Tyre Rim (LH) & distanta A			\$ 325.30 ✓
	Rear Wheel Hub-Cap (LH) Cnt			\$ 107.10 ✓
	Rear Wheelbearing ING & Hub & Down			\$ 362.00 ✓
	Rear Trailing Arm (LH) & distanta			\$ 192.00 ✓
	Rear Assist (LH) & distanta			\$ 145.70 ✓
	Rear Shock Absorber (LH) & distanta			\$ 276.30 ✓
	Rear Shock Absorber Mounting (LH) Nm			\$ 81.30 X
	Rear Crossmember & distanta			\$ 1,021.50 ✓
	Stabilizer Bar & distanta			\$ 199.60 ✓
	Stabilizer Link & distanta			\$ 85.90 ✓
	Rear Upper Arm (LH) & distanta			\$ 335.75 ✓
	Rear Lower Arm (LH) & distanta			\$ 353.80 ✓
	Rear Knuckle Arm (LH) & distanta			\$ 545.60 ✓
	SUB TOTAL		17416.95	\$ 19,552.25
	LESS 20%		13933.56	\$ 3,910.45
	DISCOUNTED TOTAL			\$ 15,641.80
	Rear Bumper Rubber Mat Huc			\$ 50.00 Nett ✓
	Rear Windscreen Sealant Huc			\$ 46.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) Huc			\$ 80.00 Nett ✓
	Front Door Coloured Comfort Logo (LH) Huc			\$ 75.00 Nett ✓
	Rear Tyre (LH) Svc		251.00	\$ 216.00 Nett X
				\$ 467.00

SH 6936T

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 900/-
	Spray Painting Charge			\$ 1,750.00 900/-
	Wiring Charge			\$ 100.00 44
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 44
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 7150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System (LH/RH)	\$	200.00	\$ 400.00 44
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00 44
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 44
			2370.00	
	TOTAL LABOUR			\$ 6,280.00
	ESTIMATE TOTAL			\$ 22,388.80
	13/12/2018 e 0945hs		16554.56	
	Wrt Arthur		4/5 13200/-	
	2/5mm			
	8 days.			
	ryan			
	LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SH 6936 T

Technician:

Mileage: 637416

Time Printed 13.12.18 11:47 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°27'		-3°00' 3°00'
3°40'		-0°19' 5°41'
-0°27'		-1°30' 1°30'
12°48'		
12°21'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°26'		-3°00' 3°00'
3°58'		-0°19' 5°41'
0°24'		-1°30' 1°30'
13°06'		
12°41'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°02'		-3°00' 3°00'
-0°18'		-3°00' 3°00'
-0°18'		-3°00' 3°00'
-0°02'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
3°43'		-3°30' 2°30'
4°52'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
1°05'		-3°30' 2°30'
0°40'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
2°39'		-3°00' 3°00'
5°32'		-3°00' 3°00'
2°06'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022417/Dqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8390K	Veh. Inspected	SH 6936T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008783MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	13/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMEU061447	Colour	BLUE	
Odometer	637416	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/12/2018	Inspection Date	13/12/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6936T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CUT	553.00	553.00
1	REAR FENDER WITH HOUSING (LH)	BUCKLED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (LH)	SERVICEABLE	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR DOOR (LH)	BUCKLED	2,201.10	2,201.10
1	REAR DOOR RUBBER (LH)	NECESSARY	280.50	280.50
1	REAR DOOR GEAR/REGULATOR (LH)	NOT NECESSARY	242.80	-
1	REAR DOOR POWER MOTOR (LH)	NOT NECESSARY	158.60	-
1	FRONT DOOR (LH)	BUCKLED	2,256.40	2,256.40
1	FRONT DOOR RUBBER	NECESSARY	290.50	290.50
1	FRONT DOOR GEAR/REGULATOR (LH)	MOUNTING CRACKED	250.60	250.60
1	FRONT DOOR POWER MOTOR LH	NOT NECESSARY	172.70	-
1	DOOR CENTRE PILLAR OUTER (LH)	DENTED	2,527.80	2,527.80
1	ROCKER PANEL OUTER GARNISH (LH)	MOUNTING CRACKED	341.40	341.40
1	ROCKER PANEL OUTER	NOT NECESSARY	1,310.60	-
1	REAR TYRE RIM (LH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (LH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	192.00	192.00
1	REAR ASSIST (LH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED	1,021.50	1,021.50
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60

Report Ref No. CS/FCI18022417/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,910.45	-3,483.39
			15,641.80	13,933.56
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT DOOR COLOURED COMFORT LOGO (LH)(SN)	NECESSARY	75.00	75.00
1	REAR TYRE (LH)(SN)	SERVICEABLE	216.00	-
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
			467.00	251.00
	<u>LABOUR</u>			
	PANEL BEATING.		2,000.00	900.00
	SPRAY PAINTING CHARGE.		1,750.00	900.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	RE-SET REAR ABS SYSTEM (LH/RH).	NOT NECESSARY	400.00	-
	RE-SET FRT & REAR POWER WINDOW SYSTEM.	NOT NECESSARY	400.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	-		-	-
	-		-	-
	-		-	-
			6,280.00	2,370.00
	GRAND TOTAL		22,388.80	16,554.56
	RECOMMENDED COST OF LUMP SUM REPAIR (TO ITS PRE-ACCIDENT CONDITION)			13,200.00

Report Ref No. CS/FCI18022417/Dqd3n2



Report Ref No. CS/FCI18022417/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.