

Date/Time	STAGE	DATE/PIC
09/08/2018 (2018) 17:00:00 @ 3030m	Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final): Notification Itr (if non-pickup): Call Off: 19032018 After call Itr to OI	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	
	After call Itr to OI	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time: 31/01/18	Sent By: Shirley Wong	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: \$5	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability: %	** (and / Assessed) BOLA S/N No.:	If NO or B 28, Ass. Lia:
Repair Cost: \$5		
Loss of Rental (LOR) \$5	(days)	
Loss of Use (LOU) \$5	(S x days)	
Loss of Income (LOI) \$5	(S x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search \$5		
Medical: \$5		
Disbursement: \$5	(e.g. Tow/ Independent)	
Legal Cost \$5		
Total: \$5	Global Sum \$5:	
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: \$5	Name 1:	
Payee 2: (Strike if N.A.) \$5	Name 2:	
Payee 3: (Strike if N.A.) \$5	Name 3:	

2-8-18 EMAILED TP TO RE-DIRECT CLAIM TO FBC 2528C.
14/12/18 - TP want to purchase live report



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18001826/Uks3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Date : 30-01-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 9401A	Veh. Inspected	GBD 7544G	
Policy No.	DMPCSN1006921707	Coverage (\$)	0.00	
Claim No.	SNM18D00565C05/1	Excess (\$)	0.00	
Assign From		Assign Date	30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/01/2018	Inspection Date	30/01/2018	
Survey held at	LBA AUTOMOTIVE PTE. LTD. 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

501/1, 502/25 PAYA LEBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (965) 62563561 FAX : (965) 62564315

Your ref: TBA
Our ref: CC6/CTI18001826/Uks3

Date: 31.01.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBD 7544G

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30.01.2018 at the premises of M/s LBA Automotive Pte Ltd (Kaki Bukit) and have the following to report:-

Workshop Estimate Amount	: S\$	8,750.84
Revised Estimate Amount	: S\$	6,889.20
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Thursday, 2 August 2018 9:51 AM
To: LBA Automotive Pte. Ltd.
Cc: Admin A; Hsiao Tong (LKKAuto)
Subject: GBD 7544G ON 27.01.2018 / CHINA T. SJN 9401A

WITHOUT PREJUDICE

Dear Sirs,

We refer to the subject.

In the application of BOLA 28 (g), we will not be held liable to your client/ claimant owner of vehicle GBD 7544G. There is no direct contact between our insured vehicle to your client's vehicle.

In view of this, we are instructed by our principal to advise you to re-direct your claim to the insurer of vehicle FBC 2528S.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Shirley Hiew (LKK Auto)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Thursday, 8 March 2018 2:25 PM
To: Shirley Hiew (LKK Auto)
Cc: Zaini (LKK Auto)
Subject: FW: OUR REF: SNM18D00565C05/1 & YR REF: GBD7544G (TP : LKK REF - CC6/CTI18001826/Uks3) on 27/01/2018
Attachments: SNM18D00565C01 20180308 TO INSURED -LKK ASSIGNMENT LTR.pdf; MANC18014516-01-SJN9401A.pdf

Dear Shirley,

Re-send

Thank you

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co Reg No 200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential. Its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Angie Foo
Sent: Thursday, 8 March, 2018 2:22 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: Chong Boon Sen; Claims Dept of CTI; Zaini (LKK Auto)
Subject: OUR REF: SNM18D00565C05/1 & YR REF: GBD7544G (TP : LKK REF - CC6/CTI18001826/Uks3) on 27/01/2018

Dear Shirley,

We refer to your email of 1st March 2018.

We attached our Insured's and Third Party of SAS Report and assignment letter for your necessary action.

Kindly take note, the claim handler for this case is Chong Boon Sen 6389 6171.

Thank you.

Regards,

Angie Foo

Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co.Reg.No.200208384E

DID: 6369 6186

Fax: 6224 7478 / 6224 7175

Email: angie.foo@sg.cntaiping.com

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or in part, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Thursday, 1 March, 2018 1:20 PM

To: Angie Foo

Subject: FW: Direct Settlement - Accident Involving SJN9401A (OI : CTI - TBA) AND GBD7544G (TP : LKK REF - CC6/CTI18001826/Uks3) on 27/01/2018

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Wednesday, 31 January 2018 4:42 PM

To: claimsdept@sg.cntaiping.com; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: Admin A <admin-a@lkkauto.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>; Hsiao Tong (LKKAuto) <chewnt@lkkauto.com>

Subject: Direct Settlement - Accident Involving SJN9401A (OI : CTI - TBA) AND GBD7544G (TP : LKK REF - CC6/CTI18001826/Uks3) on 27/01/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle GBD 7544G at M/s LBA Automotive Pte Ltd - Kaki Bukit.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISIT PASS
Immigration Regulations

Name
ISLAM NAZRUL



Date of Birth: **01-01-1983** Sex: **M** Nationality: **BANGLADESHI**
Title: Date of Issue: Date of Expiry:
G7931467L 01-08-2017 03-07-2019

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS:

EFFECTIVE DATE

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ 19 Dec 201



NP 428A

S PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
K.K.ROOFING CONTRACTORS PTE. LTD.

Industry: **CONSTRUCTION**



Name:
ISLAM NAZRUL
Occupation:
CONSTRUCTION SUPERVISOR

S Pass No.: **0 62349204** Date of Application: **30-06-2017**
Date of Issue: **01-08-2017**
Date of Expiry: **03-07-2019**



L5182413

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **G7931467L**

Name:
ISLAM NAZRUL



Birth Date: **01 Jan 1983**
Valid Till: **13 Dec 2016**
Valid Till 16/12/2021



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 4929K

Vehicle Details

Vehicle No.: GBD7544G

Vehicle to be Exported: Yes

Intended De-registration Date: 29 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: DYNA 3.0 M

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: 1KD2465495

Chassis No.: KDY2318018040

Maximum Power Output: -

Open Market Value: \$28,276.00

Original Registration Date: 24 Apr 2015

First Registration Date: 24 Apr 2015

Transfer Count: 2

Actual ARF Paid: \$1,414.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Apr 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$23,996.00

COE Rebate Amount: \$17,363.00

Total Rebate Amount: \$17,363.00

The information contained herein is correct as at 29 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 4929K

Vehicle Details

Vehicle No.: GBD7544G
Vehicle to be Exported: No
Intended De-registration Date: 30 Jan 2018
Vehicle Make: TOYOTA
Vehicle Model: DYNA 3.0 M
Primary Colour: Silver
Manufacturing Year: 2014
Engine No.: 1KD2465495
Chassis No.: KDY2318018040
Maximum Power Output: -
Open Market Value: \$28,276.00
Original Registration Date: 24 Apr 2015
First Registration Date: 24 Apr 2015
Transfer Count: 2
Actual ARF Paid: \$1,414.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Apr 2025
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
PQP Paid: \$23,996.00
COE Rebate Amount: \$17,356.00
Total Rebate Amount: \$17,356.00

The information contained herein is correct as at 30 Jan 2018

OK

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 043580
Tel (65) 6224 0010 Fax (65) 6224 0080
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S60500296 / GST Reg. No.: M480617735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MANC 18014 SJL Vehicle Registration No: SDN 9401A
Name (as shown in NRIC): Low Eng Pat NRIC/FIN/Passport No: 87593006D
(* Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: _____ Singapore ()
Contact (Tel): _____ Mobile No.: 93832650
Email Address: _____
Date of Accident: 27/01/2018 Time of Accident: 08:05
Place of Accident: UNDER BUKITTIMAN RD TURNING TO BARTLEY RD JUNCTION
Insurance Company: CHINA TIANJING

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

1) To amend the accident year.

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



LBA AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

SIN9401A

LKK Auto Claims Department
The Repair Estimate

- To survey before repair and painting
- To supply (to new parts) and survey
- Parts and labour on the estimation
- This estimate is on "Without Prejudice" basis

ESTIMATE (This is allowed)
* Subject to inspection and approval by the insurance company

DATE : 29.01.2018
VEHICLE NO : GBD7544G
MAKE/MODEL : TOYOTA DYNA
ACC DATE : 27.01.2017

*Not Authorised
h/c
2/5 \$5300/-
6 day.
30/1/18
take photo After rep.*

PARTICULAR	QTY	UNIT PRICE	AMOUNT
		SS	SS
<u>LIST PRICE</u>			
1 1 FRT WINDSCREEN RUBBER		297.40	297.40 ✓
2 1 FRT PANEL		1,100.30	1,100.30 ✓
3 1 FRT PANEL STICKER 'DYNA'		74.10	74.10 ✓
4 1 FRT PANEL CENTRE GARNISH		258.45	258.45 ✓
5 1 FRT GRILLE		517.45	517.45 ✓
6 1 FRT GRILLE EMBLEM 'LOGO'		85.90	85.90 ✓
7 1 FRT GRILLE RUBBER SEAL		103.20	103.20 ✓
8 1 FRT CORNER PANEL RH		330.45	330.45 ✓
9 1 FRT CORNER GARNISH RH (BOTTOM)		99.85	99.85 ✓
10 1 FRT CORNER GARNISH RH (TOP)		230.60	230.60 ✓
11 1 FRT HEADLAMP RH		868.00	868.00 ✓
12 1 FRT HEADLAMP LOWER RUBBER RH		35.30	35.30 ✓
13 1 FRT BUMPER		755.90	755.90 ✓
14 2 FRT BUMPER BRACKET RH/LH		161.45	322.90 ✓
15 1 FRT BUMPER FOG LAMP RH		310.40	310.40 ✓
16 1 FRT BUMPER FOG LAMP COVER RH		127.40	127.40 ✓
17 1 FRT DOOR RH		1,528.70	1,528.70 ✓
18 1 FRT DOOR TOP HINGE RH		115.30	115.30 ✓
19 1 FRT DOOR RUBBER		198.05	198.05 ✓
20 1 FRT DOOR SIGNAL LAMP		88.30	88.30 ✓
21 1 CHASSIS FRONT CROSSMEMBER		426.50	426.50 ✓
			7,874.45
		LESS 25%	1,968.61
			5,905.84

SPECIAL NETT ITEMS

1 1 FRT DOOR LETTERING STICKER	25.00	25.00 ✓
--------------------------------	-------	---------

LABOUR CHARGES :

1 TO KNOCK OUT DENT, CUT/WELD FRONT PANEL, FRONT CHASSIS CENTRE CROSS MEMBER AND REPLACE ACCIDENT PARTS	800	1,000.00
2 TO SPRAY PAINTING ON ACCIDENT PORTION	900	1,200.00
3 TO CHECK WIRING	20	30.00
4 TO REMOVE, REFIX WINDSCREEN	60	120.00
5 TO REMOVE, REFIX DASHBOARD	160	280.00
6 TO REMOVE, REFIX AIR CON BLOWER AND REFILL GAS	100	100.00
7 TO TUFF KOTE	80	90.00
		2,820.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 8,750.84



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18001826/Uja3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 03-08-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 9401A	Veh. Inspected	GBD 7544G	
Policy No.	DMPCSN1006921707	Coverage (\$)	0.00	
Claim No.	SNM18D00565C05/1/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	30/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KDY2318018040	Colour	SILVER	
Odometer	130783	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	CONDOR	6 mm	
L/H Front Tyre	195 R15	CONDOR	6 mm	
R/H Rear Tyre	165 R13 (D)	CONDOR	6/6 mm	
L/H Rear Tyre	165 R13 (D)	CONDOR	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/01/2018	Inspection Date	30/01/2018	
Survey held at	LBA AUTOMOTIVE PTE. LTD. 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 7544G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT WINDSCREEN RUBBER	NECESSARY	297.40	297.40
1	FRT PANEL	BADLY DENTED	1,100.30	1,100.30
1	FRT PANEL STICKER "DYNA"	NECESSARY	74.10	74.10
1	FRT PANEL CENTRE GARNISH	NOT NECESSARY	258.45	-
1	FRT GRILLE	CRACKED	517.45	517.45
1	FRT GRILLE EMBLEM "LOGO"	NECESSARY	85.90	85.90
1	FRT GRILLE RUBBER SEAL	TORN	103.20	103.20
1	FRT CORNER PANEL RH	DENTED	330.45	330.45
1	FRT CORNER GARNISH RH (BOTTOM)	CRACKED	99.85	99.85
1	FRT CORNER GARNISH RH (TOP)	NOT NECESSARY	230.60	-
1	FRT HEADLAMP RH	BROKEN	868.00	868.00
1	FRT HEADLAMP LOWER RUBBER RH	TORN	35.30	35.30
1	FRT BUMPER	TWISTED	755.90	755.90
2	FRT BUMPER BRACKET RH/LH @\$161.45	NOT NECESSARY	322.90	-
1	FRT BUMPER FOG LAMP RH	NOT NECESSARY	310.40	-
1	FRT BUMPER FOG LAMP COVER RH	SCRATCHED	127.40	127.40
1	FRT DOOR RH	DENTED / BENT	1,528.70	1,528.70
1	FRT DOOR TOP HINGE RH	BENT	115.30	115.30
1	FRT DOOR RUBBER	NECESSARY	198.05	198.05
1	FRT DOOR SIGNAL LAMP	CRACKED	88.30	88.30
1	CHASSIS FRONT CROSSMEMBER	TO REPAIR SEE LABOUR	426.50	-
LESS 25% DISCOUNT			-1,968.61	-1,581.40
			5,905.84	4,744.20
<u>SPECIAL NETT ITEMS</u>				
1	FRT DOOR LETTERING STICKER (SN)	NECESSARY	25.00	25.00
			25.00	25.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK OUT DENT, CUT/WELD FRONT PANEL, FRONT CHASSIS CENTRE CROSS MEMBER AND REPLACE ACCIDENT PARTS, INCLUSIVE OF THE REPAIR OF CHASSIS FRONT CROSSMEMBER.		1,000.00	800.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		1,200.00	900.00
	TO CHECK WIRING.		30.00	20.00
	TO REMOVE, REFIX WINDSCREEN.		120.00	60.00
	TO REMOVE, REFIX DASHBOARD.		280.00	160.00
	TO REMOVE, REFIX AIR CON BLOWER AND REFILL GAS.		100.00	100.00
	TO TUFF KOTE.		90.00	80.00
			2,820.00	2,120.00
	GRAND TOTAL		8,750.84	6,889.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,500.00

Report Ref No. CC6/CT118001826/Uja3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LBA AUTOMOTIVE PTE. LTD.		Ref : CC6/CTI18001826/Uja3n2-1		
1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAYSINGAPORE 417883		Date : 14-12-2018		
ON BEHALF OF KK ROOFING CONTRACTORS PTE LTD		Code : TP394		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		GBD 7544G	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		08/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KDY2318018040	Colour	SILVER	
Odometer	130783	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	CONDOR	6 mm	
L/H Front Tyre	195 R15	CONDOR	6 mm	
R/H Rear Tyre	165 R13 (D)	CONDOR	6/6 mm	
L/H Rear Tyre	165 R13 (D)	CONDOR	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/01/2018	Inspection Date	30/01/2018	
Survey held at	LBA AUTOMOTIVE PTE. LTD. 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 7544G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT WINDSCREEN RUBBER	NECESSARY	297.40	297.40
1	FRT PANEL	BADLY DENTED	1,100.30	1,100.30
1	FRT PANEL STICKER "DYNA"	NECESSARY	74.10	74.10
1	FRT PANEL CENTRE GARNISH	NOT NECESSARY	258.45	-
1	FRT GRILLE	CRACKED	517.45	517.45
1	FRT GRILLE EMBLEM "LOGO"	NECESSARY	85.90	85.90
1	FRT GRILLE RUBBER SEAL	TORN	103.20	103.20
1	FRT CORNER PANEL RH	DENTED	330.45	330.45
1	FRT CORNER GARNISH RH (BOTTOM)	CRACKED	99.85	99.85
1	FRT CORNER GARNISH RH (TOP)	NOT NECESSARY	230.60	-
1	FRT HEADLAMP RH	BROKEN	868.00	868.00
1	FRT HEADLAMP LOWER RUBBER RH	TORN	35.30	35.30
1	FRT BUMPER	TWISTED	755.90	755.90
2	FRT BUMPER BRACKET RH/LH @\$161.45	NOT NECESSARY	322.90	-
1	FRT BUMPER FOG LAMP RH	NOT NECESSARY	310.40	-
1	FRT BUMPER FOG LAMP COVER RH	SCRATCHED	127.40	127.40
1	FRT DOOR RH	DENTED / BENT	1,528.70	1,528.70
1	FRT DOOR TOP HINGE RH	BENT	115.30	115.30
1	FRT DOOR RUBBER	NECESSARY	198.05	198.05
1	FRT DOOR SIGNAL LAMP	CRACKED	88.30	88.30
1	CHASSIS FRONT CROSSMEMBER	TO REPAIR SEE LABOUR	426.50	-
	LESS 25% DISCOUNT		-1,968.61	-1,581.40
			5,905.84	4,744.20
SPECIAL NETT ITEMS				
1	FRT DOOR LETTERING STICKER (SN)	NECESSARY	25.00	25.00
			25.00	25.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK OUT DENT,CUT/WELD FRONT PANEL,FRONT CHASSIS CENTRE CROSS MEMBER AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF CHASSIS FRONT CROSSMEMBER.		1,000.00	800.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		1,200.00	900.00
	TO CHECK WIRING.		30.00	20.00
	TO REMOVE,REFIX WINDSCREEN.		120.00	60.00
	TO REMOVE,REFIX DASHBOARD.		280.00	160.00
	TO REMOVE,REFIX AIR CON BLOWER AND REFILL GAS.		100.00	100.00
	TO TUFF KOTE.		90.00	80.00
			2,820.00	2,120.00
	GRAND TOTAL		8,750.84	6,889.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,500.00

Report Ref No. CC6/CT118001826/Uja3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.