

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: GS001845
Version: SMEMOT01/1
Date Calculated: 14/12/2018 07:10

Full Report - V1
Registration: SKR5689E
Printed: 14/12/2018 15:11

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	10/12/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	OD	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	CLA Class
Sub Model:	CLA 250
Model Sheet Number:	375 45
Registration:	SKR5689E
Registration Month:	December
Registration Year:	2014
VIN Number:	WDD1173442N115568
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM VIN N070761	ALU DESIGN PARTS
MODEL 2015	A/C THERMATIC
RAIN SENSOR	DIPPING DOOR MIRROR
ELECT FOLDING MIRROR	AUDIO 20 CD CHANGER
BI-XENON HEADLAMPS	LIGHT-/VIEW PACKAGE
HEADLAMP WASHER UNIT	LEATHERETTE PAD
AMG LINE	MULTI FUNCT S-WHEEL
SILL MLDG ILLUMINAT	S/WHEEL TIP SWITCHES
LEATHER STRG WHEEL	DRIVER SEAT MEMORY
PASS SEAT MEMORY	ELECT LUMBAR ADJUST
SEAT COMFORT PACKAGE	MEDIA INTERFACE
ILLUM SUN VISOR	REARVIEW CAMERA
EMISSION STD EURO 6	STRATIFIED CHARGE
ECO START/STOP	ELECTRIC HORN
CRUISE CONTROL	7 SPEED AUTOMATIC
PARAMETER STEERING	SPORTS SUSPENSION
TYRES 225/40 WR 18	WHEELS 7.5J X 18 ALU
PAINTED GRILLE	KNEE AIRBAG
ELECTRIC SUNROOF	PARKTRONIC
AMG STYLING	BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on	
	Inspection:	
Brakes Pedal Travel:	Date of Inspection:	12/12/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	

Claim Reference:

Full Report - V1

Assessment Number: GS001845


Registration: SKR5689E

Version: SMEMOT01/1


Printed: 14/12/2018 15:11

Date Calculated: 14/12/2018 07:10

Tread Depth LHR:
Damage Areas:



Tread Depth RHR:
Direction of Impact:



Addresses

Cost Summary

Total Labour	\$342.00
Total Paint/Material	\$99.47
Total Parts	\$3,536.50
Excess:	TBA
Grand Total Exc GST:	\$3,977.97
7 % GST:	\$278.46
Grand Total Inc GST:	\$4,256.43

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
61-1071 01	R + R FRONT LOWER ENGINE COMPARTMENT COVER	5.0	22.50
88-1102 01	R + R FRONT BUMPER CPL	8.0	36.00
88-1105 01	DIS + ASS FRONT BUMPER (BUMPER REMOVED)	7.0	31.50
	AFTER CHECK: RENEW PARTS IF NECESSARY		
88-1360 01	ADDITION TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARK ASSISTANT)	3.0	13.50
88-1355 01	ADDITION TO DIS + ASS FRONT BUMPER (VEHICLE WITH HEADLAMP WASHER SYSTEM)	2.0	9.00
82-4800 01)	RENEW RIGHT HEADLAMP (BUMPER DETACHED)	5.0	22.50
	UMFASST: HEADLAMP AND FOG LAMPS ADJUST		
82-4885 01	ADDITIONAL TO RENEW RIGHT HEADLAMP (VEHICLE WITH XENON HEADLAMP)	3.0	13.50
88-3983 01	RENEW R/FR WING (BUMPER REMOVED/DETACHED)	8.0	36.00
	INCLUDES: R/F WHEELHOUSE COVER CPL REMOVE AND REFIT		
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.00
97-2500 ZAX	APPLY RUST PROOFING ON R/F WING	2.0	9.00

LABOUR COST

Total Work Units	45.0
Corrosion Protection	
Corrosion Protection External Labour	0.0HRS 0.00
Corrosion Protection Internal Labour	0.4HRS 18.00

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E

Version: SMEMOT01/1

Printed: 14/12/2018 15:11

Date Calculated: 14/12/2018 07:10

Sub Total	4.5HRS	\$202.50
Paint Labour	3.1HRS	\$139.50
Total Labour	7.6HRS	\$342.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- BASECOAT CLEAR		
98-1682 01	FRONT BUMPER PAINTING STAGE I-M	11.0	
98-2615 01	R/F WING PAINTING STAGE I-M	6.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	14.0	
LABOUR COST - PAINT			
TIME(PAINT)		0.0	
Total Work Units (10WU/HR)		31.0	
Total Paintwork Labour		3.1HRS	\$139.50
MATERIAL COST - PAINT			Cost Price
Total Excluding Pearlescent Uplift			\$99.47
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$99.47

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
283	1	FRONT BUMPER	117 880 4840 9999		0% 1,150.00*
349	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% 35.00*
742	1	R/F WING	117 881 0201		0% 430.00*
562	1	RIGHT HEADLAMP ASSY	117 906 6600		0% 1,600.00*
f: OEM Parts		Sub Total			\$3,215.00
g: Original		Mark Up From Cost (10 %)			\$321.50
h: Secondhand		Total Parts			\$3,536.50
p: Parallel					
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00**Final Calculation**

Total Parts	\$3,536.50
Labour	
Total Panel/Mechanical	\$184.50
Total Paintwork	\$139.50
Corr Prot Internal 4 WU	\$18.00
Total Labour	\$342.00
Additional Costs	
Corr Prot Materials External	\$0.00
Total Paint/Material Costs	\$99.47
Grand Total Excludes GST	\$3,977.97
GST @ 7 %	\$278.46
Grand Total Includes GST	\$4,256.43

Assessment Notes

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E

Version: SMEMOT01/1

Printed: 14/12/2018 15:11

Date Calculated: 14/12/2018 07:10
