



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 8761H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT WINDSCREEN PILLAR OUTER PANEL LH | TO REPAIR SEE LABOUR | 763.60 | - |
| 1 | FRONT PILLAR INNER TRIM GARNISH LH | NOT NECESSARY | 181.00 | - |
| 4 | FRONT PILLAR INNER TRIM GARNISH CLIPS LH | NOT NECESSARY | 7.20 | - |
| 14 | ROOF LINING INNER CLIPS | NECESSARY | 21.00 | 21.00 |
| 1 | ALUMINIUM ALLOY ROOF SIDE RAIL LH (AIR FREIGHT) | GRAZED / DENTED | 2,350.00 | 500.00 |
| 1 | ALUMINIUM ALLOY ROOF SIDE RAIL RH (AIR FREIGHT) | GRAZED / DENTED | 2,350.00 | 500.00 |
| 1 | ALUMINIUM ALLOY ROOF SIDE RAIL FRONT RUBBER MOULDING LH | NOT NECESSARY | 85.00 | - |
| 1 | ALUMINIUM ALLOY ROOF SIDE RAIL FRONT RUBBER MOULDING RH | NOT NECESSARY | 85.00 | - |
| 1 | ALUMINIUM ALLOY ROOF SIDE RAIL REAR RUBBER MOULDING LH | NOT NECESSARY | 121.00 | - |
| 1 | ALUMINIUM ALLOY ROOF SIDE RAIL REAR RUBBER MOULDING RH | NOT NECESSARY | 121.00 | - |
| 4 | ALUMINIUM ALLOY ROOF SIDE RAIL SCREW COVER LH | BENT | 32.00 | 32.00 |
| 4 | ALUMINIUM ALLOY ROOF SIDE RAIL SCREW COVER RH | BENT | 32.00 | 32.00 |
| 1 | FRONT WINDSCREEN MOULDING | NOT NECESSARY | 74.60 | - |
| | LESS 20% DISCOUNT | | - | -217.00 |
| | | | 6,223.40 | 868.00 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | FRONT WINDSCREEN GUM (SN) | NOT NECESSARY | 60.00 | - |
| | | | 60.00 | - |
| <u>LABOUR</u> | | | | |
| | TO APPLY ANTI RUST COAT. | NOT NECESSARY | 150.00 | - |
| | TO REMOVE / REFIX ROOF LINER LINING AND FRONT PILLAR INNER TRIM LH TO ASSIST IN REPAIR. | | 350.00 | 80.00 |
| | TO SPRAY ROOF PANEL, FRONT WINDSCREEN PILLAR OUTER PANEL & ETC. | | 1,600.00 | 400.00 |
| | TO APPLY PAINT PROTECTION SEALANT. | NOT NECESSARY | 400.00 | - |
| | TO RENEW DAMAGED PARTS, REPAIR, ALIGN ROOF PANEL, FRONT LH PILLAR OUTER PANEL & ECT. INCLUSIVE OF THE REPAIR OF FRONT WINDSCREEN PILLAR OUTER PANEL LH. | | 1,600.00 | 500.00 |

Report Ref No. CS3/AXA18004045/Btbe2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|---------------|---------------------------|-------------------|
| | TO REMOVE & REFIX FRONT WINDSCREEN GLASS. | NOT NECESSARY | 150.00 | - |
| | | | 4,250.00 | 980.00 |
| GRAND TOTAL | | | 10,533.40 | 1,848.00 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 1,450.00 |

Report Ref No. CS3/AXA18004045/Btbe2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.