

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTRK%	DISC QUNTY%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	39	1			R/F UPP BUMPER BRKT (WCP)			Serviceable	0				0	Reviewing	
	40	1			R/F WING (WCP)			Repair	0				0	Reviewing	
	41	5			R/F WING CLAMP KIT (WCP)			Serviceable	0				0	Reviewing	
	42	1			R/GRILLE TRIM (10%) (WCP)			Cracked	25.3				25.3	Reviewing	
	43	1			R/RAD-GRILLE BRACKET (WCP)			Repair	0				0	Reviewing	
	44	1			R/WING MOULDING (WCP)			Serviceable	0				0	Reviewing	
	45	1			RAD GRILLE BRACKET (10%) (WCP)			Damaged	19.8				19.8	Reviewing	
	46	1			RAD GRILLE COVER (10%) (WCP)			Cracked	159.5				159.5	Reviewing	
	47	1			RADIATOR (WCP)			Serviceable	0				0	Reviewing	
	48	1			RADIATOR COOLANT (WCP)			Serviceable	0				0	Reviewing	
	49	1			UP/CVR RADIAT GRILLE (WCP)			Serviceable	0				0	Reviewing	
	50	1			WASHER RESERVOIR (WCP)			Serviceable	0				0	Reviewing	
	51	1			W-SCREEN WASHER PUMP (WCP)			Serviceable	0				0	Reviewing	

Labour

Auto

Approve

Deny

Submit All

	EDIT	SR NO.	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		11	1			FRT BUMPER SUPPORT (10%) (WCP)			Necessary	220				220	Reviewing	
		12	1			FRT NUMBER PLATE (10%) (WCP)			Dented	38.5				38.5	Reviewing	
		13	1			GRILLE (10%) (WCP)			Cracked	203.5				203.5	Reviewing	
		14	1			GRILLE BADGE (10%) (WCP)			Necessary	19.8				19.8	Reviewing	
		15	1			GRILLE MOUNTING KIT (10%) (WCP)			Necessary	27.5				27.5	Reviewing	
		16	1			LIBONNET HINGE (WCP)			Repair	0				0	Reviewing	
		17	1			LIBONNET SEAL (WCP)			Serviceable	0				0	Reviewing	
		18	1			LIBONNET SEAL (WCP)			Serviceable	0				0	Reviewing	
		19	1			LIBUMPER CORNER BRKT (10%) (WCP)			Damaged	33				33	Reviewing	
		20	1			LIF AIR DUCT (WCP)			Serviceable	0				0	Reviewing	
		21	1			LIF HEADLAMP CPL (WCP)			Serviceable	0				0	Reviewing	
		22	1			LIF MOULDING (WCP)			Serviceable	0				0	Reviewing	
		23	1			LIF UPP BUMPER BRKT (WCP)			Serviceable	0				0	Reviewing	
		24	5			LIF WING CLAMP KIT (WCP)			Serviceable	0				0	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Sum Insured	0	0
Market Value	0	62000

CATEGORY	ENCL INFORMATION	POST SURVEY INFORMATION
License Type		
License Issue Date		mm/dd/yyyy
License Expiration Date		mm/dd/yyyy
Address	79D TOA PAYOH CENTRAL #05-59, 314079, Singapore	
Address type	Residential	
Gender	Male	
Marital status	Married	
Identification #	S7966319J	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
KHONG Lynn	12/14/18 11:33 AM	3661.67	3661.67	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
Resurvey photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	January 29, 2019
SKX 5640M photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	January 29, 2019
SKX5640M AUDATEX ESTIMATE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	December 18, 2018
PREL ADVISED SKX 5640M.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	December 18, 2018
BAC00055.pdf	Forms / Claim Documents	Estimate / Quotation	BH AUTO SERVICES PTE LTD	December 13, 2018
GA288825-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	WANG Peter	December 11, 2018