



## Case Details

Case Reference Number :  
TAX/12/18/2054

Type of Repair : Accident Repair

Vehicle Registration Number :  
SHB1638Z

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-4949-ID

Assigned By : Taxi Claims Manager  
Team

Insurance Company Name : China Taiping Insurance (Singapore)  
Pte Ltd

Accident Date and Time : 12/12/2018 12:30 AM

Vehicle Age(In Months) : 51

## Documents / Photographs

View Documents / Photographs

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| BOM Type              | Costing Type | Portion | Material Number | SMRT Recommendation           |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |
|-----------------------|--------------|---------|-----------------|-------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|
|                       |              |         |                 | Part Name                     | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |
| One Time Key In       | Main         |         |                 | BUMPER FRT                    | 1   | 482.00                  | 482.00         | 25.00  | 361.50          | Replace         | 1                 | 361.50                   | Replace ▾      |
| One Time Key In       | Main         |         |                 | BUMPER GRILLE SUB-ASSY, LOWER | 1   | 311.10                  | 311.10         | 25.00  | 233.33          | Replace         | 1                 | 233.33                   | Replace ▾      |
| One Time Key In       | Main         |         |                 | BRACKET, FR BUMPER            | 1   | 110.40                  | 110.40         | 25.00  | 82.80           | Replace         | 1                 | 82.80                    | Replace ▾      |
| One Time Key In       | Main         |         |                 | NUMBER PLATE                  | 1   | 15.00                   | 15.00          | 0.00   | 15.00           | Replace         | 1                 | 15.00                    | Replace ▾      |
| One Time Key In       | Main         |         |                 | NUMBER PLATE FRAME            | 1   | 12.00                   | 12.00          | 0.00   | 12.00           | Replace         | 1                 | 12.00                    | Replace ▾      |
| One Time Key In       | Main         |         |                 | BUMPER ENERGY ABSORBER FRT    | 1   | 78.80                   | 78.80          | 25.00  | 59.10           | Replace         | 0                 | 0                        | Check ▾        |
| One Time Key In       | Main         |         |                 | BUMPER REINFORCEMENT FRT      | 1   | 498.40                  | 498.40         | 25.00  | 373.80          | Replace         | 0                 | 0                        | Check ▾        |
| One Time Key In       | Main         |         |                 | BUMPER FRT ABSORBER LOWER     | 1   | 127.70                  | 127.70         | 25.00  | 95.78           | Replace         | 0                 | 0                        | Not Give ▾     |
| Total Spare Part Cost |              |         |                 |                               |     |                         |                |        | 1,233.31        |                 | Surveyor Total    | 704.63                   |                |
| Lump Sum Discount (%) |              |         |                 |                               |     |                         |                |        | 20.00           |                 | Lump Sum Dis (%)  | 20                       |                |
| Final Spare Part Cost |              |         |                 |                               |     |                         |                |        | 939.37          |                 | Final Sur Total   | 563.70                   |                |

### Labour's Cost Detail

| S.No.  | Job Scope               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|-------------------------|-------------------------|-------------------------|---------|
| 1      | TO REPAIR FRONT PORTION | 338.00                  | 200                     |         |
| Total: |                         | 338.00                  | 200.00                  |         |

Spray Cost Detail

| S.No.  | Job Scope                     | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|-------------------------------|-------------------------|-------------------------|---------|
| 1      | TO REPSRAY FRONT BUMPER       | 378.00                  | 200                     |         |
| 2      | TO RESPRAY FRONT LOWER GRILLE | 180.00                  | 0                       |         |
| Total: |                               | 558.00                  | 200.00                  |         |

Other Cost Detail

| S.No.  | Job Scope                           | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|-------------------------------------|-------------------------|-------------------------|---------|
| 1      | TOWING CHARGE                       | 84.00                   | 0                       |         |
| 2      | TO CHECK WIRING AND SYSTEM FUNCTION | 80.00                   | 30                      |         |
| 3      | TO REPLACE SUNDRY PARTS             | 100.00                  | 0                       |         |
| 4      | TO WASH AND VACUUM                  | 60.00                   | 0                       |         |
| Total: |                                     | 324.00                  | 30.00                   |         |

## Summary

|                          | Estimator Assesment(\$)             | Surveyor Assesment(\$)              |
|--------------------------|-------------------------------------|-------------------------------------|
| Total Spare Part Detail  | 939.37                              | 563.70                              |
| Total Labour Cost        | 338.00                              | 200.00                              |
| Total Spray Painting     | 558.00                              | 200.00                              |
| Other                    | 324.00                              | 30.00                               |
| Overall Total            | 2,159.37                            | 1,134.63                            |
| Lump Sum Repair Option   | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Lump Sum Total           | 2,150.00                            | 1,150.00                            |
| Surveyor Approved Amount |                                     | 1,150.00                            |
| No of Repair Days*       | 3                                   | 2                                   |

|               | Estimator Assessment(\$)                                                          | Surveyor Assessment(\$)                                                                       |
|---------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| Remarks       |                                                                                   | L/S photo after paint. supple mentary item pls send e-mail to<br>: naz@lkkauto.com (91803151) |
| Surveyor Name |                                                                                   | Hwee jie                                                                                      |
| Signature     |  |            |
| Survey Date   | 13/12/2018                                                                        | <div>Save Clear</div>                                                                         |

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**