Monmen Kenneth	ASSIG	8022557/Ks (Office)		
Estimated Cost:		Bill to:	Dat	e/Time 17/12/18/09.26
OD THE WS TTP RES ! OD RE	S/EVA/INV/M	V7CS		
To Inspect Vehicle No:	GBC 9	854D	Insured:	160053 A
at Workshop m/s	Esteem 1	Perfemence	Tel:	64841221
of BK 503	33, AMK In	d. Park 2#	01-259	
Policy No:			578	983
Sum Insured:		Excess:		
Make of Veh: (Client's Record)		19	D.O	A 03/12/2018 .
CA / REV / REP. / REV 24 H	RS Cups		14	O.D. Endorsement:
Date/Time: 9.350m8 7 12 1	Person Contact	ed: Juny		
Date/Time Action/Instruction		V		0
GBC 985	4D-X	a nec		
YP99234-				
/ /		ed IA to	# Kat	heire wang vi'a
0 3 7				

Tech Invs (\$

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

3.020.20 AP

10

160

) Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

LAIM SUBF	OLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Authled	Status		
Main	14 Dec 2018		17 Dec 2018 09:26 Assign					1	Assignme el Case	nt
1-	tain	Re	ference		Claim Details		Docume	nts	7 [Show All
CLAIM SUE	FOLDER DE	TAILS				Create	d by insurer1			
Insured:	WLK ENG	INEERING PTE L	TD, Co. Reg. N	o.: 2015426	35G	Leicate	a by maurer			
Main Claimant:		L CAR RENTAL P								
Vehicle Reg. No.:	GBC985	4D			Date of Loss:		18 00:00 - :59 hs and 18 Days	From LTA F	Reg Date (Man Yr)1
Claim Type:	TP / 578	983			Policy/Cover Note No.:	[55 Months and 18 Days From LTA Reg Date (Man Yi 29109613MKC (Comprehensive) Coverage: 29/11/2018 - 28/11/2019				
Vehicle Reg. No. (Insured):	YP9923Y				Policy No. (Claimant):					
D 1	<u> </u>	_			Excess:					
Repairer:	Esteem Pe	erformance Pte L	.td (HQ) Blk 50:	33 Ang Mo K	io Ind Park 2, #	01-259, 56	9536 Ang Mo Ki	o - Tel:		
Handling Insurer:	MSIG Inst	rance (Singapo	re) Pte. Ltd. (H	Q) - Tel: +6	5 6827 7888	[Handled b	y Katherine W	ong Chew	Shong -	6594 254
Adjuster:	LKK Auto	Consultants Pte	Ltd (HO) - Tel:	6256-3561	[Imm.Adv	ice due 1	8/12/20181			
Adj Asg. Remarks:	Car in. on \	WP. Please contact Park 2 #01-259 S	us ASAP if you	cannot atten	d this assignmen	nt. TP surve	ev at Esteem Pe	rformance (hong)	Pte Ltd, B	lk 5033 Ar
ASSOCIATI	ED MAIL REG							View All	Compos	e Case Mail
There are no	mail for this	case.						THE PAIL	Composi	case Mail
ALL ASSOC	CIATED TAS	KS⊟				View All	Search Tasks	Create t	New Task	Camal
Due Date	Priority	Type Tack	Group Cubi	art House	dlan Andrew					Complete
	riversky	The Task	armap aubj	ect nanc	ner Assign	ed by	Completed O	n Cre	ated On	Done'
Due Date No results.	Priority	Type Task (Group Subj	ect Hand	dler Assign	ed By	Completed O	n Cre	ated On	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

> 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Katherine Wong Chew Shong

Date: 18 Dec 2018

Preliminary Advice

Insured Vehicle No : YP9923Y

TP Vehicle No

: GBC9854D

Accident Date

: 03/12/2018

Make

: MITSUBISHI L200

Assignment Date

: 17/12/2018

Date of Inspection : 17/12/2018

Est. Duration of Repair

: 4 days

Inspection At

: Esteem Performance Pte Ltd (HQ)

Blk 5033 Ang Mo Kio Ind Park 2, #01-259

Singapore 569536

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,735.00
Revised Amount	:S\$	3,020.20
Check Items (Estimated)	:S\$	522.00
Total	:S\$	3,542.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	control at a straining of this report at the define and to express of the report being more available
大型医量型 在 电影中的影响和电影 金属的	ACCIDENT STATEMENT
Date Of Report	05/12/2018 11:03
Date Of Accident	03/12/2018 14:00
Exact Location Of Accident	CALTEX JALAN AHMAD IBRAHIM
Country/State of Loss	SINGAPORE
THE RESERVE OF THE PERSON OF	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBC9854D
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82990695
Alternative Phone No	OFFICE-82990695
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	L200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD18V00032/VCZ/R03
Cover Note Number	
Driver	
Name of Driver	SHUKOR BIN MD DOM
NPIC No.	\$2522472B

 NRIC No
 S2532472B

 Date Of Birth
 22/08/1965

 Occupation
 OUTDOOR

 Date Of Driving Pass
 25/02/1999

Driving Experience 19 YEARS AND 9 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-82990695

Fax Number Contact Number

EMail Address NOEMAIL

Address

BLK 589 WOODLANDS DRIVE 16 #02-24

Postcode

730589

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

DRIZZLING

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?
Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

1

Details of Police Action

Was the accident reported to the police?

Number of Passengers (Including Driver)

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YP9923Y

Vehicle Make/Model/Colour

MIT FUSO

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

YAP SOO KEE

NRIC/Passport Number

Contact Number

69043236

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the malling of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:


Driver Signature

(If driver is not the policyholder)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Main Read

My vehicle was sta-	tionery in lot to fill up fuel in Ca	thex. The larry was moving out
	right side body brushed against	
	11/11 3140 0007 0100100 4/	11,11,14 7,000
While maring.		
CLADATION	1	
ECLARATION ENTAL	culars are true in every respect.	
(1 (3 () E	11/20/1	
LAMBAN S.	14/2010	
licyholder's Signature	Driver Street Live	Reporting Centre Personnel's Signature
te & Time:	Driver's Senature (If driver is not the policyholder)	Name:
	Date & Time;	NRIC/FIN No.:



Repair Estimates

ESTEEM PERFORMANCE PTE LTD

No Nothank

			(1) Bis
Parts (a) Cost / List Price Items			Merry Afer Pains
Plus/Less	_		, and
Total of Cost / List			
(b) Nett Price Items	\$	6,800.00	LKK Auto Consultants hence notify the Repairer of the following:
Less10%	\$	680.00	To result by before other spray painting To does a commod parties during resulting
Total of Nett Item	\$	6,120.00	The property of the state
(c) Special Nett Items	\$	45.00	Supplies the state of the
Total Parts Cost	\$	6,165.00	Acknowledge of courses
Labour	\$	2,570.00	Signature: Date:
Total	\$	8,735.00	
The above total will be subjected to	7% G.S.T.		Simonto
Name of Surveyor	: .		Kennerh 18/12/18
Company	: .		
Survey conducted on	:	17	1/2/18 at
Demorks Dy Curveyer			
Remarks By Surveyor			529
(a) The repair of this vehicle is	authorized / i		r notice.
(b) Recommended Days of Re	pair :	04	day(s)
(c) Resurvey	:	Required / Not Required	
(d) Excess	:\$		
(e) Signature of surveyor		-	Le Date: 17/12/18
\-/ -/ -/g or our rojo/			

GBC 9854 D



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No.	:
Make & Model	:
Chassis No	:

GBC 9854 D

MITSUBISHI L200 MMBJYKB40FD004958 Submit By

Year Manufacture : Engine No. : Carmen Lim

2013

Cost / List

	Part Description Qty Unit Price Disposition I								
S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor				
1	Front number plate N.C (Pd)	1	\$45.00	S.N	X				
2	Front number plate garnish N. c (Dd)	1	\$54.00	N	X				
3	Bonnet	1	\$604.00	N	X				
4	Bonnet lock	1	\$55.00	N	×				
5	Bonnet hinge LH	1	\$59.00	N	×				
6	Bonnet hinge RH	1	\$59.00	N	X				
7	Headlamp LH N·c (CM)	/ 1	\$820.00	N	×				
8	Headlamp RH cn	. 1	\$820.00	N					
9	Headlamp clip	10	\$30.00	N	?				
10	Headlamp lower panel LH	1							
11	Headlamp lower panel RH	n 1	\$955.00	N	X				
12	Front support panel (complete)	1							
13	Front grille	1							
14	Front grille Chrome	1	\$550.00	N	?				
15	Front grille logo	1							
16	Front bumper CP4	1	\$775.00	N	150				
17	Front bumper clip	10	\$30.00	N					
18	Front bumper reinforcement n	1	\$348.00	N	X				
19	Front bumper side retainer LH	1	\$19.00	N	X				
20	Front bumper side retainer RH	/ 1	\$19.00	N					
21	Front bumper bracket LH	1	\$54.00	N	X				
22	Front bumper bracket RH	n_1	\$54.00	N	*				
23	Front bumper lower centre silver	~ 1	\$97.00	N	X				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :	GBC 9854 D	Submit By	:	Carmen Lim
Make & Model:	MITSUBISHI L200	Year Manufacture	:	2013
Chassis No :	MMBJYKB40FD004958	Engine No.	:	
_		Cost / List		

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
24	Fog lamp RH	Sn	1	\$274.00	N	X
25	Fog lamp cover RH	SL	1	\$114.00	N	Y
26	RH front fender	R	1	\$562.00	N	
27	RH front fender undershield	Su	1	\$146.00	N	×
28	RH front fender undershield clip	na	10	\$30.00	N	Х
29	RH front fender protector	Cn	1	\$272.00	N	
30	·					
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						
41						
42						
43						
44						
45						
46						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	GBC 9854 D	Submit By :	Carmen Lim
Make & Model	:	MITSUBISHI L200	Year of Manufacture :	2013

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL,	\$1,000.00	4501
	RHF FENDER,RHF FENDER PROTECTOR)		
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL	\$1,200.00	6001
	RHF FENDER,RHF FENDER PROTECTOR)		
3	To check wiring, focus headlamp	\$50.00	201
4	To tuff coat.	\$200.00	301
5	To conduct water leakage tests to ensure proper air and	\$120.00	Χ
	sealing		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ESTEEM PERFORMANCE PTE LTD

Repair Estimates	GE	C 9854 D	Finalised.	Nos Wihann
Parts (a) Cost / List Price Items Plus/Less				Nos Nothanse Ulang Br Menny After Pains
Total of Cost / List				LKK Auto Consultants hence notify
(b) Nett Price Items Less 10%	\$	6,800.00	1703	the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation
Total of Nett Item	\$	6,120.00	1532.70	 * Hard party survey is on a "Without Prejudice" basis * No illegal modification(s) is allowed * Supplementary item(s) must be resurveyed and
(c) Special Nett Items	\$	45.00	387.50	is subject to final approval from Insurance Compan
Total Parts Cost	\$	6,165.00	1920-20	Acknowledged by Repairer Signature:
Labour	\$	2,570.00	1100	Date:
Total	\$	8,735.00	3020-20 V	rok
The above total will be subjected to	7% G.S.T.			
Name of Surveyor	: _		Ken	nerh
Company			6	Kle
Survey conducted on	: _		17/12/18	at
Remarks By Surveyor				
(a) The repair of this vehicle is a				
(b) Recommended Days of Rep (c) Resurvey	decin of	equired / Not-Reg	day(s)	
(d) Excess	:\$		4	474-1-0
(e) Signature of surveyor	: _			Date:

工业次程



ESTEEM PERFORMANCE PTE

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : Make & Model:

Chassis No

GBC 9854 D

MITSUBISHI L200

MMBJYKB40FD004958

Submit By

Year Manufacture : Engine No.

Carmen Lim 2013

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	N.C (Rd)	1	\$45.00	S.N	X
2	Front number plate garnish	N.C (Dd)	1	\$54.00	N	X
3	Bonnet	n	1	\$604.00	N	X
4	Bonnet lock	Λ	1	\$55.00	N	×
5	Bonnet hinge LH	N	1	\$59.00	N	X
6	Bonnet hinge RH	И	1	\$59.00	N	X
7)	Headlamp LH	N.C (CN	1 1	\$820.00	N	X
(8)	Headlamp RH	cn	1 1	\$820.00	N	1
9	Headlamp clip	·N·	10	\$30.00	N	F
10	Headlamp lower panel LH	7	1			
11	Headlamp lower panel RH	_	N 1	\$955.00	N	X
12	Front support panel (complete)	J	1			
13	Front grille	٦	1			
14	Front grille Chrome	-	f-1	\$550.00	N	3
15	Front grille logo	J	1			
(16)	Front bumper	CPA	1	\$775.00	N 387.30	S.N 50
17	Front bumper clip	M	10	\$30.00	N	-
18 /	Front bumper reinforcement	N	1	\$348.00	N	X
19	Front bumper side retainer LH	Sh	1	\$19.00	N	X
(20)	Front bumper side retainer RH	0.	1 1	\$19.00	N	
21	Front bumper bracket LH		1 1	\$54.00	N	X
22	Front bumper bracket RH		N 1	\$54.00	N	×
23	Front bumper lower centre silve	r J	7 1	\$97.00	N	X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N

N: 869 N: 869

Spare Parts

Vehicle No. Make & Model: Chassis No :

GBC 9854 D

MITSUBISHI L200 MMBJYKB40FD004958

Submit By

Carmen Lim Year Manufacture : 2013 Engine No.

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
24	Fog lamp RH	fn	1	\$274.00	N	X
25	Fog lamp cover RH	82	1	\$114.00	N	X
(26)	RH front fender	R	1	\$562.00	1	
27	RH front fender undershield	Su	1	\$146.00	N	X
28	RH front fender undershield clip	na	10	\$30.00	N	X
(29)	RH front fender protector	Cn	1	\$272.00 L	N	
30				14272.00	111	
31						-
32	7 1 205					
33						
34		- U				
35						†
36						
37	9					
38						
39						
40						-
41						
42						
43						
44						
45						
46						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Klo, Ind Park 2 #01-251/ 259, 589536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	GBC 9854 D	Submit By	:	Carmen Lim
Make & Model	:	MITSUBISHI L200	Year of Manufacture	:	2013
	-				

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL,	\$1,000.00	4501
	RHF FENDER,RHF FENDER PROTECTOR)		
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL	\$1,200.00	6001
	RHF FENDER,RHF FENDER PROTECTOR)		
3	To check wiring, focus headlamp	\$50.00	201
4	To tuff coat.	\$200.00	301
5	To conduct water leakage tests to ensure proper air and	\$120.00	Χ
	sealing		
-			1000 Hand

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main			\$\$3,020.20 Edit Estimates			Pending for Survey Report Cancel Case		
-	Main	R	eference	Claim De	tails	Documents	Show All	
CLAIM SU	BFOLDER DE	TAILS			[Create	d by insurer]		
Insured:	WLK ENG	INEERING PTE L	TD, Co. Reg. No.:	201542635G				
Main Claimant:	GOLDBEL	L CAR RENTAL P	TE LTD, Co. Reg.	No.: 200710651D				
Vehicle Reg No.:	GBC985	4D		Date of		018 00:00 - :59 ths and 18 Days Fro	om LTA Reg Date (Man Yr)]	
Claim Type:	TP / 578	1983		Policy/0 Note No		29109613MKC (Comprehensive) Coverage: 29/11/2018 - 28/11/2019		
Vehicle Reg No. (Insured):		YP9923Y			No. ant):			
				Excess				
Repairer:	Esteem P	erformance Pte	Ltd (HQ) Blk 5033	Ang Mo Kio Ind Parl	2, #01-259, 56	9536 Ang Mo Kio - 1	Tel:	
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +65 6827 78	88 [Handled t	by Katherine Wong	Chew Shong - 6594 2544	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	d by KENNETH	KONG] [Final F	Rpt due 16/01/2019]	
Adj Asg. Remarks:						ey, at Esteem Perfor 221 (Ms Jenny Chon	rmance Pte Ltd, Blk 5033 An	
ASSOCIAT	ED MAIL RE	CEIVED				Vie	w All Compose Case Mail	
There are n	mail for this	case.						
ALL ASSO	CIATED TAS	sks⊡			View All	Search Tasks C	reate New Task Complete	
Due Date	Priority	Type Task	Group Subject	t Handler	Assigned By	Completed On	Created On Done	

Claim Documents

*GBC9854D (578983)

[YP9923Y]

TP

GOLDBELL CAR RENTAL PTE LTD

Dec 3 2018 12:00AM

[WLK ENGINEERING PTE LTD]

Esteem Performance Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser				
Ass	essment Reports		1 per p	page 🔻	~		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	18/12/18 15:14	Adjuster Immediate Advice	0	Load HTM			
Pho	otos/Images		3 per p	page 🔻	V		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	18/02/19 10:23	General View	0	Load JPG	✓		
2	18/02/19 10:23	Odometer Reading	0	Load JPG	~		
3	18/02/19 10:23	General View	0	Load JPG	V		
4	18/02/19 10:23	General View	0	Load JPG	~		
5	18/02/19 10:23	General View	0	Load JPG	~		
6	18/02/19 10:23	General View	0	Load JPG	4		
7	18/02/19 10:23	General View	0	Load JPG	~		
8	18/02/19 10:23	General View	0	Load JPG	V		
9	18/02/19 10:23	General View	0	Load JPG	V		
10	18/02/19 10:23	General View	0	Load JPG	✓		
11	18/02/19 10:23	General View	0	Load JPG	V		
12	18/02/19 10:23	Chassis Number	Ð	Load JPG	✓		
13	18/02/19 10:24	Reinspection Photo	0	Load JPG	V		
14	18/02/19 10:24	Reinspection Photo	Ð	Load JPG	✓		
Dod	umentation		1 per p	page 🔽	V		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 pc. p	Thumbnail			
1	14/12/18 16:41	TP EST BILL & ACCDT REPORT	0	Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18022557/KSD3E2

Date:

18/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29109613MKC

Claimant Vehicle GBC9854D

Insured Vehicle No:

YP9923Y

Date of Loss:

03/12/2018

Nature of Claim:

TP

Claim No: 578983

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

GBC9854D

Make & Model:

MITSUBISHI L200, 2.4 D DOUBLE CAB (M)

Engine No:

4D56UCEW2255

67788 km

Reg. Date:

15/04/2014 (Man. Year: 2013) Metallic Silver

Chassis No: Odometer:

MMBJYKB40FD004958

Colour: Engine Capacity:

2477 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

245/70 R16

Rear Tyre Size:

245/70 R16

Front Tyre Size: Front Left Side:

Falken 8 mm

Rear Left Side:

Falken 8 mm

Front Right Side:

Falken 8 mm

Rear Right Side:

Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,165.00	1,920.20	4,244.80	68.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,100.00	1,470.00	57.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,735.00	3,020.20	5,714.80	65.42
+ GST 7.00/7.00% (S\$)	611.45	211.41	400.04	65.42
Nett Amount (S\$)	9,346.45	3,231.61	6,114.84	65.42

INSPECTION

Date of Assignment:

17/12/2018

Date Inspected:

17/12/2018 Inspected At:

Esteem Performance Pte Ltd (HQ)

Blk 5033 Ang Mo Kio Ind Park 2, #01-259

Singapore 569536

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG

Manager:

Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen Part Source		(Last Synchronised: 18 Feb 2019)		
Parts:	N/A	MITSUBISHI L200 2.4 D DOUBLE CAB (M) (Model not available in database)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted	, no print-code for GBC9854D)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE (DENTED)	Not Consistent With The Impact	45.00 FS	*-FS
2	1		*FRONT NUMBER PLATE GARNISH (DENTED)	Not Consistent With The Impact	54.00 FN	*-FN
3	1		*BONNET	Repair	604.00 FN	*-FN
4	1		*BONNET LOCK	Repair	55.00 FN	*-FN
5	1		*BONNET HINGE LH	Repair	59.00 FN	*- FN
6	1		*BONNET HINGE RH	Repair	59.00 FN	*- FN
7	1		*HEADLAMP LH (CRACKED)	Not Consistent With The Impact	820.00 FN	*- FN
8	1		*HEADLAMP RH	Cracked	820.00 FN	*820.00 FN
9	10		*HEADLAMP CLIP	Not Necessary	30.00 FN	*- FN
10	1		*HEADLAMP LOWER PANEL LH }	8	0.00 FN	*- FN
11	1		*HEADLAMP LOWER PANEL RH }	Repair	955.00 FN	*- FN
12	1		*FRONT SUPPORT PANEL (COMPLETE) }	Ex.Com (* 15.4500)	0.00 FN	*- FN
13	1		*FRONT GRILLE }		0.00 FN	*- FN
14	1		*FRONT GRILLE CHROME }	Serviceable	550.00 FN	*- FN
15	1		*FRONT GRILLE LOGO }		0.00 FN	*- FN
16	1		*FRONT BUMPER (\$775.00) (50%)	Cracked	697.50 FS	*387.50 FS
17	10		*FRONT BUMPER CLIP	Necessary	30.00 FN	*30.00 FN
18	1		*FRONT BUMPER REINFORCEMENT	Repair	348.00 FN	*- FN
19	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	19.00 FN	*- FN
20	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	19.00 FN	*19.00 FN
21	1		*FRONT BUMPER BRACKET LH	Repair	54.00 FN	*- FN
22	1		*FRONT BUMPER BRACKET RH	Repair	54.00 FN	*- FN
23	1		*FRONT BUMPER LOWER CENTRE SILVER	Serviceable	97.00 FN	*- FN
24	1		*FOG LAMP RH	Serviceable	274.00 FN	*- FN
25	1		*FOG LAMP COVER RH	Serviceable	114.00 FN	*- FN
26	1		*RH FRONT FENDER	Bent	562.00 FN	*562.00 FN
27	1		*RH FRONT FENDER UNDERSHIELD	Serviceable	146.00 FN	*- FN
28	10		*RH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	30.00 FN	*- FN
29	1		*RH FRONT FENDER PROTECTOR	Cracked	272.00 FN	*272.00 FN
2000	anchise	part. S=S	SpcNett. N=NettItemDisc.			
			*	Sub Total (S\$)	6,767.50	2,090.50
			- Nett Item Discount	on N Items 10.00/10.00% (S\$)	602.50	170.30
				Total Parts (S\$)	6,165.00	1,920.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

rticulars	Lab.Type	Repairer's	Amount
tems			
RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT PAIR AREA. (FRONT BUMPER, BONNET, SUPPORT NEL, RHF FENDER, RHF FENDER PROTECTOR)	New	1,000.00	450.00
PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT PAIR AREA. (FRONT BUMPER, BONNET, SUPPORT NEL, RHF FENDER, RHF FENDER PROTECTOR)	New	1,200.00	600.00
CHECK WIRING, FOCUS HEADLAMP	New	50.00	20.00
TUFF COAT	New	200.00	30.00
CONDUCT WATER LEAKAGE TESTS TO ENSURE COPER AIR AND SEALING	New	120.00	0.00
Gross Labo		2,570.00	1,100.00
	RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT PAIR AREA. (FRONT BUMPER, BONNET, SUPPORT NEL, RHF FENDER, RHF FENDER PROTECTOR) PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT PAIR AREA. (FRONT BUMPER, BONNET, SUPPORT NEL, RHF FENDER, RHF FENDER PROTECTOR) CHECK WIRING, FOCUS HEADLAMP TUFF COAT CONDUCT WATER LEAKAGE TESTS TO ENSURE OPER AIR AND SEALING	RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT PAIR AREA. (FRONT BUMPER, BONNET, SUPPORT NEL, RHF FENDER, RHF FENDER PROTECTOR) PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT PAIR AREA. (FRONT BUMPER, BONNET, SUPPORT NEL, RHF FENDER, RHF FENDER PROTECTOR) CHECK WIRING, FOCUS HEADLAMP New TUFF COAT New CONDUCT WATER LEAKAGE TESTS TO ENSURE New	RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT PAIR AREA. (FRONT BUMPER, BONNET, SUPPORT NEL, RHF FENDER, RHF FENDER PROTECTOR) PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT PAIR AREA. (FRONT BUMPER, BONNET, SUPPORT NEL, RHF FENDER, RHF FENDER PROTECTOR) CHECK WIRING, FOCUS HEADLAMP New 50.00 TUFF COAT New 200.00 CONDUCT WATER LEAKAGE TESTS TO ENSURE New 120.00 OPER AIR AND SEALING

< END OF ESTIMATES >