

INS. CASE OWNER:

Chee Hong

CC 6 / MG 180

22573,

Ufa352

LKK:

IDAC:

SERVITOR:

MARINS

DOI:

ASSIGNMENT

17/12/18

Date / Time:

17/12/18

Registered in Merimen:

17/12/18

Pre-assign / CCU / FTE

GBE 4165 G



Insured Vehicle No.:

Name of Insured:

UNICO DISTRIBUTION SRS PLZ

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

12/12/18

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

PIE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN THIAM SIANG

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

GBD 4430E



INSRS:

WSP:

Tel:

Liability:

RMKS:

Uu's bro.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

13-11-19

AS MALAYSIA VEHICLE IS INVOLVED AND PIR IS AGAINST HIM. PLS
DIRECT TP CLAIM AGAINST MALAYSIA VEHICLE

18/11/19 - FIVE PAS TO HMMU TO CLOS

Reject Case

JIE LE

4

15-11-19

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@yahoo.com

Invoice/Ref No: GBD4470E181212

Estimate

Customer

Page 01 - 02

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 14-12-18

Address: Motor Claims Department

Vehicle No: GBD4470E

78 Shenton Way #07-16

Model/Make: Fiat Doblo Cargo

AIG Building Singapore 079120

SX JTD 1.6 MJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Door	\$ 2,159.20	
2	Door Outer Protector	\$ 320.00	
3	Door "Corporate Detail" Advertisement & Artwork	\$ 880.00	SN 5005.2
4	Door View Mirror	\$ 701.50	
5	Door View Mirror Signal Lamp	\$ 289.00	
6	Door Outer Pillar	\$ 989.50	X
7	Door Hinges 02 pcs (@ S\$260.00 SN)	\$ 520.00	SN X
8	Door Inner Rubber	\$ 385.40	X
9	Door Inner Trim Board	\$ 420.00	X
10	Door LTA "Corporate Detail" Sticker	\$ 48.00	SN X
11	Bumper	\$ 1,245.50	
12	Bumper Side Holder	\$ 68.00	
13	Bumper Clips 1 set	\$ 50.00	SN
14	Fender	\$ 1,277.50	
15	Fender Inner Shield	\$ 316.00	
16	Fender Inner Shield Clips 1 set	\$ 65.00	SN
17	Fender Inner Panel	\$ 672.00	X
18	Shock Absorber	\$ 490.00	
19	Lower Arm	\$ 390.00	
20	Knuckle Arm	\$ 684.00	
21	Knuckle Arm Bearing	\$ 215.00	
22	Wheel Hub Bearing	\$ 486.30	X
23	Drive Shaft	\$ 980.00	X
24	Wheel Hub Cap	\$ 225.00	SN 1505.2
25	Steel Wheel	\$ 280.00	SN 505.2
26	Head Lamp	\$ 862.40	
	To check Fr Lh all wiring & electrical component for proper function	\$ 30.00	15
	To apply Rust Proofing , reseal tuff-coating treatment on Fr Lh accident area	\$ 80.00	50
	To check and re-adjust Fr Lh wheel alignment	\$ 120.00	80
	To Dismantle & Replacing Fr Lh Undercarriage parts & components	\$ 150.00	120
	To remove, replace and transfer Fr Lh door panel, fitting and mechanisms	\$ 80.00	60
	Labor for Fr Lh Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	500
	To putty & spray painting & including touch up paint on Fr Lh accident affected area	\$ 1,000.00	700
	C/F Balance ---->	\$ 17,279.30	

not approved
L/S \$ 18500
17/12/18
15 day

9018-1
811629
10458-29
202
8368



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBD4470E181212

Estimate

Customer

Page 02 -02

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 14-12-18

Address: Motor Claims Department

Vehicle No: GBD4470E

78 Shenton Way #07-16

Model/Make: Fiat Doblo Cargo

AIG Building Singapore 079120

SX JTD 1.6 MJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 17,279.30	
27	Front Bonnet	\$ 1,170.00	
28	Bonnet "Corporate" Advertisement & Artwork 1 set	\$ 300.00	SN ✓
29	Bonnet Hinges 02 pcs (@ S\$135.00)	\$ 270.00	X
30	Bonnet Inner Lock	\$ 138.00	X
31	Bumper Lower Centre Grille	\$ 288.60	X
32	Bumper Top Grille	\$ 128.50	X
33	Bumper Logo	\$ 139.70	X
34	Bumper Side Holder Rh	\$ 60.60	X
35	Bumper Sponge	\$ 117.60	X
36	Bumper Reinforcement	\$ 724.70	X
37	Bumper Towing Cover	\$ 60.00	X
38	Aircon Condenser	\$ 1,278.00	X
39	Inter Cooler	\$ 3,640.00	X
40	Inner Cooler Garnish	\$ 157.00	X
41	Inner Cooler Clip 1 set	\$ 28.00	SN X
42	Radiator	\$ 754.30	X
43	Radiator Fan Assy	\$ 378.00	X
44	Support Panel	\$ 745.20	X
45	Fender 0/5	\$ 1,277.80	X
46	Fender "Corporate" Advertisement & Artwork 1 set	\$ 580.00	SN 3005.2
47	Power Steering Pump	\$ 572.60	X
48	Aircon Compressor	\$ 1,160.00	X
49	Turbo Charge	\$ 4,856.30	X
50	Fuel Pump	\$ 580.00	X
51	Chassic Member	\$ 720.00	X
52	Air Duct	\$ 177.35	X
53	Head Lamp 0/5	\$ 658.80	X
54	Number Plate & Base	\$ 48.00	SN 40
55	Radiator Coolant	\$ 50.00	SN ✓
	To check Front all wiring & electrical component for proper function	\$ 30.00	20
	To remove & refix Front air con, re-fill air con gas & test for leakages	\$ 120.00	100
	Remove & reinstall Front engine to faciliate chassic realignment	\$ 380.00	250
	To apply Rust Proofing , reseal tuff-coating treatment on Front accident area	\$ 100.00	80
	To check and reinstall Front Turbo	\$ 100.00	50
	To mount vehicle onto Front chassis alignment bench & to conduct alignment	\$ 380.00	X
	Labor for Front Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	1000
	To putty & spray painting & including touch up paint on Front accident affected are	\$ 1,200.00	900

Total Parts & Labour of estimate for damaged vehicle

\$ 42,148.35

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

14078.25

M/s Liu's Brother Auto Engrg Wks

102
12670
S.N 690



2400
15760
12600

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1196N

Vehicle Details

Vehicle No.: GBD4470E

Vehicle to be Exported: Yes

Intended Deregistration Date: 17 Dec 2018

Vehicle Make: FIAT

Vehicle Model: DOBLO CARGO SX JTD 1.6 MJ

Primary Colour: White

Manufacturing Year: 2013

Engine No.: 198A30006992755

Chassis No.: ZFA26300006107510

Maximum Power Output: -

Open Market Value: \$20,062.00

Original Registration Date: 28 Oct 2014

First Registration Date: 28 Oct 2014

Transfer Count: 1

Actual ARF Paid: \$1,004.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Oct 2024

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$52,010.00

COE Rebate Amount: \$30,478.00

Total Rebate Amount: \$30,478.00

The information contained herein is correct as at 17 Dec 2018

OK



doblo

Price Range

Depreciation

2014

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Prem Roy Motoring » Fiat Doblo Cargo Maxi 1.6A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Fiat Doblo Cargo Maxi 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map



COMPLETE CAR TRADE SOLUTIONS

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$49,000**Depreciation** \$8,380 /yr
View models with similar depreciation**Reg Date** 21-Oct-2014
(5yrs 10mths 3days COE left)**Manufactured** 2014**Mileage** 35,985 km (8.7k /yr)**Transmission** Auto**Engine Cap** 1,598 cc**Curb Weight** 1,500 kg**Fuel type** Diesel**Features** Just Renewed Road Tax And Insurance Up To 20/10/2018.**Accessories** Original With Good Condition.**Description** 1 Owner, Seldom Driven, High PARF Rebate, New Road Tax, Regularly Servicing At Agent, Consignment Unit! Trade In Welcome! Loan And Insurance Available! Call Now For Viewing Appointment!**COE** \$49,901**OMV** \$20,654**ARF** \$1,033**Dereg Value** \$29,175 as of today (change)**No. of Owners** 1**Type of Veh** Van**Category** -**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 07-Dec-2018 | Last Updated on: 07-Dec-2018

Tags: Fiat Doblo, fiat doblo, 2014 Fiat Doblo, 2014 fiat doblo, Fiat, Doblo, doblo, Used Fiat



Location Map

Seller Information

Company

Prem Roy Motoring

» dealer's pricelist

» 151 vehs sold | 203 vehs available

Address

9 Tagore Lane #02-03

Search cars nearby this location

Location

9@Tagore

Office No

66028046

Contact Person(s)

Zin

90025579

Ashvini

98896985

Compare

Upfront Payment

» more Financial info



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-193262

Date of Request: 14/12/2018

Your Ref No:

Online Purchase

LIU'S BROTHER AUTO WORKSHOP

1 Kaki Bukit Ave 6 #01-01

Auto Bay@Kaki Bukit

Singapore 417883

Dear Sir/Madam,

Enquiry Date 14/12/2018

Enquiry By Susan Low Siew Yian

TP Vehicle No. GBE4165G

Accident Date 12/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBE4165G	AIG Asia Pacific Insurance Pte. Ltd.	24/11/2018-23/11/2019	65-6419-3000

Thank You

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Nivitha (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 14 December 2018 4:19 PM
To: assignments
Subject: FW: Request for 3rd party claims survey GBD4470E Claims against GBE4165G
Attachments: GBD4470E Search.pdf; Untitled attachment 01079.html; GBD4470E181212.pdf; Untitled attachment 01082.html

9:23am @ 17/12/2018

person @ Susan
vehicle @ In
SUR @ Marcus

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Susan Low [mailto:liusbro@gmail.com]

Sent: Friday, 14 December 2018 4:14 PM

To: Admin A. <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Marcus Chua (LKKAuto) <marcuschua@lkkauto.com>

Subject: Request for 3rd party claims survey GBD4470E Claims against GBE4165G

Accident on 12/12/2018 Along PIE Towards BKE

Involving GBD4470E and GBE4165G

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:-

Name of Authorise Surveyor:-

Surveyor Email:

Remark :-

Our Ref: GBD4470E181212

Date: 12/01/2019

Your Ref:

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Chartis Building
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG PIE TOWARDS BKE
INVOLVING GBD4470E AND GBE4165G ON 12/12/2018**

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**), the registered owners of m/vehicle – **GBD4470E** at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my on his recommendation for **S\$18,500-00** being the repair for **15 Days** (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **GBE4165G** when the same was involved in the aforesaid accident with our/my m/vehicle – **GBD4470E**.

We/I whereby you are the insurers of m/vehicle **GBE4165G** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GBD4470E** has suffered loss and damage as follows:

(a) Cost of repairs	S\$ 18,500-00
(b) LOU for pre-repair notice 02 days @\$60-00	120-00
(c) LOU Fee for 15 days @\$60-00	900-00
(d) GIA / LTA search fee	2-00
(e) Towing Fee	-

Total Amount

S\$ 19,522-00

We/I enclose herewith copies of the supporting documents for vehicle no. **GBD4470E** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,


The owner of m/vehicle **GBD4470E**
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBD4470E181212

Estimate

Customer	Page 01 - 02
Name: AIG Asia Pacific Insurance Pte Ltd	Date: 14-12-18
Address: Motor Claims Department	Vehicle No: GBD4470E
78 Shenton Way #07-16	Model/Make: Fiat Doblo Cargo
AIG Building Singapore 079120	SX JTD 1.6 MJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Door		
2	Door Outer Protector	\$ 2,159.20	\$ -
3	Door "Corporate Detail" Advertisement & Artwork	\$ 320.00	\$ -
4	Door View Mirror	\$ 880.00	\$ -
5	Door View Mirror Signal Lamp	\$ 701.50	\$ -
6	Door Outer Pillar	\$ 289.00	\$ -
7	Door Hinges 02 pcs (@ S\$260.00 SN)	\$ 989.50	\$ -
8	Door Inner Rubber	\$ 520.00	\$ -
9	Door Inner Trim Board	\$ 385.40	\$ -
10	Door LTA "Corporate Detail" Sticker	\$ 420.00	\$ -
11	Bumper	\$ 48.00	\$ -
12	Bumper Side Holder	\$ 1,245.50	\$ -
13	Bumper Clips 1 set	\$ 68.00	\$ -
14	Fender	\$ 50.00	\$ -
15	Fender Inner Shield	\$ 1,277.50	\$ -
16	Fender Inner Shield Clips 1 set	\$ 316.00	\$ -
17	Fender Inner Panel	\$ 65.00	\$ -
18	Shock Absorber	\$ 672.00	\$ -
19	Lower Arm	\$ 490.00	\$ -
20	Knuckle Arm	\$ 390.00	\$ -
21	Knuckle Arm Bearing	\$ 684.00	\$ -
22	Wheel Hub Bearing	\$ 215.00	\$ -
23	Drive Shaft	\$ 486.30	\$ -
24	Wheel Hub Cap	\$ 980.00	\$ -
25	Steel Wheel	\$ 225.00	\$ -
26	Head Lamp	\$ 280.00	\$ -
		\$ 862.40	\$ -
	To check Fr Lh all wiring & electrical component for proper function	\$ 30.00	\$ -
	To apply Rust Proofing, reseal tuff-coating treatment on Fr Lh accident area	\$ 80.00	\$ -
	To check and re-adjust Fr Lh wheel alignment	\$ 120.00	\$ -
	To Dismantle & Replacing Fr Lh Undercarriage parts & components	\$ 150.00	\$ -
	To remove, replace and transfer Fr Lh door panel, fitting and mechanisms	\$ 80.00	\$ -
	Labor for Fr Lh Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	\$ -
	To putty & spray painting & including touch up paint on Fr Lh accident affected area	\$ 1,000.00	\$ -
	C/F Balance -->	\$ 17,279.30	\$ -



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBD4470E181212

Customer

Estimate

Name: AIG Asia Pacific Insurance Pte Ltd

Page 02 - 02

Address: Motor Claims Department

Date: 14-12-18

78 Shenton Way #07-16

Vehicle No: GBD4470E

AIG Building

Singapore 079120

Model/Make: Fiat Doblo Cargo

SX JTD 1.6 MJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance -->		
27	Front Bonnet	\$ 17,279.30	\$ -
28	Bonnet "Corporate" Advertisement & Artwork 1 set	\$ 1,170.00	\$ -
29	Bonnet Hinges 02 pcs (@ \$5135.00)	\$ 300.00	\$ -
30	Bonnet Inner Lock	\$ 270.00	\$ -
31	Bumper Lower Centre Grille	\$ 138.00	\$ -
32	Bumper Top Grille	\$ 288.60	\$ -
33	Bumper Logo	\$ 128.50	\$ -
34	Bumper Side Holder Rh	\$ 139.70	\$ -
35	Bumper Sponge	\$ 60.60	\$ -
36	Bumper Reinforcement	\$ 117.60	\$ -
37	Bumper Towing Cover	\$ 724.70	\$ -
38	Aircon Condenser	\$ 60.00	\$ -
39	Inter Cooler	\$ 1,278.00	\$ -
40	Inner Cooler Garnish	\$ 3,640.00	\$ -
41	Inner Cooler Clip 1 set	\$ 157.00	\$ -
42	Radiator	\$ 28.00	\$ -
43	Radiator Fan Assy	\$ 754.30	\$ -
44	Support Panel	\$ 378.00	\$ -
45	Fender	\$ 745.20	\$ -
46	Fender "Corporate" Advertisement & Artwork 1 set	\$ 1,277.80	\$ -
47	Power Steering Pump	\$ 580.00	\$ -
48	Aircon Compressor	\$ 572.60	\$ -
49	Turbo Charge	\$ 1,160.00	\$ -
50	Fuel Pump	\$ 4,856.30	\$ -
51	Chassic Member	\$ 580.00	\$ -
52	Air Duct	\$ 720.00	\$ -
53	Head Lamp	\$ 177.35	\$ -
54	Number Plate & Base	\$ 658.80	\$ -
55	Radiator Coolant	\$ 48.00	\$ -
		\$ 50.00	\$ -
	To check Front all wiring & electrical component for proper function	\$ 30.00	\$ -
	To remove & refix Front air con, re-fill air con gas & test for leakages	\$ 120.00	\$ -
	Remove & reinstall Front engine to faciliate chassic realignment	\$ 380.00	\$ -
	To apply Rust Proofing, reseal tuff-coating treatment on Front accident area	\$ 100.00	\$ -
	To check and reinstall Front Turbo	\$ 100.00	\$ -
	To mount vehicle onto Front chassis alignment bench & to conduct alignment	\$ 380.00	\$ -
	Labor for Front Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	\$ -
	To putty & spray painting & including touch up paint on Front accident affected are	\$ 1,200.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 42,148.35

Total amount in Lump Sum Basis for repaired vehicle

\$ 18,500.00

SDLS: Eighteen Thouand Five Hundred Only

M/s Liu's Brother Auto Engrg Wks





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-193262

Date of Request: 14/12/2018

Your Ref No:

Online Purchase

LIU'S BROTHER AUTO WORKSHOP

1 Kaki Bukit Ave 6 #01-01

Auto Bay@Kaki Bukit

Singapore 417883

Dear Sir/Madam,

Inquiry Date: 14/12/2018
Enquiry By: Susan Low Siew Yian
TP Vehicle No: GBE4165G
Accident Date: 12/12/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBE4165G	AIG Asia Pacific Insurance Pte. Ltd.	24/11/2018-23/11/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Your Ref :
Our Ref : TP/IP/68563/2018

Date : 7 January 2019

FILMORE JR AMPELOQUIO
APT BLK 560 CHOA CHU KANG NORTH 6
#05-78
SINGAPORE 680560

Dear Sir/Madam,

TRAFFIC ACCIDENT INVOLVING AFP3262, GBD4470E AND GBE4165G ALONG PAN ISLAND EXPRESSWAY SLIP ROAD INTO BUKIT TIMAH EXPRESSWAY ON 12 DECEMBER 2018 AT ABOUT 4.46 P.M.

I refer to the above accident.

2. We have completed investigation into the case. Our investigation shows that the offence of **Driving Without Due Care and Attention under Section 65(a) of the Road Traffic Act Chapter 276** was disclosed against the driver of **AFP3262**. Action has been initiated against the driver for the said offence.

3. This is for your information.

Yours faithfully,

**RAZIZ BIN TAHAR, SENIOR STAFF SERGEANT
for HEAD TRAFFIC INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

Jia Le (LKK Auto)

Subject:

Your ref: 7914357472SG [ACCIDENT INVOLVING VEHICLES GBE4165G AND GBD4470E ON 12/12/2018]

Dear Chee Heng,

OI reported that a Malaysia vehicle ^{LOST} lose control and collided onto TPV, causing TPV collided onto OIV.

TP reported ^{THAT} Malaysia vehicle ^{LOST} lose control and ^{SPUN} spin towards his lane, TP could not stop in time and knock ^{ed} onto the Malaysia vehicle, the Malaysia vehicle continued to spin towards OI'S lane and collided onto OIV, OI tried to avoid and collided onto TPV. *THERE ARE SOME CONFLICTING VERSION OF COLLISION SEQUENCE BETWEEN T/P AND O/V.*

We received the PIR from TP ^{WHICH IS} and PIR against the Malaysia vehicle. As such, we propose to re-direct the claim to the Malaysia vehicle.

Kindly let us have your instruction.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Dec 2018 Edit Reg		17 Dec 2018 00:00 Edit Adj Rpt	S\$18,500.00 Edit Estimates	S\$18,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	UNICO DISTRIBUTION SERVICES PTE LTD, Co. Reg. No.: 199707266N		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GBD4470E	Date of Loss:	12/12/2018 16:00 - :59 [49 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7914357472SG	Policy/Cover Note No.:	2100439985 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE4165G	Policy No. (Claimant):	29090793
		Excess:	
Repairer:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/12/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBD4470E (7914357472SG)**
[GBE4165G]

TP

GOLDBELL LEASING PTE LTD

Dec 12 2018 4:00PM

[UNICO DISTRIBUTION SERVICES PTE LTD]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/12/18 20:48	Chassis Number	 Load JPG	☒
2	17/12/18 20:48	Odometer Reading	 Load JPG	☒
3	17/12/18 20:49	General View	 Load JPG	☒
4	17/12/18 20:49	General View	 Load JPG	☒
5	17/12/18 20:49	General View	 Load JPG	☒
6	17/12/18 20:49	General View	 Load JPG	☒
7	17/12/18 20:49	General View	 Load JPG	☒
8	17/12/18 20:49	General View	 Load JPG	☒
9	17/12/18 20:49	General View	 Load JPG	☒
10	17/12/18 20:49	General View	 Load JPG	☒
11	17/12/18 20:49	General View	 Load JPG	☒
12	17/12/18 20:49	General View	 Load JPG	☒
13	17/12/18 20:49	General View	 Load JPG	☒
14	17/12/18 20:49	General View	 Load JPG	☒
15	17/12/18 20:49	General View	 Load JPG	☒
16	17/12/18 20:49	General View	 Load JPG	☒
17	17/12/18 20:49	General View	 Load JPG	☒
18	17/12/18 20:49	General View	 Load JPG	☒
19	17/12/18 20:49	General View	 Load JPG	☒
20	17/12/18 20:49	General View	 Load JPG	☒
21	17/12/18 20:49	General View	 Load JPG	☒
22	17/12/18 20:49	General View	 Load JPG	☒
23	17/12/18 20:49	General View	 Load JPG	☒
24	17/12/18 20:49	General View	 Load JPG	☒
25	17/12/18 20:49	General View	 Load JPG	☒
26	17/12/18 20:49	General View	 Load JPG	☒
27	17/12/18 20:49	General View	 Load JPG	☒
28	17/12/18 20:49	General View	 Load JPG	☒
29	17/12/18 20:49	General View	 Load JPG	☒
30	17/12/18 20:49	General View	 Load JPG	☒
31	17/12/18 20:49	General View	 Load JPG	☒
32	17/12/18 20:49	General View	 Load JPG	☒
33	17/12/18 20:49	General View	 Load JPG	☒
34	17/12/18 20:49	General View	 Load JPG	☒
35	17/12/18 20:49	General View	 Load JPG	☒
36	17/12/18 20:49	General View	 Load JPG	☒
37	17/12/18 20:49	General View	 Load JPG	☒
38	17/12/18 20:49	General View	 Load JPG	☒
39	17/12/18 20:49	General View	 Load JPG	☒
40	17/12/18 20:49	General View	 Load JPG	☒

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	17/12/18 20:49	General View	 Load JPG	☒
42	17/12/18 20:49	General View	 Load JPG	☒
43	17/12/18 20:49	General View	 Load JPG	☒
44	17/12/18 20:49	General View	 Load JPG	☒
45	17/12/18 20:49	General View	 Load JPG	☒
46	17/12/18 20:49	General View	 Load JPG	☒
47	17/12/18 20:49	General View	 Load JPG	☒
48	17/12/18 20:49	General View	 Load JPG	☒
49	17/12/18 20:49	General View	 Load JPG	☒
50	17/12/18 20:49	General View	 Load JPG	☒
51	17/12/18 20:49	General View	 Load JPG	☒
52	17/12/18 20:49	General View	 Load JPG	☒
53	17/12/18 20:49	General View	 Load JPG	☒
54	17/12/18 20:49	General View	 Load JPG	☒
55	17/12/18 20:49	General View	 Load JPG	☒
56	17/12/18 20:49	General View	 Load JPG	☒
57	17/12/18 20:49	General View	 Load JPG	☒
58	17/12/18 20:49	General View	 Load JPG	☒
59	17/12/18 20:49	General View	 Load JPG	☒
60	17/12/18 20:49	General View	 Load JPG	☒
61	17/12/18 20:49	General View	 Load JPG	☒
62	17/12/18 20:49	General View	 Load JPG	☒
63	17/12/18 20:49	General View	 Load JPG	☒
64	17/12/18 20:49	General View	 Load JPG	☒
65	17/12/18 20:49	General View	 Load JPG	☒
66	17/12/18 20:49	General View	 Load JPG	☒
67	17/12/18 20:49	General View	 Load JPG	☒
68	17/12/18 20:49	General View	 Load JPG	☒
69	17/12/18 20:49	General View	 Load JPG	☒
70	17/12/18 20:49	General View	 Load JPG	☒
71	17/12/18 20:49	General View	 Load JPG	☒
72	17/12/18 20:49	General View	 Load JPG	☒
73	17/12/18 20:49	General View	 Load JPG	☒
74	17/12/18 20:49	General View	 Load JPG	☒
75	17/12/18 20:49	General View	 Load JPG	☒
76	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
77	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
78	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
79	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
80	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
81	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
82	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
83	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
84	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
85	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
86	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
87	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
88	21/12/18 12:44	Reinspection Photo	Load JPG	☒
89	21/12/18 12:44	Reinspection Photo	Load JPG	☒
90	21/12/18 12:44	Reinspection Photo	Load JPG	☒
91	21/12/18 12:44	Reinspection Photo	Load JPG	☒
92	21/12/18 12:44	Reinspection Photo	Load JPG	☒
93	21/12/18 12:44	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
94	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
95	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
96	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
97	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
98	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
99	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
100	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
101	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
102	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
103	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
104	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
105	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
106	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
107	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
108	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
109	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
110	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
111	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
112	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
113	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
114	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
115	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
116	21/12/18 12:44	Reinspection Photo	 Load JPG	☒
117	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
118	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
119	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
120	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
121	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
122	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
123	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
124	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
125	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
126	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
127	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
128	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
129	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
130	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
131	02/01/19 17:34	Reinspection Photo	 Load JPG	☒
132	03/01/19 18:20	Reinspection Photo	 Load JPG	☒
133	03/01/19 18:20	Reinspection Photo	 Load JPG	☒
134	03/01/19 18:20	Reinspection Photo	 Load JPG	☒
135	03/01/19 18:20	Reinspection Photo	 Load JPG	☒
136	03/01/19 18:20	Reinspection Photo	 Load JPG	☒
137	03/01/19 18:20	Reinspection Photo	 Load JPG	☒
138	03/01/19 18:20	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/12/18 14:56	TP GIA REPORT	 Load PDF	
2	17/12/18 14:57	GIA Search	 Load PDF	
3	03/12/19 11:08	EMAIL	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/12/18 09:45	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18022573/UDA3S2

Date: 03/12/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100439985
Claimant Vehicle No :	GBD4470E	Insured Vehicle No :	GBE4165G
Date of Loss:	12/12/2018	Nature of Claim:	TP
		Claim No:	7914357472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD4470E		
Make & Model:	FIAT DOBLO, 1.6 D CARGO MJ (M)	Engine No:	198A30006992755
Reg. Date:	28/10/2014 (Man. Year: 2013)	Chassis No:	ZFA26300006107510
Colour:	White	Odometer:	73326 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R16C	Rear Tyre Size:	195/60 R16C
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,078.35	22,291.71	13,786.64	38.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,070.00	3,925.00	2,145.00	35.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,148.35	26,216.71	15,931.64	37.80
Approved Total (Overridden) (S\$)		18,500.00		
(S\$)	42,148.35	18,500.00	23,648.35	56.11
+ GST 7.00/7.00% (S\$)	2,950.38	1,295.00	1,655.38	56.11
Nett Amount (S\$)	45,098.73	19,795.00	25,303.73	56.11

INSPECTION

Date of Assignment:	17/12/2018	
Date Inspected:	17/12/2018 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	15.0 days	

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Dented / Bent	2,159.20 F	*2,159.20 FL
2	1		*FRONT LH DOOR OUTER PROTECTOR	Necessary	320.00 F	*320.00 FL
3	1		*FRONT LH DOOR VIEW MIRROR	Cracked	701.50 F	*701.50 FL
4	1		*FRONT LH DOOR VIEW MIRROR SIGNAL LAMP	Cracked	289.00 F	*289.00 FL
5	1		*FRONT LH DOOR OUTER PILLAR	Repair	989.50 F	*- FL
6	1		*FRONT LH DOOR INNER RUBBER	Not Necessary	385.40 F	*- FL
7	1		*FRONT LH DOOR INNER TRIM BOARD	Not Necessary	420.00 F	*- FL
8	1		*FRONT LH BUMPER	Distorted	1,245.50 F	*1,245.50 FL
9	1		*FRONT LH BUMPER SIDE HOLDER	Bent	68.00 F	*68.00 FL
10	1		*FRONT LH FENDER	Bent / Buckled	1,277.50 F	*1,277.50 FL
11	1		*FRONT LH FENDER INNER SHIELD	Distorted	316.00 F	*316.00 FL
12	1		*FRONT LH FENDER INNER PANEL	Repair	672.00 F	*- FL
13	1		*FRONT LH SHOCK ABSORBER	Bent	490.00 F	*490.00 FL
14	1		*FRONT LH LOWER ARM	Necessary	390.00 F	*390.00 FL
15	1		*FRONT LH KNUCKLE ARM	Bent	684.00 F	*684.00 FL
16	1		*FRONT LH KNUCKLE ARM BEARING	Necessary	215.00 F	*215.00 FL
17	1		*FRONT LH WHEEL HUB BEARING	Repeated	486.30 F	*- FL
18	1		*FRONT LH DRIVE SHAFT	Not Necessary	980.00 F	*- FL
19	1		*FRONT LH HEAD LAMP	Cracked	862.40 F	*862.40 FL
20	1		*FRONT LH CORPORATE DETAIL ADVERTISEMENT & ARTWORK	Necessary	880.00 FS	*500.00 FS
21	2		*FRONT LH DOOR HINGES	Not Necessary	520.00 FS	*- FS
22	1		*FRONT LH DOOR LTA CORPORATE DETAIL STICKER	Not fitted	48.00 FS	*- FS
23	1		*SET FRONT LH BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	65.00 FS	*65.00 FS
25	1		*FRONT LH WHEEL HUB CAB	Cut	225.00 FS	*150.00 FS
26	1		*FRONT LH STEEL WHEEL	Dented	280.00 FS	*50.00 FS
27	1		*FRONT BONNET	Buckled	1,170.00 F	*1,170.00 FL
28	2		*FRONT BONNET HINGES	Not Necessary	270.00 F	*- FL
29	1		*FRONT INNER LOCK	Twisted	138.00 F	*138.00 FL
30	1		*FRONT BUMPER LOWER CENTRE GRILLE	Torn	288.60 F	*288.60 FL
31	1		*FRONT BUMPER TOP GRILLE	Not Necessary	128.50 F	*- FL
32	1		*FRONT BUMPER LOGO	Necessary	139.70 F	*139.70 FL
33	1		*FRONT BUMPER SIDE HOLDER RH	Bent	60.60 F	*60.60 FL
34	1		*FRONT BUMPER SPONGE	Torn	117.60 F	*117.60 FL
35	1		*FRONT BUMPER REINFORCEMENT	Bent	724.70 F	*724.70 FL
36	1		*FRONT BUMPER TOWING COVER	Torn	60.00 F	*60.00 FL
37	1		*FRONT AIRCON CONDENSER	Bent / Punctured	1,278.00 F	*1,278.00 FL
38	1		*FRONT INTER COOLER	Punctured	3,640.00 F	*3,640.00 FL
39	1		*FRONT INNER COOLER GARNISH	Dented	157.00 F	*157.00 FL
40	1		*FRONT RADIATOR	Cracked	754.30 F	*754.30 FL
41	1		*FRONT RADIATOR FAN ASSY	Crumpled	378.00 F	*378.00 FL
42	1		*FRONT SUPPORT PANEL	Bent	745.20 F	*745.20 FL
43	1		*FRONT FENDER O/S	Bent	1,277.80 F	*1,277.80 FL
44	1		*FRONT POWER STEERING PUMP	Bent / Jammed	572.60 F	*572.60 FL
45	1		*FRONT AIRCON COMPRESSOR	Cracked / Jammed	1,160.00 F	*1,160.00 FL
46	1		*FRONT TURBO CHARGE	Serviceable	4,856.30 F	*- FL
47	1		*FRONT FUEL PUMP	Cracked	580.00 F	*580.00 FL
48	1		*FRONT CHASSIS MEMBER	Repair	720.00 F	*- FL
49	1		*FRONT AIR DUCT	Dented	177.35 F	*177.35 FL
50	1		*FRONT HEAD LAMP O/S	Cracked	658.80 F	*658.80 FL
51	1		*SET FRONT BONNET CORPORATE ADVERTISEMENT & ARTWORK	Necessary	300.00 FS	*300.00 FS
52	1		*SET FRONT INNER COOLER CLIP	Not Necessary	28.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*SET FRONT FENDER CORPORATE ADVERTISEMENT & ARTWORK	Necessary	580.00 FS	*300.00 FS
54	1		*FRONT NUMBER PLATE & BASE	Broken	48.00 FS	*40.00 FS
55	1		*FRONT RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	36,078.35	24,601.35
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	2,309.64
Total Parts (S\$)	36,078.35	22,291.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FR LH ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.	New	30.00	15.00
2	TO APPLY RUST-PROOFING, RESEAL TUFF-COATING TREATMENT ON FR LH ACCIDENT AREA.	New	80.00	50.00
3	TO CHECK AND RE-ADJUST FR LH WHEEL ALIGNMENT.	New	120.00	80.00
4	TO DISMANTLE & REPLACING FR LH UNDERCARRIAGE PARTS & COMPONENTS.	New	150.00	120.00
5	TO REMOVE, REPLACE AND TRANSFER FR LH DOOR PANEL, FITTING AND MECHANISMS.	New	80.00	60.00
6	LABOR FOR FR LH PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC.	New	800.00	500.00
7	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON FR LH ACCIDENT AFFECTED AREA.	New	1,000.00	700.00
8	TO CHECK FRONT ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.	New	30.00	20.00
9	TO REMOVE & REFIX FRONT AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES.	New	120.00	100.00
10	REMOVE & INSTALL FRONT ENGINE TO FACILITATE CHASSIS REALIGNMENT.	New	380.00	250.00
11	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON FRONT ACCIDENT AREA.	New	100.00	80.00
12	TO CHECK AND REINSTALL FRONT TURBO.	New	100.00	50.00
13	TO MOUNT VEHICLE ONTO FRONT CHASSIS ALIGNMENT BENCH & TO CONDUCT ALIGNMENT.	New	380.00	0.00
14	LABOR FOR FRONT PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC.	New	1,500.00	1,000.00
15	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON FRONT ACCIDENT AFFECTED AREA.	New	1,200.00	900.00
Gross Labour Cost (\$\$)			6,070.00	3,925.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >