

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2004241

INV Date 02/06/2020

Reference CC6/CTI18022587/Uea3q2

Code

### **PROFESSIONAL SERVICE FEE**

Vehicle No. SJJ 2749P

Insured Veh. GBA 9577P

Claim No. SNM18D05801C02/7

Policy No. DMCVSN1810381800

Accident Date 14/12/2018

Inspection Date 17/12/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

		Affiliated to Federation Internationale Des Experts En Automobile						
CHIN	CHINA TAIPING INSURANCE (S) PTE LTD Ref : CC6/CTI18022587/Uea3q2							
	SON ROAD #16-0 NGLEAF TOWER	0 SINGAPORE 079909	Date: 02-06-2020 Code: CTI					
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	GBA 9577P	Veh. Inspected	SJJ 2749P				
	Policy No.	DMCVSN1810381800	Coverage (\$)	0.00				
	Claim No.	SNM18D05801C02/7	Excess (\$)	0.00				
	Assign From		Assign Date	17/12/2018				
2.		Vehicle Partic	culars & Condition					
	Make & Model	HONDA STREAM (A)	c.c	1799				
	Engine No.	HIDDEN	Year of Reg.	2008				
	Chassis No.	JHMRN68408S204301	Colour	BLUE				
	Odometer	168817	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	SPORTS RIM				
	General	GOOD						
3.		Conditi	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	215/60 R16	HIFLY	6 mm				
	L/H Front Tyre	215/60 R16	HIFLY	6 mm				
	R/H Rear Tyre	215/60 R16	HIFLY	6 mm				
	L/H Rear Tyre	215/60 R16	HIFLY	6 mm				
4.	1	•	on of Damages					
	THE VEHICLE SUS COLLISION.	STAINED DAMAGES AT THE N/S	BODY.THE UNDERCARRIA	AGE AFFECTED DUE TO				
	DAMAGES SEE DI	ETAILS.						
5.	1		I Information					
	Accident Date	14/12/2018	Inspection Date	17/12/2018				
	Survey held at	FASTECH AUTO PTE LTD						
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Days					



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 2749P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR N/S	DENTED / BENT	1,255.10	960.70
1	FRONT DOOR OUTER HANDLE N/S	TWISTED / JAMMED	305.90	266.50
1	FRONT DOOR GLASS OUTER MOULDING N/S	BENT / NECESSARY	188.50	142.30
1	FRONT DOOR INNER LOCK N/S	TWISTED / SHORTED	399.20	399.20
1	FRONT DOOR INNER TRIM BOARD N/S	DEFORMED / CRACKED	845.20	545.10
1	SET FRONT DOOR INNER TRIM BOARD CLIPS N/S	NECESSARY	35.00	35.00
1	FRONT DOOR GLASS REGULATOR N/S	BENT	215.00	215.00
1	FRONT DOOR GLASS REGULATOR MOTOR N/S	JAMMED	450.00	425.30
1	FRONT DOOR MIRROR N/S	NOT NECESSARY	650.00	-
1	SET FRONT DOOR FRAME BLACK STICKER N/S	NECESSARY	100.00	65.00
1	CENTRE PILLAR N/S	TO REPAIR SEE LABOUR	689.10	-
1	REAR DOOR N/S	DENTED / BENT	1,150.10	896.20
1	REAR DOOR GLASS OUTER MOULDING N/S	NECESSARY	188.50	142.30
1	REAR DOOR INNER LOCK N/S	NOT NECESSARY	399.20	-
1	REAR DOOR INNER TRIM BOARD N/S	DENTED / CRACKED	845.20	522.10
1	SET REAR DOOR INNER TRIM BOARD CLIPS N/S	NECESSARY	35.00	35.00
1	REAR DOOR GLASS REGULATOR N/S	NOT NECESSARY	208.00	-
1	REAR DOOR GLASS REGULATOR MOTOR N/S	NOT NECESSARY	420.00	-
1	SET REAR DOOR FRAME BLACK STICKER N/S	NECESSARY	100.00	65.00
1	REAR FENDER N/S	BADLY DENTED	1,148.20	925.10
1	REAR FENDER INNER TRIM BOARD	NOT NECESSARY	392.50	-
1	REAR SHOCK ABSORBER N/S	NOT NECESSARY	425.00	-
1	REAR WHEEL HUB N/S	BENT	615.00	615.00
1	REAR WHEEL HUB BEARING N/S	DAMAGED	388.00	299.00
1	REAR AXLE BEAM	NOT NECESSARY	1,922.30	-
1	REAR BUMPER	CUT / TORN	654.00	654.00
1	REAR BUMPER SIDE HOLDER N/S	BENT	39.00	39.00

Report Ref No. CC6/CTI18022587/Uea3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

7,000.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	35.00
1	ROCKER PANEL N/S	TO REPAIR SEE LABOUR	688.10	-
	LESS 20% DISCOUNT		-	-1,456.36
			14,786.10	5,825.44
	SPECIAL NETT ITEMS			
1	REAR SPORT RIM N/S (SN)	CUT	650.00	400.00
1	REAR FENDER GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
			700.00	440.00
	LABOUR			
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE.		380.00	120.00
	TO DISMANTLE & REFIX PETROL TANK.		80.00	60.00
	TO DISMANTLE & REFIX REAR FENDER GLASS N/S.		120.00	100.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO TRANSFER BOTH N/S DOOR COMPONENTS.		180.00	120.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO SPRAY RUST PROOFING.		150.00	90.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF CENTRE PILLAR N/S AND ROCKER PANEL N/S.		1,280.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,100.00
			4,470.00	2,600.00
	GRAND TOTAL		19,956.10	8,865.44

Report Ref No. CC6/CTI18022587/Uea3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

CHUA KANG SENG

Licensed Appraiser




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SJJ 2749P

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SJJ 2749P



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SJJ 2749P

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315





