MOVA AUTOMOTIVE PTE LTD

MOVA BUILDING 22 JALAN KILANG SINGAPORE 159419

Claim Reference:

Assessment Number: CK133506

Version: MOVAAUTO/1

Date Calculated: 13/12/2018 08:52

Full Report - V1 Registration: SJW1686A

Printed: 13/12/2018 16:52

SGD

TBA

Summary Information

Claim

Location:

Printed by:

Work Provider:

Authorisation Status:

Interim

Ltd

Claim Reference: Policy Number: Other Reference:

Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

CAREN TEOH

AXA Insurance S'pore Pte Repairs Authorised:

TP

True

Currency:

Date of Incident:

Able to Authorise Repairs: TBA

Estimated Repair Time:

Ouote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Model Specs

FROM VIN 309022

ILLUMINATED MIRROR

REAR HEADPHONES

HEADLAMP WASHERS

REAR CENTRE ARMREST

ELEC DRIVER SEAT MEM

KEYLESS ENTRY

TRIM CHROME

RAIN SENSOR

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model: Model Sheet Number: Registration:

Registration Month:

Registration Year:

VIN Number: Odometer:

Colour:

Engine Number: Fuel Level:

VOLVO

XC60 BASE MODEL

K50 01 SJW1686A

PNVDZ475BC5333141

%

Not Known

DIP REAR VIEW MIRROR ULTRASONIC PARK SYS FRONT DRIVE

PWR STRG SPEED CONT RR DUAL EXHAUST PIPE TYRES 235/60 VR 18

RR B/DISC VENTILATED **AUTOMATIC TAILGATE**

AUTO AIR CON

ELEC CHILD LOCKING FOLDING DOOR MIRRORS ADAPT XENON HEADLAMP TRIM PARTIAL LEATHER NAVIGATION SYSTEM

WOOD TRIM

W/FRAME CHROMED MLDG ANTI THEFT ALARM RR INTEG CHILD SEAT 2.0 LTR 177KW

6-SPEED AUTOMATIC ELECT PARKING BRAKE COLLISION WARN SYS WHEELS 7.5J X 18 ALU ROOF RACK ALU TWO COAT METALLIC

Vehicle Condition

Vehicle Status

Pre-Accident Condition: Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR: Damage Areas:

Severity of Impact: Vehicle Status on Inspection:

Date of Inspection:

13/12/2018

Tread Depth RHF:

Tread Depth RHR: Direction of Impact:

MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK133506


Version: MOVAAUTO/1


Date Calculated: 13/12/2018 08:52

Full Report - V1

Registration: SJW1686A

Printed: 13/12/2018 16:52





Addresses

Cost Summary

Total Labour	\$432.00
Total Paint/Material	\$101.32
Total Parts	\$4,795.50
Excess:	TBA
Grand Total Exc GST:	\$5,328.82
7 % GST:	\$373.02
Grand Total Inc GST:	\$5.701.84

Repair Information

LABOUR

Time Basis	10	WU	=	1	HR.	Price/	CL	1	=	\$45.00/HR
						Price/D	Der	١t	=	\$45.00/HR

Repair /			
Guide Numbe	er Repair Details	WU	Cost Price (\$)
86101-2	R + R REAR BUMPER CPL	5.0	22.50
NO NUMBER	R + R REAR BUMPER PROTECTION	4.0	18.00
86131-3	R + R L/R INNER BUMPER CARRIER	3.0	13.50
86131-3	R + R R/R INNER BUMPER CARRIER	3.0	13.50
86112-3	R + R BUMPER ABSORBER	1.0	4.50
84543-2	R + R REAR END PANEL TRIM	3.0	13.50
36701-3	R + R L/R PARKING SYSTEM SENSOR	1.0	4.50
36700-2)	ADD/WORK FOR PARKING SYSTEM	1.0	4.50
36700-2)	R + R PARKING SYSTEM SENSOR	2.0	9.00
82652-2)	R + R L/REAR INNER WING	2.0	9.00
82652-2)	R + R R/REAR INNER WING	2.0	9.00
25210-2	R + R REAR SILENCER	3.0	13.50
NO NUMBER	R + R HEAT PROTECTIVE PANEL	1.0	4.50
77061-2	R + R LEFT REAR WHEEL	1.0	4.50
77061-2	R + R RIGHT REAR WHEEL	1.0	4.50
2581	REPAIR REAR BUMPER	15.0*	67.50
2668	CHECK R/R PARK SYS SENSOR		
2731	CHECK REAR BUMPER SUPPORT		
LA	BOUR COST		
	Total Work Units	48.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	4.8HRS	\$216.00
	Paint Labour	4.8HRS	\$216.00
	Total Labour	9.6HRS	\$432.00

PAINT WORK Guide Number Description Time Basis 10 WU = 1 HR. Price = \$45.00/HR
WU Cost Price (\$)

MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK133506

Version: MOVAAUTO/1

Date Calculated: 13/12/2018 08:52

	- TWO COAT METALLIC		
2581	REAR BUMPER REPAIR PAINT PLASTIC	14.0	
2614	REAR BUMPER COVER SURFACE PAINT PLAST.	3.0	
2931	BOOTLID/TAILGATE SURFACE PAINT PLAST.	10.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	27.0	
	Preparation Main Work Plastic	21.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	48.0	
	Total Paintwork Labour	4.8HRS	\$216.00
	MATERIAL COST - PAINT		Cost Price
	Surface Paint Plastic		\$47.58
	Repair Painting Plastic		\$35.64
	Material-Const Main Work Plastic		\$18.10
	Total Excluding Pearlescent Uplift		\$101.32
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$101.32

					Price Va	lid: 01/01/2001
Guide No.	.Qty	Description 7	Part Number	Supplier	Bet.	Price (\$)
2640	1	CTR RR BUMPER REINF	30763441		0%	1,380.00*
2641	1	L/R INN BUMPER BRKT	31214458		0%	85.00*
2617	1	L/R OUT BUMPER BRKT .	30763437		0%	90.00*
2667	1	L/R PARK SYS SENSOR 1 /	31445162		0%	185.00*
2642	1	R/R INN BUMPER BRKT	31214458		0%	85.00*
2618	1	R/R OUT BUMPER BRKT 7	30763438		0%	90.00*
8830	1	REAR HEAT SHIELD 14/	31353531		0%	550.00*
8833	1	REAR SILENCER 7	31355821		0%	905.00*
2606	1	REAR SPOILER SU	31294291		0%	455.00*
2650	1	RR BUMPER CLAMP KIT	USE SINGLE PARTS	5	0%	120.00*
2610	1	RR BUMPER CTR COVERSUL	30764525		0%	225.00*
f: OEM Par	rts		Sub Total			\$4,170.00
g: Original			Mark Up Fro	m Cost	(15 %)	\$625.50
h: Second			Total Parts			\$4,795.50
p: Parallel						

x: Exchange

PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

Final Calculation		
Total Parts	\$4,795.5	0
Labour		
Total Panel/Mechanical	\$216.00	
Total Paintwork	\$216.00	
Total Labour	\$432.0	00
Total Paint/Material Costs	\$101.3	32
Grand Total Excludes GST	\$5,328.8	32
GST @ 7 %	\$373.0)2
Grand Total Includes GST	\$5,701.8	34

Assessment Notes

Grand Total Includes GST

\$0.00

Full Report - V1

Registration: SJW1686A

Printed: 13/12/2018 16:52

MOVA AUTOMOTIVE PTE LTD

Claim Reference:

Assessment Number: CK133506

Version: MOVAAUTO/1

Date Calculated: 13/12/2018 08:52

Full Report - V1

Registration: SJW1686A

Printed: 13/12/2018 16:52

Rem alter sport

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before after spray painting

To display damaged part(s) during resurvey

- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: