12/26/2018 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18022613/K1VBS2

619861 km

Date: 26/12/2018

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MJ001357

Claimant Vehicle CHOOSE

No: SHC8208E Insured Vehicle No: SMF9128X

Date of Loss: 15/12/2018 Nature of Claim: TP Claim No: M1806440

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC8208E

 Make & Model:
 MERCEDES-BENZ E220, 2.1 D CDI (W211) (A)
 Engine No:
 65192432757075

 Reg. Date:
 13/05/2015 (Man. Year: 2015)
 Chassis No:
 WDD2120012B171201

Colour: White Odometer:

Engine Capacity: 2143 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 225/55R16 Rear Tyre Size: 225/55R16
Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm
Front Right Side: West Lake 7 mm
West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,282.00	1,258.00	24.00	1.87
Miscellaneous Items		10.00	10.00	0.00	0.00
Labour		850.00	430.00	420.00	49.41
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,142.00	1,698.00	444.00	20.73
	Approved Total (Overridden) (S\$)		1,350.00		
	(S\$)	2,142.00	1,350.00	792.00	36.97
	+ GST 7.00/7.00% (S\$)	149.94	94.50	55.44	36.97
	Nett Amount (S\$)	2,291.94	1,444.50	847.44	36.97

INSPECTION

Date of Assignment: 18/12/2018 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 17/12/2018 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2018)

Parts: 143 MERCEDES-BENZ E220 2.1 D CDI (W211) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC8208E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR BUMPER COVER	Deformed	1,510.00 FL	*1,510.00 FL
1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
1		*WIRING	Not Necessary	30.00 FL	*- FL
ınchise	part. S=SpcNe	tt. L=ListItemDisc.			
			Sub Total (S\$)	1,590.00	1,560.00
		- List Item Discount o	on L Items 20.00/20.00% (S\$)	308.00	302.00
			Total Parts (S\$)	1,282.00	1,258.00
	1 1 1	1 1 1 nnchise part. S=SpcNe	1 *REAR BUMPER COVER 1 *REAR BUMPER RUBBER MAT 1 *WIRING Inchise part. S=SpcNett. L=ListItemDisc.	1 *REAR BUMPER COVER Deformed 1 *REAR BUMPER RUBBER MAT Necessary 1 *WIRING Not Necessary Inchise part. S=SpcNett. L=ListItemDisc. Sub Total (\$\$) - List Item Discount on L Items 20.00/20.00% (\$\$)	1 *REAR BUMPER COVER Deformed 1,510.00 FL 1 *REAR BUMPER RUBBER MAT Necessary 50.00 FS 1 *WIRING Not Necessary 30.00 FL Inchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 1,590.00 - List Item Discount on L Items 20.00/20.00% (S\$) 308.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		10.00	10.00
	Sub Total (S\$)	10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	300.00	200.00
3	WIRING	New	30.00	-
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
		Gross Labour Cost (S\$)	850.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >