

REPAIR ESTIMATE*

DATE : 13.12.2018

TEL : 6542 5119

FAX : 6542 6039

AIG/~~NTUC~~

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>cut</i>			\$ 1,052.20 ✓
	Front Bumper Sponge <i>NH</i>			\$ 99.20 X
	Front Bumper Reinforcement <i>NH photo taken</i>			\$ 402.10 X
	Front Bumper Bracket (RH) <i>src</i>			\$ 24.60 X
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40 ✓
	Headlamp (RH) <i>mounting broken</i>			\$ 1,388.00 ✓
	Front Fender (RH) <i>src</i>			\$ 566.30 ✓
	Front Fender Apron Panel (RH) <i>Replaced NH Replaced</i>			\$ 637.00 X ✓
	Front Fender Shield (RH) <i>deformed</i>			\$ 174.90 ✓
	Front Door (RH) <i>vt</i>			\$ 2,256.40 ✓
	Front Windscreen Pillar Outer(RH) <i>Replaced</i>			\$ 1,745.50 ✓
	Front Windscreen Moulding <i>NH</i>			\$ 113.30 ✓
	Wiper Container <i>deformed</i>			\$ 61.90 ✓
	Wiper Container Motor <i>src</i>			\$ 75.00 X
	Front Wheel Rim (RH) <i>2 distorted</i>			\$ 325.30 2 ✓
	Front Wheel Hub Cap (RH) <i>cut</i>			\$ 107.10 ✓
	Front Wheel Bearing <i>2 Down</i>			\$ 540.50 2 ✓
	Front Shock Absorber (Assy) (RH) <i>2 distorted</i>			\$ 342.20 2 ✓
	Front Shock Absorber Mounting (RH) <i>NH</i>			\$ 108.80 X
	Front Drive Shaft (RH) <i>2 Down</i>			\$ 1,030.80 2 ✓
	Rack & Pinion Assy <i>2 Down</i>			\$ 969.60 2 ✓
	STG Tie End <i>2 distorted</i>			\$ 62.60 2 ✓
	Front Suspension Lower Arm (RH) <i>2 distorted</i>			\$ 529.30 2 ✓
	Knuckle Arm (RH) <i>2 distorted</i>			\$ 552.00 2 ✓
	Engine Under Cover <i>NH</i>			\$ 334.60 X
	Engine Crossmember <i>2 distorted</i>			\$ 2,094.40 2 ✓
	ABS Sensor,RH <i>NH</i>			\$ 234.00 X
	Electric Power Steering <i>NH</i>			\$ 4,880.50 X
	SUB TOTAL			\$ 21,615.50
	LESS 20%			\$ 4,323.10
	DISCOUNTED TOTAL			\$ 17,292.40
	Front Fender Advertisement Logo (RH) <i>NH</i>			\$ 100.00 Nett ✓
	Front Door Comfort Logo (RH) <i>NH</i>			\$ 75.00 Nett ✓
	Front Door Advertisement Logo (RH) <i>NH</i>			\$ 100.00 Nett ✓
	Front Tyre (RH) <i>punctured / cut 50% depreciation</i>			\$ 216.00 Nett ✓
	Front Windscreen Sealant <i>NH</i>			\$ 46.00 Nett ✓
				\$ 537.00

SHA 7998A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00
	Spray Painting Charge			\$ 1,250.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Transfer of Door			\$ 120.00
	Remove/Refix Undercarriage (FRT)			\$ 200.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Remove/Refix Dashboard			\$ 450.00
	Remove/Refix Front Windscreen Glass			\$ 120.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
	Re-set FRT ABS System			\$ 200.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
		</		

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 7998 A

Technician:

Mileage: 405535

Time Printed 14.12.18 2:06 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
1°46'		-3°00' 3°00'
3°53'		-0°19' 5°41'
0°02'		-1°30' 1°30'
16°49'		
18°35'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
3°10'		-3°00' 3°00'
3°53'		-0°19' 5°41'
6°08'		-1°30' 1°30'
10°22'		
13°32'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-1°24'		-3°00' 3°00'
0°00'		-3°00' 3°00'
6°27'		-3°00' 3°00'
6°10'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-2°30'		-3°30' 2°30'
-0°14'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°32'		-3°30' 2°30'
0°20'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°58'		-3°00' 3°00'
0°06'		-3°00' 3°00'
-0°17'		-3°00' 3°00'