



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 3958T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RR SILENCER CLAMPING BUSH (SN)	BENT	60.60	60.60
2	RR SILENCER CLAMPING BUSH (SN)	NOT NECESSARY	121.20	-
2	RUBBER MOUNTING (SN)	NOT NECESSARY	34.00	-
1	BRACKET FOR RR SILENCER LH (SN)	BENT	57.20	57.20
1	BRACKET RR MUFFLER RH (SN)	NOT NECESSARY	57.20	-
1	TAILPIPE TRIM CHROME (SN)	CUT	118.65	118.65
1	FRONT PIPE - EXHAUST (SN)	NOT NECESSARY	505.00	-
1	REAR MUFFLER (SN)	BENT	1,017.40	1,017.40
1	CENTRE MUFFLER (SN)	NOT NECESSARY	811.25	-
1	RR BUMPER BOTTOM REINFORCEMENT (SN)	CRACKED	69.80	69.80
1	REAR BUMPER CENTRE GUIDE (SN)	CRACKED	32.90	32.90
1	REAR BUMPER CARRIER (ECE) (SN)	BENT	467.95	467.95
1	REAR DECORATIVE STRIP (SPORT LINE) (SN)	NOT NECESSARY	57.00	-
1	REAR BUMPER PANEL PRIMED BASIS (SN)	TORN	1,172.30	1,172.30
1	RR BUMPER FLAP TOWING EYE PRIMED (SN)	NOT NECESSARY	43.25	-
1	SET REAR PDC HOLDER (SN)	NECESSARY	24.60	24.60
1	REAR BUMPER LH SIDE GUIDE (SN)	DEFORMED	58.50	58.50
1	REAR BUMPER RH SIDE GUIDE (SN)	NOT NECESSARY	58.50	-
1	(S/L) LH PROTECTION FOIL (SN)	NOT NECESSARY	7.90	-
1	(S/L) RH PROTECTION FOIL (SN)	NOT NECESSARY	7.90	-
1	LETTERING 320I (SN)	NOT NECESSARY	64.10	-
2	GROMMET (SN)	NOT NECESSARY	1.50	-
1	PLAQUE 74MM (SN)	NOT NECESSARY	71.25	-
1	LOADING SILL COVER (SN)	NOT NECESSARY	85.05	-
1	RR BUMPER LH REFLECTOR (SN)	CRACKED	36.80	36.80
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	UNDERBODY PANELLING REAR LH (SN) (ADDITIONAL)	CRACKED	38.40	38.40
6	PLUG BLACK D=5MM (SN) (ADDITIONAL)	NECESSARY	5.40	5.40
1	SENSOR WIRE FOR SMART OPENER TOP (SN) (ADDITIONAL)	NECESSARY	43.15	43.15

Report Ref No. CS/FCI18022700/Gvbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	(DG/SL) ADHESIVE SET K6 (SN) (ADDITIONAL) <u>LABOUR</u> REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE REPAIR ON ACCIDENT AREA. SPRAY PAINTING REAR BUMPER AND REAR BOOT LID. TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS. TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION. TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK. TO DIAGNOSE AND REPLACE TOP SENSOR WIRE FOR SMART OPENER INCLUDE PROGRAMMING AND CONDUCTING TESTS FOR PROPER FUNCTION. (ADDITIONAL)	NECESSARY	53.05	53.05
			5,331.80	3,336.70
		NOT NECESSARY	2,550.00	850.00
			1,923.00	1,038.00
			271.00	-
			177.00	159.00
			531.00	478.00
			150.00	150.00
	5,602.00	2,675.00		
GRAND TOTAL			10,933.80	6,011.70
RECOMMENDED COST OF REPAIRS				6,011.70

Report Ref No. CS/FCI18022700/Gvbs2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.