

22/03/2002

ASS. REC. BY:

REF:

CS/CTU8022715/Ksbe2

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTL

Date/Time: 18/22018 434pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKM 4243R

Insured:

SJZ 132Y

at Workshop m/s

Esteem Performance

Tel:

of

5033 Amk Ind Park 2 # 01-259

Policy No:

DMPCSN3091331700

Claim No:

SNM18D05825C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14.122018

CA / REV / REP. / REV 24 HRS Wpn

H.O.D. Endorsement:

Date/Time:

18/22018 508pm

Person Contacted:

Jenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKM 4243R - NBA / LIP15012014 / Y

D.O.A: 16082015

SJZ 132Y - X

19/12

11 Lm @ 15,000. cash

ASS. REC. BY:

REF: 6721

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

152%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKM 4243 Rr Regn: 02 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer E250

c.c

1991

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

95800

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2120362A 828020

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

3

mm

L/Bal.

5

mm

L/Bal.

3

mm

D.O.A.

14/12/18

D.O.I.

18/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/12

File report Customer

13/02/19

Confirmed L/S \$15,000/- @ 12 days with Kenneth
(\$6,553.70 R/L - 30%)

RECEIVED 18 FEB 2019

Date/Time, File Pass to?

18/02/19



: Prel. Report



: Final Report

1) Type
Date/Time, File Return to?

2)

Days Of Repair:

12

Resurvey No. of Trlp:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

220

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

220

Report Format :

Lump Sum / I.B.I: (\$

15,000/- H/S)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018		18 Dec 2018 16:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	ANG MING SIANG, ID: S1807991G		
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Vehicle Reg. No.:	SKM4243R	Date of Loss:	14/12/2018 15:00 - :59
Claim Type:	TP / SNM18D05825C02	Policy/Cover Note No.:	DMPCSN3091331700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJZ132Y	Policy No. (Claimant):	SD18V00033/VPZ/R03
		Excess:	\$50.00
Repairer:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/12/2018]		
Driver/Custodian (Insured):	ANG MING SIANG (51 / Male), NRIC: S1807991G		
Adj Asg. Remarks:	EST \$4190, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS								View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?		
No results.											

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/12/2018 08:59
Date Of Accident	14/12/2018 15:30
Exact Location Of Accident	PIE BEFORE THOMSON EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM4243R
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	AAABORDIA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90696857
Alternative Phone No	OFFICE-90696857

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250

Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
--	-------------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD18V00033/VPZ/R03
Cover Note Number	

Driver

Name of Driver	BORDIA AABHA
Passport No/FIN	G3157123K
Date Of Birth	30/01/1976
Occupation	INDOOR
Date Of Driving Pass	05/09/2016
Driving Experience	2 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90696857
Fax Number	
Contact Number	
Email Address	AAABORDIA@GMAIL.COM

'Address -
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : AMIT BORDIA (HUSBAND)
 GENDER: : MALE
 Passenger 2 NAME: : SON
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJZ132Y
 Vehicle Make/Model/Colour MERC
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver ANG MING SIANG
 NRIC/Passport Number S1807991G
 Contact Number 82641388
 Address
 Postcode
 Insurance Company Name

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A SKM 4243R
B SJ2 132Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


We were driving on PIE (towards Changi) around 3:30 pm on Dec 14, 2018. The traffic was a bit slow. We were in lane 3. We were moving slowly. Then we had to ~~stop~~ brake because the car in front of us braked. There was enough distance. Suddenly we were hit from behind. The driver at the back did not slow down or brake and so slammed into our car. The front of his car and the back of our car got damaged. This happened before the Thomson exit on PIE. We have taken and passed on all particulars of the driver of the car behind us (black E200 SJ2 132 Y). There was no other passenger in that car. In our car, there were three of us - me, my husband & our son.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SKM 4243 R

Parts	(a) Cost / List Price Items	\$	19,243.00
	Plus/Less 10%	\$	1,924.30
	Total of Cost / List	\$	17,318.70
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	17,363.70
Labour		\$	4,190.00
Total		\$	21,553.70

The above total will be subjected to 7% G.S.T.

Not Authorized
L1/Rup &?
Resurvey After Painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 18/12/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 12 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 18/12/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SKM 4243 R**
Make & Model : **MERC E250**
Chassis No : **WDD2120362A828020**

Submit By : **Carmen Lim**
Year Manufacture : **2013**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>phon</i>	2	\$350.00		✓
2	Rear number plate <i>CM</i>	1	\$45.00	S.N	✓
3	Rear No.plate lamp LH <i>sn</i>	1	\$70.00		X
4	Rear No.plate lamp RH <i>sn</i>	1	\$70.00		X
5	Rear bumper <i>CM</i>	1	\$1,650.00		✓
6	Rear bumper clip <i>me</i>	10	\$50.00		✓
7	Rear bumper side retainer LH <i>sn</i>	1	\$69.00		X
8	Rear bumper side retainer RH <i>sn</i>	1	\$69.00		X
9	Rear bumper bracket LH	1	\$125.00		?
10	Rear bumper bracket RH <i>me</i>	1	\$125.00		✓
11	Rear bumper sponge <i>CRM</i>	1	\$144.00		✓
12	Rear bumper reinforcement <i>me</i>	1	\$590.00		✓
13	Rear bumper chrome moulding LH <i>me</i>	1	\$130.00		✓
14	Rear bumper chrome moulding RH <i>me</i>	1	\$130.00		✓
15	Rear bumper lower garnish <i>me</i>	1	\$226.00		✓
16	Rear bumper tow cover <i>me</i>	1	\$67.00		✓
17	Bootlid <i>me</i>	1	\$2,709.00		✓
18	Bootlid lock	1	\$1,115.00		?
19	Bootlid hinge LH <i>me</i>	1	\$144.00		X
20	Bootlid hinge RH <i>me</i>	1	\$144.00		X
21	Bootlid emblem <i>me</i>	1	\$45.00		✓
22	Wording "E250" <i>me</i>	1	\$75.00		✓
23	Wording "7G-TRONIC" <i>me</i>	1	\$145.00		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SKM 4243 R**
Make & Model : MERC E250
Chassis No : WDD2120362A828020

Submit By : **Carmen Lim**
Year Manufacture : 2013
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Bootlid chrome <i>sn</i>	1	\$115.00		X
25	Bootlid reflector LH <i>sn</i>	1	\$441.00		X
26	Bootlid reflector RH <i>sn</i>	1	\$441.00		X
27	Tail end panel <i>Bj</i>	1	\$2,100.00		✓
28	Tail end panel garnish <i>Dij</i>	1	\$1,091.00		✓
29	Tail end panel garnish clip <i>me</i>	8	\$40.00		✓
30	Boot weatherstrip <i>cut</i>	1	\$175.00		50% <i>sn</i>
31	Tail lamp LH	1	\$700.00		?
32	Tail lamp RH	1	\$700.00		?
33	Spare tyre well panel <i>Bj</i>	1	\$1,780.00		✓
34	Spare tyre board	1	\$60.00		?
35	Head rest LH	1	\$900.00		?
36	Head rest RH	1	\$900.00		?
37	Driver seat back rest cover	1	\$54.00		?
38	Passenger seat back rest cover	1	\$54.00		?
39	Airbag control unit <i>me</i>	1	\$1,450.00		✓
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SKM 4243 R** Submit By : **Carmen Lim**
Make & Model : **MERC E250** Year of Manufacture : **2013**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	1100
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	60
5	To tuff coat	\$150.00	90
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
7	To reset airbag control unit.	\$250.00	200
8	To remove & refit driver & passenger head rest to assit work load	\$400.00	200
9	To transfer boot mechanism to new boot	\$150.00	60
10	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ESTEEM PERFORMANCE Pte Ltd

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SKM 4243 R

Finalised - Not Authorized
16059 6/12/18 @ 15,000
1605.90 Resurvey After Paint
14453.10

(a) Cost / List Price Items \$ 19,243.00

Plus/Less 10% \$ 1,924.30

Total of Cost / List \$ 17,318.70

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items \$ 45.00

Parts Cost \$ 17,363.70

\$ 4,190.00

\$ 21,553.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

132.50
14585.60

3060

17645.10

151
→ 15,000

Overall total will be subjected to 7% G.S.T.

22072.50

Name of Surveyor

:

Kenneth

Company

:

LKK

Survey conducted on

:

18/12/18

at

Remarks By Surveyor

The repair of this vehicle is authorized / is not authorized until further notice.

Recommended Days of Repair : 12 day(s)

Resurvey : Required / Not Required

Excess : \$

Signature of surveyor

:

K

Date:

18/12/18

Attn: Teh



**ESTEEM
PERFORMANCE**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SKM 4243 R**
Make & Model : **MERC E250**
Chassis No : **WDD2120362A828020**

Submit By : **Carmen Lim**
Year Manufacture : **2013**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>phor</i>	2	\$350.00 ✓		✓
2	Rear number plate <i>cm</i>	1	\$45.00 ✓	S.N	✓
3	Rear No.plate lamp LH <i>sn</i>	1	\$70.00		X
4	Rear No.plate lamp RH <i>sn</i>	1	\$70.00		X
5	Rear bumper <i>cm</i>	1	\$1,650.00 ✓		✓
6	Rear bumper clip <i>mc</i>	10	\$50.00 ✓		✓
7	Rear bumper side retainer LH <i>sn</i>	1	\$69.00		X
8	Rear bumper side retainer RH <i>sn</i>	1	\$69.00		X
9	Rear bumper bracket LH <i>Missing</i> <i>mt</i>	1	\$125.00		✓
10	Rear bumper bracket RH <i>mt</i>	1	\$125.00 ✓		✓
11	Rear bumper sponge <i>CRM</i>	1	\$144.00 ✓		✓
12	Rear bumper reinforcement <i>mt</i>	1	\$590.00 ✓		✓
13	Rear bumper chrome moulding LH <i>mc</i>	1	\$130.00 ✓		✓
14	Rear bumper chrome moulding RH <i>mc</i>	1	\$130.00 ✓		✓
15	Rear bumper lower garnish <i>mt</i>	1	\$226.00 ✓		✓
16	Rear bumper tow cover <i>mt</i>	1	\$67.00 ✓		✓
17	Bootlid <i>mt</i>	1	\$2,709.00 ✓		✓
18	Bootlid lock <i>mt</i>	1	\$1,115.00 ✓		✓
19	Bootlid hinge LH <i>mt</i>	1	\$144.00		X
20	Bootlid hinge RH <i>mt</i>	1	\$144.00		X
21	Bootlid emblem <i>mc</i>	1	\$45.00 ✓		✓
22	Wording "E250" <i>mc</i>	1	\$75.00 ✓		✓
23	Wording "7G-TRONIC" <i>mc</i>	1	\$145.00 ✓		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

7551
SN: 45

Spare Parts

Vehicle No. : SKM 4243 R
 Make & Model : MERC E250
 Chassis No : WDD2120362A828020

Submit By : Carmen Lim
 Year Manufacture : 2013
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Bootlid chrome <i>mgm</i>	1	\$115.00	✓	✓
25	Bootlid reflector LH <i>sn</i>	1	\$441.00		X
26	Bootlid reflector RH <i>sn</i>	1	\$441.00		X
27	Tail end panel <i>By</i>	1	\$2,100.00	✓	✓
28	Tail end panel garnish <i>By</i>	1	\$1,091.00	✓	✓
29	Tail end panel garnish clip <i>mc</i>	8	\$40.00	✓	✓
30	Boot weatherstrip <i>Co</i>	1	\$175.00	87.50 (S.N)	50% <i>sn</i>
31	Tail lamp LH <i>mgm</i>	1	\$700.00	✓	②
32	Tail lamp RH <i>u u</i>	1	\$700.00	✓	②
33	Spare tyre well panel <i>By</i>	1	\$1,780.00	✓	✓
34	Spare tyre board <i>sn</i>	1	\$60.00		X
35	Head rest LH <i>sn</i>	1	\$900.00		X
36	Head rest RH <i>sn</i>	1	\$900.00		X
37	Driver seat back rest cover <i>sn</i>	1	\$54.00		X
38	Passenger seat back rest cover <i>sn</i>	1	\$54.00		X
39	Airbag control unit <i>mc</i>	1	\$1,450.00	✓	✓
40	<i>Washing Machine</i>	1			
41	<i>Washing Machine</i>	1			
42	<i>Washing Machine</i>	1			
43	<i>Washing Machine</i>	1			
44	<i>Washing Machine</i>	1			
45	<i>Washing Machine</i>	1			
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

D Repair 7th Street 1st 2nd 3rd 4th 5th 6th 7th 8th 9th 10th 11th 12th 13th 14th 15th 16th 17th 18th 19th 20th 21st 22nd 23rd 24th 25th 26th 27th 28th 29th 30th 31st 32nd 33rd 34th 35th 36th 37th 38th 39th 40th 41st 42nd 43rd 44th 45th 46th 47th 48th 49th 50th 51st 52nd 53rd 54th 55th 56th 57th 58th 59th 60th 61st 62nd 63rd 64th 65th 66th 67th 68th 69th 70th 71st 72nd 73rd 74th 75th 76th 77th 78th 79th 80th 81st 82nd 83rd 84th 85th 86th 87th 88th 89th 90th 91st 92nd 93rd 94th 95th 96th 97th 98th 99th 100th

*79.76
87.50 (S.N)*

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare PartsVehicle No. :
Make & Model :
Chassis No. :**SKM 4243 R**

MERC E250

WDD2120362A828020

Submit By :
Year Manufacture :
Engine No. :
Cost / List**CARMEN LIM**

2013

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Spare Wheel well Bottom <i>CM</i>	1	\$342.00		✓
2	Spare wheel well <i>Scrubber</i> <i>CM</i>	1	\$105.00		✓
3	Rear bumper lower cover LH - MISSING <i>CM</i>	1	\$85.00		✓
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

532



ESTEEM PERFORMANCE

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 669536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SKM 4243 R** Submit By : **Carmen Lim**
Make & Model : **MERC E250** Year of Manufacture : **2013**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	1100
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	60
5	To tuff coat	\$150.00	90
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
7	To reset airbag control unit.	\$250.00	200
8	To remove & refit driver & passenger head rest to assist work load	\$400.00	200
9	To transfer boot mechanism to new boot	\$150.00	60
10	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

2060

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Dec 2018		18 Dec 2018 16:34 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ANG MING SIANG, ID: S1807991G		
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Vehicle Reg. No.:	SKM4243R	Date of Loss:	14/12/2018 15:00 - :59 [58 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05825C02	Policy/Cover Note No.:	DMPCSN3091331700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJZ132Y	Policy No. (Claimant):	SD18V00033/VPZ/R03
		Excess:	S\$0.00
Repairer:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/12/2018]		
Driver/Custodian (Insured):	ANG MING SIANG (51 / Female), NRIC: S1807991G		
Adj Asg. Remarks:	EST \$4190, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)










Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents





















*SKM4243R (SNM18D05825C02)
[SJZ132Y]
TP
GOLDBELL CAR RENTAL PTE LTD
Dec 14 2018 3:00PM
[ANG MING SIANG]
Esteem Performance Pte Ltd


























Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	15/12/18 09:09	Accident Statement		Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	15/12/18 09:08	Driving License [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
12	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
13	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
14	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
15	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
16	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
17	15/12/18 09:08	Driving License [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
18	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
19	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
20	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
21	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
22	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
23	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
24	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
25	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)		Thumbnail Print
26	15/12/18 09:08	Driving License [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
27	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
28	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
29	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
30	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
31	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
32	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
33	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
34	15/12/18 09:08	Driving License [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
35	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
36	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
37	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
38	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
39	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
40	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
41	15/12/18 09:08	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
2	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
3	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
4	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
5	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
6	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
7	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
8	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
9	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
10	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
11	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
12	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
13	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
14	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
15	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
16	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
17	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
18	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
19	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
20	18/02/19 09:59	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
21	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
22	18/02/19 09:59	Chassis Number		Load JPG <input checked="" type="checkbox"/>
23	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
24	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
25	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
26	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
27	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>
28	18/02/19 09:59	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
29	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	18/02/19 10:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/12/18 16:33	REPAIR EST WITH TP GIA	 Load PDF	
2	18/12/18 16:33	OI GIA	 Load PDF	
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	15/12/18 09:08	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	15/12/18 09:08	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	15/12/18 09:08	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/02/19 13:58	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	15/12/18 09:09	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	15/12/18 09:08	Driving License	 Load JPG	<input checked="" type="checkbox"/>
12	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	15/12/18 09:08	Driving License	 Load JPG	<input checked="" type="checkbox"/>
18	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
20	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
21	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
23	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
24	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
25	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
26	15/12/18 09:08	Driving License	 Load JPG	<input checked="" type="checkbox"/>
27	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
28	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
29	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
30	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
31	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
32	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
33	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
34	15/12/18 09:08	Driving License	 Load JPG	<input checked="" type="checkbox"/>
35	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
36	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
37	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
38	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
39	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
40	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
41	15/12/18 09:08	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	15/12/18 09:08	Sketch Plan	 Load TIF	
2	15/12/18 09:08	Sketch Plan #2	 Load TIF	
3	15/12/18 09:08	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118022715/KSBE2

Date: 18/02/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3091331700
Claimant Vehicle No :	SKM4243R	Insured Vehicle No :	SJZ132Y
Date of Loss:	14/12/2018	Nature of Claim:	TP
		Claim No:	SNM18D05825C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM4243R	Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2120362A828020
Reg. Date:	01/02/2014 (Man. Year: 2014)	Odometer:	95800 km
Colour:	Metallic Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 3 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,842.50	14,698.10	3,144.40	17.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	3,060.00	1,130.00	26.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,032.50	17,758.10	4,274.40	19.40
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	22,032.50	15,000.00	7,032.50	31.92
+ GST 7.00/7.00% (S\$)	1,542.28	1,050.00	492.28	31.92
Nett Amount (S\$)	23,574.78	16,050.00	7,524.78	31.92

INSPECTION

Date of Assignment:	18/12/2018	
Date Inspected:	18/12/2018	Inspected At: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536
Estimated Period of Repair:	12.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2019)
Parts: 143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKM4243R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REVERSE SENSOR	Shorted	350.00 FL	*350.00 FL
2	1		*REAR NUMBER PLATE	Cracked	45.00 FS	*45.00 FS
3	1		*REAR NO. PLATE LAMP LH	Serviceable	70.00 FL	*- FL
4	1		*REAR NO. PLATE LAMP RH	Serviceable	70.00 FL	*- FL
5	1		*REAR BUMPER	Cracked	1,650.00 FL	*1,650.00 FL
6	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
7	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	69.00 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	69.00 FL	*- FL
9	1		*REAR BUMPER BRACKET LH	Missing	125.00 FL	*125.00 FL
10	1		*REAR BUMPER BRACKET RH	Bent	125.00 FL	*125.00 FL
11	1		*REAR BUMPER SPONGE	Cracked	144.00 FL	*144.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	590.00 FL	*590.00 FL
13	1		*REAR BUMPER CHROME MOULDING LH	Necessary	130.00 FL	*130.00 FL
14	1		*REAR BUMPER CHROME MOULDING RH	Necessary	130.00 FL	*130.00 FL
15	1		*REAR BUMPER LOWER GARNISH	Missing	226.00 FL	*226.00 FL
16	1		*REAR BUMPER TOW COVER	Dented	67.00 FL	*67.00 FL
17	1		*BOOTLID	Bent	2,709.00 FL	*2,709.00 FL
18	1		*BOOTLID LOCK	Dented / Jammed	1,115.00 FL	*1,115.00 FL
19	1		*BOOTLID HINGE LH	Repair	144.00 FL	*- FL
20	1		*BOOTLID HINGE RH	Repair	144.00 FL	*- FL
21	1		*BOOTLID EMBLEM	Necessary	45.00 FL	*45.00 FL
22	1		*WORDING E250	Necessary	75.00 FL	*75.00 FL
23	1		*WORDING 7G-TRONIC	Necessary	145.00 FL	*145.00 FL
24	1		*BOOTLID CHROME	Mtg Cracked	115.00 FL	*115.00 FL
25	1		*BOOTLID REFLECTOR LH	Serviceable	441.00 FL	*- FL
26	1		*BOOTLID REFLECTOR RH	Serviceable	441.00 FL	*- FL
27	1		*TAIL END PANEL	Bent	2,100.00 FL	*2,100.00 FL
28	1		*TAIL END PANEL GARNISH	Distorted	1,091.00 FL	*1,091.00 FL
29	8		*TAIL END PANEL GARNISH CLIP	Necessary	40.00 FL	*40.00 FL
30	1		*BOOT WEATHERSTRIP (\$175.00) (50%)	Cut	157.50 FS	*87.50 FS
31	1		*TAIL LAMP LH	Mtg Cracked	700.00 FL	*700.00 FL
32	1		*TAIL LAMP RH	Mtg Cracked	700.00 FL	*700.00 FL
33	1		*SPARE TYRE WELL PANEL	Bent	1,780.00 FL	*1,780.00 FL
34	1		*SPARE TYRE BOARD	Serviceable	60.00 FL	*- FL
35	1		*HEAD REST LH	Serviceable	900.00 FL	*- FL
36	1		*HEAD REST RH	Serviceable	900.00 FL	*- FL
37	1		*DRIVER SEAT BACK REST COVER	Serviceable	54.00 FL	*- FL
38	1		*PASSENGER SEAT BACK REST COVER	Serviceable	54.00 FL	*- FL
39	1		*AIRBAG CONTROL UNIT	Necessary	1,450.00 FL	*1,450.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SPARE WHEEL WELL BOTTOM	Cracked	342.00 FL	*342.00 FL
41	1		*SPARE WHEEL WELL	Cracked	105.00 FL	*105.00 FL
42	1		*REAR BUMPER LOWER COVER LH - MISSING	Missing	85.00 FL	*85.00 FL
					Sub Total (S\$)	19,802.50 16,316.50
					- List Item Discount on L Items 10.00/10.00% (S\$)	1,960.00 1,618.40
					Total Parts (S\$)	17,842.50 14,698.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, BOOTLID, END PANEL, SPARE TYRE WELL PANEL)	New	1,400.00	1,200.00
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, BOOTLID, END PANEL, SPARE TYRE WELL PANEL)	New	1,400.00	1,100.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	60.00
5	TO TUFF COAT	New	150.00	90.00
6	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD	New	150.00	100.00
7	TO RESET AIRBAG CONTROL UNIT	New	250.00	200.00
8	TO REMOVE & REFIT DRIVER & PASSENGER HEAD REST TO ASSIST WORK LOAD	New	400.00	200.00
9	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	150.00	60.00
10	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	30.00
Gross Labour Cost (\$\$)			4,190.00	3,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >