

ASS. REC. BY:

REF:

CS/CT218022716/DVbnz

Special Instruction:

Survivor:

## ASSIGNMENT (Office)

From (Person):

Tune Tay

of

CTL

Date/Time:

18/12/2018 459pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 6819A

Insured:

GX 2087C

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

Blk 10 Amk Ind Park 2A #03-19

Policy No:

DMCVSN301671800

Claim No:

SNM18D05804C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

19.12.2018

H.O.D. Endorsement:

Date/Time:

18/12/2018

5:04pm

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 6819A - CS / FCL18007772 / G211bs

DA: 22042018

GX 2087C - CS / INC10010910 / KVN

DA: 07032010

REF:

## ASSIGNMENT

COE April 2023

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no/s

of

Insured

Policy No


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 129 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No 8HD 6819 AYr Regn: 2015 AprilType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Hyundai I40 C.C. 1685Colour Blue A/C Insured / Std / NI / NASp. Reading 450820 T/Radio: Insured / Std / NI / NAEng/No: D4FDEU500061C/No: KMHLB41UMFU068775Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 15/12/2018 D.O.I. 20/12/2018Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

China Teeping GX2087C18/11/19 Jmmer +/S 14450/- with 14 days of rev (Red 10, 204.16, 419)

RECEIVED 18 JAN 2019.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 18/1 - typistDays Of Repair: 14Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Report Format :

MerimenLump Sum / I.B.I: (\$) 14,450/-Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

) S + R5, SI

) Photos

) Others

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2018		18 Dec 2018 16:59 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	NYEE GUAN FISH BALL FOOD INDUSTRY, Co. Reg. No.: 52832670L								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHD6819A	Date of Loss:	15/12/2018 03:00 - :59						
Claim Type:	TP / SNM18D05804C02	Policy/Cover Note No.:	DMCVSN3016171800 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	GX2087C	Policy No. (Claimant):	D-18088936MFSH						
		Excess:	S\$0.00						
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/12/2018]								
Driver/Custodian (Insured):	ZHANG XIANGMIN (31 / Male), NRIC: G8736570R, Tel: +6598147934								
Adj Asg. Remarks:	EST \$24,674.16, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All   Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All   Search Tasks   Create New Task   Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD618161670 / ComfortDelGro Engineering Pte Ltd - Loyang  
ENTRY DATE & TIME: 18/12/2018 08:04  
SUBMITTED BY: Catherine Por Moy Juan

**SINGAPORE ACCIDENT STATEMENT****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	16/12/2018 08:04
Date Of Accident	15/12/2018 03:30
Exact Location Of Accident	SENGKANG EAST AVE X PUNGGOL RD
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SHD6819A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	ABDUL RAHIM B ISNIN
NRIC No	S1661654J
Date Of Birth	02/10/1964
Occupation	OUTDOOR
Date Of Driving Pass	08/01/2003
Driving Experience	15 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93663414
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 896C #02-80 WOODLANDS DRIVE 50  
 Postcode 732896  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - CROSS JUNCTION  
 Weather Conditions CLEAR  
 Road Surface DRY  
**Other Information**  
 Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : -  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

SEE ATTACH.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GX2087C  
 Vehicle Make/Model/Colour  
**Details Of Properties**  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver ZHANG XIANG MIN  
 NRIC/Passport Number  
 Contact Number 98147934  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage REAR LEFT

No. Of Passenger (Including Driver)

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 15.12.2018  
@ 11:30hrs

Reporting Centre Personnel's Signature  
Name: Diana Choo  
NRIC/FIN No:

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15.12.2018 at about 03:30 hours I was travelling along Sengkang East Ave x Junction of Punggol Road with One Male Passenger onboard .

While travelling straight on the extreme left lane with green light in my favour , suddenly Veh B ( GX 2087C ) did not give way to me and collided into my taxi A - Whole Front Portion .

After the accident my taxi sustain damages on the whole front portion .

I have company video and photos at scene to support my claims .

No injury in this accident.

Veh B ( GX 2087C ) - Mr Zhang Xiang Min H/P : 9814 7934

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 15.12.2018  
@ 11:30hrs

Reporting Centre Personnel's Signature  
Name: *Deanna Choo*  
NRIC/FIN No.:

To survey by UKC

## CHUNNI MOTOR WORK PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHD 6819A

DATE : 17.12.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

ChinaTaiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>bnc</i>			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) <i>1/1</i>	\$	41.00	\$ 82.00	✓
	Bonnet Lock <i>1/1</i>			\$ 36.90	✓
	Bonnet Absorber <i>svc</i>	\$	58.10	\$ 116.20	X
	Bonnet Insulator <i>1/1</i>			\$ 196.50	✓
	Bonnet Insulator Clips <i>h/c</i>			\$ 8.40	✓
	Radiator Grille <i>broken</i>			\$ 251.00	✓
	Radiator Grille H Emblem <i>h/c</i>			\$ 27.50	✓
	Front Bumper Cover <i>broken</i>			\$ 544.50	✓
	Front Bumper Sponge <i>for</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>1/1</i>			\$ 402.10	✓
	Front Bumper Bracket Top (LH/RH) <i>svc</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>svc o/s n/s broken</i>	\$	24.60	\$ 49.20	X ✓
	Headlamp Support Top Cover <i>cut</i>			\$ 222.60	✓
	Headlamp Support Panel Assy <i>1/1</i>			\$ 907.40	✓ photo
	Headlamp (LH/RH) <i>broken</i>	\$	1,388.00	\$ 2,776.00	✓
	Headlamp Halogen Bulb (LH) <i>HH</i>			\$ 14.40	X
	Radiator <i>1/1</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95	✓
	Radiator Bracket (RH/LH) <i>HH</i>	\$	6.50	\$ 13.00	X
	Radiator Guard <i>HH</i>	\$	20.00	\$ 40.00	X
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60	✓
	Front Fender (LH) <i>Deformed</i>			\$ 566.30	✓
	Front Fender Apron Panel (LH) <i>bnc</i>			\$ 637.00	✓
	Front Fender Shield (LH) <i>svc</i>			\$ 174.90	X
	Air Cleaner Assy <i>broken</i>			\$ 118.60	✓
	Air Duct <i>broken</i>			\$ 134.60	✓
	Air Flow Sensor <i>HH</i>			\$ 502.20	X
	Aircon Condenser <i>1/1</i>			\$ 927.50	✓
	Battery Tray <i>HH</i>			\$ 52.00	X
	Front Pillar Upper Cover/Garnish <i>broken</i>			\$ 83.50	✓
	Front Windscreen Glass <i>crack</i>			\$ 1,017.80	✓
	Front Windscreen Moulding <i>h/c</i>			\$ 113.30	✓
	Front Windscreen Pillar Outer (LH) <i>Deformed</i>			\$ 1,745.50	✓
	Wiper Panel Top Garnish <i>deformed / cut</i>			\$ 222.60	✓
	Inter Cooler <i>1/1</i>			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) <i>HH</i>			\$ 25.90	X
	Hose B To Inter Cooler <i>HH</i>			\$ 229.70	X
	Hose C To Inter Cooler Inlet <i>deformed</i>			\$ 294.50	✓
	Pipe To Inter Cooler <i>HH</i>			\$ 167.05	X
	Pipe To Inter Cooler Outlet <i>HH</i>			\$ 244.55	X
	Wiring-Engine <i>broken</i>			\$ 3,326.00	✓
	Engine Top Cover <i>HH</i>			\$ 386.00	X
	EGR Valve & Pipe Assy <i>HH</i>			\$ 2,480.50	X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	SUB TOTAL		19703.15	\$ 24,218.95
	LESS 20%			\$ 4,843.79
	DISCOUNTED TOTAL		15762.52	\$ 19,375.16
	Front Fender Advertisement Logo (LH) HLC			\$ 100.00 Nett ✓
	New Battery HM			\$ 207.00 Nett x
	Front Windscreen Sealant HLC			\$ 46.00 Nett ✓
	Front ERP Sticker HLC			\$ 26.00 Nett ✓
			172.00	\$ 379.00
	Labour Charge			\$ 2,000.00 1000/-
	Panel Beating			\$ 1,250.00 700/-
	Spray Painting Charge			\$ 50.00 40/-
	Wiring Charge			\$ 100.00 40/-
	Tuff Kote			\$ 50.00 HM
	Towing Charge			\$ 150.00 80/-
	Remove/Refix Aircon & Refill Gas			\$ 450.00 150/-
	Remove/Refix Dashboard			\$ 180.00 50/-
	Remove/Refix Fuse Box			\$ 120.00 80/-
	Remove/Refix Front Windscreen Glass			\$ 90.00 HM
	Remove/Refix Cushion & Upholstery Front			\$ 480.00 HM
	Diagnostic & Resetting To Erase Fault Code			
	TOTAL LABOUR			\$ 4,920.00
	ESTIMATE TOTAL			\$ 24,674.16
	20/12/2018 @ 0900hrs Mr Andrew 2 hours 14 days <u>Ryan</u> LKK Auto		18074.52 41314450/-	
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118022716/DVBN2

Date: 21/01/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3016171800
Claimant Vehicle No :	SHD6819A	Insured Vehicle No :	GX2087C
Date of Loss:	15/12/2018	Nature of Claim:	TP
		Claim No:	SNM18D05804C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD6819A	Engine No:	D4FDEU500061
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMFU068775
Reg. Date:	23/04/2015 (Man. Year: 2015)	Odometer:	450820 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,754.16	15,934.52	3,819.64	19.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,920.00	2,140.00	2,780.00	56.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>24,674.16</b>	<b>18,074.52</b>	<b>6,599.64</b>	<b>26.75</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>14,450.00</b>		
<b>(\$\$)</b>	<b>24,674.16</b>	<b>14,450.00</b>	<b>10,224.16</b>	<b>41.44</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,727.19</b>	<b>1,011.50</b>	<b>715.69</b>	<b>41.44</b>
<b>Nett Amount (\$\$)</b>	<b>26,401.35</b>	<b>15,461.50</b>	<b>10,939.85</b>	<b>41.44</b>

## INSPECTION

Date of Assignment:	18/12/2018
Date Inspected:	20/12/2018 Inspected At:

CHUNNI MOTOR WORK PTE LTD  
BLK 10 ANG MO KIO IND. PARK 2A,  
#03-19 AMK AUTOPOINT  
SINGAPORE 568047.

Estimated Period of Repair: 14.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD6819A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Bent	82.00 FL	*82.00 FL
3	1		*BONNET LOCK	Bent	36.90 FL	*36.90 FL
4	2		*BONNET ABSORBER	Serviceable	116.20 FL	*- FL
5	1		*BONNET INSULATOR	Bent	196.50 FL	*196.50 FL
6	1		*BONNET INSULATOR CLIPS	Necessary	8.40 FL	*8.40 FL
7	1		*RADIATOR GRILLE	Broken	251.00 FL	*251.00 FL
8	1		*RADIATOR GRILLE H EMBLEM	Necessary	27.50 FL	*27.50 FL
9	1		*FRONT BUMPER COVER	Broken	544.50 FL	*544.50 FL
10	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
12	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Serviceable	44.80 FL	*- FL
13	1		*FRONT BUMPER BRACKET (LH/RH)	N/s Broken/O/s Serviceable	49.20 FL	*24.60 FL
14	1		*HEADLAMP SUPPORT TOP COVER	Cut	222.60 FL	*222.60 FL
15	1		*HEADLAMP SUPPORT PANEL ASSY	Bent	907.40 FL	*907.40 FL
16	2		*HEADLAMP (LH/RH)	Broken	2,776.00 FL	*2,776.00 FL
17	1		*HEADLAMP HALOGEN BULB (LH)	Not Necessary	14.40 FL	*- FL
18	1		*RADIATOR	Bent	698.30 FL	*698.30 FL
19	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Broken	792.95 FL	*792.95 FL
20	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
21	2		*RADIATOR GUARD	Not Necessary	40.00 FL	*- FL
22	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
23	1		*FRONT FENDER (LH)	Dented	566.30 FL	*566.30 FL
24	1		*FRONT FENDER APRON PANEL (LH)	Buckled	637.00 FL	*637.00 FL
25	1		*FRONT FENDER SHIELD (LH)	Serviceable	174.90 FL	*- FL
26	1		*AIR CLEANER ASSY	Broken	118.60 FL	*118.60 FL
27	1		*AIR DUCT	Broken	134.60 FL	*134.60 FL
28	1		*AIR FLOW SENSOR	Not Necessary	502.20 FL	*- FL
29	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
30	1		*BATTERY TRAY	Not Necessary	52.00 FL	*- FL
31	1		*FRONT PILLAR UPPER COVER/GARNISH	Broken	83.50 FL	*83.50 FL
32	1		*FRONT WINDSCREEN GLASS	Cracked	1,017.80 FL	*1,017.80 FL
33	1		*FRONT WINDSCREEN MOULDING	Necessary	113.30 FL	*113.30 FL
34	1		*FRONT WINDSCREEN PILLAR OUTER (LH)	Dented	1,745.50 FL	*1,745.50 FL
35	1		*WIPER PANEL TOP GARNISH	Deformed/Cut	222.60 FL	*222.60 FL
36	1		*INTER COOLER	Bent	1,032.50 FL	*1,032.50 FL
37	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
38	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
39	1		*HOSE C TO INTER COOLER INLET	Deformed	294.50 FL	*294.50 FL
40	1		*PIPE TO INTER COOLER	Not Necessary	167.05 FL	*- FL
41	1		*PIPE TO INTER COOLER OUTLET	Not Necessary	244.55 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*WIRING-ENGINE	Broken	3,326.00 FL	*3,326.00 FL
43	1		*ENGINE TOP COVER	Not Necessary	386.00 FL	*- FL
44	1		*EGR VALVE & PIPE ASSY	Not Necessary	2,480.50 FL	*- FL
45	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
46	1		*NEW BATTERY	Not Necessary	207.00 FS	*- FS
47	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
48	1		*FRONT ERP STICKER	Necessary	26.00 FS	*26.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	24,597.95	19,875.15
- List Item Discount on L Items 20.00/20.00% (S\$)	4,843.79	3,940.63
<b>Total Parts (S\$)</b>	<b>19,754.16</b>	<b>15,934.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	2,000.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,250.00	700.00
3	WIRING CHARGE	New	50.00	40.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
7	REMOVE/REFIX DASHBOARD	New	450.00	150.00
8	REMOVE/REFIX FUSE BOX	New	180.00	50.00
9	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	-
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>4,920.00</b>	<b>2,140.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;