



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 6778A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	L/R BUMPER SUPPORT (WCP)	SERVICEABLE	20.00	-
1	R/R BUMPER SUPPORT (WCP)	SERVICEABLE	20.00	-
1	R/R LAMP ASSY (WCP)	BROKEN	115.00	115.00
1	R/R SIDE PANEL CPL (WCP)	TO REPAIR SEE LABOUR	880.00	-
1	REAR BUMPER (WCP)	SERVICEABLE	450.00	-
7	RR BUMPER CLAMP KIT (WCP)	NOT NECESSARY	18.00	-
1	RR TAIL LAMP CLIP (WCP)	NECESSARY	7.00	7.00
	COST PLUS 15%		226.50	18.30
			1,736.50	140.30
	<u>LABOUR</u>			
	PANEL /MECHANICAL .INCLUSIVE OF THE REPAIRO OF R/R SIDE PANEL CPL .		481.50	481.50
	PAINTWORK.		310.50	310.50
	PAINT/MATERIAL COSTS.		93.45	93.45
			885.45	885.45
GRAND TOTAL			2,621.95	1,025.75

RECOMMENDED COST OF REPAIRS			1,025.75
------------------------------------	--	--	-----------------

Report Ref No. CC4/ASM18022721/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.