

22/03/18

AS REC. BY:

REF: CS/FCL18022722/Dqbn2

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): CWS Joanne Yong of FCL Date/Time: 18/12/2018 5:42pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 8552K Insured: SHD 4107J

at Workshop m/s Churni Motor Tel: 6842 0051

of Bk 10 AMK Ind Park 2A #03-19

Policy No: Claim No: D18008895 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 15.12.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS '08' 19.12.2018 H.O.D. Endorsement:

Date/Time: Person Contacted: Lynn Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHC 8552K - NS/WC17003755/HIGH354	DOA: 20072017
	SHD 4107J - NS/WC17012620/MINIBUS	DOA: 23062017
11/12/18 @ 5:42pm	REVISED to Joanne Yong by email.	

REF:

ASSIGNMENT

10E Dec 2023

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 8HC 8552KYr Regn: 2015 DecType: M.Car / M.Cycle / Bus / Van / Lorry ☒ / Prime Mover /

Truck / Trailer or _____

Make: Hyundai A40 C.C. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 263692 T/Radio: Insured / Std / NI / NAEng/No: D4FDFU564629C/No: KMHLB41UHG080731Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: - 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wistake

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 15/12/2018 D.O.I. 20/12/2018Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital 8HD4107J

03/01/19 Insured 2/5 15500/- with 8 days of rep
(per 69287.52, 37%)

RECEIVED 04 JAN 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 04/1 Insured☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 8Resurvey No. of Trip: 2Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)Report Format: TPLump Sum / I.B.F. (\$) 15500

Survey Fee:

Transportation:

) S + RS + GI

) Photo 550

) Chassis

) 411/19

TOTAL

14X15: 210

170+210

50

50+50

248

778

MOTOR SURVEY ASSIGNMENT

Date	17-12-2018	Our Ref No. D18008895MFSH
Accident Date	15-12-2018	Claim Type. Third Party
Insured Vehicle	SHD4107J	Third Party Vehicle. SHC8552K
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE; WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 21 December 2018 5:24 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D18008895MFSH/1
Attachments: CSFCI18022722Dqb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHC 8552K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]
Sent: Tuesday, 18 December, 2018 6:05 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D18008895MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 18 December, 2018 5:42 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008895MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008895MFSH
Our Ref: CS/FCI18022722/Dqb

Date: 21 December 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 8552K

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/12/2018 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 24,517.82 .
Revised Estimate Amount	: S\$ 19,394.82 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the front & rear portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 8552K

DATE : 18.12.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

CLC-1

KCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille & mounting cradle			\$ 1,110.10	2 ✓
	Radiator Grille H Emblem & H			\$ 39.50	2 ✓
	Front Bumper Cover distorted / mounting cradle			\$ 1,052.20	✓
	Front Bumper Sponge torn			\$ 99.20	✓
	Front Bumper Reinforcement Bt			\$ 402.10	✓
	Front Bumper Bracket Top (LH/RH) SVC	S	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) SVC	S	24.60	\$ 49.20	X
	Headlamp Support Top Cover SVC			\$ 222.60	X
	Headlamp Support Panel Assy & Bt			\$ 907.40	2 ✓
	Headlamp (LH/RH) mounting cradle	S	1,388.00	\$ 2,776.00	✓
	Radiator & Bt			\$ 698.30	2 ✓
	Radiator Fan Blade, Cowling, Motor Assy HH			\$ 792.95	X
	Radiator Bracket (RH/LH) HH	S	6.50	\$ 13.00	X
	Radiator Guard broken	S	20.00	\$ 40.00	✓
	Horn Unit (LH/RH) broken	S	73.80	\$ 147.60	✓
	Aircon Condenser & Bt			\$ 927.50	2 ✓
	Inter Cooler & Bt			\$ 1,032.50	2 ✓
	Inter Cooler Mounting (2 PCS) HH			\$ 25.90	X
			9232.40		
			7386.92		
	SUB TOTAL			\$ 10,380.85	
	LESS 20%			\$ 2,076.17	
	DISCOUNTED TOTAL			\$ 8,304.68	
	Front Number Plate HH			\$ 25.00	Nett X
	Front No Plate Trim Cover HH			\$ 30.00	Nett X
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charge			\$ 60.00	HH
	Remove/Refix Aircon & Refill Gas			\$ 150.00	280/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	HH
			810.00		
	TOTAL LABOUR			\$ 1,990.00	

SHC 8552K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>vt</i>			\$ 2,174.90 ✓
	Boot Lid Rubber <i>defrmed</i>			\$ 96.50 ✓
	Boot Lid Hinge (LH/RH) <i>H</i>		\$ 142.30	\$ 284.60 X
	Boot Lid Lock Upper <i>vt</i>			\$ 102.60 ✓
	Boot Lid Lock Lower <i>H</i>			\$ 31.70 X
	Boot Lid 'H' Emblem <i>H</i>			\$ 28.70 ✓
	Boot Lid CRDI Plate <i>H</i>			\$ 27.90 ✓
	Boot Lid Lamp (LH/RH) <i>CACUC</i>		\$ 565.60	\$ 1,131.20 ✓
	Boot Lid Trimboard <i>torn</i>			\$ 116.40 ✓
	Boot Lid Trimboard Clips (10pcs) <i>H</i>			\$ 11.00 ✓
	Bootlid Moulding <i>H</i>			\$ 85.00 X
	Bootlid i40 Emblem <i>SVC</i>			\$ 27.90 X
	Bootlid Lower Garnish <i>H</i>			\$ 227.90 X
	Rear Bumper <i>distorted</i>			\$ 553.00 ✓
	Rear Bumper Reinforcement <i>& crack</i>			\$ 428.40 Z ✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>& vt</i>		\$ 80.30	\$ 160.60 Z ✓
	Rear Bumper Clip 10 pcs <i>H</i>			\$ 22.00 ✓
	Rear Bumper Bracket <i>H</i>		\$ 35.60	\$ 71.20 X
	Rear Bumper Sponge <i>torn</i>			\$ 118.40 ✓
	Rear Bumper Under Cover <i>defrmed</i>			\$ 228.00 ✓
	Tail Lamp (LH/RH) <i>crack</i>		\$ 697.80	\$ 1,395.60 ✓
	Rear Panel <i>Dented</i>			\$ 526.70 ✓
	Rear Panel Garnish <i>mounting broken</i>			\$ 57.70 ✓
	Rear Panel Lower Panel <i>Dented</i>			\$ 495.50 ✓
	Spare Tyre Holder <i>broken</i>			\$ 223.10 ✓
	Spare Tyre Panel <i>Dented</i>			\$ 852.80 ✓
	Spare Tyre Panel Cushion <i>H</i>			\$ 209.05 X
	Rear Towing Hook <i>H</i>			\$ 94.60 X
	Member Assy- Rear Floor Centre <i>H</i>			\$ 570.40 X
	Exhaust Pipe Insulator <i>H</i>		\$ 58.55	\$ 117.10 X
	Exhaust Silencer <i>& vt</i>		\$ 967.70	\$ 1,935.40 Z ✓
	Exhaust Pipe Hanger <i>H</i>		\$ 58.55	\$ 117.10 X
	Exhaust Pipe Centre <i>metal distorted</i>			\$ 730.10 X ✓
	SUB TOTAL		11416.50	\$ 13,253.05
	LESS 20%		9133.20	\$ 2,650.61
	DISCOUNTED TOTAL			\$ 10,602.44
	Boot Lid Comfort Logo & Tel No. Sticker <i>H</i>			\$ 30.00 Nett ✓
	Boot Lid Advertisement Logo <i>H</i>			\$ 100.00 Nett ✓
	Rear Bumper Reverse Sensor <i>Don</i>			\$ 135.70 Nett ✓
	Rear Bumper Advertisement Logo <i>H</i>			\$ 50.00 Nett ✓
	Rear Bumper Rubber Mat <i>H</i>			\$ 50.00 Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>H</i>		\$ 100.00	\$ 200.00 Nett ✓
			565.70	\$ 565.70

4517.82

SHC 8552K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 700/-
	Spray Painting Charge			\$ 1,250.00 700/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Exhaust Pipe		1570.00	\$ 300.00 60/-
	TOTAL LABOUR			\$ 3,270.00
	ESTIMATE TOTAL			\$ 24,787.82
	20/12/2018 e oqoons NA Antm 2/sum 8 days. ryan LKK Auto		19464.82 4/515500/-	
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118022722/Dqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4107J	Veh. Inspected	SHC 8552K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008895MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	18/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU080731	Colour	BLUE	
Odometer	263692	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2018	Inspection Date	20/12/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8552K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RADIATOR GRILLE	MOUNTING CRACKED	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	NECESSARY	39.50	39.50
1	FRONT BUMPER COVER	DISTORTED / MOUNTING CRACKED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	BENT	402.10	402.10
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	SERVICEABLE	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	SERVICEABLE	49.20	-
1	HEADLAMP SUPPORT TOP COVER	SERVICEABLE	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BENT	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	MOUNTING CRACKED	2,776.00	2,776.00
1	RADIATOR	BENT	698.30	698.30
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	NOT NECESSARY	792.95	-
2	RADIATOR BRACKET (LH/RH) @\$6.50	NOT NECESSARY	13.00	-
2	RADIATOR GUARD @\$20.00	BROKEN	40.00	40.00
2	HORN UNIT (LH/RH) @\$73.80	BROKEN	147.60	147.60
1	AIRCON CONDENSER	BENT	927.50	927.50
1	INTER COOLER	BENT	1,032.50	1,032.50
1	INTER COOLER MOUNTING (2 PCS)	NOT NECESSARY	25.90	-
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID RUBBER	DEFORMED	96.50	96.50
2	BOOT LID HINGE (LH/RH) @\$142.30	NOT NECESSARY	284.60	-
1	BOOT LID LOCK UPPER	BENT	102.60	102.60
1	BOOT LID LOCK LOWER	NOT NECESSARY	31.70	-
1	BOOT LID "H" EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
2	BOOT LID LAMP (LH/RH) @\$565.60	CRACKED	1,131.20	1,131.20
1	BOOT LID TRIMBOARD	TORN	116.40	116.40
10	BOOT LID TRIMBOARD CLIPS	NECESSARY	11.00	11.00

Report Ref No. CS/FCI18022722/Dqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID MOULDING	NOT NECESSARY	85.00	-
1	BOOTLID I40 EMBLEM	SERVICEABLE	27.90	-
1	BOOTLID LOWER GARNISH	NOT NECESSARY	227.90	-
1	REAR BUMPER	DISTORTED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	BENT	160.60	160.60
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	NOT NECESSARY	71.20	-
1	REAR BUMPER SPONGE	TORN	118.40	118.40
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
2	TAIL LAMP (LH/RH) @\$697.80	CRACKED	1,395.60	1,395.60
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL GARNISH	MOUNTING BROKEN	57.70	57.70
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
1	SPARE TYRE HOLDER	BROKEN	223.10	223.10
1	SPARE TYRE PANEL	DENTED	852.80	852.80
1	SPARE TYRE PANEL CUSHION	NOT NECESSARY	209.05	-
1	REAR TOWING HOOK	NOT NECESSARY	94.60	-
1	MEMBER ASSY-REAR FLOOR CENTRE	NOT NECESSARY	570.40	-
2	EXHAUST PIPE INSULATOR @\$58.00	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$967.70	BENT	1,935.40	1,935.40
2	EXHAUST PIPE HANGER @\$58.55	NOT NECESSARY	117.10	-
1	EXHAUST PIPE CENTRE	DISTORTED	730.10	730.10
	LESS 20% DISCOUNT		-4,726.78	-4,129.78
			18,907.12	16,519.12
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT NO PLATE TRIM COVER (SN)	NOT NECESSARY	30.00	-
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70

Report Ref No. CS/FCI18022722/Dqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
			620.70	565.70
	LABOUR			
	PANEL BEATING.		2,500.00	1,200.00
	SPRAY PAINTING CHARGE.		1,500.00	900.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX EXHAUST PIPE.		300.00	60.00
			5,260.00	2,380.00
GRAND TOTAL			24,787.82	19,464.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,500.00

Report Ref No. CS/FCI18022722/Dqbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.