

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18022732/T1DA3Q2

Date: 24/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994809

Claimant
Vehicle No : SMF3570R **Insured Vehicle No :** SLK5828X

Date of Loss: 04/12/2018 Nature of Claim: TP Claim No: 0354779620SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF3570R		
Make & Model:	SUBARU XV, 2.0 I-S EYESIGHT AWD CVT (A)	Engine No:	FB20YE77057
Reg. Date:	03/11/2018 (Man. Year: 2018)	Chassis No:	JF1GT7KL5JG047593
Colour:	Orange	Odometer:	1490 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,023.53	2,748.17	275.36	9.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,670.00	3,610.00	7,060.00	66.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,693.53	6,358.17	7,335.36	53.57
+ GST 7.00/7.00% (\$\$)	958.55	445.07	513.48	53.57
Nett Amount (\$\$)	14,652.08	6,803.24	7,848.84	53.57
+ Medical Costs (\$\$)		158.00		
+ Car Rental (7.0 x S\$110.00/day + 7.00% GST) (\$\$)		823.90		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		7,792.59		

INSPECTION

Date of Assignment: 18/12/2018

Date Inspected: 19/12/2018 Inspected At:

Motor Image Enterprises Pte Ltd
(Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*CUSHION EXH RH/LH	Not Necessary	21.60 FL	*- FL
2	1		*MUFFLER ASSY W20	Bent	576.00 FL	*576.00 FL
3	1		*BUMPER FACE R XV	Cracked	401.10 FL	*401.10 FL
4	1		*BRKT SD R XV RH	Necessary	12.10 FL	*12.10 FL
5	1		*BRKT SD R XV LH	Necessary	12.10 FL	*12.10 FL
6	1		*BRKT CORNER R 5D RH	Not Necessary	21.60 FL	*- FL
7	1		*BRKT CORNER R 5D LH	Not Necessary	21.60 FL	*- FL
8	2		*BRKT LWR R	Necessary	50.40 FL	*50.40 FL
9	1		*BEAM COMPL R EU	Bent	202.90 FL	*202.90 FL
10	1		*COVER HOOK R XV	Missing	6.50 FL	*6.50 FL
11	1		*PANEL COMPL R GAT	Bent	940.00 FL	*940.00 FL
12	1		*GLASS ASSY R G	Necessary	1,062.00 FL	*1,062.00 FL
13	1		*DAM RUBBER	Necessary	18.00 FL	*18.00 FL
14	1		*LETTER MK R	Necessary	90.00 FL	*90.00 FL
15	1		*LETTER MK R XV	Necessary	36.00 FL	*36.00 FL
16	1		*EYE SIGHT EMBLEM (TCS)	Necessary	43.20 FS	*43.20 FS
17	1		*SUNDRIES	Necessary	150.00 FS	*20.00 FS
18	2		*POINT REVERSE SENSOR	Not Working	400.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,065.10	3,770.30
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,041.57	1,022.13
Total Parts (\$\$)	3,023.53	2,748.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT ANTI-RUST PROTECTION FOR REAR UNDERCARRIAGE WITH ANTI RUST COATING	New	550.00	290.00
2	TO CONDUCT PANEL PROTECTION FOR REAR UNDERCARRIAGE	New	500.00	250.00
3	TO REPAIR AND REPLACE REAR BUMPER ,TAILGATE ,REAR BUMPER BEAM,REAR END PANEL AND SPARE TYRE WELL	New	3,360.00	1,000.00
4	TO RESPRAY REAR BUMPER ,TAILGATE ,REAR BUMPER BEAM ,REAR END PANEL ,REAR BOTH SIDE FENDE AND SPARE TYRE WELL	New	3,960.00	625.00
5	REMOVE AND REFIX EXHAUST FOR FACILITATE REPAIR AND CHECKING	New	500.00	250.00
6	TRANSFER TAILGATE MECHANISM	New	350.00	180.00
7	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	New	350.00	180.00
8	REMOVE & INSTALL REAR WINDSCREEN	New	350.00	240.00
9	TO SUPPLY AND INSTALL REAR WINDSCREEN TINT FILM	New	300.00	145.00
10	TO RESPRAY REAR END PANEL	New	200.00	200.00
11	TO REPAIR REAR END PANEL	New	250.00	250.00
Gross Labour Cost (S\$)			10,670.00	3,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >