

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18022753/T1GA3Q2

Date: 16/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHA9261D	Insured Vehicle No :	SH6843C
Date of Loss: 17/12/2018	Nature of Claim: TP	Claim No: MCT18120506

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA9261D	Engine No:	G4LEJU080154
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU107267
Reg. Date:	21/08/2018 (Man. Year: 2018)	Odometer:	43601 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,269.90	1,855.36	3,414.54	64.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,660.00	1,040.00	38.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,969.90	3,515.36	4,454.54	55.89
+ GST 7.00/7.00% (\$\$)	557.89	246.08	311.81	55.89
Nett Amount (\$\$)	8,527.79	3,761.44	4,766.35	55.89
+ Loss of Use (18.0 x S\$40.00/day) (\$\$)		720.00		
+ Car Rental (18.0 x S\$117.00/day) (\$\$)		2,106.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,594.89		
Global Sum Settlement (\$\$)		6,000.00		

INSPECTION

Date of Assignment:	12/12/2018	
Date Inspected:	27/12/2018	Inspected At: 31 Corporation Road
		Repairer : Ding Automotive Pte Ltd
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2019)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA9261D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	559.40 FL	*559.40 FL
2	1		*REAR BUMPER FOG LAMP ASSY	Not Necessary	301.50 FL	*- FL
3	1		*REAR BUMPER LOWER CENTER MOULDING	Not Necessary	57.50 FL	*- FL
4	1		*REAR BUMPER RETAINER LH	Necessary	43.10 FL	*43.10 FL
5	1		*REAR BUMPER RETAINER RH	Necessary	43.10 FL	*43.10 FL
6	1		*REAR BUMPER CENTER GARNISH	Cut	370.10 FL	*370.10 FL
7	1		*REAR TOWING CAP	Not Necessary	19.10 FL	*- FL
8	1		*REAR BUMPER REFLECTOR LH	Cut	41.90 FL	*41.90 FL
9	1		*REAR BUMPER REFLECTOR RH	Cut	41.90 FL	*41.90 FL
10	1		*REAR BUMPER LOWER COVER	Not Necessary	38.70 FL	*- FL
11	1		*REAR BUMPER SIDE COVER LH	Deformed	37.50 FL	*37.50 FL
12	1		*REAR BUMPER SIDE COVER RH	Not Necessary	37.50 FL	*- FL
13	1		*REAR REVERSE SENSOR SET IONIQ	Not Necessary	272.20 FL	*- FL
14	1		*REAR SMARTKEY ANTENNA	Not Necessary	133.88 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Not Necessary	148.10 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	148.10 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT LOWER BRACKET X3	Not Necessary	12.80 FL	*- FL
19	1		*REAR END PANEL	Not Necessary	632.20 FL	*- FL
20	1		*REAR FENDER RHS	Repair	2,171.80 FL	*- FL
21	1		*FRONT WHEEL CAP LHS	Cut	276.80 FL	*276.80 FL
22	1		*FRONT WHEEL CAP RHS	Cut	276.80 FL	*276.80 FL
23	1		*REAR WHEEL CAP LHS	Cut	276.80 FL	*276.80 FL
24	1		*REAR WHEEL CAP RHS	Cut	276.80 FL	*276.80 FL
25	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
26	1		*REAR CENTER GARNISH CLIP & SCREW	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,572.38	2,304.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,302.48	448.84
Total Parts (\$\$)	5,269.90	1,855.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,500.00	800.00
2	RESPRAY FRONT BUMPER	New	230.00	200.00
3	RESPRAY REAR BUMPER	New	230.00	200.00
4	RESPRAY REAR BUMPER GARNISH	New	230.00	100.00
5	RESPRAY REAR FENDER RHS	New	230.00	200.00
6	TOWING CHARGE	New	160.00	120.00
7	REMOVE & REFIT SPARE TYRE & CAR PET & SIDE TRIM	New	120.00	40.00
Gross Labour Cost (\$\$)			2,700.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >