



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 1340U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR FRONT COVER	TO REPAIR SEE LABOUR	152.00	-
1	HANDLE BAR REAR COVER	USABLE	112.50	-
1	HANDLE BAR	NOT DAMAGE	102.90	-
2	HANDLE BAR BRACKET @ \$46.80	NOT DAMAGE	93.60	-
1	SET HANDLE BAR	GRAZED	40.00	40.00
1	SET MIRROR	GRAZED	112.00	112.00
1	HEAD LAMP	NOT DAMAGE	175.00	-
1	HEADLAMP BRACKET	NOT DAMAGE	77.00	-
1	FRONT COWLING	CRACKED	216.00	216.00
1	FRONT SIGNAL RH	GRAZED	63.00	63.00
1	FRONT MUDGUARD	TO REPAIR SEE LABOUR	78.00	-
1	SIDE FAIRING RH	GRAZED	165.20	165.20
1	SIDE FAIRING PANEL	USABLE	87.00	-
1	FRONT FOOT REST BAR	BENT	80.60	80.60
1	FRONT FOOT REST RUBBER	CUT	16.00	16.00
1	BRAKE PEDAL	BENT	58.00	58.00
1	EXHAUST PROTECTOR (FRONT)	NOT DAMAGE	85.00	-
1	MUFFLER PROTECTOR CHROME	SCRATCHED	120.00	120.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	630.00	-
	LESS 10% DISCOUNT		-246.38	-87.08
			2,217.42	783.72
<u>SPECIAL NETT ITEMS</u>				
2	FRONT FORK OIL SEAL (SN)	NOT NECESSARY	140.00	-
3	LITRS FRONT FORK OIL (SN)	NOT NECESSARY	60.00	-
1	SET STEERING CONE & BEARING (SN)	NOT NECESSARY	160.00	-
1	SET BODY STICKER (SN)	NECESSARY	150.00	120.00
1	REAR BOX (SN)	GRAZED	450.00	150.00
1	REAR BOX RACK WITH BASE (SN)	TO REPAIR SEE LABOUR	180.00	-
			1,140.00	270.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	FRONT FORK ALIGN.		400.00	100.00
	STEERING STEM ALIGN.		200.00	50.00
	BODY CHASSIS ALIGN.		450.00	-
	DISMANTLE & REPLACE DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF HANDLE BAR FRONT COVER, FRONT MUDGUARD EXHAUST ASSY AND REAR BOX RACK WITH BASE.		400.00	250.00
			1,450.00	400.00
	GRAND TOTAL		4,807.42	1,453.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,150.00

Report Ref No. CS3/ASM18022761/K1td3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.