

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 18/12/2018
TP Vehicle No. : SKZ-3020-E
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

IVAN TEO
ABWIN SERVICE PTE LTD
DID: 67139416
Fax: 67139415
HP: 86680608

Owner : SING SOON HUAT PLASTIC TRADING ENTERPRISE
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5092717644-01
Vehicle No. : GBG-2343-L
Make & Model : TOYOTA DYNA 150 3.0 DIESEL Y (M)

Accident Date: 18/12/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAIL LAMP ASSY RH	C47 \$236.40	✓
	Sub Total	\$236.40	
	Discount 25% on Parts	(\$59.10)	
		\$177.30	

Special Nett

1	CUSTOMISED REAR DOOR RH	20/12 \$2,200.00	1200
1	CUSTOMISED STEP BRACKET	50/12 \$550.00	✓
1	CUSTOMISED END PANEL GARNISH	2 \$800.00	X
	Sub Total	\$3,550.00	

Labour & Misc

LABOUR TO FACILITATE REPAIR	\$800.00	700
TO SPRAY PAINT ON AFFECTED AREAS	\$300.00	220
TO RUST PROOF AFFECTED AREA	11 \$100.00	X
Sub Total	\$1,200.00	

Sub Total \$4,927.30
GST 7% \$344.91
Total \$5,272.21

not authorized
19/12/18
the photo after repair
4 day

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: