

CS/CTI 18022772/THD302

REF:

CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Patricia

Veh No: SLK839IT Yr Regn: 2017 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Jager XE

C.C.

1999

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 56764

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SA 5744AN 7MC P00318

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 225 / 45 R18

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Confidential

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. 20/12/18

Survey held at

Wearnes Long Hill

Des. of Damages: Frt / Rear / P/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Part by Part \$10,978.36 (Red: 5338.85, 32%)

RECEIVED 10 JAN 2019

Submit report in minutes

Date/Time, File Pass to?

1) 18/11 Typist

Date/Time, File Return to?

2) _____

☒ Prel. Report☐ Final Report

Days Of Repair: 6

Resurvey No. of Trip: -

Survey Fee: 220

Transportation: _____

) S + RS. SI

) Photos

) Others

TOTAL

220

Report Format : TP

Lump Sum / I.B.I.: (\$ _____)

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 17/12/2018

WIP No. : 43665

Veh.In/Out:

*Tel.No. : Mobile: 94564904

Reg.No. : SLK8391T

Reg.date : 31/01/2017

Mileage : 0

Chassis No: SAJAB4AN7HCP00318

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT RH DOOR, 900	0	3600.00	0		3,600.00 S	2250 ✓
	REAR RH DOOR, RH ROCKET PANEL, RHF DOOR HANDLE, ETC						
800	TO PUTTY SPRAYPAINT ON 800	0	3200.00	0		3,200.00 S	2400 ✓
	FRT RH DOOR, REAR RH DOOR, RH ROCKET PANEL, ETC						
802	TO TRANSFER FRT RH DOOR PART	0	500.00	0		500.00 S	✓
802	TO TRANSFER REAR RH DOOR PART	0	500.00	0		500.00 S	✓
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 S	✓
	RESETTING OF ALL ELECTRICAL MODULES						
	DOOR PANEL RHF XE	1.0 EA	1492.30			1,492.30 S	bt 1343.07
	SOUND DEADENING PAD	2.0 EA	250.00			500.00 S	re 450
	DOOR PANEL RHR XE	1.0 EA	1824.10			1,824.10 S	bt 1641.69
	JT4N13770LML/MOUL DIN	1.0 EA	549.50			549.50 S	re 499.55
	DOOR FINISHER RH FRT	1.0 EA	316.60			316.60 S	x nn
	DOOR FINISHER RH FRT	1.0 EA	256.50			256.50 S	x nn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanglim 97495749

WP

20/12/18 @ 12pm

X Ronny before paint.

sur @ lkkauto.com

6 days

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC

Hitachi Capital Asia Pacific Pte Ltd

Attn: Mr Ang

484b Choa Chu Kang Avenue 5

Singapore 682484

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 17/12/2018

WIP No. : 43665

Veh.In/Out:

*Tel.No. : Mobile: 94564904

Reg.No. : SLK8391T

Reg.date. : 31/01/2017

Mileage : 0

Chassis No: SAJAB4AN7HCP00318

Closed by : Patricia Kueh Anak S

Svc Consultant :

Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

FINISHER CHROME C PI

1.0 EA 264.40

264.40 S

DOOR FINISHER RH REA

1.0 EA 263.90

263.90 S

SEAL-DOOR FRT

1.0 EA 232.30

232.30 S

SEAL-DOOR REAR

1.0 EA 207.10

207.10 S

HANDLE-DOOR FRT

1.0 EA 397.20

397.20 S

HANDLE-DOOR REAR

1.0 EA 397.20

397.20 S

LATCH

1.0 EA 620.90

620.90 S

ADHESIVE SEALER FL2

1.0 EA 549.10

549.10 S

Gross Total. 16,157.10

Labour Total 8,286.00

Parts Total 7,871.10

Package Total 0.00

Net..... 16,157.10

GST @ 7.0% 1,131.00

Total..... 17,288.10

Paid..... 0.00

Please Pay.. 17,288.10

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 08/04/2019
 SINGAPORE 079909 WIP No. . : 43665
 Veh.In/Out: 18/01/2019 28/01/2019
 *Tel.No. . : 63896111
 Reg.No. . : SLK8391T
 Closed by : Paul Ong Qing Yong Reg.date . : 31/01/2017
 Svc Consultant : ACC Mileage . : 58,315
 Remarks : Hitachi Capital Asia Chassis No: SAJAB4AN7HCP00318

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT RH DOOR, REAR RH DOOR, RH ROCKET PANEL, RHF DOOR HANDLE, ETC	0	2250.00	0		2,250.00	S
800	TO PUTTY SPRAYPAINT ON FRT RH DOOR, REAR RH DOOR, RH ROCKET PANEL, ETC	0	2400.00	0		2,400.00	S
802	TO TRANSFER FRT RH DOOR PART	0	500.00	0		500.00	S
802	TO TRANSFER REAR RH DOOR PART	0	500.00	0		500.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
	DOOR PANEL RHF XE	1.0 EA	1492.30	10		1,343.07	S
	SOUND DEADENING PAD	2.0 EA	250.00	10		450.00	S
	DOOR PANEL RHR XE	1.0 EA	1824.10	10		1,641.69	S
	JT4N13770LML/MOULGIN	1.0 EA	549.50	10		494.55	S
	SEAL-DOOR FRT	1.0 EA	232.30	10		209.07	S
	SEAL-DOOR REAR	1.0 EA	207.10	10		186.39	S

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. : B&P 0 Page 2
 #16-00, SPRINGLEAF TOWER Inv.date. : 08/04/2019
 SINGAPORE 079909 WIP No. : 43665
 Veh.In/Out: 18/01/2019 28/01/2019
 *Tel.No. : 63896111
 Reg.No. : SLK8391T
 Closed by : Paul Ong Qing Yong Reg.date. : 31/01/2017
 Svc Consultant : ACC Mileage : 58,315
 Remarks : Hitachi Capital Asia Chassis No: SAJAB4AN7HCP00318

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HANDLE-DOOR FRT	1.0 EA	397.20	10		357.48	S
	BEZEL <i>supp</i>	1.0 EA	45.90	10		41.31	S
	BUMPER NUT XF <i>supp</i>	30.0 EA	4.40	10		118.80	S

Gross Total. 10,978.36

Labour Total 6,136.00
 Parts Total 4,842.36
 Package Total 0.00

Net..... 10,978.36
 GST @ 7.0% 768.49
 Total..... 11,746.85
 Paid..... 0.00
 Please Pay.. 11,746.85

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

supp

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 08/04/2019
 SINGAPORE 079909 WIP No. . : 43665
 Veh.In/Out: 18/01/2019 28/01/2019
 *Tel.No. . : 63896111
 Reg.No. . : SLK8391T
 Closed by : Paul Ong Qing Yong Reg.date . : 31/01/2017
 Svc Consultant : ACC Mileage .. : 58,315
 Remarks : Hitachi Capital Asia Chassis No: SAJAB4AN7HCP00318

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BEZEL	1.0 EA	45.90	10		41.31	S 3/13 neu ✓
	BUMPER NUT XF	30.0 EA	4.40	10		118.80	S

163/17.21

			Gross Total.	160.11
Labour Total	0.00	Net.....	160.11	
Parts Total	160.11	GST @ 7.0%	11.21	
Package Total	0.00	Total.....	171.32	
		Paid.....	0.00	
		Please Pay..	171.32	

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2018		19 Dec 2018 15:05 Edit Adj Rpt	\$10,978.36 Edit Estimates	\$10,978.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD									
Vehicle Reg. No.: SLK8391T		Date of Loss: 14/12/2018 00:00 - :59 [22 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05850C02		Policy/Cover Note No.: DMPCSN3098841700							
Vehicle Reg. No. (Insured): SGU8871G		Policy No. (Claimant):							
		Excess: \$0.00							
Repairer: Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/04/2019]									
Adj Asg. Remarks: EST \$17,288.10, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPING (08/04/2019): Report Send Back Alerts - SLK8391T (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK8391T (SNM18D05850C02)
[SGU8871G]
TP
HITACHI CAPITAL ASIA PACIFIC PTE LTD
Dec 14 2018 12:00AM
[-]
Wearnes Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	18/01/19 15:37	General View						Load JPG	☒	
2	18/01/19 15:37	General View						Load JPG	☒	
3	18/01/19 15:37	General View						Load JPG	☒	
4	18/01/19 15:37	General View						Load JPG	☒	
5	18/01/19 15:37	General View						Load JPG	☒	
6	18/01/19 15:37	General View						Load JPG	☒	
7	18/01/19 15:37	General View						Load JPG	☒	
8	18/01/19 15:37	General View						Load JPG	☒	
9	18/01/19 15:37	General View						Load JPG	☒	
10	18/01/19 15:37	General View						Load JPG	☒	
11	18/01/19 15:37	General View						Load JPG	☒	
12	18/01/19 15:37	General View						Load JPG	☒	
13	18/01/19 15:37	General View						Load JPG	☒	
14	18/01/19 15:37	General View						Load JPG	☒	
15	18/01/19 15:37	General View						Load JPG	☒	
16	18/01/19 15:37	General View						Load JPG	☒	
17	18/01/19 15:37	General View						Load JPG	☒	
18	18/01/19 15:37	General View						Load JPG	☒	
19	18/01/19 15:37	General View						Load JPG	☒	
20	18/01/19 15:37	General View						Load JPG	☒	
21	18/01/19 15:37	General View						Load JPG	☒	
22	18/01/19 15:37	General View						Load JPG	☒	
23	18/01/19 15:37	General View						Load JPG	☒	
24	18/01/19 15:37	General View						Load JPG	☒	
25	18/01/19 15:37	General View						Load JPG	☒	
26	18/01/19 15:37	General View						Load JPG	☒	
27	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
28	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
29	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
30	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
31	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
32	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
33	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
34	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
35	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
36	11/04/19 15:48	Reinspection Photo						Load JPG	☒	
37	11/04/19 15:48	Reinspection Photo						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/04/19 15:48	Reinspection Photo	 Load JPG	☒
39	11/04/19 15:48	Reinspection Photo	 Load JPG	☒
40	11/04/19 15:48	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/12/18 15:05	REPAIR EST	 Load PDF	
2	19/12/18 15:05	TP GIA	 Load PDF	
3	27/12/18 16:02	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/19 09:41	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2018		19 Dec 2018 15:05 Edit Adj Rpt	S\$10,978.36 Edit Estimates	S\$10,978.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD								
Vehicle Reg. No.:	SLK8391T	Date of Loss:	14/12/2018 00:00 - :59 [22 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05850C02	Policy/Cover Note No.:	DMPCSN3098841700						
Vehicle Reg. No. (Insured):	SGU8871G	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/04/2019]								
Adj Asg. Remarks:	EST \$17,288.10, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPING (08/04/2019): Report Send Back Alerts - SLK8391T (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK8391T (SNM18D05850C02)
[SGU8871G]

TP

HITACHI CAPITAL ASIA PACIFIC PTE LTD

Dec 14 2018 12:00AM

[-]

Wearnes Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	18/01/19 15:37	General View								Load JPG	☒	
2	18/01/19 15:37	General View								Load JPG	☒	
3	18/01/19 15:37	General View								Load JPG	☒	
4	18/01/19 15:37	General View								Load JPG	☒	
5	18/01/19 15:37	General View								Load JPG	☒	
6	18/01/19 15:37	General View								Load JPG	☒	
7	18/01/19 15:37	General View								Load JPG	☒	
8	18/01/19 15:37	General View								Load JPG	☒	
9	18/01/19 15:37	General View								Load JPG	☒	
10	18/01/19 15:37	General View								Load JPG	☒	
11	18/01/19 15:37	General View								Load JPG	☒	
12	18/01/19 15:37	General View								Load JPG	☒	
13	18/01/19 15:37	General View								Load JPG	☒	
14	18/01/19 15:37	General View								Load JPG	☒	
15	18/01/19 15:37	General View								Load JPG	☒	
16	18/01/19 15:37	General View								Load JPG	☒	
17	18/01/19 15:37	General View								Load JPG	☒	
18	18/01/19 15:37	General View								Load JPG	☒	
19	18/01/19 15:37	General View								Load JPG	☒	
20	18/01/19 15:37	General View								Load JPG	☒	
21	18/01/19 15:37	General View								Load JPG	☒	
22	18/01/19 15:37	General View								Load JPG	☒	
23	18/01/19 15:37	General View								Load JPG	☒	
24	18/01/19 15:37	General View								Load JPG	☒	
25	18/01/19 15:37	General View								Load JPG	☒	
26	18/01/19 15:37	General View								Load JPG	☒	
27	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
28	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
29	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
30	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
31	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
32	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
33	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
34	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
35	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
36	11/04/19 15:48	Reinspection Photo								Load JPG	☒	
37	11/04/19 15:48	Reinspection Photo								Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/04/19 15:48	Reinspection Photo	 Load JPG	☒
39	11/04/19 15:48	Reinspection Photo	 Load JPG	☒
40	11/04/19 15:48	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/12/18 15:05	REPAIR EST	 Load PDF	
2	19/12/18 15:05	TP GIA	 Load PDF	
3	27/12/18 16:02	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/04/19 09:41	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18022772/T1TD3E2

Date: 12/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3098841700

Claimant Vehicle
No: SLK8391TInsured Vehicle
No: SGU8871G

Date of Loss: 14/12/2018

Nature of Claim: TP

Claim
No: SNM18D05850C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK8391T

Make & Model: JAGUAR XE, 2.0 (A)

Reg. Date: 31/01/2017 (Man. Year: 2016)

Colour: Blue

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 160518W0100204DTD

Chassis No: SAJAB4AN7HCP00318

Odometer: 56764 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,031.21	4,842.36	3,188.85	39.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,286.00	6,136.00	2,150.00	25.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,317.21	10,978.36	5,338.85	32.72
+ GST 7.00/7.00% (S\$)	1,142.20	768.49	373.71	32.72
Nett Amount (S\$)	17,459.41	11,746.85	5,712.56	32.72

INSPECTION

Date of Assignment: 19/12/2018

Date Inspected: 20/12/2018 Inspected At:

Wearnes Automotive Pte Ltd (Leng Kee)
28 Leng Kee Road
Singapore 159105

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2019)
Parts: 143	JAGUAR XE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLK8391T)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL RHF XE	Bent	1,492.30 FS	*1,343.07 FS
2	2		*SOUND DEADENING PAD	Necessary	500.00 FS	*450.00 FS
3	1		*DOOR PANEL RHR XE	Bent	1,824.10 FS	*1,641.69 FS
4	1		*JT4N13770LML/MOUL DIN	Necessary	549.50 FS	*494.55 FS
5	1		*DOOR FINISHER RH FRT	Not Necessary	316.60 FS	*- FS
6	1		*DOOR FINISHER RH FRT	Not Necessary	256.50 FS	*- FS
7	1		*FINISHER CHROME C PI	Not Necessary	264.40 FS	*- FS
8	1		*DOOR FINISHER RH REA	Not Necessary	263.90 FS	*- FS
9	1		*SEAL-DOOR FRT	Necessary	232.30 FS	*209.07 FS
10	1		*SEAL-DOOR REAR	Necessary	207.10 FS	*186.39 FS
11	1		*HANDLE-DOOR FRT	Distorted	397.20 FS	*357.48 FS
12	1		*HANDLE-DOOR REAR	Not Necessary	397.20 FS	*- FS
13	1		*LATCH	Not Necessary	620.90 FS	*- FS
14	1		*ADHESIVE SEALER FL2	Not Necessary	549.10 FS	*- FS
15	1		*BEZEL	Necessary	41.31 FS	*41.31 FS
16	1		*BUMPER NUT XF (30PCS)	Necessary	118.80 FS	*118.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,031.21	4,842.36
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRT RH DOOR, REAR RH DOOR, RH ROCKET PANEL, RH DOOR HANDLE, ETC	New	3,600.00	2,250.00
2	TO PUTTY SPRAYPAINT ON FRT RH DOOR, REAR RH DOOR, RH ROCKET PANEL, ETC	New	3,200.00	2,400.00
3	TO TRANSFER FRT RH DOOR PART	New	500.00	500.00
4	TO TRANSFER REAR RH DOOR PART	New	500.00	500.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	486.00	486.00
Gross Labour Cost (S\$)			8,286.00	6,136.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >