

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 4517K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	TAILLAMP ASSY (LH/RH) @\$250.00 (WCP)	O/S CRACKED	500.00	250.00
1	REAR NUMBER PLATE LAMP (WCP)	CRACKED	75.00	75.00
	COST PLUS 15%		86.25	48.75
			661.25	373.75
<u>SPECIAL NETT ITEMS</u>				
1	TAILGATE (SN)	NOT NECESSARY	2,500.00	-
2	TAILGATE '60KM/H' STICKER @\$25.00 (SN)	NOT NECESSARY	50.00	-
1	TAILGATE '40PAX' STICKER (SN)	NOT NECESSARY	25.00	-
2	TAILGATE RUBBER STOPPER (LH/RH) @\$250.00 (SN)	O/S CRACKED	500.00	250.00
1	REAR NUMBER PLATE (SN)	DENTED	40.00	20.00
1	REAR NUMBER PLATE BRACKET (SN)	TO REPAIR SEE LABOUR	100.00	-
1	REAR REINFORCEMENT (SN)	BENT	1,200.00	1,200.00
1	RIGHT REAR TOOL BOX (LOCAL REPAIR) (SN)	DENTED	1,200.00	250.00
			5,615.00	1,720.00
<u>LABOUR</u>				
	TO REMOVE,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR NUMBER PLATE BRACKET.		500.00	350.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		600.00	360.00
	TO FOCUS TAILLAMPS .TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	20.00
			1,150.00	730.00
GRAND TOTAL			7,426.25	2,823.75

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	-----------------

Report Ref No. CC4/LPC18022789/Kds3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.