5	Monmon	Kenneth	ASSIGNMEN		1.0	110	1	
		Ong chin kiat	of	CTI	1	100 Della 100 100 100 100 100 100 100 100 100 10	11.31cm	
	Estimated Cos			Bill to:				
	To hispect Ve	/TP RES / OD RES /) hicle No:_	SLM 366	-	Insured:	GBJ HOC		
	at Workshop r	n/sCh	ew Goon Mot	or	Tel:	6484 1626		
	of		Id Pork 2A #	01-15/16				
	Policy No:	DMCVSN18380		Claim No:	SNM	UR DUS815C02		
	Sum Insured_			Excess:				
	Make of Vch. (Client's Record)		5		0.0.A 15/12/2018	3 .	
	CA / REV	REP. / REV 24 HRS	lup)			H.O.D. Endorsement:	•	
	Date/Time: 1	Date/Time: 11:44am 20/12/18 Person Contacted: Gruce Vehicle POTT						
	Date/Time	Action/lestruction (✓ Estimate					
		SLM 3663G-2	×					
		GB5140C-X						
	716	872101		2 - 1				
	Pil	8251Pd-3 (\$9,687.	o emoil	x consin	me!		-	
		1 39 /27	20 01	28/				

- -

4881GNMENT

From Date 20 12 18 Estimated Cost	Veh No SIM 3663G Yr Regn 03 17 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or A) Wages 100
To Inspect Vehicle No. SLM 3663G	Make: New GLC 250 G.G. 1991
at Workshop m/s Chew Guon Motor	Colour 19-13 IRCK
Blk 10, AMR Ind. Park 2A # 01-15/16	Sp. Reading 380 % T/Radio: Insured / Std / NI / NA
Insured 4	Eng/No:
Policy No.	CINO WOC 2539 462 F-147867
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured Excess:	Steering: Inerder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh.	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: 235/60RI8
Remark. The yeh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FT SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal, or Market Value:	Front O Rear O
IDAC Accident Rport: Consistent? : Yes or No.	R/Bal. C mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal.
Est Repairs: 10 Gd days Res.: Yes or No	D.O.A. 15/12/18 D.O.I. 20/12/18
Lum Sum: /- R / % 3 Val.: Yes or No	Survey held at
lup	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS \ Vehicle: IN / OUT	4 150
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
/12 Fle pass to Corton	
RECEIVED	1 1 JUN 2019
KLOC.	
Cute/Time, File Pass/6? : Prell. Report	Days Of Repair: /O
11/06/19 Einal Papart	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation
2) Add Fee	2: Site Insp (\$)s+R8Si
	: Interview (\$) Photos
Report Format :	Tech, Invs (\$) Others
Lump Sum (1.B.1) (\$ 25, 198.50 p/p)	Weekend (\$ >) - 210
	TOTAL

...CLAIM SUBFOLDER...(New Assignment)

AIM SUBFO	LDER TRA	CKING			Tarren	744 - 4	Ins Auth'ed	Status		
Case No	tified	Est Submitted	Adj Assigned	Adj Rpt	Adj Subr	nitted	Ins Auth ed		2 82	
Main 20	Dec 2018		20 Dec 2018 11:31 Assign					Cancel Ca	A CONTRACTOR OF THE PARTY OF TH	
Ма	in	Re	ference		Claim Details	\Box	Documer	nts	Sh	ow All
CLAIM SUBF	OLDER DE	TATIS	COMPANDADO COMPANDA	NAME OF TAXABLE PARTY.	The state of the s	[Create	d by insurer]			
Insured:	M/S GR B	SUILDING & CON	STRUCTION PT	ELTD, Co	, Reg. No.: 2015	28049W				
Main Claimant:		HYGIENE SERVIC								
Vehicle Reg. No.:	SLM366	3G			Date of Loss:	15/12/20	018 19:00 - :59			
Claim Type:	TP / SNI	M18D05815C02			Policy/Cover Note No.:	DMCVSN	11838601800 (Co	mprehensive))	
Vehicle Reg. No. (Insured):	GBJ140C				Policy No. (Claimant):	5098369	53			
(Insureu).					Excess:	S\$0.00				666
Repairer:	Chew Go 64841626	on Motor (AMK)	Blk 10 Ang Mo k	(io Industria	l Park 2A, #01-15	5/16 & 17,	, AMK Autopoint,	568047 Ang 1	Mo Kio - 1	el:
Handling Insurer:	China Ta	iping Insurance	(Singapore) Pt	e. Ltd. (HÇ) - Tel: 6389 611	1 [Han	dled by Ong Chi	n Kiat]		
Claimant's Insurer:		come Insurance								
Adjuster:	LKK Auto	Consultants Pto	Ltd (HQ) - Tel	: 6256-356	[Final Rpt	due 02/	01/2019]			
Driver/Custo dian (Insured):	MD RABIU	JAL ISLAM MD SAI	DER ALI BISWAS	(36 / Male)), NRIC: G7280	445M, T	el: +6594687625			
Adj Asg. Remarks:	NO EST, O	CASE WITH SJE.						acu-		
ASSOCIATE	D MAIL R	ECEIVED						View All	Compose	Case Ma
There are no	mail for thi	s case.								
ALL ASSOC	TATED TA	sks ⁼				View A	All Search Tasks	Create Ne	w Task	Comple
Due Date			Group Sul	oject Ha	indler Assig	ned By	Completed (On Crea	sted On	Don
No results.	1.100.00		DELINOSTRATOR DE SONOTO	arcesten add						

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Vernete
Owner ID Type:	Company
Owner ID: Vehicle Details	2717H
Vehicle No.:	SLM3663G
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLC250 4MATIC AUTO
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	27492030808082
Chassis No.:	WDC2539462F147467
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$42,921.00
Original Registration Date:	03 Mar 2017
First Registration Date:	03 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$52,090.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2027
PARF Rebate Amount:	\$39,067.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,621.00
COE Rebate Amount:	\$41,533.00
Total Rebate Amount:	\$80,600.00

The information contained herein is correct as at 17 Dec 2018



MCGM18162189 / Chew Goon Motor - AMK ENTRY DATE & TIME: 17/12/2018 15:07 SUBMITTED BY: Liu Yan Jing

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT	STAT	ΈM	ENT
----------	------	----	-----

Date Of Report

17/12/2018 15:07

Date Of Accident

15/12/2018 19:05

Exact Location Of Accident

MOULMEIN RD SLIP RD TOWARDS CTE

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLM3663G

Insured/Policyholder

Name Of Registered Owner

RENTAL HYGIENE SERVICES PTE LTD

Co Reg No

200202717H

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No

OFFICE-64811300

Vehicle Particulars

Manufacturer

MERCEDES-BENZ

Model

GLC250 4MATIC AUTO

Exact Purpose for which vehicle was being used at PRIVATE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

COMPREHENSIVE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

Fleet Policy

NO

Policy Number

5098369553

Cover Note Number

Driver

Name of Driver

GOH CHOON KWEE

NRIC No Date Of Birth S1566557B

Occupation

01/05/1962

Date Of Driving Pass

INDOOR

15/05/1980

Driving Experience

38 YEARS AND 7 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-96801543

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 29A ADAM ROAD #02-12

Postcode

289902

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

•

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

120

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: MDM KOH

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 15/12/2018 AT AROUND 1905HRS, I WAS DRIVING ALONG SLIP ROAD TOWARDS CTE, IT WAS RAINING, MY FRONT VEHICLE C (SJQ2358Y) STOPPED, I ALSO STOPPED, WITHIN A SECOND, SUDDENLY VEHICLE B (GBJ140C) KNOCKED BANG ONTO MY VEHICLE A (SLM3663G) REAR AND MY VEHICLE MOVED FORWARD AND HIT VEHICLE C (SJQ2358Y) AND VEHICLE C (SJQ2358Y) HIT VEHICLE D (GBG8412G).

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBJ140C

Vehicle Make/Model/Colour

Details Of Properties Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

MD RABIUAL ISLAM MD SADER ALI BISWAS

NRIC/Passport Number

G7200445M

Contact Number

92262484

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJQ2358Y

Vehicle Make/Model/Colour

KIA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

HIU KIAN QUAN

NRIC/Passport Number

S8318289Z

Contact Number

83712705

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GBG8412G

Vehicle Make/Model/Colour

NISSAN

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my dalms;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of onvelopes/mail packages); and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature (If driver is not the policyholder)

Date & Time:


Reporting Centre Name: NRIC/FIN No.: onnel's Signature

r arts the early wanter Ma


Sketch Plan #2

CTE B: GBJ 14 C: STD 23 D: G66 84 C: STD 23 D: G66 84 Slip trad toward CTE It was raining. My front vehicle C stopped, I also stopped, within a cocond, saddenly vehicle B trusted, bang outs my vehicle har and my vehicle moved forward and let vehicle C and Vehicle C hit vehicle D		TWO DAY
CTE C:STQ23 C:STQ23	Roun	
CTE C:STQ23 C:STQ23		A:54m36
CRIBE CIRCUMSTANCES OF THE ACCIDENT On 15/12/2018 at about 0705, 1 was driving a long slip trad toward CTE. It was raining. My front vehicle C stapped, 1 also stopped, within a court which suddenly vehicle B knowled, Board out my rehicle normal forward and let vehicle C and Vehicle C hit vehicle P ARATION ARATION		8 48314
CRIBE CIRCUMSTANCES OF THE ACCIDENT On 15/12/2018 at about 0705, 1 was driving a long slip trad toward CTE. It was raining. My front vehicle C stapped, 1 also stopped, within a court which suddenly vehicle B knowled, Board out my rehicle normal forward and let vehicle C and Vehicle C hit vehicle P ARATION ARATION	(C:STQ28
CRIBE CIRCUMSTANCES OF THE ACCIDENT On 15/17 2018 at about 0701, 1 was driving a long slip trad toward CTE. It was raining. My front vehicle C stapped, 1 also stopped, noting a second, suddenly vehicle B tracked, Bane out in any vehicle moved forward and bit vehicle C and Vehicle C hit vehicle D ARATION Indeptre the foregoing particulars are true in every respect. ARATION Indeptre the foregoing particulars are true in every respect. ARATION Indeptre the foregoing particulars are true in every respect. ARATION Indeptre the foregoing particulars are true in every respect. ARATION Reporting Centre the sorner's signature. Reporting Centre the sorner's signature.		
On 15/12/2018 ast about 070t, I was driving a long slip trad toward CTE It was raining. My front vehicle C stapped, I also stopped. Nithing a cocond, saddlendy vehicle B knowled, bang out my vehicle ray and my vehicle moved forward and let vehicle C and Vehicle C hit wehicle P ARATION Bestere the foregoing particulars are true in every respect. Bestere the foregoing particulars are true in every respect.		
On 15/12/2018 ast about 070t, I was driving a long slip trad toward CTE It was raining. My front vehicle C stapped, I also stopped. Nithing a cocond, saddlendy vehicle B knowled, bang out my vehicle ray and my vehicle moved forward and let vehicle C and Vehicle C hit wehicle P ARATION Bestere the foregoing particulars are true in every respect. Bestere the foregoing particulars are true in every respect.		
Slip stoad toward CTE It was raining. My front vehicle C stopped, I also stopped. Noting G cocond, saddbardy vehicle B knoward, bang outs my vehicle nav and my vehicle moved forward and let vehicle C and Vehicle C hit vehicle D ARATION Bestre the foregoing particulars are true in every respect. Driver's Signature Driver's Signature Reporting Centre Personnel's Signature	CRIBE CIRCUMSTANCES OF	THE ACCIDENT
Slip stoad toward CTE It was raining. My front vehicle C stopped, I also stopped. Noting G cocond, saddbardy vehicle B knoward, bang outs my vehicle nav and my vehicle moved forward and let vehicle C and Vehicle C hit vehicle D ARATION Bestre the foregoing particulars are true in every respect. Driver's Signature Driver's Signature Reporting Centre Personnel's Signature		
Slip stoad toward CTE It was raining. My front vehicle C stopped, I also stopped. Noting G cocond, saddbardy vehicle B knoward, bang outs my vehicle nav and my vehicle moved forward and let vehicle C and Vehicle C hit vehicle D ARATION Bestre the foregoing particulars are true in every respect. Driver's Signature Driver's Signature Reporting Centre Personnel's Signature	On 15/12/2	2018 at about 070t, I was driving a long
ARATION lactore the foregoing particulars are true in every respect. Reporting Centre Personner's Signature Reporting Centre Personner's Signature Reporting Centre Personner's Signature Reporting Centre Personner's Signature	Slip toat to	oward CTE. It was raining.
ARATION Batter Briver's Signature Driver's Signature Reporting Center-Provonce's Signature	My front ve	
ARATION lactare the foregoing particulars are true in every respect. ARATION lactare the foregoing particulars are true in every respect. ARATION Reporting Centre Personnel's Signature Reporting Centre Personnel's Signature	a second, s	addenly vehicle B knowled, bong outs
ARATION lecture to foregoing particulars are true in every respect. Driver's Signature Reporting Centre Per'sonnoi's Signature Reporting Centre Per'		
ARATION Isoclare the foregoing particulars are true in every respect. ARATION Indicates Signature Driver's Signature Reporting CentrePersonnel's Signature		
actare the foregoing particulars are true in every respect. Reporting Centre Personnel's Signature Reporting Centre Personnel's Signature	-(11 444	by a stop young a stop young y
actare the foregoing particulars are true in every respect. Reporting Centre Personnel's Signature Reporting Centre Personnel's Signature	ALEST TERMINATED AND ADDRESS OF THE PARTY OF	
actare the foregoing particulars are true in every respect. Reporting Centre Personnel's Signature Reporting Centre Personnel's Signature		
actare the foregoing particulars are true in every respect. Reporting Centre Personnel's Signature Reporting Centre Personnel's Signature		
actare the foregoing particulars are true in every respect. Reporting Centre Personnel's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
actare the foregoing particulars are true in every respect. Reporting Centre Personnel's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
Reporting Centre Personnel's Signature Driver's Signature Reporting Centre Personnel's Signature		
nider's Signature Reporting Centre Personnel's Signature		
And the second of the second o	ARATION	
And the second of the second o		are true in every respect
Control of the contro		are true in every respect.
	lecture the foregoing particulars	(John) 20











Certificate of Insurance

Certificate Number: 5098369553	Cover : drivo PREMIUM
MOTOR VEHICLES [THIRD PARTY RISKS] RULES, 1959.	(MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPEN ROAD TRANSPORT ACT, 1987 (MALAYSIA)	ISATION) RULES, 1960
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPEN	

Certificate Number: 5098369553

1. Index mark and Registration Number of Vehicle Chassis Number

2. Name of Policyholder 3. Effective Date of Insurance

4. Expiry Date of Insurance

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

: SLM3663G

: 03 Mar 2018

: 02 Mar 2019

: WDC2539462F147467

: RENTAL HYGIENE SERVICES PTE LTD

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	± \$\$600
EXCESS (SECTION 2)	⇒ N/A
WINDSCREEN EXCESS	3, \$\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	g YES
INSURE WITH COE	St. YES
NCD PROTECTION	⇒ NO
TRANSPORT ALLOWANCE	₹ NO
EXCESS WAIVER	3 NO
PRIMARY DRIVER	s N/A
NAMED DRIVER (1)	i N/A
NAMED DRIVER (2)	1 N/A
HIRE PURCHASE COMPANY	₹ N/A
SUM INSURED	MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: ABWIN PTE LTD (00000614234)

Date of Issue

23 Feb 2018 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notharke Reserve, B& paint 8 25198:50 China Taiping Insurance (S) Pte Ltd 19,12,2018 Date: Accident Date: 15.12.2018

Specialised in Car Painting, Welding, Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及 代理各种车辆赔偿

数 量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 額 \$ cts
	Estimate Cost of Repair to "Mercedes GLC250" Reg. No.SLM	3663G	
	Claiming Against Your Insured Veh. No. GBJ140C		
100.00	Bonnet By		
1pc	Bonnet Emblem Na —		1970.00
1pc	Bonnet Insulator Clips		72.00
14pcs	O-illo CM	10.00	140.00
1pc	Grille Top Retainers CALLY X FLX	83.00	166.00 X
2pcs	Grille Top Retainer Center CM-	03.00	77.00
1pc	Grille Top Garnish (3 FORT)	65.00	195.00
1pc	Grille Emblem CM	03.00	62.00
1pc	Grille Emblem Housing CM		81.00
1pc 1pc	Grille Garnish CM	1	269.00
4pcs	Grille Mouldings Ma-	70.00	280.00
1pc	Grille Side Air Guide LH	70.00	58.00
2pcs	Headlamps McM	2990.00	5980.00
1pc	Front Bumper Bu-	2770.00	1364.00
12pcs	- 18 Olles 111	10.00	120.00
1pc	Front Bumper Sponge	10.00	315.00
1pc	Front Bumper Reinforcement		452.00
1pc	Front Bumper Center Core	5.20. 555	209.00 390.00
2pcs	Front Bumper Sensors	195.00	\$40000 M. DOMES
1pc	Front Rumper Lower Air Grille		305.00
1pc	Front Bumper Lower Air Grille Moulding		627.00
1pc	Front Bumper Number Plate Holder	600	137.00
1pc	= I D Anti Collucion Sensor		215.00
1pc	Front Bumper Inner Anti Collusion Sensor Module	and the same	1250.00 X
2pcs	Front Bumper Sensor Holders	pa 15.00	30.00
1pc	Tailgate Br-	11/12	2720.00
1pc	Tallgate Glass Moulding		121.00
1pc	Tailgate Emblem	1	54.00 101.00
1pc	Tailgate Badge 'GLC' 124		98.00
1pc	Tailgate Badge '250'		102.00
1po	Tallgate Badge '4 Matic'	1	26.00
1pc	Tailgate Number Plate Lamp CM— Tailgate Lamps Sum MscM 4	554 00	1112.00-4
2pcs		556.00	
2pcs	Tallgate Lamp Gaskets	21.00	343:88 ×
1pc			395.00
1pc	Tailgate Weatherstrip		
	**	C/F	20,116.00 .

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To:_	China Taiping Insurance (S) Pt	e Ltd	Policy No:	THIRD PARTY
85			Date:	19.12.2018
-	Accident Date : 15.12.2018	0		
	Car Painting, Welding,	ESTIMATE		承接汽车烧焊喷漆及

Specia

数 量 Quantity	货 名 DESCRIPTION	单价 Unit Price	银 Amount 額 \$ cts.
	Estimate Cost of Repair to "Mercedes GLC250" Reg. No. SLM36 Claiming Against Your Insured Veh. No. GBJ140C	663G	
	909 CO 1	B/F	20,116.00-
1pc 10pcs 1pc 1pc 1pc 1pc	Tailgate Trim Board Tailgate Trim Board Clips Tailgate Auto Lift Mechanism Tailgate Inner Locking Motor Tailgate Lower Trim Board Rear Bumper Tailgate Trim Board Tailgate Lower Trim Board Tailgate Lower Trim Board	10.00	423.00 150.00 1880.00 X 553.00 142.00 932.00
12pcs 2pcs	Rear Bumper Clips Rear Bumper Brackets X R	10.00	120.00
1pc 1pc 1pc	Rear Bumper Reinforcement Rear Bumper Center Core Rear Bumper Top Cover	34.00	68.00 × 776.00 145.00
2pcs	Rear Bumper Top Cover Top Retainers	46.00	302.00 92.00
2pcs	Rear Bumper Top Cover Corner Holders	75.00	150.00
2pcs	Rear Bumper Sensors 1401—	188.00	376.00
6pcs 1pc 1pc 1pc	Rear Bumper Sensor Holders Rear Bumper Sensor Wiring Harness Rear Bumper Reflector LH Rear Bumper Tow Cover	15.00	90.00 218.00 32.00 60.00
1pc 2pcs 1pc	Rear Bumper Lower Diffuser Cover (Chrome) Rear Bumper Lower Exhaust Finishers (Chrome) Rear Bumper Lower Cover Sux	452.00	495.00 904.00 X 539.00 X
lpc lpc	End Panel Inner Trim Board		342.00 1545.00 × 227.00 × 30,677.00-
	Less 10%		3067.70 - 27,609.30 -
1pc	Front Number Plate	40.	45.00 SN
1pc	Tailgate Glass Sealant	30	1 30.00 311
1pc	Tallgate Glass Fastener To Conduct Front Electrical Check, Reprogram Front Adaptive, Direction Headlamp		180.00 / 0
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		150.00 6
	v.	-	28,084.30

趙源摩哆 Chew Goon Motor Bik 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0485

Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To:_	China Taiping Insurance (S)	Pte Ltd	Policy No:		PARTY	
-			Date:		.2018	
_	Accident Date : 15.12.2018		RESPANISHED			
	Car Painting, Welding, and Insurance Claim.	ESTIMATE		承接汽车烧焊喷漆及 代理各种车辆赔偿		
数 量 Quantity	货 DES	名 CRIPTION	单 价 Unit Price	银 Ai	mount 额 cts.	
	Estimate Cost of Repair to"! Claiming Against Your Insu	Mercedes GLC250" Reg. No. SLM3663 red Veh. No. GBJ140C	G B/F	28,084	. 30	
*	To Dismantle / Replace Tallga	ate Lifting Mechanism With Programming			~160.00 X	
	To Dismantle / Refit Tailgate	Glass	2		160.00 120/	
238	To Dismantle / Transfer Rear / Garnish and Rear Fenders II Facilitate Repair	Spare Tyre Panel Inner Trims Boards nner Trims Boards / Garnish to		n	120.00 🗶	
	To Supply End Panel Body Se	ealant		nn	00.00	
	To Replace Front and Rear P Systems	arking Sensors and Reprogram PDC			180.00 fax	
	To Apply Rust Proofing / Rese / Replaced / Repair Panel	eal Tuff Coating Treatment to Respray			120.00 30	
	Labour Charge - Panel Beatin Chassis Member, Inner Panel End Panel and Parts Replace	g Repairing Of Support Panel, Rear , Spare Tyre Panel Etc. Cnt, Weld	52		1,800.00 / 000	
	To Respray Affected Areas		¥n		1,400.00	
	To Reseal Paint Protection (I	Diamondbrite) to Spray Paint Areas	Total :	32,8	750.00 X	
		LKK Auto Consultanta hence notify the Repairer of the fullowing: To resurvey before/after spray painting: To display damaged part(s) during resurvey: Parts prices are subject to confirmation: Third party survey is on a "Without Prejudics": No illegal modification(s) is allowed: Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Con	id	34	386.36	
		Acknowledged by Repairer	nigotif.			

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼) Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

京富。2 1 一点 网络双方拉

ALT TO STUDY " F PRESCH AMP'A-

THE RESERVE TO SERVE

n i Translat i Nova A. Nova y Tali i Nova A.

China Taiping Insurance (S) Pte Ltd

Third Party

29.01.2018

Accident Date : 15.12.2018

Estimate Cost of Repair to "Mercedes GLC250" Reg. No.SLM3663G Claiming Against Your Insured Veh. No. GBJ140C

			12 TO 12 TO 12
	2 - La Cara Bireta V Mer	10.00	60.00
6pcs	Front Bumper Center Core Rivets	70.00	140.00
2pcs	Front Bumper Side Cores		230.00
1pc	Front Bumper Sensor Wire	206.00	412.00
2pcs	Front Bumper Air Guides	200.00	358.00
1pc	Support Panel Top Panel (Aluminium)	and the consequences	
1100000	The Deard Cline	10.00	150.00
15pcs	Tim Board Clins	10.00	40.00 X
4pcs	Tallgate Lower Triff Board Only	10.00	100.00 1
10pcs	Tailgate Top Trim Board Clips	10.00	40.00
4pcs	Rear Bumper Center Core Rivers	# (TERM 2003)	294.00
2pcs	Rear Bumper Side Cores	147.00	
2pcs	Rear Bumper Lower Holders	54.00	108.00
Sec. 10. 10. 10. 10.	Rear Bumper Inner Auto Boot Sensor Strip Top		139.00
1pc	Rear Bumper Inner Auto Boot Sensor Strip Bottom		139.00
1pc	End Panel Inner Trim Board Clips X	10.00	60.00 X
6pcs	End Panel Inner Tilli Board Clips X		2280.00 -
			228.00 -
	Less 10%		2052.00
			2002.00

LKK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and
is subject to final approval from insurance Company
Acknowledged by Repairer

2052.00 -

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO Not Nothanke Reservey B& paint Sday,

To:_	China Taiping Insurance (S) Pte Ltd	Policy No:	THIRD PARTY
_		-	19.12.2018
	Accident Date : 15.12.2018	Date:	

Specialised in Car Painting, Welding, Panel-Beating and Insurance Claim. 承接汽车烧焊喷漆及代理各种车辆赔偿

数 量	货 名	单价	银 Amount
奴 里 luantity	DESCRIPTION	Unit Price	\$ c
	Estimate Cost of Repair to "Mercedes GLC250" Reg. N Claiming Against Your Insured Veh. No. GBJ140C	Io.SLM3663G	
1pc	Bonnet By	1570 Table 1000 C. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	
1pc	Bonnet Emblem Nei —		/2
14pcs	Bonnet Insulator Clips 14-		
1pc	0.111 (104 -		
2pcs	Grille Top Retainers ALX		
1pc	Grille Top Retainer Center CM-		
1pc	Grille Top Garnish CM —		E
1pc	Grille Emblem CM-		
1pc	Grille Emblem Housing CM		
1pc	Grille Garnish CM-		
4pcs	Grille Mouldings		
1pc	Grille Side Air Guide LH 7		
2pcs	Headlamps McM		
1pc	Front Bumper Bu —	E .	
12pcs	Front Bumper Clips		
1pc	Front Bumper Sponge 7		
1pc	Front Bumper Reinforcement		
1pc	Front Bumper Center Core ?	1	
2pcs	Front Bumper Sensors		
1pc	Front Bumper Lower Air Grille		
1pc	Front Bumper Lower Air Grille Moulding		
1pc	Front Bumper Number Plate Holder		
1pc	Front Bumper Inner Anti Collusion Sensor		
1pc	Front Bumper Inner Anti Collusion Sensor Module 7		
2pcs	Front Bumper Sensor Holders ?		
1pc	Tailgate Br —		
1pc	Tailgate Glass Moulding	LKK Auto Consultants hend	N KINGS
1pc	Tailgate Emblem 14.—	the Repairer of the followin	
1pc	Tailgate Badge 'GLC' 144 —	To resurvey before/alter spray p	
1pc	Tailgate Badge '250'	. To display damaged part(s) duri	
1pc	Tailgate Badge '4 Matic'	 Parts prices are subject to confi 	
1pc	Tailgate Number Plate Lamp CM-	 Third party survey is on a "With 	
2pcs	Tailgate Lamps From Miscan 4	 No illegal modification(s) is allow 	
2pcs	Tailgate Lamp Gaskets	 Supplementary item(s) must be 	resurveyed and
1pc	Tailgate Lock ?	is subject to final approval from	Insurance Company
1pc	Tailgate Weatherstrip		
		Acknowledged by Repairer	
		Signature:	1
		C/F	

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To:	China Taiping Insurance (S) Pte Ltd	Policy No:	THIRD PARTY
5		Date:	19.12.2018
	Accident Date : 15.12.2018	Date.	s
	Car Painting, Welding, and Insurance Claim.		承接汽车烧焊喷漆及 代理各种车辆赔偿
数 量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 額 \$ cts.
	Estimate Cost of Repair to "Mercedes GLC250" Reg. No. SLM Claiming Against Your Insured Veh. No. GBJ140C	136 6 3G	
	Ad 04	B/F	-
1pc 10pcs 1pc	Tailgate Trim Board Clips Tailgate Auto Lift Mechanism		*
1pc 1pc 1pc	Tailgate Inner Locking Motor Tailgate Lower Trim Board Rear Bumper Rear Bumper		200
12pcs 2pcs 1pc	Rear Bumper Clips Rear Bumper Brackets Rear Bumper Reinforcement		:
1pc 1pc 2pcs	Rear Bumper Center Core Rear Bumper Top Cover Rear Bumper Top Cover Top Retainers		-
2pcs 2pcs	Rear Bumper Top Cover Corner Holders Rear Bumper Sensors		-
6pcs 1pc 1pc 1pc	Rear Bumper Sensor Wiring Harness Rear Bumper Reflector LH		
1pc 2pcs 1pc	Rear Bumper Lower Diffuser Cover (Chrome) Rear Bumper Lower Exhaust Finishers (Chrome) Rear Bumper Lower Cover Sux		858
1pc 1pc 1pc	Rear Bumper Inner Boot Sensor ? End Panel End Panel Inner Trim Board ?		
	Less 10%		
1pc 1pc	Front Number Plate Tailgate Glass Sealant		45.00 SN Fa 50.00 SN Fa 50.00 SN 30
1pc	Tailgate Glass Fastener To Conduct Front Electrical Check, Reprogram Front Adaptive,		180.00 1001
	Direction Headlamp To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		150.00 bol
	To Distribute the second		

475.00

C/F

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To:_	China Taiping Insurance (S) Pte Ltd		Policy No:	THIRD PARTY
S-			 Date:	19.12.2018
92	Accident Date : 15.12.2018			
	Car Painting, Welding, and Insurance Claim.	ESTIMATE		承接汽车烧焊喷漆及 代理各种车辆赔偿
数 量 Quantity		き 名 SCRIPTION	单 价 Unit Price	银 Amount 額 \$ cts.
	Claiming Against Your Ins	"Mercedes GLC250" Reg. No. SLM360 ured Veh. No. GBJ140C	33G	
			 B/F	475.00
	To Dismantle / Replace Tail Adjustment	gate Lifting Mechanism With Programmi	ng	160.00 -7
	To Dismantle / Refit Tailgate	e Glass		160.00 120
	To Dismantle / Transfer Rea / Garnish and Rear Fenders Facilitate Repair	ar Spare Tyre Panel Inner Trims Boards s Inner Trims Boards / Garnish to		120.00 7
	To Supply End Panel Body	Sealant		60.00 7
	MISSE.	Parking Sensors and Reprogram PDC		180.00 fee
		eseal Tuff Coating Treatment to Respray		120.00 39
	Labour Charge - Panel Bea Chassis Member, Inner Pa End Panel and Parts Repla	ating Repairing Of Support Panel, Rear nel, Spare Tyre Panel Etc. Cnt, Weld accement		1,800.00 ?
	To Respray Affected Areas			1,400.00
	To Reseal Paint Protection	(Diamondbrite) to Spray Paint Areas	Total:	750.00 7 5,225.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18022823/KSD3N2

Date:

12/06/2019

REFERENCE

Handling Insurer: Claimant China Taiping Insurance

(Singapore) Pte. Ltd.

SLM3663G

Vehicle No:

15/12/2018

Policy No:

DMCVSN1838601800

Insured Vehicle GBJ140C No:

Claim:

Nature of

TP

Claim No:

SNM18D05815C02

27492030808082

38046 km

WDC2539462F147467

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLM3663G

Make & Model:

Date of Loss:

MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)

03/03/2017 (Man. Year: 2016)

Reg. Date: Colour:

Metallic Black 1991 cc

Engine Capacity: Market Value/New Car

Price:

N/A

Market Value/New Car Price

Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

Front Left Side:

235/60R18 Pirelli 8 mm

Pirelli 8 mm

Rear Tyre Size:

Rear Left Side: Rear Right Side: 235/60R18

Pirelli 8 mm Pirelli 8 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 29,806.30 0.00	Adjuster's 22,808.50 0.00	Difference 6,997.80 0.00	Diff % 23.48
Labour Paintwork Labour	5,080.00 0.00	2,390.00 0.00	2,690.00 0.00	52.95
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,886.30	25,198.50	9,687.80	27.77
+ GST 7.00/7.00% (S\$)	2,442.04	1,763.90	678.14	27.77
Nett Amount (S\$)	37,328.34	26,962.40	10,365.94	27.77

INSPECTION

Date of Assignment:

20/12/2018

Date Inspected:

20/12/2018 Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint

Singapore 568047

Estimated Period of Repair:

10.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	е
-----------	---

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jun 2019)

Parts: M1-SUV MERCEDES-BENZ GLC 250 2.0 4MATIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM3663G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent		*1,970.00 FL
2	1		*BONNET EMBLEM	Necessary	72.00 FL	*72.00 FL
3	14		*BONNET INSULATOR CLIPS	Necessary	140.00 FL	*140.00 FL
4	1		*GRILLE	Cracked	262.00 FL	*262.00 FL
5	2		*GRILLE TOP RETAINERS	Serviceable	166.00 FL	*-FL
6	1		*GRILLE TOP RETAINER CENTER	Cracked	77.00 FL	*77.00 FL
7	3		*GRILLE TOP GARNISH	Cracked	195.00 FL	*195.00 FL
8	1		*GRILLE EMBLEM	Cracked	62.00 FL	*62.00 FL
9	1		*GRILLE EMBLEM HOUSING	Cracked	81.00 FL	*81.00 FL
10	1		*GRILLE GARNISH	Cracked	269.00 FL	*269.00 FL
11	4		*GRILLE MOULDINGS	Necessary	280.00 FL	*280.00 FL
12	1		*GRILLE SIDE AIR GUIDE LH	Cracked	58.00 FL	*58.00 FL
13	2		*HEADLAMPS	Mtg Cracked		*5,980.00 FL
14	1		*FRONT BUMPER	Buckled	1,364.00 FL	*1,364.00 FL
15	12		*FRONT BUMPER CLIPS	Necessary	120.00 FL	*120.00 FL
	1		*FRONT BUMPER SPONGE	Cracked	315.00 FL	*315.00 FL
16	1		*FRONT BUMPER REINFORCEMENT	Bent	452.00 FL	*452.00 FL
17 18	1		*FRONT BUMPER CENTER CORE	Cracked	209.00 FL	*209.00 FL
			*FRONT BUMPER SENSORS	Shorted	390.00 FL	*390.00 FL
19	2		*FRONT BUMPER SENSORO *FRONT BUMPER LOWER AIR GUIDE	Cracked	305.00 FL	*305.00 FL
20	1		*FRONT BUMPER LOWER AIR GUIDE MOULDING	Cracked	627.00 FL	*627.00 FL
21	1		*FRONT BUMPER NUMBER PLATE HOLDER	Cracked	137.00 FL	*137.00 FL
22	1		*FRONT BUMPER INNER ANTI COLLUSION SENSOR	Serviceable	215.00 FL	*- FL
23 24	1		*FRONT BUMPER INNER ANTI COLLUSION SENSOR MODULE		1,250.00 FL	*-FL
25	0		*FRONT BUMPER SENSOR HOLDERS	Necessary	30.00 FL	
25 26	2		*TAILGATE	Bent	2,720.00 FL	*2,720.00 FL
27	1		*TAILGATE GLASS MOULDING	Necessary	121.00 FL	
28	1		*TAILGATE EMBLEM	Necessary	54.00 FL	
29	1		*TAILGATE BADGE GLC	Necessary	101.00 FL	
30	1		*TAILGATE BADGE 250	Necessary	98.00 FL	
	1		*TAILGATE BADGE 4 MATIC	Necessary	102.00 Fl	
31	1		*TAILGATE NUMBER PLATE LAMP	Cracked	26.00 FL	*26.00 FL
32			*TAILGATE LAMPS	N/s Cracked	1,112.00 Fl	*556.00 FL
33	1		*TAILGATE LAMP GASKETS	Serviceable	42.00 FI	. *-FL
34	2			Dented	319.00 FI	*319.00 FL
35	1		*TAILGATE LOCK *TAILGATE WEATHERSTRIP	Cut	395.00 FI	*395.00 FL
36	1		*TAILGATE WEATHERSTRIF	Mtg Cracked	423.00 F	*423.00 FL
37 38	1		*TAILGATE TRIM BOARD CLIPS	Necessary	150.00 F	
00	- 4		*TAILGATE AUTO LIFT MECHANISM	Repair	1,880.00 F	
39			*TAILGATE INNER LOCKING MOTOR	Jammed	553.00 F	L *553.00 FL
40 41	1		*TAILGATE LOWER TRIM BOARD	Mtg Cracked	142.00 F	L *142.00 Fl

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition F	Repairer's	Amount
42	1		*REAR BUMPER	Buckled	932.00 FL	*932.00 FL
43	12		*REAR BUMPER CLIPS	Necessary	120.00 FL	*120.00 FL
44	2		*REAR BUMPER BRACKETS	Repair	68.00 FL	*-FL
45	1		*REAR BUMPER REINFORCEMENT	Bent	776.00 FL	*776.00 FL
46	1		*REAR BUMPER CENTER CORE	Cracked	145.00 FL	*145.00 FL
47	1		*REAR BUMPER TOP COVER	Buckled	302.00 FL	*302.00 FL
48	2		*REAR BUMPER TOP COVER TOP RETAINERS	Distorted	92.00 FL	*92.00 FL
			*REAR BUMPER TOP COVER CORNER HOLDERS	Distorted	150.00 FL	*150.00 FL
49	2		*REAR BUMPER SENSORS	Shorted	376.00 FL	*376.00 FL
50	2		*REAR BUMPER SENSOR HOLDERS	Necessary	90.00 FL	*90.00 FL
51	6			Torn	218.00 FL	*218.00 FL
52	1		*REAR BUMPER SENSOR WIRING HARNESS	Cracked	32.00 FL	*32.00 FL
53	1		*REAR BUMPER REFLECTOR LH	Dented	60.00 FL	*60.00 FL
54	1		*REAR BUMPER TOW COVER			*495.00 FL
55	1		*REAR BUMPER LOWER DIFFUSER COVER (CHROME)	Dented	495.00 FL	*-FL
56	2		*REAR BUMPER LOWER EXHAUST FINISHERS (CHROME)	Serviceable	904.00 FL	
57	1		*REAR BUMPER LOWER COVER	Serviceable	539.00 FL	*-FL
58	1		*REAR BUMPER INNER BOOT SENSOR	Shorted	342.00 FL	*342.00 FL
59	1		*END PANEL	Repair	1,545.00 FL	*-FL
60	1		*END PANEL INNER TRIM BOARD	Serviceable	227.00 FL	*-FL
61	6		*FRONT BUMPER CENTER CORE RIVETS	Necessary	60.00 FL	*60.00 FL
62	2		*FRONT BUMPER SIDE CORES	Cracked	140.00 FL	*140.00 FL
63	1		*FRONT BUMPER SENSOR WIRE	Torn	230.00 FL	*230.00 FL
64	2		*FRONT BUMPER AIR GUIDES	Cracked	412.00 FL	*412.00 FL
65	1		*SUPPORT PANEL TOP PANEL (ALUMINIUM)	Dented	368.00 FL	*368.00 FL
66	15		*TAILGATE TRIM BOARD CLIPS	Not Necessary	150.00 FL	*-FL
67	4		*TAILGATE LOWER TRIM BOARD CLIPS	Not Necessary	40.00 FL	*- FL
68	10		*TAILGATE TOP TRIM BOARD CLIPS	Not Necessary	100.00 FL	*- FL
69	4		*REAR BUMPER CENTER CORE RIVETS	Necessary	40.00 FL	*40.00 FL
70	2		*REAR BUMPER SIDE CORES	Cracked	294.00 FL	*294.00 FL
	- 120		*REAR BUMPER LOWER HOLDERS	Cracked	108.00 FL	*108.00 FL
71 72	1		*REAR BUMPER INNER AUTO BOOT SENSOR STRIP TOP		139.00 FL	*139.00 FL
73	1		*REAR BUMPER INNER AUTO BOOT SENSOR STRIP BOTTOM	Cracked	139.00 FL	*139.00 FL
74	6		*END PANEL INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*-FL
75	1		*FRONT NUMBER PLATE	Bent	45.00 FS	
76	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
77	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
	ranchis	e part. S=	SpcNett. L=ListItemDisc.		22 422 22	25 220 00
			- List Item Discount on L Items 10	Sub Total (S\$) .00/10.00% (S\$)		25,330.00 2,521.50
			Pi -	Total Parts (S\$	20 906 20	22,808.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			5926
1	TO DISMANTLE/REPLACE TAILGATE LIFTING MECHANISM WITH PROGRAMMING ADJUSTMENT	New	160.00	0.00
2	TO DISMANTLE/REFIT TAILGATE GLASS	New	160.00	120.00
3	TO DISMANTLE/TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS/GARNISH AND REAR FENDERS INNER TRIMS BOARDS/GARNISH TO FACILITATE REPAIR	New	120.00	0.00
4	TO SUPPLY END PANEL BODY SEALANT	New	60.00	0.00
5	TO REPLACE FRONT AND REAR PARKING SENSORS AND REPROGRAM PDC SYSTEMS	New	180.00	80.00
6	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	120.00	30.00
7	LABOUR CHARGE-PANEL BEATING REPAIRING OF SUPPORT PANEL, REAR CHASSIS MEMBER, INNER PANEL, SPARE TYRE PANEL ETC, CNT, WELD END PANEL AND PARTS REPLACEMENT	New	1,800.00	1,000.00
8	TO RESPRAY AFFECTED AREAS	New	1,400.00	1,000.00
9	TO RESEAL PAINT PROTECTION (DIAMONDBRITE) TO SPRAY PAINT AREAS	New	750.00	0.00
10	TO CONDUCT FRONT ELECTRICAL CHECK, REPROGRAM FRONT ADAPTIVE, DIRECTION HEADLAMP	New	180.00	100.00
11	TO DISMANTLE/REFIT TAILGATE FITTINGS/ANCILLARY ACCESSORIES	New	150.00	60.00
	Gross Labor	ır Cost (S\$)	5,080.00	2,390.00
	Report was unsubmitted duri	na this print-out		

< END OF ESTIMATES >