

趙 源 摩 哆 Chew Goon Motor

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)

Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint

Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

◀ 修理各种汽车敲焊打吗咭喷漆等 ▶

China Taiping Insurance (S) Pte Ltd

Third Party

29.01.2018

Accident Date : 15.12.2018

Estimate Cost of Repair to "Mercedes GLC250" Reg. No.SLM3663G
Claiming Against Your Insured Veh. No. GBJ140C

6pcs	Front Bumper Center Core Rivets	✓ <i>nn</i>	10.00	60.00
2pcs	Front Bumper Side Cores	✓ <i>cm</i>	70.00	140.00
1pc	Front Bumper Sensor Wire	✓ <i>nn</i>		230.00
2pcs	Front Bumper Air Guides	✓ <i>cm</i>	206.00	412.00
1pc	Support Panel Top Panel (Aluminium)	✓ <i>nn</i>		368.00
15pcs	Tailgate Trim Board Clips	X <i>nn</i>	10.00	150.00
4pcs	Tailgate Lower Trim Board Clips	X <i>nn</i>	10.00	40.00
10pcs	Tailgate Top Trim Board Clips	X <i>nn</i>	10.00	100.00
4pcs	Rear Bumper Center Core Rivets	✓ <i>nn</i>	10.00	40.00
2pcs	Rear Bumper Side Cores	✓ <i>cm</i>	147.00	294.00
2pcs	Rear Bumper Lower Holders	✓ <i>cm</i>	54.00	108.00
1pc	Rear Bumper Inner Auto Boot Sensor Strip Top	✓ <i>nn</i>		139.00
1pc	Rear Bumper Inner Auto Boot Sensor Strip Bottom	✓ <i>cm</i>		139.00
6pcs	End Panel Inner Trim Board Clips	X <i>nn</i>	10.00	60.00
				2280.00 -
				228.00 -
				2052.00

Less 10%

Grand Total :

2052.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: