

**PROGRESSIVE CAR CARE
PTE LTD
BLK 3022A UBI ROAD 1
#01-45/46
SINGAPORE 408716
Email:
claims@procarcare.com.sg**

**Claim Reference: TP 1218 - 5336
Assessment Number: PA001776
Version: PROGRESS/1
Date Calculated: 19/12/2018 08:01**

**Full Report - V1
Registration: SMC4820D
Printed: 19/12/2018 16:02**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Wayne Lim	Date of Incident:	17/12/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA

Claim Reference:	TP 1218 - 5336	Estimated Repair Time:	
Policy Number:	GA389708	Quote Due Date:	
Other Reference:	TP 1218 - 5336	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Odyssey
Sub Model:	VTI-L
Model Sheet Number:	HCF 03
Registration:	SMC4820D
Registration Month:	June
Registration Year:	2018
VIN Number:	LFA1907105
Manufacture Year:	2018
Odometer:	Not Known
Colour:	Blue
Engine Number:	H41167219
Fuel Level:	%

Model Specs

FROM MODEL 2015	3 ZONE AUTO AIR CON
CENTRAL LOCKING	FOG LAMPS
LED HEADLAMP	AUTO HEADLAMP LEVEL
LEATHER SEATS	ELEC ADJ DRIVER SEAT
START & STOP SYSTEM	AUTO DIPPING MIRROR
L/ELECT SLIDING DOOR	REAR SUN BLIND
ERM BRAKE ASSIST	PARKING ASSISTANT
REARVIEW CAMERA	2356CCM 129KW
GEARBOX CVT	MULTI FUNC S-WHEEL
TYRES 215/55 VR 17	WHEELS 7J X 17 ALLOY
SUNROOF	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:

Damage Areas:

Severity of Impact:

Vehicle Status on

Inspection:

Date of Inspection: 19/12/2018

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis and no modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- Full approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

PROGRESSIVE CAR CARE PTE LTD

Claim Reference: TP 1218 - 5336
 Assessment Number: PA001776
 Version: PROGRESS/1
 Date Calculated: 19/12/2018 08:01

Full Report - V1
 Registration: SMC4820D
 Printed: 19/12/2018 16:02



Addresses

Repairer

Name : PROGRESSIVE
 Address :
 Post Code :

Cost Summary

Total Labour	\$693.00
Total Paint/Material	\$129.43
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$864.43
7 % GST:	\$60.51
Grand Total Inc GST:	\$924.94

The Assessment Contains Unpriced Parts

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$45.00/HR

Repair /

Guide Number Repair Details

NO NUMBER	RUST PROOFING BODY SHELL PART
NO NUMBER	RIGHT REAR WING CPL RUST PROOFING
2583	REPAIR REAR BUMPER
2586	REPAIR R/R BUMPER CORNER
3482	REPAIR R/R SIDE PANEL

WU	Cost Price (\$)
2.0	9.00
1.0	4.50
30.0*	135.00 ✓
10.0*	45.00 ✓
20.0*	90.00 ✓

LABOUR COST

Total Work Units

63.0

Corrosion Protection

Corrosion Protection External Labour

0.0HRS

0.00

Corrosion Protection Internal Labour

0.3HRS

13.50

Sub Total

6.3HRS

\$283.50

Paint Labour

9.1HRS

\$409.50

Total Labour

15.4HRS

\$693.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

Guide Number Description

	- TWO COAT METALLIC	
	- PREPARE OFF VEHICLE	
2583	REAR BUMPER REPAIR PAINT PLASTIC	15.0
2586	R/R BUMPER CORNER REPAIR PAINT PLASTIC	10.0
3482	R/R SIDE PANEL REPAIR PAINTING <50%	14.0
2585	L/R BUMPER CORNER SURFACE PAINT PLAST.	4.0
2587	FRT TOWING EYE COVERSURFACE PAINT PLAST.	3.0

15.0

10.0

14.0

4.0

3.0

PROGRESSIVE CAR CARE PTE LTD

Claim Reference: TP 1218 - 5336

Assessment Number: PA001776

Version: PROGRESS/1

Date Calculated: 19/12/2018 08:01

Full Report - V1

Registration: SMC4820D

Printed: 19/12/2018 16:02

3113	L/R OUT PARKING SENSSURFACE PAINT PLAST.	3.0	
3114	R/R OUT PARKING SENSSURFACE PAINT PLAST.	3.0	
3115	L/R INN PARKING SENSSURFACE PAINT PLAST.	3.0	
3116	R/R INN PARKING SENSSURFACE PAINT PLAST.	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	58.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	91.0	
	Total Paintwork Labour	9.1HRS	\$409.50
MATERIAL COST - PAINT			
	Surface Paint Plastic		Cost Price
	Repair Painting		\$11.00
	Repair Painting Plastic		\$21.64
	Material-Const Main Work Plastic		\$55.49
	Total Excluding Pearlescent Uplift		\$12.70
	Pearlescent Uplift @ 0.0%		\$129.43
	Total Paint Material Cost		\$0.00
			\$129.43

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
f:		OEM Parts				
g:		Original				
h:		Secondhand				
p:		Parallel				
x:		Exchange				
			Sub Total			\$0.00
			Mark Up From Cost	(15 %)		\$0.00
			Sundry Parts	(Fixed)		\$0.00
			Total Parts			\$0.00

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
	Total Extras	\$42.00

The Assessment Contains Unpriced Parts

Final Calculation

Total Parts		\$0.00
Labour		
Total Panel/Mechanical	\$270.00	
Total Paintwork	\$409.50	
Corr Prot Internal 3 WU	\$13.50	
Total Labour		\$693.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Cost of Specialist	\$42.00	
Total of Additional Costs		\$42.00
Total Paint/Material Costs		\$129.43
Grand Total Excludes GST		\$864.43
GST @ 7 %		\$60.51
Grand Total Includes GST		\$924.94

Assessment Notes

PROGRESSIVE CAR CARE PTE LTD

Claim Reference: TP 1218 - 5336

Assessment Number: PA001776

Version: PROGRESS/1

Date Calculated: 19/12/2018 08:01

Full Report - V1

Registration: SMC4820D

Printed: 19/12/2018 16:02