

ASS. REC. BY:

REF:

es/CT#18022860/R1+d3k

Special Instruction:

Surveyor
Meunien

Rau1

ASSIGNMENT (Office)

From (Person):

Ong chin Kiat

of

CT#

Date/Time: 20/12/18 @ 3:35pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 9020Y

Insured:

PC1143J

at Workshop m/s

Falcon Air

Tel:

6779 5665

of

176 Sin Ming Drive # 01-06

Policy No:

DMB1SN1729511801

Claim No:

SNM18D05864C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/12/2018

CA / REV / REP. / REV 24 HRS

1up

03-01-2018 @ 12pm - 2pm

H.O.D. Endorsement:

Date/Time:

3:36pm @ 20/12/18

Person Contacted:

Andy

Vehicle IN / ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	Insp: No-8 pundan loop (Blk K/1)
	GBG 9020Y - X
	PC1143J - CS/CT#18010559 / 6
	DOA: 6/6/2018
	Confirm Part by Part \$6982.39, 7days
	(Red: 4216.72; 37%)

Signature: *[Signature]*

REF: C71

62524

ASSIGNMENT

From: Date: 03012019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: G86 90204
at Workshop m/s Falcon - Air
of No. 8 Pandan Loop (SikK/1)

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

12pm - 2pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: G86 90204 Yr Regn: 2017 NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI CANTEX FEA 01BA C.C 2998

Colour: WHITE A/C: Insured / Std / NI / NA

Sp.Reading: 46899 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FEA 01BA 2674

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NR / S/Rim / STD A/Rim or

Tyre Size: F: 18 S/75R15

R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 12/12/18 D.O.I. 03/01/19

Survey held at FALCON-AIR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 FEB 2019

Date/Time, File Pass to?

14/2 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) TP 6882.39

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2018		20 Dec 2018 15:35 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	AISA EXEL PTE LTD		
Vehicle Reg. No.:	GBG9020Y	Date of Loss:	18/12/2018 00:00 - :59
Claim Type:	TP / SNM18D05864C02	Policy/Cover Note No.:	DMB1SN1729511801
Vehicle Reg. No. (Insured):	PC1143J	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0880		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/01/2019]		
Adj Asg. Remarks:	EST \$10,885.83, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/12/2018 10:51
Date Of Accident	18/12/2018 08:30
Exact Location Of Accident	JURONG EAST ST 24/ JURONG EAST AVE 1 JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG9020Y
Insured/Policyholder	
Name Of Registered Owner	ASIA EXEL PTE LTD
Co Reg No	200716252H <i>NS</i>
Email Address	SALES@ASIAEXCEL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-98415394

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LORRY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096280406
Cover Note Number	

Driver

Name of Driver	MOHAMED SHAHROUN BIN MOHAMED AYOB
NRIC No	S8219565C
Date Of Birth	13/07/1982
Occupation	OUTDOOR
Date Of Driving Pass	25/11/2004
Driving Experience	14 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98415394
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 843 JURONG WEST ST 81 #06-173
Postcode	640843
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLANS

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC1143J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	YAAKOB BIN MOHD SHARIP
NRIC/Passport Number	S1211494Z
Contact Number	81197954
Address	BLK 980A BUANGKOK CRECENT #06-97
Postcode	531980
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened along Jurong East Ave 1 / Jurong East St 24 junction.


I was travelling along ^{Jurong} East Ave 1 (from Jurong Town Hall toward Jurong East Central) when Vehicle No. PC 1143 J emerged from Jurong East St 24 suddenly, intending to turn right into Jurong East Ave 1, and collided on to the front of my vehicle.

PC 1143 J did not stop at the stop line before proceeding to make a right turn.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



FALCON-AIR

ASIA EXEL PTE LTD
2 JURONG EAST STREET 21 #03-12
IMM BUILDING SINGAPORE 609601

Attention : Motor Claim Department

Contact : 66650107 98415394

Estimate : ES003351

Date : 19/12/2018

Vehicle Num. : GBG9020Y

Make/Model : MITSUBISHI FUSO

Chassis/Eng# : FEA01BA20674

Accident Date : 18/12/2018

Claim No. :

Reference : TP NTUC VS CHN

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT WINDSCREEN GLASS RUBBER <i>neu /</i>		423.66 ✓
2.	1	RH SIDE MIRROR COVER <i>? scu /</i>		38.61 ✓
3.	1	RH SIDE MIRROR GARNISH <i>scu /</i>		18.00 ✓
4.	1	RH CORNER PANEL <i>cha /</i>		506.70 ✓
5.	1	RH SIDE LAMP <i>pro /</i>		222.38 ✓
6.	2	HEADLAMP LH/RH <i>cha /</i>	501.42	1,002.84 ✓
7.	1	FRONT CENTRE PANEL <i>bt /</i>		1,080.65 ✓
8.	1	WIPER PANEL <i>? x scu /</i>		1,290.86 X
9.	1	EMBLEM <i>neu /</i>		154.95 ✓
10.	1	FRONT GRILLE <i>cha /</i>		444.75 ✓
11.	1	FRONT GRILLE LOGO <i>neu x n /</i>		82.45 X
12.	1	HORN <i>neu /</i>		125.41 ✓
13.	1	FRONT BUMPER <i>bt /</i>		795.48 ✓
14.	2	FRONT BUMPER SIDE GARNISH LH/RH <i>scu /</i>		621.40 ✓
15.	2	FRONT BUMPER BRACKET LH/RH <i>? x n /</i>		225.62 X
16.	1	AIRCON /BLOWER/HEATER BOX ASSY (TO CHECK) <i>? x n</i>		2,584.78 X
List TotalS\$:				9,618.54
20.00% Discount S\$:				1,923.71
				7,694.83
SPECIAL NETT ITEMS :				
1.	1	ERP IU BRACKET <i>neu /</i>		26.00 ✓

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

ASIA EXEL PTE LTD
2 JURONG EAST STREET 21 #03-12
IMM BUILDING SINGAPORE 609601

Attention : Motor Claim Department

Contact : 66650107 98415394

Estimate : ES003351

Date : 19/12/2018

Vehicle Num. : GBG9020Y

Make/Model : MITSUBISHI FUSO

Chassis/Eng#: FEA01BA20674

Accident Date : 18/12/2018

Claim No. :

Reference : TP NTUC VS CHN

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1	FRONT NUMBER PLATE <i>PM</i>		35.00 ✓
----	---	------------------------------	--	---------

Special Nett Total S\$:

61.00

LABOUR :

TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM
TO REMOVE/REFIX FRONT WINDSCREEN GLASS
TO RUST PROOF ON ACCIDENT DAMAGED PARTS
TO REMOVE/REFIX FRONT DASHBOARD TO FACILITATE REPAIR
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER
TO REMOVE/REPLACE AIRCON BLOWER ASSY, COOLING/HEATING
BOX, AIRCON PANEL, METER PANEL, STEERING, WIRING, BRAKE
PEDAL, RADIO AND TO RECHARGE IN AIRCON GAS
TO CUT OUT/REWELD FRONT CENTRE PANEL PANEL, REPAIR
FLOOR BOARD, RH FRONT DOOR PILLAR, RH FRONT DOOR, FRONT
CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS

Labour Total S\$:

3,130.00

Handwritten calculations:
~~80~~ ✓ 30.00
~~150~~ ✓ 100.00
~~150~~ ✓ 80
~~250~~ ✓ 200
~~1,300~~ ✓ 800
~~300~~ ✓ 200
~~1,000~~ ✓ 800

E. & O.E.

Total S\$:

10,885.83



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: **FALCON-AIR AUTO SERVICES PTE LTD**

Date: (a subsidiary of Falcon Air Holdings Pte Ltd)

Handwritten notes:
 Same
 Hp 9001.00 68
 7 days
 P/P
 03/01/19 @ 1400
 Reay b p part

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD Supplementary Estimate : ES003389
3 ANSON ROAD #16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Date : 24/01/2019
Vehicle Num. : GBG9020Y
Make/Model : MITSUBISHI FUSO
Chassis/Eng# : FEA01BA20674
Accident Date : 18/12/2018
Claim No. : CTI: SNM18D05864C02
Reference : TP NTUC VS CHN
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS : RH SIGNAL LAMP		266.60 <i>CR</i>
		List TotalS\$:		266.60
		20.00% Discount S\$:		53.32
				213.28



for FALCON AIR AUTO SERVICES PTE LTD

E. & O.E.

Total S\$: 213.28

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

ASIA EXEL PTE LTD
2 JURONG EAST STREET 21 #03-12
IMM BUILDING SINGAPORE 609601Attention: Motor Claim Department
Contact: 66650107 98415394

Estimate: ES003351

Date: 19/12/2018
Vehicle Num: GBG9020Y
Make/Model: MITSUBISHI FUSO
Chassis/Eng#: FEA01BA20674
Accident Date: 18/12/2018
Claim No.:
Reference: TP NTUC VS CHN
Policy No.:

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS:				
1	1	FRONT WINDSCREEN GLASS RUBBER <i>See ✓</i>		423.66
2	1	✓ RH SIDE MIRROR COVER		38.61
3	1	RH SIDE MIRROR GARNISH		18.00
4	1	RH CORNER PANEL		506.70
5	1	RH SIDE LAMP <i>MISSING</i>		222.38
6	2	HEADLAMP LH/RH	501.42	1,002.84
7	1	FRONT CENTRE PANEL		1,080.85
8	1	X WIPER PANEL <i>X</i>		1,290.86 <i>X</i>
9	1	EMBLEM		154.95
10	1	FRONT GRILLE		444.75
11	1	X FRONT GRILLE LOGO <i>X</i>		82.45 <i>X</i>
12	1	HORN		125.41
13	1	FRONT BUMPER		795.48
14	2	FRONT BUMPER SIDE GARNISH LH/RH <i>See ✓</i>	310.70	621.40
15	2	FRONT BUMPER BRACKET LH/RH	112.81	225.62 <i>X</i>
16	1	X AIRCON / BLOWER / HEATER BOX ASSY (TO CHECK) <i>X</i>		2,584.78 <i>X</i>
List Total S\$:				9,618.54
20.00% Discount S\$				1,923.71
				7,694.83
SPECIAL NETT ITEMS:				
1	1	ERP IU BRACKET <i>See ✓</i>		26.00

CONTINUE / ...

SUPPLEMENTARY

RH SIGNAL LAMP (CRACKED) 266.60
(A)

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

ASIA EXEL PTE LTD
2 JURONG EAST STREET 21 #03-12
IMM BUILDING SINGAPORE 609601

Attention: Motor Claim Department
Contact: 66650107 98415394

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-0114
GST REG. NO.: 19-950114

Estimate: ES003351

Date: 19/12/2018
Vehicle Num.: GBG9020Y
Make/Model: MITSUBISHI FUSO
Chassis/Eng#: FEA01BA20674
Accident Date: 18/12/2018
Claim No.:
Reference: TP NTUC VS CHN
Policy No.:

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	FRONT NUMBER PLATE		35.00
		Special Nett Total S\$		61.00
		LABOUR:		
		TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM		30.00
		TO REMOVE/REFIX FRONT WINDSCREEN GLASS	80	100.00
		TO RUST PROOF ON ACCIDENT DAMAGED PARTS		150.00
		TO REMOVE/REFIX FRONT DASHBOARD TO FACILITATE REPAIR	180	250.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		1,300.00
		TO REMOVE/REPLACE AIRCON BLOWER ASSY, COOLING/HEATING		
		BOX, AIRCON PANEL, METER PANEL, STEERING, WIRING, BRAKE		
		PEDAL, RADIO AND TO RECHARGE IN AIRCON GAS		300.00
		TO CUT OUT/REWELD FRONT CENTRE PANEL PANEL, REPAIR		
		FLOOR BOARD, RH FRONT DOOR PILLAR, RH FRONT DOOR, FRONT		
		CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS		1,000.00
		Labour Total S\$:		3,130.00

E. & O.E.

Total S\$ 10,885.83

for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR-AUTO-SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Rame
Up 9001.00 68
7 days
P/P
03/01/19 @ 1400
Ramy by paid

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES003388

Date : 21/01/2019

Vehicle Num. : GBG9020Y

Make/Model : MITSUBISHI FUSO

Chassis/Eng# : FEA01BA20674

Accident Date : 18/12/2018

Claim No. : CTI: SNM18D05864C02

Reference : TP NTUC VS CHN

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT WINDSCREEN GLASS RUBBER		423.66
2.	1	RH SIDE MIRROR COVER		38.61
3.	1	RH SIDE MIRROR GARNISH		18.00
4.	1	RH CORNER PANEL		506.70
5.	2	HEADLAMP LH/RH	501.42	1,002.84
6.	1	FRONT CENTRE PANEL		1,080.65
7.	1	EMBLEM		154.95
8.	1	FRONT GRILLE		444.75
9.	1	HORN		125.41
10.	1	FRONT BUMPER		795.48
11.	2	FRONT BUMPER SIDE GARNISH LH/RH	310.70	621.40
12.	1	FRONT BUMPER BRACKET LH		112.81
13.	1	RH SIDE LAMP (CA)		222.38
List TotalS\$:				5,547.64
20.00% Discount S\$:				1,109.53
				4,438.11
SPECIAL NETT ITEMS :				
1.	1	ERP IU BRACKET		26.00
2.	1	FRONT NUMBER PLATE		35.00
Special Nett Total S\$:				61.00

CONTINUE / ...

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES003388

Date : 21/01/2019
Vehicle Num. : GBG9020Y
Make/Model : MITSUBISHI FUSO
Chassis/Eng# : FEA01BA20674
Accident Date : 18/12/2018
Claim No. : CTI: SNM18D05864C02
Reference : TP NTUC VS CHN
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM		30.00
		TO REMOVE/REFIX FRONT WINDSCREEN GLASS		80.00
		TO RUSTPROOF ON DAMAGED PARTS		80.00
		TO REMOVE/REFIX FRONT DASHBOARD TO FACILITATE REPAIR		180.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		800.00
		TO REMOVE/REFIX AIRCON BLOWER ASSY, COOLING/HEATING BOX		
		AIRCON PANEL, METER PANEL, STEERING , WIRING BRAKE		
		PEDAL, RADIO AND TO RECHARGE IN AIRCON GAS		200.00
		TO CUT OUT/REWELD FRONT CENTRE PANEL, REPAIR FLOOR		
		BOARD, RH FRONT DOOR PILLAR , RH FRONT DOOR , FRONT		
		CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS		800.00
		Labour Total S\$:		2,170.00

E. & O.E.

Total S\$: 6,669.11

=====

SUPPLEMENTARY + 213.28

for FALCON AIR AUTO SERVICES PTE LTD

6882.39

...CLAIM SUBFOLDER...(Pending for Survey Report)





















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2018		20 Dec 2018 15:35 Edit Adj Rpt	S\$6,882.39 Edit Estimates	S\$6,882.39 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: AISA EXEL PTE LTD									
Vehicle Reg. No.: GBG9020Y		Date of Loss: 18/12/2018 00:00 - :59 [12 Months and 20 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05864C02		Policy/Cover Note No.: DMB1SN1729511801							
Vehicle Reg. No. (Insured): PC1143J		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0880									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/01/2019]									
Adj Asg. Remarks: EST \$10,885.83, CASE WITH SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG9020Y (SNM18D05864C02)
[PC1143J]
TP
AISA EXEL PTE LTD
Dec 18 2018 12:00AM
[-]
Falcon-Air Auto Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
2	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
3	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
4	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
5	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
6	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
7	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
8	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
9	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
10	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
11	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
12	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
13	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
14	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
15	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
16	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
17	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
18	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
19	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
20	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
21	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
22	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
23	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
24	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
25	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
26	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
27	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
28	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
29	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
30	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
31	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
32	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
33	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
34	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
35	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
36	14/02/19 16:12	General View							Load JPG	<input checked="" type="checkbox"/>
37	14/02/19 16:24	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/02/19 16:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/12/18 15:34	REPAIR EST	 Load PDF	
2	20/12/18 15:34	TP GIA	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/19 08:36	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18022860/R1TD3E2

Date: 15/02/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1729511801

Claimant Vehicle No: GBG9020Y Insured Vehicle No: PC1143J

Date of Loss: 18/12/2018 Nature of Claim: TP Claim No: SNM18D05864C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG9020Y**

Make & Model: MITSUBISHI CANTER, 3.0 D (A) Engine No: 4P10C77796

Reg. Date: 28/11/2017 (Man. Year: 2017) Chassis No: FEA01BA20674

Colour: White Odometer: 46899 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/75 R15 Rear Tyre Size: 185/75 R15 (D)

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7/7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,969.11	4,712.39	3,256.72	40.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	2,170.00	960.00	30.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,099.11	6,882.39	4,216.72	37.99
+ GST 7.00/7.00% (S\$)	776.94	481.77	295.17	37.99
Nett Amount (S\$)	11,876.05	7,364.16	4,511.89	37.99

INSPECTION

Date of Assignment: 20/12/2018

Date Inspected: 03/01/2019 Inspected At: Falcon-Air Auto Services Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-06, Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Feb 2019)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG9020Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS RUBBER	Necessary	423.66 FL	*423.66 FL
2	1		*RH SIDE MIRROR COVER	Scratched	38.61 FL	*38.61 FL
3	1		*RH SIDE MIRROR GARNISH	Scratched	18.00 FL	*18.00 FL
4	1		*RH CORNER PANEL	Cracked	506.70 FL	*506.70 FL
5	1		*RH SIDE LAMP	Broken	222.38 FL	*222.38 FL
6	2		*HEADLAMP LH/RH	Cracked	1,002.84 FL	*1,002.84 FL
7	1		*FRONT CENTRE PANEL	Bent	1,080.65 FL	*1,080.65 FL
8	1		*WIPER PANEL	Serviceable	1,290.86 FL	*- FL
9	1		*EMBLEM	Necessary	154.95 FL	*154.95 FL
10	1		*FRONT GRILLE	Cracked	444.75 FL	*444.75 FL
11	1		*FRONT GRILLE LOGO	Not Necessary	82.45 FL	*- FL
12	1		*HORN	Not Working	125.41 FL	*125.41 FL
13	1		*FRONT BUMPER	Bent	795.48 FL	*795.48 FL
14	2		*FRONT BUMPER SIDE GARNISH LH/RH	Scratched	621.40 FL	*621.40 FL
15	1		*FRONT BUMPER BRACKET LH/RH	N/S Bent	225.62 FL	*112.81 FL
16	1		*AIRCON / BLOWER / HEATER BOX ASSY	Not Necessary	2,584.78 FL	*- FL
17	1		*ERP IU BRACKET	Necessary	26.00 FS	*26.00 FS
18	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
19	1		*RH SIGNAL LAMP	Cracked	266.60 FL	*266.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,946.14	5,875.24
- List Item Discount on L Items 20.00/20.00% (S\$)	1,977.03	1,162.85
Total Parts (S\$)	7,969.11	4,712.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM	New	30.00	30.00
2	TO REMOVE / REFIX FRONT WINDSCREEN GLASS	New	100.00	80.00
3	TO RUST PROOF ON ACCIDENT DAMAGED PARTS	New	150.00	80.00
4	TO REMOVE / REFIX FRONT DASHBOARD TO FACILITATE REPAIR	New	250.00	180.00
5	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER / OUTER	New	1,300.00	800.00
6	TO REMOVE / REPLACE AIRCON BLOWER ASSY, COOLING / HEATING BOX, AIRCON PANEL, METER PANEL, STEERING, WIRING, BRAKE PEDAL, RADIO AND TO RECHARGE IN AIRCON GAS	New	300.00	200.00
7	TO CUT OUT/REWELD FRONT CENTRE PANEL, REPAIR FLOOR BOARD, RH FRONT DOOR PILLAR, RH FRONT DOOR, FRONT CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS	New	1,000.00	800.00
Gross Labour Cost (S\$)			3,130.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >