

Elite Adjustments (M) Sdn Bhd (Co.Reg.No:108135-H)

60-A, Jalan 30A/119, Taman Taynton View, Cheras
56000 Kuala Lumpur, Wilayah Persekutuan

GST No: 001943150592

Tel: 03-91302111 / 91305111 Fax: 03-91319111 Email: kl@easb.com.my

TAX INVOICE

KAVINJIT SINGH A/L RAJINDER SINGH

NO 428 JALAN MEDAN 23

TAMAN MEDAN

46000 PETALING JAYA

SELSNGOR

Tax Invoice No: JB-1807-0253

Your Ref: N/A

Our Ref: TP/214883/07/18/JB/TCK

Tax Invoice Date: 18-07-18

Claim Type: TP
Vehicle Reg. No.: WJU 3432
Vehicle Make : HYUNDAI
Model : ELANTRA 1.8L (A)
Year Model : 2002

Date of Loss: 19-04-18
Policy/Cover Note No:
Claimant: KAVINJIT SINGH A/L
RAJINDER SINGH

No	Description	Qty	U.Price (RM)	Amount (RM)	GST
1	Adjuster Fee	1	350.00	350.00	0.00%
2	Expenses	1	70.00	70.00	0.00%
3	Travelling	1	70.00	70.00	0.00%
3	Photographs	109	2.00	218.00	0.00%
4	Miscellaneous	1	30.00	30.00	0.00%
5	Merimen	1	10.00	10.00	0.00%
Total before GST:				678.00	
GST 0.00%:				-	
Total after GST:				678.00	

Ringgit Malaysia: SIX HUNDRED SEVENTY EIGHT only

Place of survey : **Soon Hong Motor
Workshop**



ELITE ADJUSTMENTS (M) SDN. BHD.

(108135-H)

No. 60A, Jalan 30A/119, Taman Taynton View
56000 Cheras, Kuala Lumpur.
Tel: 603-91302111, 91305111 Fax: 603-91319111
Email: elitehq@easb.com.my

T.R. N^o 74710

RECEIPT

Date: 18/07/2018

RECEIVED from: Kaviraj Singh Bh Rajinder Singh

the sum of Ringgit: Six hundred Seventy Eight Only.

being payment of: WDU 3432 Gp1 214883/07/18/76/702

RM 678/00
100

Cheque No.

ELITE ADJUSTMENTS (M) SDN. BHD.

Authorized Signatory

N.B. Payments should be made payable in favour to ELITE ADJUSTMENTS (M) SDN. BHD. only by cross
A/C. Payee cheques only, cash payment will not be entertained or recognised



ELITE ADJUSTMENTS (M) SDN. BHD.

(108135-H)

Licensed by Bank Negara Malaysia and Ministry of Home Affairs
PRIVATE INVESTIGATORS, INSURANCE LOSS ADJUSTERS & SURVEYORS

Email: elitehq@easb.com.my

億例有限公司
(調查、保險審估)

Our ref. : TP/214883/07/18/JB/TCK

18 July 2018

KAVINJIT SINGH A/L RAJINDER SINGH
NO 428 JALAN MEDAN 23
TAMAN MEDAN
46000 PETALING JAYA
SELSNGOR

**WITHOUT PREJUDICE
PRIVATE & CONFIDENTIAL**

Dear Sir / Madam,

Re: Assessment Cost of Repair for Accident Vehicle

Make : HYUNDAI
Model : ELANTRA 1.8L (A)
Year Model : 2002
Regn No. : WJU 3432

Pursuant to your instruction, we have proceeded to inspect the condition of the above vehicle at M/S.
Soon Hong Motor Workshop
No 2 Jalan Bayu 2/5
Kawasan Perindustrian Tampoi Jaya
81200 Johor Bahru
Johor.

Assessment Cost of Repairs

Our recommended amount corresponds to Replacement parts, Labour charges, Towing and Spray painting.
The breakdown of which is as follows: -

Replacement Parts	13,010.08
Labour Charges	2,200.00
Spray painting	2,000.00
Towing	150.00

Total Repair Cost (RM)	17,360.08
-------------------------------	------------------

Extent of Damages

Damage sustained to the FRONT & REAR portions.



ELITE ADJUSTMENTS (M) SDN. BHD.

(108135-H)

Licensed by Bank Negara Malaysia and Ministry of Home Affairs
PRIVATE INVESTIGATORS, INSURANCE LOSS ADJUSTERS & SURVEYORS

Email: elitehq@easb.com.my

億例有限公司
(調查、保險審估)

Our ref. : TP/214883/07/18/JB/TCK

Regn No.: WJU 3432

Parts Prices

Parts prices were at current quotation and are subject to change without prior notice. As usual, a 10% trade discount on the parts prices and 40% betterment have been deducted.

Remarks

Nil.

Consistency

Based on the contents of the Police report lodged, the damages appears to be consistent.

Note

Please note that our above recommended figure is merely for you to hold it as a reference of settlement only. We shall not be held responsible for any other consequences which may arise on our above visual inspection of the said damaged vehicle.

Enclosure

Enclosed herewith a set of photographs of the said damaged vehicle and our bill for services rendered for your kind consideration.

Thanking you.

Yours faithfully,

ELITE ADJUSTMENTS (M) SDN.BHD.

Attended by: LIM KOK HIN

Elite Adjustments (M) Sdn.Bhd.(108135-H)

60-A, Jalan 30A/119, Taman Taynton View, 56000 Cheras, Kuala Lumpur.

Tel : 03-91302111 / 91305111 Fax 03-91319111

Email : elitehq@easb.com.my / elitpax1@streamyx.com

VEHICLE INSPECTION REPORT

OUR REF. : TP/214883/07/18/JB/TCK
INSPECTION AT : Soon Hong Motor Workshop
No 2 Jalan Bayu 2/5
Kawasan Perindustrian Tampoi Jaya
81200 Johor Bahru
Johor.
DATE OF INSPECTION : 23 April 2018
THIRD PARTY REGN NO. SHD 4603 T
DATE OF LOSS : 19 April 2018
INSURED : KAVINJIT SINGH A/L RAJINDER SINGH

IDENTIFICATION & DETAILS OF VEHICLE

REGN. NO. : WJU 3432
MAKE : HYUNDAI
MODEL : ELANTRA 1.8L (A)
ENGINE NO. : G4GB1M00950
CHASSIS NO. : MHD01C01220
YEAR : 2002
COLOUR : BEIGE
SPEEDOMETER READING : 136646 Km/h
CUBIC CAPACITY (C.C.) : 1795 c.c.
CARRYING CAPACITY : 5

ACCESSORIES

AIR-CONDITIONER : Yes
WING MIRRORS : Yes
RADIO : Yes
SEAT BELTS : Yes
3RD. BRAKE LIGHTS : Yes

GENERAL CONDITION

PAINTWORK : Good
HANDBRAKES : Good
FOOT BRAKES : Good
STEERING : Good
ENGINE MODIFICATION : Nil

TYRES PERCENTAGE OF REMAINING THREAD

7MM ===|=== 7MM
7MM ===|=== 7MM

Tyre : BRIDGESTONE
Size : 195/60/R15

VEHICLE REPAIRABLE OR BORDERLINE

	Repairer's Estimates	Our Recom mendation
Replacement Parts	23,738.20	13,010.08
Labour	3,760.00	2,200.00
Spray Painting	3,100.00	2,000.00
Towing	300.00	150.00
Total Repair Cost	30,898.20	17,360.08
Different	13,538.12	

ESTIMATED PERIOD FOR REPAIR : app. 18 working days

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



ELITE ADJUSTMENTS (M) SDN. BHD.

(108135-H)

Licensed by Bank Negara Malaysia and Ministry of Home Affairs
PRIVATE INVESTIGATORS, INSURANCE LOSS ADJUSTERS & SURVEYORS

Email: elitehq@easb.com.my

億例有限公司
(調查、保險審估)

No	Item	Description of Replacement Parts	WJU 3432	Condition	Repairer's Estimates	Our Recommendation
1	1pc	Bumper Bracket Front LH		Cracked	14.00	14.00 NH
2	1pc	Bumper Front Cover		Torn	859.00	859.00 ✓
3	1pc	Bumper Front Fog Lamp Finisher LH [Lower]		Cracked	12.10	12.10 NH
4	1pc	Bumper Front Fog Lamp Finisher RH [Lower]		Cracked	12.10	12.10 ✓
5	1pc	Bumper Front Lower Grille		Cracked	83.00	83.00 ✓
6	1pc	Bumper Front Moulding		Dented	112.00	112.00 ✓
7	1pc	Bumper Front Shock Absorber [Foam Type]		Broken	214.00	214.00 ✓
8	1pc	Bumper Reinforcement Front		Dented	466.00	466.00 ✓
9	1pc	Grille Front		Broken	285.00	285.00 ✓
10	1pc	Headlamp Assy LH		Cracked	585.00	585.00 ✓
11	1pc	Headlamp Assy RH		Cracked	585.00	585.00 ✓
12	1pc	Bonnet		Dented	2,040.00	2,040.00 ✓
13	1pc	Bonnet Hinge LH		Bent	43.20	43.20 NH
14	1pc	Bonnet Hinge RH		Bent	43.20	43.20 NH
15	1pc	Front Panel Upper		Dented	250.00	250.00 NH
16	1pc	Washer Tank Windscreen Front		Cracked	88.00	88.00 NH
17	1pc	Windscreen Washer Pump		Broken	84.50	84.50 ✓
18	1pc	Driveshaft Front LH		Bent	1,643.90	1,643.90 NH
19	1pc	Fender Front Liner LH		Cut	113.00	113.00 NH
20	1pc	Knuckle Arm Front LH		Bent	688.00	688.00 ✓
21	1pc	Shock Absorber Front LH		Bent	319.00	319.00 ✓
22	1pc	Suspension Arm Front LH		Bent	650.00	650.00 ✓
23	1pc	Boot Lid Lock		Jammed	63.90	63.90 ✓
24	1pc	Bumper Bracket Rear LH		Cracked	131.00	131.00 ✓
25	1pc	Bumper Rear Cover		Torn	843.00	843.00 ✓
26	1pc	Bumper Rear Moulding		Dented	197.00	197.00 ✓
27	1pc	Bumper Rear Reinforcement		Dented	622.00	622.00 ✓
28	1pc	Bumper Rear Shock Absorber [Foam Type]		Broken	265.00	265.00 ✓
29	1pc	Lamp Assembly Rear LH (tts)		Cracked	362.00	362.00 ✓
30	1pc	Rear Panel Assembly		Dented	725.00	725.00 ✓
31	1pc	Boot Lid		Dented	2,010.00	2,010.00 R
32	1pc	Driveshaft Front RH		Bent	1,643.90	1,643.90 NH
33	1pc	Fender Front Liner RH		Cut	113.00	113.00 ✓
34	1pc	Fender Front RH		Dented	607.00	607.00 R
35	1pc	Knuckle Arm Front RH		Bent	688.00	688.00 ✓
36	1pc	Shock Absorber Front RH		Bent	319.00	319.00 ✓
37	1pc	Suspension Arm Front RH		Bent	634.00	634.00 ✓
38	2pcs	Wheel Rim Alloy (@RM879.10)		Deeply Scratched	1,758.20	1,758.20 ✓
39	1pc	Stabiliser Bar Front		Bent	358.00	358.00 ✓
40	1pc	Steering Tie Rod End		Bent	132.00	132.00 ✓
41	1pc	Subframe Front		Dented/Bent	2,660.00	2,660.00 ✓
Less 0% / 10% trade discount except nett item :					23,322.00	23,322.00
Less 0% / 40% trade discount except nett item					23,322.00	20,989.80
					-	8,395.92
42	1pc	Bumper Rear Sensor		Snapped	23,322.00	12,593.88
43	1pc	Boot Extractor Vent		Cut	351.00	351.00
					65.20	65.20
					23,738.20	13,010.08

15228.80
13705.92
10% 40% 8223.55

351.00

Nett ✓
Nett NH

- End of Part Descriptions -



ELITE ADJUSTMENTS (M) SDN. BHD.

(108135-H)

Licensed by Bank Negara Malaysia and Ministry of Home Affairs
PRIVATE INVESTIGATORS, INSURANCE LOSS ADJUSTERS & SURVEYORS
Email: elitehq@easb.com.my

(調查、保險審估)
億例有限公司

Labour Charges -

WJU 3432

Replacement Parts B/F.....

23,738.20

13,010.88

LABOUR

- | | | | | |
|-----------------------|--|----------|----------|----|
| 1 | To remove and dismantle all damaged parts as listed above to facilitate repairs and replacement of parts. To weld and cut out to where necessary. To repair and knock out dents to where necessary. To refit, reweld new and repaired parts inclusive of adjusting same. | 1,800.00 | 1,200.00 | ✓ |
| 2 | To disconnect wiring systems to effect other repairs, to reconnect same. | 100.00 | 60.00 | ✓ |
| 3 | To check front and rear wheel alignment and tyres balancing. | 100.00 | 60.00 | ✓ |
| 4 | To remove engine unit/gear box assy/exhaust system to facilitate repairs and replacement of parts and to refit same. | 500.00 | 250.00 | NH |
| 5 | To hydraulic jack and realign front and rear LH & RH chassis frames and where necessary. | 500.00 | 250.00 | NH |
| 6 | To supply labour to remove/refix rear windscreen glass to effect repairs and replacement of parts and to refit same | 360.00 | 180.00 | NH |
| 7 | To supply rear windscreen glass sealants. | 400.00 | 200.00 | NH |
| SPRAY PAINTING | | | | |
| 8 | To supply material for spray painting, underseal & antirust. | 800.00 | 450.00 | ✓ |
| 9 | To supply labour for spray painting on the new and repaired parts and where necessary inclusive of cementing, polishing and underseal. | 2,300.00 | 1,550.00 | ✓ |
| TOWING | | | | |
| 10 | To remove the damaged vehicle from the scene of accident to police station and back to workshop. | 300.00 | 150.00 | ✓ |

Total Labour :	7,160.00	4,350.00
Total Parts :	23,738.20	13,010.08
Total Repair C :	30,898.20	17,360.08
Different :	13,538.12	

- End of Labour charges -

RM 12044.55
10 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018		17 Dec 2018 13:31 Edit Adj Rpt	S\$12,044.55 Edit Estimates	S\$12,044.55 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	KAVINJIT SINGH A/L RAJINDER SINGH, ID: 910701105079		
Vehicle Reg. No.:	WJU3432	Date of Loss:	19/04/2018 08:00 - :59 [195 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18040531	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	SHD4603T	Policy No. (Claimant):	MCOM0015
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 27/12/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***WJU3432 (MCT18040531)
[SHD4603T]**

TP

**KAVINJIT SINGH A/L RAJINDER SINGH
Apr 19 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]**

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	28/12/18 12:06	Video - Accident	Load MP4	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	17/12/18 13:32	Letter of Demand from Third Party TPD LOD FROM CHNG, YIN & CO	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/19 16:20	LETTER	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/04/18 14:51	Accident Statement	Load HTM	
2	25/04/18 09:26	Addendum Sheet	Load TIF	
3	25/04/18 09:29	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	19/04/18 14:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	19/04/18 14:50	Sketch Plan	Load TIF	
2	25/04/18 09:27	police report	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS1/III18022891/DQBS2

Date: 09/01/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	WJU3432	Insured Vehicle No :	SHD4603T
Date of Loss:	19/04/2018	Nature of Claim:	TP
		Claim No:	MCT18040531

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	WJU3432	Engine No:	G4GB1M00950
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	MHD01C01220
Reg. Date:	01/01/2002 (Man. Year: 2002)	Odometer:	136646 km
Colour:	Beige		
Engine Capacity:	1795 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,138.20	8,574.55	15,563.65	64.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,760.00	3,470.00	3,290.00	48.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	30,898.20	12,044.55	18,853.65	61.02

INSPECTION

Date of Assignment:	17/12/2018	
Date Inspected:	17/12/2018	Inspected At: SOON HONG MOTOR NO.2 JLN BAYU 2/5 KAWASAN PERINDUSTRIAN TAMPOI JAYA 81200 JB
Estimated Period of Repair:	10.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(RINGGIT MALAYSIA)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WJU3432)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER BRACKET FRONT LH	Not Necessary	14.00 F	*- FL
2	1		*BUMPER FRONT COVER	Torn	859.00 F	*859.00 FL
3	1		*BUMPER FRONT FOG LAMP FINISHER LH (LOWER)	Not Necessary	12.10 F	*- FL
4	1		*BUMPER FRONT FOG LAMP FINISHER RH (LOWER)	Cracked	12.10 F	*12.10 FL
5	1		*BUMPER FRONT LOWER GRILLE	Not Necessary	83.00 F	*- FL
6	1		*BUMPER FRONT MOULDING	Dented	112.00 F	*112.00 FL
7	1		*BUMPER FRONT SHOCK ABSORBER (FRONT TYPE)	Broken	214.00 F	*214.00 FL
8	1		*BUMPER REINFORCEMENT FRONT	Dented	466.00 F	*466.00 FL
9	1		*GRILLE FRONT	Broken	285.00 F	*285.00 FL
10	1		*HEADLAMP ASSY LH	Cracked	585.00 F	*585.00 FL
11	1		*HEADLAMP ASSY RH	Cracked	585.00 F	*585.00 FL
12	1		*BONNET	Dented	2,040.00 F	*2,040.00 FL
13	1		*BONNET HINGE LH	Not Necessary	43.20 F	*- FL
14	1		*BONNET HINGE RH	Not Necessary	43.20 F	*- FL
15	1		*FRONT PANEL UPPER	Not Necessary	250.00 F	*- FL
16	1		*WASHER TANK WINDSCREEN FRONT	Not Necessary	88.00 F	*- FL
17	1		*WINDSCREEN WASHER PUMP	Broken	84.50 F	*84.50 FL
18	1		*DRIVESHAFT FRONT LH	Not Necessary	1,643.90 F	*- FL
19	1		*FENDER FRONT LINER LH	Not Necessary	113.00 F	*- FL
20	1		*KNUCKLE ARM FRONT LH	Bent	688.00 F	*688.00 FL
21	1		*SHOCK ABSORBER FRONT LH	Bent	319.00 F	*319.00 FL
22	1		*SUSPENSION ARM FRONT LH	Bent	650.00 F	*650.00 FL
23	1		*BOOT LID LOCK	Not Necessary	63.90 F	*- FL
24	1		*BUMPER BRACKET REAR LH	Not Necessary	131.00 F	*- FL
25	1		*BUMPER REAR COVER	Torn	843.00 F	*843.00 FL
26	1		*BUMPER REAR MOULDING	Dented	197.00 F	*197.00 FL
27	1		*BUMPER REAR REINFORCEMENT	Not Necessary	622.00 F	*- FL
28	1		*BUMPER REAR SHOCK ABSORBER (FRONT TYPE)	Broken	265.00 F	*265.00 FL
29	1		*LAMP ASSEMBLY REAR LH (TTS)	Cracked	362.00 F	*362.00 FL
30	1		*REAR PANEL ASSEMBLY	Repair	725.00 F	*- FL
31	1		*BOOT LID	Repair	2,010.00 F	*- FL
32	1		*DRIVESHAFT FRONT RH	Not Necessary	1,643.90 F	*- FL
33	1		*FENDER FRONT LINER RH	Cut	113.00 F	*113.00 FL
34	1		*FENDER FRONT RH	Repair	607.00 F	*- FL
35	1		*KNUCKLE ARM FRONT RH	Bent	688.00 F	*688.00 FL
36	1		*SHOCK ABSORBER FRONT RH	Bent	319.00 F	*319.00 FL
37	1		*SUSPENSION ARM FRONT RH	Bent	634.00 F	*634.00 FL
38	2		*WHEEL RIM ALLOY	Deeply Scratched	1,758.20 F	*1,758.20 FL
39	1		*STABILIZER BAR FRONT	Bent	358.00 F	*358.00 FL
40	1		*STEERING TIE ROD END	Bent	132.00 F	*132.00 FL
41	1		*SUBFRAME FRONT	Dented / Bent	2,660.00 F	*2,660.00 FL
42	1		*BUMPER REAR SENSOR	Snapped	351.00 FS	*351.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*BOOT EXTRACTOR VENT	Not Necessary	65.20 FS	*- FS
44	1		*REAR WINDSCREEN GLASS SEALANTS	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)						24,138.20 15,579.80
- List Item Discount on L Items 0.00/10.00% (S\$)						0.00 1,522.88
- Add. Disc. on L,N Items 0.00/40.00% (S\$)						0.00 5,482.37
Total Parts (S\$)						24,138.20 8,574.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND DISMANTLE ALL DAMAGED PARTS AS LISTED ABOVE TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS. TO WELD AND CUT OUT TO WHERE NECESSARY. TO REPAIR AND KNOCK OUT DENTS TO WHERE NECESSARY. TO REFIT, REWELD NEW AND REPAIRED PARTS INCLUSIVE OF ADJUSTING SAME.	New	1,800.00	1,200.00
2	TO DISCONNECT WIRING SYSTEMS TO EFFECT OTHE REPAIRS, TO RECONNECT SAME.	New	100.00	60.00
3	TO CHECK FRONT AND REAR WHEEL ALIGNMENT AND TYRES BALANCING.	New	100.00	60.00
4	TO REMOVE ENGINE UNIT / GEAR BOX ASSY / EXHAUST SYSTEM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS AND TO REFIT SAME.	New	500.00	0.00
5	TO HYDRAULIC JACK AND REALIGN FRONT AND REAR LH & RH CHASSIS FRAMES AND WHERE NECESSARY.	New	500.00	0.00
6	TO SUPPLY LABOUR TO REMOVE / REFIX REAR WINDSCREEN GLASS TO EFFECT REPAIRS AND REPLACEMENT OF PARTS AND TO REFIT SAME.	New	360.00	0.00
7	TO SUPPLY MATERIAL FOR SPRAY PAINTING, UNDERSEAL & ANTIRUST.	New	800.00	450.00
8	TO SUPPLY LABOUR FOR SPRAY PAINTING ON THE NEW AND REPAIRED PARTS AND WHERE NECESSARY INCLUSIVE OF CEMENTING, POLISHING AND UNDERSEAL.	New	2,300.00	1,550.00
9	TO REMOVE THE DAMAGED VEHICLE FROM THE SCENE OF ACCIDENT TO POLICE STATION AND BACK TO WORKSHOP.	New	300.00	150.00
Gross Labour Cost (\$\$)			6,760.00	3,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >