



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWER
SINGAPORE 068811
ATTN: STACEY NG

INV No. AC2004732
INV Date 06/07/2020
Reference CC3/AXA14013995/Kpa3s2
Code AXA2



PROFESSIONAL SERVICE FEE

Vehicle No. SHF 505J
Insured Veh. SGJ 4349H
Claim No.
Policy No. VPA/P1385770
Accident Date 17/07/2014
Inspection Date 22/07/2014

Description	Total
Third Party Express Settlement	350.00
Less:Invoice no.AC1513333 dated 23/11/2015	-250.00
Subtotal	100.00
GST (7%)	7.00
Grand Total	107.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/AXA14013995/Kpa3s2-1

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 06-07-2020



ATTN: STACEY NG

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 4349H	Veh. Inspected	SHF 505J
Policy No.	VPA/P1385770	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/07/2014

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278212	Colour	METALLIC WHITE / RED
Odometer	24116	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GOODYEAR	9 mm
L/H Front Tyre	215/60R16	GOODYEAR	9 mm
R/H Rear Tyre	215/60R16	GOODYEAR	9 mm
L/H Rear Tyre	215/60R16	GOODYEAR	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/07/2014	Inspection Date	22/07/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 505J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT (CONSISTENT)	SERVICEABLE	807.32	-
1	FENDER PANEL FRT LH (CONSISTENT)	SERVICEABLE	502.46	-
1	DOOR PANEL FRT LH (CONSISTENT)	BENT	1,823.50	1,823.50
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	176.07	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	192.66	-
1	DOOR CHECK FRT LH / RH (CONSISTENT)	SERVICEABLE	207.66	-
1	DOOR HANDLE OUTER FRT LH (CONSISTENT)	SERVICEABLE	165.46	-
1	DOOR MOULDING FRT LH (CONSISTENT)	SERVICEABLE	113.34	-
1	DOOR WATER SHIELD FRT LH (CONSISTENT)	SERVICEABLE	118.15	-
1	DOOR FINOSHER INNER FRT LH (CONSISTENT)	SERVICEABLE	207.33	-
1	DOOR MIRROR LH (CONSISTENT)	SERVICEABLE	950.90	-
1	ROCKER PANEL OUTER LH (CONSISTENT)	BENT	633.01	633.01
1	DOOR PANEL REAR LH (CONSISTENT)	BENT	1,823.50	1,823.50
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	202.40	-
1	DOOR HINGE LOWER LH (CONSISTENT)	TO REPAIR SEE LABOUR	192.66	-
1	DOOR CHECK REAR LH / RH (CONSISTENT)	SERVICEABLE	130.17	-
1	DOOR GUIDE REAR LH (CONSISTENT)	SERVICEABLE	113.34	-
1	DOOR HANDLE OUTER REAR LH (CONSISTENT)	SERVICEABLE	81.09	-
1	DOOR MOULDING REAR LH (CONSISTENT)	SERVICEABLE	113.34	-
1	DOOR WEATHERSTRIP REAR LH (CONSISTENT)	SERVICEABLE	304.23	-
1	DOOR SEAL REAR LH (CONSISTENT)	SERVICEABLE	119.92	-
1	CENTRE PILLAR OUTER LH (CONSISTENT)	TO REPAIR SEE LABOUR	512.90	-
1	CENTRE PILLAR INNER LH (CONSISTENT)	TO REPAIR SEE LABOUR	529.00	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	2,114.83	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	348.38	-
1	BUMPER COVER REAR (CONSISTENT)	TO REPAIR SEE LABOUR	710.55	-

Report Ref No. CC3/AXA14013995/Kza3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	87.11	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	28.84	-
	LESS 10% DISCOUNT		-1,331.01	-428.00
			11,979.11	3,852.01
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	SET WHEELARCH CLIP (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	SET DOOR MOULDING CLIP (SN) (CONSISTENT)	NOT NECESSARY	9.90	-
1	SET DOOR CASING CLIP (SN) (CONSISTENT)	NOT NECESSARY	64.00	-
1	DOOR STICKER "TRANS-CAB" (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR STICKER "CLASSIC" (SN) (CONSISTENT)	NECESSARY	15.00	15.00
1	DOOR STICKER "6555-3333" (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	SET WHEELARCH CLIP (SN) (CONSISTENT)	NOT NECESSARY	15.00	-
1	CAP HUB LH REAR (SN) (CONSISTENT)	SCRATCHED	35.00	35.00
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
			490.90	170.00
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER LH, DOOR HINGE LOWER LH, DOOR HINGE UPPER LH, DOOR HINGE LOWER LH, CENTRE PILLAR OUTER LH, CENTRE PILLAR INNER LH, FENDER PANEL REAR LH AND BUMPER COVER REAR.		2,800.00	800.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	1,100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF SIDE ROCKER PANEL OUTER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	80.00
	TO TRANSFER OF REAR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	120.00
			6,700.00	2,180.00
GRAND TOTAL			19,170.01	6,202.01
RECOMMENDED COST OF REPAIRS				6,202.01

Report Ref No. CC3/AXA14013995/Kza3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.