

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9644S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	BUCKLED	1,202.00	1,202.00
1	FRONT BUMPER FOG LAMP OUTER COVER LH (CONSISTENT)	SERVICEABLE	32.40	-
1	FRONT BUMPER RETAINER LH (CONSISTENT)	SERVICEABLE	102.00	-
1	FRONT HEADLAMP LH (CONSISTENT)	CUT	816.00	816.00
1	FRONT FENDER LINER LH (CONSISTENT)	SERVICEABLE	47.00	-
1	FRONT FENDER LH (CONSISTENT)	BENT	837.60	837.60
	LESS 10% DISCOUNT		-303.70	-285.56
			2,733.30	2,570.04
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER FASTENER CLIP (NECESSARY) (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT FENDER LINER CLIP (NECESSARY) (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT TYRE LH (SN) (CONSISTENT)	SERVICEABLE	360.00	-
1	FRONT WHEEL RIM LH (SN) (CONSISTENT)	SERVICEABLE	254.00	-
1	HUB CUP RIM (SN) (CONSISTENT)	SERVICEABLE	35.00	-
			709.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.		1,400.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	30.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED .		1,350.00	400.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
			3,360.00	910.00
	GRAND TOTAL		6,802.30	3,510.04

RECOMMENDED COST OF LUMP SUM REPAIRS	2,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC3/AXA14017623/Kha3q2





Report Ref No. CC3/AXA14017623/Kha3q2

KONG SENG CHEONG

Licensed Appraiser