

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5444D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	BENT	585.36	585.36
1	FRONT BUMPER RETAINER LH (CONSISTENT)	DISTORTED	74.50	74.50
1	FRONT BUMPER RETAINER RH (CONSISTENT)	TO REPAIR SEE LABOUR	74.50	-
1	FRONT BUMPER LOWER ABSORBER (CONSISTENT)	SERVICEABLE	130.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	318.11	-
1	FRONT FENDER LH (CONSISTENT)	BENT	837.60	837.60
1	FRONT FENDER LINER LH (CONSISTENT)	DISTORTED	369.14	369.14
1	FRONT FENDER INDICATOR LAMP LH (CONSISTENT)	SERVICEABLE	95.80	-
1	FRONT HEADLAMP LH (CONSISTENT)	CRACKED	672.00	672.00
	LESS 25% DISCOUNT		-789.25	-634.65
			2,367.76	1,903.95
	SPECIAL NETT ITEMS			
1	SET BUMPER FASTENER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	CNG STICKER (SN) (CONSISTENT)	NECESSARY	30.00	15.00
1	SET FRONT FENDER LINER CLIP LH (CONSISTENT)	NECESSARY	30.00	30.00
			110.00	95.00
	<u>LABOUR</u>			
	TO RUST -PROOFING OF THE AFFECTED AREAS.		220.00	30.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER RETAINER RH AND FRONT BUMPER REINFORCEMENT .		1,400.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,350.00	400.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	20.00
			3,310.00	850.00
	GRAND TOTAL		5,787.76	2,848.95

Report Ref No. CC3/AXA14018175/Kha3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC3/AXA14018175/Kha3q2

KONG SENG CHEONG

Licensed Appraiser