

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT19000312	Page	1
	3 ANSON ROAD #16-00	Date	: 17. Jan 2019		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SFA7123G	Engine No	: R16B25500894		
Chassis No	: MRHFC5650JT000812	Date Time	: 17. Jan 2019 5:17:33 PM		
Model	: CIVIC 1.6 VTI YM2018	Surveyor Name	:		
Owner's Name	: LEE HWEE NGUAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
SUPPLEMENTARY PARTS & LABOUR							
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>missing</i>	1	80.00		A 80.00	5.60	85.60
71121-TEA-T01	BASE,FR.GRILLE CHROME <i>Smashed</i>	1	73.80	25	A 55.35	3.87	59.22
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE <i>Smashed</i>	1	85.60	25	A 64.20	4.49	68.69
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE <i>Smashed</i>	1	85.60	25	A 64.20	4.49	68.69
71125-TEA-T01	MOLDINGFR.GRILLE <i>Smashed</i>	1	100.40	25	A 75.30	5.27	80.57
74127-TEA-T00	COVERFR.BULKHEAD <i>Distorted</i>	1	18.20	25	A 13.65	0.96	14.61
74146-TEA-T00	RUBBERHOOD SEAL <i>Cut</i>	1	27.60	25	A 20.70	1.45	22.15
74175-SMA-000	CUSHIONHOOD <i>Cut</i>	2	5.00	25	A 7.50	0.53	8.03
75700-TBA-A00	EMBLEM	1	15.00	25	A 11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	A 3.15	0.22	3.37
91504-TBA-A01	CLIP,HOOD SEAL	6	0.50	25	A 2.25	0.16	2.41
91505-TM8-003	CLIP,BUMPER	20	2.30	25	A 34.50	2.42	36.92
74128-TED-Q00	LABEL, FR. BULKHEAD COVER	1	1.50	25	A 1.12	0.08	1.20
71101-TEA-T00ZZ	FACEFR.BUMPER <i>Distorted</i>	1	579.90	25	A 434.92	30.44	465.36
71102-TBA-A10	GRILLEFR.BUMPER LOWER	1	36.10	25	A 27.07	1.89	28.96
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	18.00	25	A 13.50	0.95	14.45
71108-TEA-T00	GARNISHL.FR.BUMPER SIDE	1	18.00	25	A 13.50	0.95	14.45
71130-TEA-T00	BEAM COMPFR.BUMPER	1	345.90	25	A 259.42	18.16	277.58
71140-TEA-T00	BEAMR.FR.BUMPER UPPER	1	26.70	25	A 20.02	1.40	21.42
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	26.70	25	A 20.02	1.40	21.42
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP	1	214.80	25	A 161.10	11.28	172.38
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	A 7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	A 7.80	0.55	8.35
71201-TEA-T00	PLATER.FR.BUMPER SIDE INDUCTN	1	43.30	25	A 32.47	2.27	34.74
71206-TEA-T00	PLATEL.FR.BUMPER SIDE INDUCTN	1	44.00	25	A 33.00	2.31	35.31
71207-TEA-T00	EXTENSIONL.SIDE INDUCTN PLATE	1	44.00	25	A 33.00	2.31	35.31
19504-5BA-A00	HOSE BWATER LOWER <i>Damaged</i>	1	11.80	25	A 8.85	0.62	9.47
19511-RB0-004	CLIPWATER HOSE <i>rec</i>	2	4.30	25	A 6.45	0.45	6.90
16400-5FA-Z01	THROTTLE BODYELECTRONIC CTL <i>Damaged</i>	1	1065.10	25	A 798.82	55.92	854.74



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SFA7123G
Chassis No : MRHFC5650JT000812
Model : CIVIC 1.6 VTI YM2018
Owner's Name : LEE HWEE NGUAN
Ins Policy No :
Date of Accident :
Document No. : SQT19000312
Date : 17. Jan 2019
Customer No. : WZC008
Svc Advisor : RUEBEN THOMAS
Engine No : R16B25500894
Date | Time : 17. Jan 2019 5:17:33 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
51320-TBA-A01	LINK COMPFR.STABILIZER <i>Cracked</i>	1	70.50	25	A 52.87	3.70	56.57
44306-TEA-T01	DRIVESHAFT ASSY,L. <i>Bt</i>	1	870.00	25	A 652.50	45.68	698.18
32600-TBA-A00	CABLE ASSYBATTERY EARTH <i>Cut</i>	1	14.50	25	A 10.87	0.76	11.63
80050-TG7-000	LABLE AIR CON <i>nec</i>	1	0.80	25	A 0.60	0.04	0.64
19043-5AA-E00	LABEL, COOLANT INFORMATION <i>nec</i>	1	10.00	25	A 7.50	0.53	8.03
31521-TEA-T00	BOXBATTERY <i>Def</i>	1	87.70	25	A 65.77	4.60	70.37
19422-R1A-A60	HOSEATF WARMER OUT <i>damaged</i>	1	4.60	25	A 3.45	0.24	3.69
19421-R1A-A60	HOSEATF WARMER IN <i>damaged</i>	1	4.20	25	A 3.15	0.22	3.37
91408-RWC-A01	CLIPWATER HOSE <i>nec</i>	2	4.00	25	A 6.00	0.42	6.42
19121-5AA-A00	HOSE BEXPANSION TANK INLET <i>damaged</i>	1	4.50	25	A 3.37	0.24	3.61
60714-TEA-T10ZZ	MEMBER L FR WHEEL HOUSE UPP <i>Distorted</i>	1	76.80	25	A 57.60	4.03	61.63
19109-5BA-A00	HOSE BEXPANSION TANK OUTLET <i>damaged</i>	1	4.60	25	A 3.45	0.24	3.69
Sum Item					<u>3178.04</u>	<u>222.48</u>	<u>3,400.52</u>

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____
Total Amount 3,178.04 222.48 3,400.52
Total (Inclusive of GST) 3,400.52

Printed on 30/1/2019 6:25:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)