

03/03/2018

ASS. REC. BY:

REF CS/FCI/18023062/T1sd3/n2

Special Instruction

Surveyor
CWS

Tau Pich

ASSIGNMENT (Office)

From (Person)

Eileen Lee

of FCI

Date/Time 12:04pm @ 24/12/18

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 2133X

Insured:

SHA 7888J

at Workshop m/s

Prime Auto

Tel:

68610908

of

6 Benoi place

Policy No:

Claim No:

D18009028MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 23/12/2018

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

12:19pm @ 26/12/18

Person Contacted:

per yee

Vehicle:

IN/OUT


Date/Time	Action/Instruction (✓) Estimate
	SHD 2133X - NS/INC/18023022/k/q/b DOA: 23/12/18
	SHA 7888J - CC3/CTI/1600864/H/w/b/3n2 DOA: 5/5/2016
27/12/18	Email preli revised to FCI

QWYVUDC *Taufleh*

REF: FCI

ASSIGNMENT

From: _____ Date: **24-12-2018**
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To inspect Vehicle No: **SHD 2133X**
 at Workshop m/s: **Prime Auto**
 of: **6 Benia Place**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: **Yes or No**
 GIA / PR Seen: _____ Consistent?: **Yes or No**
 Est. Repairs: _____ days Res.: **Yes or No**
 Lum Sum: _____ % 3 Val.: **Yes or No**
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**



Veh No: **SHD 2133X** Yr Regn: **2015 May**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Volfire** c.c. **2362**
 Colour: **Pearl white** A/C: **Insured / Std / NI / NA**
 Sp. Reading: _____ T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **ATH 208047124**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modi: **Nil** / SRim / STD A/Rim or
 Tyre Size: F: _____ R: _____
215 / 65R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Goodride**
 Front: _____ Rear: _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. _____ D.O.I. **24/12/18 @ 430**
 Survey held at: **Prime Auto**
 Des. of Damages: **Frnt** / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>Mr Bailey meate</i>
08/01/19	Confirmed r/p \$7,907.25 @ 10 days with Taufleh (\$3,875.58 red-33%)

RECEIVED 08 JAN 2019

Date/Time. File Pass to? **08/01/19**
 1) **Typist**
 Date/Time. File Return to?
 2)

: Preli. Report
 : Final Report

Days Of Repair: **10**
 Resurvey No. of Trip: **1**

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee: **170 + 15**
 Transportation: **50**
 Photos: **50**
 Others: **75**
 TOTAL: **350**

Report Format :
 Lump Sum / I.B.I: (\$ **7,907.25 p/p**)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18009028MFSH

Our ref: CS/FCI18023062/T1sd3

Date: 27/12/2018

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SHD 2133X


We thank you for your instruction on 26/12/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/12/2018 at the premises of M/s PRIME AUTO CLAIMS SERVICE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,782.83
Revised Estimate Amount	: S\$7,869.75
"Check" Items Amount	: S\$1,555.08
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	24-12-2018	Our Ref No. D18009028MFSH
Accident Date	23-12-2018	Claim Type. Third Party
Insured Vehicle	SHA7888J	Third Party Vehicle. SHD2133X
Survey Location	6 BENOI PLACE	
Contact Person.	PEI YEE	
Contact No.	68610908/ 0	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 8 January 2019 12:10 PM
To: 'Alice Leong'
Cc: SUR; Taufikh (LKKAuto)
Subject: RE: FINALIZE TO SHD2133X

Dear Alice,

Confirmed final fig of \$ 7,907.25 (part by part) @ 10 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alice Leong [mailto:aliceleong@primeautoclaims.com]
Sent: Monday, 7 January 2019 11:08 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: sur@lkkauto.com
Subject: FINALIZE TO SHD2133X
Importance: High

Hi Taufikh,

Enclosed our before & after repair photos & our calculation sheet for your retention. Shall we finalize at part by part \$7,907.25 and 10 days

Please let us have your confirmation within three days from our e-mail.

Thank you

Alice Leong
Manager, Motor Claims

Prime Auto Claims Service Pte Ltd
6 Benoi Place Singapore 629927
T (65): 6861 0908 1 F (65) 6515 2948
HP (65) 9818 4304

A member of the Prime Group

[Disclaimer](#)

This e-mail (including all attachment) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intend recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 27 December 2018 11:57 AM
To: 'CWS Motor Claims'
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18009028MFSH/1, SHD 2133X
Attachments: SHD 2133X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHD 2133X
Date of survey: 24/12/2018
Number of days : 10 days

Best Regards,

Veron Chen | Case Handler on behalf of Shirley

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 26 December 2018 12:21 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18009028MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 26 December 2018 12:04 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18009028MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
 6 Benoi Place Singapore 629927
 Tel: 6861 0908 Fax: 6515 2948

[Handwritten signature]
 28/12/18

Tanfir 97495749
 'WP'
 27/12/18 @ 3:30 pm
 Resurvey after repair
 10 days
 sue @ (Mentorian)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Date: 24.12.2018

MS First Capital Insurance Ltd
 36 Robinson Road #16-01
 City House
 Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2133X TOYOTA VELLFIRE (2014)

To Supply

1)	1pc	tailgate	\$	2,200.00	bt
2)	1pc	tailgate "Vellfire" emblem	\$	80.00	de
3)	1pc	tailgate "Toyota" logo	\$	90.00	de
4)	1pc	tailgate " E-Four" emblem	\$	70.00	de
5)	1pc	tailgate "Hybrid Synergy Drive" emblem	\$	60.00	car
6)	1pc	tailgate weatherstrip	\$	400.00	at
7)	1pc	rear bumper	\$	1,050.00	de
8)	1pc	rear bumper right retainer	\$	130.00	? x nn
9)	1pc	rear bumper left retainer	\$	130.00	de
9)	1pc	rear bumper right bracket	\$	145.00	? x nn
10)	1pc	rear bumper left bracket	\$	145.00	de
11)	1pc	rear bumper left tow hook cover	\$	35.00	mis
12)	1set	rear bumper clip	\$	35.00	de
13)	1pc	rear bumper left reflector	\$	90.00	at
14)	1pc	left tail lamp lower corner panel	\$	200.00	de
15)	1pc	right tail lamp lower corner panel	\$	200.00	de
16)	1pc	rear end panel (inner & outer)	\$	840.00	? photo x nn
17)	1pc	exhaust tail pipe	\$	430.00	x Rx
18)	1pc	exhaust tail pipe with silencer	\$	884.00	Ry
19)	1pc	exhaust gasket	\$	30.00	x nn
20)	1pc 2	rear bumper center right & left right parking sensor @\$290.00	\$	580.00	dis
21)	1pc	rear bumper left parking sensor	\$	290.00	dis
22)	1pc 3	rear bumper center parking sensor & left parking sensor cover @\$25.0	\$	75.00	at

23)	1pc	front bumper	\$	829.40	<i>ana</i>
24)	1set	front bumper clip	\$	30.00	<i>an</i>
25)	1pc	front bumper right tow hook cover	\$	35.10	<i>de</i>
26)	1pc	reverse sensor wire	\$	228.04	<i>? X } just</i>
27)	1pc	rear floor deck box	\$	684.00	<i>? X }</i>
28)	1pc	carrier spare wheel	\$	46.40	<i>? X }</i>
29)	1pc	spare tyre carrier	\$	498.50	<i>bt</i>

Sub total parts	\$	10,490.44
Less: 25% discount	\$	(2,622.61)
	\$	7,867.83

To Supply S.Nett Parts

1)	1tube	rear glass sealant	\$	45.00	<i>u</i>
2)	1pc	inner seal	\$	20.00	<i>u</i>

Sub total S.Nett Parts	\$	65.00
------------------------	----	-------

L/charges

1)	Towing charges (use king trolley)	\$	80.00	<i>✓</i>
2)	To tuff kote	\$	100.00	<i>50.</i>
3)	To remove & refit rear glass	\$	120.00	<i>✓</i>
4)	To transfer tailgate trim board, handle, mechanism parts	\$	120.00	<i>60</i>
5)	To remove & replace reverse sensors, reset sensor.	\$	60.00	<i>30.</i>
6)	To remove & replace exhaust tail pipe	\$	120.00	<i>60.</i>
7)	To remove rear bumper, tailgate & etc. cut/ welding right rear end panel, floor panel, floor panel, straighten right wheel house panel & etc.	\$	1,300.00	<i>800</i>
8)	To putty, respray painting tailgate inlet & outer, rear end panel, bumper, right & left tail lamp lower panel & lower right inner panel, floor panel & polish	\$	1,400.00	<i>900.</i>
9)	To remove and replace front bumper, align bumper & grille	\$	250.00	<i>200</i>
10)	To putty, respray painting front bumper in pearl white	\$	300.00	<i>200</i>

Sub total L/charges	\$	3,850.00
Estimated Grand total	\$	11,782.83

11820.33



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Tanfer 97493749
WP
24/12/18 @ 4:30 pm
Meeting after repair
10 days
save @ Heartson

Date: 24.12.2018

MS First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2133X TOYOTA VELLFIRE (2014)

To Supply

1)	1pc	tailgate	\$	2,200.00	bt ✓
2)	1pc	tailgate "Vellfire" emblem	\$	80.00	re ✓
3)	1pc	tailgate "Toyota" logo	\$	90.00	re ✓
4)	1pc	tailgate "E-Four" emblem	\$	70.00	re ✓
5)	1pc	tailgate "Hybrid Synergy Drive" emblem	\$	60.00	re ✓
6)	1pc	tailgate weatherstrip	\$	400.00	at ✓
7)	1pc	rear bumper	\$	1,050.00	de ✓
8)	1pc	rear bumper right retainer	\$	130.00	? X
9)	1pc	rear bumper left retainer	\$	130.00	re ✓
9)	1pc	rear bumper right bracket	\$	145.00	? X
10)	1pc	rear bumper left bracket	\$	145.00	re ✓
11)	1pc	rear bumper left tow hook cover	\$	35.00	re ✓
12)	1set	rear bumper clip	\$	35.00	re ✓
13)	1pc	rear bumper left reflector	\$	90.00	at ✓
14)	1pc	left tail lamp lower corner panel	\$	200.00	de ✓
15)	1pc	right tail lamp lower corner panel	\$	200.00	de ✓
16)	1pc	rear end panel (inner & outer)	\$	840.00	? photo X
17)	1pc	exhaust tail pipe	\$	430.00	X Ryo X
18)	1pc	exhaust tail pipe with silencer	\$	884.00	Ryo X
19)	1pc	exhaust gasket	\$	30.00	X X
20)	2pcs	rear bumper center right & left right parking sensor @ \$290.00	\$	580.00	de ✓
21)	1pc	rear bumper left parking sensor	\$	290.00	de ✓
22)	3pcs	rear bumper center parking sensor & left parking sensor cover @ \$25.0	\$	25.00 75.00	at ✓

23)	1pc	front bumper	\$	829.40	au ✓
24)	1set	front bumper clip	\$	30.00	au ✓
25)	1pc	front bumper right tow hook cover	\$	35.10	de ✓
26)	1pc	reverse sensor wire	\$	228.04	? X
27)	1pc	rear floor deck box	\$	684.00	? X
28)	1pc	carrier spare wheel	\$	46.40	? X
29)	1pc	spare tyre carrier	\$	498.50	bt ✓

Sub total parts	\$	10,490.44	71123.00
Less: 25% discount	\$	(2,622.61)	-1780.75
	\$	7,867.83	5342.25

To Supply S.Nett Parts

1)	1tube	rear glass sealant	\$	45.00	au ✓
2)	1pc	inner seal	\$	20.00	au ✓

Sub total S.Nett Parts	\$	65.00	✓
------------------------	----	-------	---

L/charges

1)	Towing charges (use king trolley)	\$	80.00	✓
2)	To tuff kote	\$	100.00	50.
3)	To remove & refit rear glass	\$	120.00	✓
4)	To transfer tailgate trim board, handle, mechanism parts	\$	120.00	60
5)	To remove & replace reverse sensors, reset sensor.	\$	60.00	30.
6)	To remove & replace exhaust tail pipe	\$	120.00	60.
7)	To remove rear bumper, tailgate & etc. cut/ welding right rear end panel, floor panel, floor panel, straighten right wheel house panel & etc.	\$	1,300.00	800
8)	To putty, respray painting tailgate inlet & outer, rear end panel, bumper, right & left tail lamp lower panel & lower right inner panel. floor panel & polish	\$	1,400.00	900.
9)	To remove and replace front bumper, align bumper & grille	\$	250.00	200
10)	To putty, respray painting front bumper in pearl white	\$	300.00	200

Sub total L/charges	\$	3,850.00	2500.00
Estimated Grand total	\$	11,782.83	7907.25



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18023062/T1sd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-01-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 7888J	Veh. Inspected	SHD 2133X
Policy No.		Coverage (\$)	0.00
Claim No.	D18009028MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	24/12/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VELLFIRE	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ATH208047124	Colour	PEARL WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/65 R16	GOODRIDE	6 mm
L/H Front Tyre	215/65 R16	GOODRIDE	6 mm
R/H Rear Tyre	215/65 R16	GOODRIDE	6 mm
L/H Rear Tyre	215/65 R16	GOODRIDE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/12/2018	Inspection Date	24/12/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2133X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BENT	2,200.00	2,200.00
1	TAILGATE "VELLFIRE" EMBLEM	NECESSARY	80.00	80.00
1	TAILGATE "TOYOTA" LOGO	NECESSARY	90.00	90.00
1	TAILGATE "E-FOUR" EMBLEM	NECESSARY	70.00	70.00
1	TAILGATE "HYBRID SYNERGY DRIVE" EMBLEM	NECESSARY	60.00	60.00
1	TAILGATE WEATHERSTRIP	CUT	400.00	400.00
1	REAR BUMPER	DEFORMED	1,050.00	1,050.00
1	REAR BUMPER RIGHT RETAINER	NOT NECESSARY	130.00	-
1	REAR BUMPER LEFT RETAINER	NECESSARY	130.00	130.00
1	REAR BUMPER RIGHT BRACKET	NOT NECESSARY	145.00	-
1	REAR BUMPER LEFT BRACKET	NECESSARY	145.00	145.00
1	REAR BUMPER LEFT TOW HOOK COVER	MISSING	35.00	35.00
1	SET REAR BUMPER CLIP	NECESSARY	35.00	35.00
1	REAR BUMPER LEFT REFLECTOR	CUT	90.00	90.00
1	LEFT TAIL LAMP LOWER CORNER PANEL	DEFORMED	200.00	200.00
1	RIGHT TAIL LAMP LOWER CORNER PANEL	DEFORMED	200.00	200.00
1	REAR END PANEL (INNER & OUTER)	NOT NECESSARY	840.00	-
1	EXHAUST TAIL PIPE	TO REPAIR SEE LABOUR	430.00	-
1	EXHAUST TAIL PIPE WITH SILENCER	TO REPAIR SEE LABOUR	884.00	-
1	EXHAUST GASKET	NOT NECESSARY	30.00	-
2	REAR BUMPER CENTER RIGHT & LEFT RIGHT PARKING SENSOR @\$290.00	DISTORTED	580.00	580.00
1	REAR BUMPER LEFT PARKING SENSOR	DISTORTED	290.00	290.00
3	REAR BUMPER CENTER PARKING SENSOR & LEFT PARKING SENSOR COVER @\$250.00	CUT	75.00	75.00
1	FRONT BUMPER	CRACKED	829.40	829.40
1	SET FRONT BUMPER CLIP	NECESSARY	30.00	30.00
1	FRONT BUMPER RIGHT TOW HOOK COVER	DEFORMED	35.10	35.10
1	REVERSE SENSOR WIRE	NOT NECESSARY	228.04	-
1	REAR FLOOR DECK BOX	NOT NECESSARY	684.00	-

Report Ref No. CS/FC118023062/T1sd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CARRIER SPARE WHEEL	NOT NECESSARY	46.40	-
1	SPARE TYRE CARRIER	BENT	498.50	498.50
	LESS 25% DISCOUNT		-2,635.11	-1,780.75
			7,905.33	5,342.25
	SPECIAL NETT ITEMS			
1	TUBE REAR GLASS SEALANT (SN)	NECESSARY	45.00	45.00
1	INNER SEAL (SN)	NECESSARY	20.00	20.00
			65.00	65.00
	LABOUR			
	TOWING CHARGES (USE KING TROLLEY).		80.00	80.00
	TO TUFF KOTE.		100.00	50.00
	TO REMOVE & REFIT REAR GLASS.		120.00	120.00
	TO TRANSFER TAILGATE TRIM BOARD,HANDLE,MECHANISM PARTS.		120.00	60.00
	TO REMOVE & REPLACE REVERSE SENSORS,RESET SENSOR.		60.00	30.00
	TO REMOVE & REPLACE EXHAUST TAIL PIPE.		120.00	60.00
	TO REMOVE REAR BUMPER,TAILGATE & ETC.CUT/WELDING RIGHT REAR END PANEL,FLOOR PANEL,FLOOR PANEL,STRAIGHTEN RIGHT WHEEL HOUSE PANEL & ETC.INCLUSIVE OF THE REPAIR OF EXHAUST TAIL PIPE AND EXHAUST TAIL PIPE WITH SILENCER.		1,300.00	800.00
	TO PUTTY,RESPRAY PAINTING TAILGATE INLET & OUTER,REAR END PANEL,BUMPER,RIGHT & LEFT TAIL LAMP LOWER PANEL & LOWER RIGHT INNER PANEL,FLOOR PANEL & POLISH.		1,400.00	900.00
	TO REMOVE AND REPLACE FRONT BUMPER,ALIGN BUMPER & GRILLE.		250.00	200.00
	TO PUTTY,RESPRAY PAINTING FRONT BUMPER IN PEARL WHITE.		300.00	200.00
	-		-	-
	-		-	-
	-		-	-
			3,850.00	2,500.00
	GRAND TOTAL		11,820.33	7,907.25



RECOMMENDED COST OF REPAIRS			7,907.25
------------------------------------	--	--	-----------------

Report Ref No. CS/FC118023062/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.