



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2008 SUZUKI SWIFT 1.6 SPORTS (SLN7802R)

Date of Loss 9 December 2018

Time of Loss 9.15

Loss Description SLN7802R (INSD) HIT REAR OF SKX2935H (TP)

Comment

Workshop Details

Total Rebate Amount 16981

Nett Loss Amount \$10,019.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 103



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SLN7802R

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

06/06/2008



Mileage

179692

Age of Vehicle

10

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2008

2008

Make

SUZUKI

SUZUKI

Model

SWIFT 1.6
SPORTS

SWIFT SPORT 1.6 M

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

PHILLIPS GRACEY REUBEN
RAJAN S/O

Date of Birth

1 December 1987

dd/mm/yyyy

Age

31

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	ZC31S202765	ZC31S202765
Engine No	M16A1311910	M16A1311910
Engine Capacity		1586
Sum Insured	0	0
Market Value	0	27000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	4	
Driver License #		
License Type		
License Issue Date		dd/mm/
License Expiration Date		dd/mm/
Address	BLK 178A RIVERVALE CRESCENT, #06-459, 541178, Singapore	
Address type	Residential	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Married	
Identification #	S8742298D	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

26/12/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1200

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/45R16

Rear Tyre Size

205/45R16

Front left side

ROADSTONE4mm

Rear left side

BRIDGESTONE6mm

Front right side

ROADSTONE4mm

Rear right side

BRIDGESTONE6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			RADIATOR SHROUD (WCP) (10%)			Cracked	104.5				104.5	Reviewing	
		2	1			L/RADIATOR BRACKET			Repair	0	0	0	0	0	Deny	
		3	1			R/RADIATOR BRACKET			Repair	0	0	0	0	0	Deny	
		4	1			LOWER WATER HOSE			Serviceable	0	0	0	0	0	Deny	
		5	1			UPPER WATER HOSE			Serviceable	0	0	0	0	0	Deny	
		6	1			ELECTRIC FAN (WCP) (10%)			Damaged	327.8				327.8	Reviewing	
		7	1			COOLING FAN (WCP) (10%)			Cracked	63.8				63.8	Reviewing	
		8	1			AIR INTAKE TUBE (WCP) (10%)			Dented	19.8				19.8	Reviewing	
		9	1			AIR FILTER RESONATOR			Serviceable	0	0	0	0	0	Deny	
		10	1			AIR FILTER ASSY			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		11	1			F/LWR REINFORCMT CVR			Serviceable	0	0	0	0	0	Deny	
		12	6			F/LWR REINF CVR CLIP			Serviceable	0	0	0	0	0	Deny	
		13	2			RAD TOP BUSH (WCP) (10%)			Missing	8.8				17.6	Reviewing	
		14	2			RAD LWR BUSH			Serviceable	0	0	0	0	0	Deny	
		15	1			FRONT BUMPER (WCP) (10%)			Cracked	473				473	Reviewing	
		16	1			UPP BUMPER ABSORBER (WCP) (10%)			Damaged	88				88	Reviewing	
		17	1			LWR BUMPER ABSORBER (WCP) (10%)			Bent	82.5				82.5	Reviewing	
		18	1			R/F TOWING LUG COVER			Serviceable	0	0	0	0	0	Deny	
		19	1			L/F BUMPER BRACKET (WCP) (10%)			Bent	30.8				30.8	Reviewing	
		20	1			R/F BUMPER BRACKET (WCP) (10%)			Bent	30.8				30.8	Reviewing	
		21	1			ENGINE ROOM COVER (WCP) (10%)			Dented	44				44	Reviewing	
		22	1			L/ENG COMPART COVER (WCP) (10%)			Dented	44				44	Reviewing	
		23	1			FRT BUMPER CLAMP KIT (WCP) (10%)			Necessary	33				33	Reviewing	
		24	1			GRILLE (WCP) (10%)			Dented	71.5				71.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		25	1			BUMPER TRIM GRILLE (WCP) (10%)			Damaged	66				66	Reviewing	
		26	1			FRONT MANUFACT BADGE (WCP) (10%)			Necessary	30.8				30.8	Reviewing	
		27	1			BONNET (WCP) (10%)			Buckled	363				363	Reviewing	
		28	1			L/BONNET HINGE (WCP) (10%)			Damaged	27.5				27.5	Reviewing	
		29	1			R/BONNET HINGE (WCP) (10%)			Damaged	27.5				27.5	Reviewing	
		30	1			BONNET LOCK (WCP) (10%)			Bent	52.8				52.8	Reviewing	
		31	1			BONNET CABLE			Serviceable	0	0	0	0	0	Deny	
		32	1			FRONT BONNET SEAL (WCP) (10%)			Cut	30.8				30.8	Reviewing	
		33	1			L/HEADLAMP CPL (WCP) (10%)			Cracked	297				297	Reviewing	
		34	1			R/HEADLAMP CPL (WCP) (10%)			Cracked	297				297	Reviewing	
		35	1			L/F FOG LAMP			Serviceable	0	0	0	0	0	Deny	
		36	1			R/F FOG LAMP			Serviceable	0	0	0	0	0	Deny	
		37	1			L/F FOG LAMP MLDG			Serviceable	0	0	0	0	0	Deny	
		38	1			R/F FOG LAMP MLDG			Serviceable	0	0	0	0	0	Deny	
		39	1			L/FOG LAMP COVER (WCP) (10%)			Dented	126.5				126.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		40	1			R/FOG LAMP COVER (WCP) (10%)			Dented	126.5				126.5	Reviewing	
		41	1			L/F WING (WCP) (10%)			Buckled	187				187	Reviewing	
		42	1			R/F WING (WCP) (10%)			Buckled	187				187	Reviewing	
		43	6			L/F WING CLAMP KIT (WCP) (10%)			Necessary	5.5				33	Reviewing	
		44	6			R/F WING CLAMP KIT (WCP) (10%)			Necessary	5.5				33	Reviewing	
		45	1			L/F WHEELHOUSE COVER (WCP) (10%)			Cracked	66				66	Reviewing	
		46	1			R/F WHEELHOUSE COVER (WCP) (10%)			Cracked	66				66	Reviewing	
		47	1			CTR FRT PANEL STRUT (WCP) (10%)			Damaged	44				44	Reviewing	
		48	1			L/F PANEL STRUT (WCP) (10%)			Buckled	82.5				82.5	Reviewing	
		49	1			R/F PANEL STRUT (WCP) (10%)			Buckled	82.5				82.5	Reviewing	
		50	1			RADIATOR CROSSMEMBER (WCP) (10%)			Bent	82.5				82.5	Reviewing	
		51	1			FRT UPP BUMPER CARR (WCP) (10%)			Bent	143				143	Reviewing	
		52	1			FRONT LOWER CARRIER (WCP) (10%)			Bent	126.5				126.5	Reviewing	
		53	1			CTR LOCK CARRIER (WCP) (10%)			Bent	77				77	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		54	1			L/BONNET LANDING PNL (WCP) (10%)			Damaged	60.5				60.5	Reviewing	
		55	1			R/BONNET LANDING PNL (WCP) (10%)			Damaged	60.5				60.5	Reviewing	
		56	1			CONDENSER (WCP) (10%)			Damaged	440				440	Reviewing	
		57	1			COMPR/CONDENSER PIPE (WCP) (10%)			Dented	96.8				96.8	Reviewing	
		58	1			COMPR/EVAP PIPE			Serviceable	0	0	0	0	0	Deny	
		59	1			COND/EVAPORATOR PIPE			Serviceable	0	0	0	0	0	Deny	
		60	1			RADIATOR (WCP) (10%)			Damaged	484				484	Reviewing	

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TOP UP AIRCON GAS	100	0	0	Reviewing		
		2		PANEL / MECHANICAL	765	0	0	Reviewing		
		3		PAINTWORK	796.5	0	0	Reviewing		
		4		PAINT / MATERIAL COSTS	291.4	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
		2	COMPRESSOR (WCP) (10%)	Reviewing	363	CRACKED/DENTED/JAMMED (SUPPLEMENTARY)	
		3	FRT NUMBER PLATE	Reviewing	45	MISSING	
		4	ANTIFREEZE 4 LTR	Reviewing	48	NECESSARY	
		5	BATTERY	Deny	0	SERVICEABLE	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$6,437.20

Claim Amount \$6,437.20

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$5,228.30

\$5,228.30

Labour

\$1,952.90

\$1,952.90

Miscellaneous

\$456.00

\$456.00

Excess

-\$1,200.00

-\$1,200.00

[Submit for Review](#)