

Comment	Reasons for recommendation of not replacing items
1	No photographic evidences to indicate leakages and overall conditions of a/c condenser is good especially the cooling fins and the serpentine tubings thus does not warrant a replacement.
2	Our resurvey photos does not indicate any bend conditions of the front brace panel. No replacement required.
3	Our resurvey photos indicate that the front bumper foglamp cover in question shows no defect to warrant a replacement.
4	Only LH foglamp requires replacement and it was given.
5	Our resurvey photos shows no damages to front bumper lower air guide to warrant replacements.(comments 5,6).
6	Front bumper lower cover was deemed as serviceable by us and to be reuse (comment 7).
7	Front bumper lower spoiler did not have any defect and considered as reuseable by us (comment 8).
8	Agree that the bumper top beam is slightly bent and only requires only repair and no replacement is required.
9	Front bumper tow hook cover was not damaged and does not warrant a replacement by us (comment10).
10	Front grille L/R brackets were deemed as Serviceable by us (comment 11).
11	Front grille upper rubber seal was deemed as serviceable as it is not damaged (comment 12).
12	Our resurvey shows only the LH front headlamp sustained sufficient damage to warrant a replacement (comment 13).
13	Front headlamp lower brackets L/R were not damaged and are considered as serviceable (comment 14).
15	Front headlamp lower panel sponge L/R were deemed as serviceable as they do not have any signs of damage.
16	Front horns were not damaged and deemed as serviceable and does not require replacements.
17	Front support panel was deemed as Repair would suffice.
18	The radiator was deemed as serviceable, a slight dent at the top rail is superficial and will not affect it's coolant flow.
19	Only the LH bumper reflector was deemed as necessary for replacement.
20	Rear end panel antenna sensor and buzzer sensor were considered as serviceable by us.
22	For your comments: 22,23,24,25,26,27,28,29,30,31,32,33,34,35,37,38,39,40,41,43,58, the items were deemed as serviceable.
23	Tailgate emblem was deemed as necessity itemto be replaced whenever the tailgate is to be replaced (comment 36).
24	Rear LH tail lamp had a fractured pin thus required a replacement (comment 42).
25	Front number plate was bent and required a replacement at \$25.00 (comment 50).
26	The radiator was deemed as serviceable thus there is no necessity to provide the coolant (comment 61).
In conclusion, after careful reinspection of the photographic evidences we consider our report submitted to the insurance is fair, reasonable and accurate beyond any reasonable doubt.	