




TOYOTA MOTOR CORPORATION JAPAN


MODEL	DBA-ZSU60K ANXGP			
ENGINE	3ZR-FAC 1986 mL			
FRAME No.	ZSU6C-0140531			
	COLOR	TRIM	PLANT	OPTION
	070 FA45 A3			
TYPE/CHL	K1 4		A	721



































Report No: 0316-18-N51

11 June 2018

ACCIDENT VEHICLE SURVEY REPORT

Tan Choo Heng
c/o N-51 Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-18
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SGK9398C	<i>Odometer:</i>	32537km
<i>Make & Model:</i>	Toyota Harrier 2.0 A	<i>Colour:</i>	White
<i>Chassis number:</i>	ZSU600040581	<i>Date of accident:</i>	08/08/2017
<i>Year of Regn.:</i>	17/06/2015	<i>Date inspected:</i>	15/08/2017
<i>Repairer at:</i>	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	22/08/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

