

ASS. REC. BY:

REF:

ES3/ALG18023117/Ged30

Special Instruction:

Surveyor:

Chin Lee Ting

ASSIGNMENT (Office)

From (Person):

of

ALG

Date/Time:

26/12/18 @ 2:35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SME 8907B

Insured:

YN 6163D

at Workshop m/s

Apex Motoring

Tel:

91690825

of

25 Kaki Bukit Rd 1 # 01-55 synergy

Policy No.:

Claim No.:

213680633186

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/12/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:32pm @ 26/12/18

Person Contacted:

pei jie

Vehicle: IN / OUT

Date/Time

Action/Instruction (X) Estimate

SME 8907B - X

YN 6163D - X

Diemantle: 28/12/2018.

PRS
Xhl.

REF: AIG

ASSIGNMENT

From: Date: 27/12/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SME 8907B

at Workshop m/s Apex Motoring
of 25 Kaki Bukit Rd 4 #01-55 synergy

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SME 8907B Yr Regn: - /

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda veezel

C.G. 1496

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

12080

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU31268951

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size:

F:

215/60R16

R:

11

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27-12-18

Survey held at

W/S

11:50

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

64 o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 1000

No GIA

31/12/2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

Report Format: DAR

Lump Sum / I.B.I. (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

TOTAL

200

-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 26/12/2018 2:35:01 PM
Attachments:  [NEW PRI - YN6163D AND SME8907B.PDF](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



24/12/2018

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way #07-16

Singapore 079120

Fax : 6415 3727

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. YN 6163 D AND VEHICLE NO. SME 8907 B
ON 19/12/2018 @ 0305 Hrs**

We are the appointed repair workshop of vehicle no. **SME 8907 B**

We understand that you are the insurer of vehicle no. **YN 6163 D**

The owner of vehicle number **SME 8907 B** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800
Mobile No. 91690825 / peijie@expresscar.com.sg. Ms Lim

Yours faithfully



SME 8907B

Front bumper - cut

" " Clips - abt.

" " Fog lamp cover - SCR.

to panel Beating : 200

spray paint ~~photo~~ : 200

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018 Edit Reg		26 Dec 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

CHIANG KANG ENTERPRISES, Co. Reg. No.: NA

Main Claimant:

UNKNOWN

Vehicle Reg. No.:

SME8907B

Date of Loss:

19/12/2018 00:00 - :59

Claim Type:

TP / 2136806331SG

Policy/Cover Note No.:

Vehicle Reg. No. (Insured):

YN6163D

Policy No. (Claimant):

Excess:

Repairer:

Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/01/2019]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (27/12/2018): No OI GIA Report
- AIG_SG (27/12/2018): Request To Upload TP GIA Report


































ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SME8907B (2136806331SG)**
[YN6163D]
TP
UNKNOWN
Dec 19 2018 12:00AM
[CHIANG KANG ENTERPRISES]
Apex Motoring

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	31/12/18 09:26	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
2	31/12/18 09:26	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
3	31/12/18 09:26	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
4	31/12/18 09:26	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
5	31/12/18 09:26	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
6	31/12/18 09:27	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
7	31/12/18 09:27	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
8	31/12/18 09:27	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
9	31/12/18 09:27	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
10	31/12/18 09:27	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
11	31/12/18 09:27	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
12	31/12/18 09:27	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
13	31/12/18 09:27	Accident Photo														Load JPG	<input checked="" type="checkbox"/>			
14	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
15	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
16	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
17	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
18	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
19	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
20	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
21	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
22	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
23	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
24	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
25	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
26	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
27	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
28	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
29	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
30	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
31	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
32	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
33	31/12/18 09:28	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18023117/GCD3E2

Date: 08/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SME8907B

Insured Vehicle No : YN6163D

Date of Loss: 19/12/2018

Nature of Claim: TP

Claim No: 2136806331SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME8907B

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: HIDDEN

Reg. Date: (Man. Year:)

Chassis No: RU31268951

Colour: Silver

Odometer: 12080 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/12/2018

Date Inspected: 27/12/2018 Inspected At:

Apex Motoring

25 Kaki Bukit Road 4, #01-55 Synergy @

KB

Singapore 417800

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	0.00 F	*- F
2	1		*FRONT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRONT BUMPER FOG LAMP COVER	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >