

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG18023158/GRA3Q2

**Date:** 01/04/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLL9679C **Insured Vehicle No :** SME1194L

**Date of Loss:** 24/12/2018 **Nature of Claim:** TP **Claim No:** 4742010327SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLL9679C</b>                   | Engine No:  | HIDDEN            |
| Make & Model:               | MERCEDES-BENZ C180K, 1.8 (A)      | Chassis No: | WDD2040452A273553 |
| Reg. Date:                  | 23/09/2009 (Man. Year: 2020)      | Odometer:   | 182053 km         |
| Colour:                     | Blue                              |             |                   |
| Engine Capacity:            | 1796 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |     |                          |     |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification:    | No  | Pre-accident Condition:  |     |

#### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 225/50 R17       | Rear Tyre Size:  | 225/50 R17       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 9,612.08          | 3,974.47          | 5,637.61          | 58.65         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 2,690.00          | 740.00            | 1,950.00          | 72.49         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>12,302.08</b>  | <b>4,714.47</b>   | <b>7,587.61</b>   | <b>61.68</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>3,750.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                        | <b>12,302.08</b>  | <b>3,750.00</b>   | <b>8,552.08</b>   | <b>69.52</b>  |
| <b>+ Car Rental (7.0 x S\$120.00/day) (S\$)</b> |                   | 840.00            |                   |               |
| <b>+ Legal Costs/Disbursements (S\$)</b>        |                   | 200.00            |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>4,790.00</b>   |                   |               |

#### INSPECTION

Date of Assignment: 27/12/2018

Date Inspected: 27/12/2018 Inspected At:

UNIMOTOR COMPANY  
NO. 1 KAKI BUKIT AVE 6 #01-94  
AUTOBAY@KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER ASSY                     | Cut           | 1,728.00 FN | *1,315.32 FN |
| 2   | 1   |          | *FRONT BUMPER INNER SPONGE             | Cracked       | 212.00 FN   | *155.00 FN   |
| 3   | 1   |          | *FRONT BUMPER REINFORCEMENT            | Not Necessary | 646.00 FN   | *- FN        |
| 4   | 1   |          | *FRONT R/H BUMPER REINFORCEMENT STAY   | Not Necessary | 118.00 FN   | *- FN        |
| 5   | 1   |          | *FRONT BUMPER LOWER COVER GARNISH      | Not Necessary | 28.00 FN    | *- FN        |
| 6   | 1   |          | *FRONT R/H BUMPER FOG LAMP             | Broken        | 356.00 FN   | *290.00 FN   |
| 7   | 1   |          | *FRONT R/H BUMPER SIDE RETAINER        | Deformed      | 35.20 FN    | *35.20 FN    |
| 8   | 1   |          | *FRONT R/H BUMPER SIDE RETAINER HOLDER | Not Necessary | 76.00 FN    | *- FN        |
| 9   | 1   |          | *FRONT R/H HEADLAMP ASSY               | Cut           | 1,476.00 FN | *1,476.00 FN |
| 10  | 1   |          | *FRONT R/H FENDER ASSY                 | Repair        | 583.00 FN   | *- FN        |
| 11  | 1   |          | *FRONT R/H FENDER INNER SHIELD (FRONT) | Not Necessary | 197.00 FN   | *- FN        |
| 12  | 1   |          | *FRONT R/H SHOCK ABSORBER              | Not Necessary | 886.00 FN   | *- FN        |
| 13  | 1   |          | *FRONT R/H SHOCK ABSORBER MOUNTING     | Not Necessary | 235.00 FN   | *- FN        |
| 14  | 1   |          | *FRONT R/H KNUCKLE ARM                 | Not Necessary | 1,123.00 FN | *- FN        |
| 15  | 1   |          | *FRONT R/H KNUCKLE BEARING             | Necessary     | 324.00 FN   | *270.00 FN   |
| 16  | 1   |          | *FRONT R/H LINKAGE                     | Not Necessary | 158.00 FN   | *- FN        |
| 17  | 1   |          | *FRONT R/H LOWER ARM                   | Bent          | 687.00 FN   | *212.00 FN   |
| 18  | 1   |          | *FRONT R/H STAY ARM                    | Bent          | 423.00 FN   | *107.00 FN   |
| 19  | 1   |          | *FRONT R/H SPORT WHEEL                 | Cut           | 900.00 FS   | *500.00 FS   |
| 20  | 1   |          | *FRONT R/H TIRE                        | Not Necessary | 350.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. N=NettItemDisc.

|   |                  |                 |
|---|------------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>10,541.20</b> | <b>4,360.52</b> |
| <b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b> | 929.12           | 386.05          |
| <b>Total Parts (S\$)</b>                                  | <b>9,612.08</b>  | <b>3,974.47</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                                 | Lab.Type | Repairer's      | Amount        |
|-------------------------------|---|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>    |   |          |                 |               |
| 1                             | TO DISM/REWIRE DAMAGED PORTION              | New      | 120.00          | 30.00         |
| 2                             | TO SPRAY UNDER COATING IN REPAIR            | New      | 100.00          | 0.00          |
| 3                             | TO DISM/RENEW FRONT R/H UNDERCARRIAGE       | New      | 350.00          | 50.00         |
| 4                             | TO COMPLETE WHEEL ALIGNMENT                 | New      | 120.00          | 60.00         |
| 5                             | TO PANEL BEAT DAMAGED PORTION & RENEW PARTS | New      | 1,000.00        | 200.00        |
| 6                             | TO PUTTY AND RESPRAY DAMAGED PORTION        | New      | 1,000.00        | 400.00        |
| <b>Gross Labour Cost (\$)</b> |   |          | <b>2,690.00</b> | <b>740.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >