

ASS. REC. BY:

REF:

CS/SNO18023175/KSbnz

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Mullman

From (Person):

Thelma Choo

of

SNO

Date/Time:

27/12/2018 3:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 2637T

Insured:

FBE 3104P

at Workshop m/s

Jin Huat

Tel:

6453 2151

of

176 Sin Ming Drive #05-01

Policy No:

D17MIM101002578

Claim No:

CMTD1805664

Sum Insured:

Excess:

Make of Vch:

D.O.A.

24/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

28/12/2018 @ 3pm

H.O.D. Endorsement:

Date/Time:

27/12/2018 3:26pm

Person Contacted:

Alice

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKE 2637T - X
	FBE 3104P - X
02/01/19	@ 16:35 p.m. revised IA to Thelma Choo via mullman.

Muller

ASSIGNMENT

From: Date: 28/12/08

Estimated Cost:

OD GP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SKE 2637T
at Workshop m/s: Jin Huat
of: 176 Sin Ming Dr #05-01

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKE 2637T Yr Regn: 02 12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M. CA 8250 C.C. 1796Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 122599 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W00 21 20 472A 547123

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 24/12/18

D.O.I. 28/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
31/12	File report to NMT9
03/01/18	Confirmed HS \$ 1,700/- @ 2 days with Kenneth. (\$ 876.00 Red - 34%)

RECEIVED 03 JAN 2019

Date/Time, File Pass to?

02/01/19

1) Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 1,700/- L/S

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos

) Others

TOTAL

250

10

260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 02 Jan 2019

Preliminary Advice

Insured Vehicle No	: FBE3104P	Accident Date	: 24/12/2018
TP Vehicle No	: SKE2637T	Assignment Date	: 27/12/2018
Make	: MERCEDES-BENZ E250	Est. Duration of Repair	: 2 days
Date of Inspection	: 28/12/2018		
Inspection At	: Jin Huat & Co (HQ) 176 SIN MING DRIVE #05-01, SIN MING AUTOCARE Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,576.00
Revised Amount	:S\$	2,117.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,117.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2018		27 Dec 2018 15:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	AMIRUL BIN ROSLI , ID: S9312601G								
Main Claimant:	BOH TUAN JEW , ID: S1198108I								
Vehicle Reg. No.:	SKE2637T	Date of Loss:	24/12/2018 15:00 - :59						
Claim Type:	TP / CMTD1805664	Policy/Cover Note No.:	D17MTMC01002578 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	FBE3104P	Policy No. (Claimant):							
		Excess:							
Repairer:	Jln Huat & Co (HQ) 176 SIN MING DRIVE #05-01, SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/01/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
-									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Alice Tan <jinhuat1951@gmail.com>
Sent: Thursday, 3 January 2019 12:56 PM
To: 'Shirley Hiew (LKK Auto)'
Subject: RE: SKE 2637T (TP) FBE 3104P (OI) DOA - 24/12/2018

Dear Shirley,

We confirm acceptance of your offer of \$1,700 (lump sum)

Regards,

Alice Tan
Jin Huat & Co
Tel: 6453 2151
Fax: 6456 3060
email: jinhuat1951@gmail.com

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Thursday, January 3, 2019 10:24 AM
To: jinhuat1951@gmail.com
Cc: SUR
Subject: SKE 2637T (TP) FBE 3104P (OI) DOA - 24/12/2018

Dear Alice,

Please confirm final fig \$1,700.00 (lump sum) @ 2 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Virus-free. www.avg.com

JIN HUAT & CO

176 Sin Ming Drive, #05-01

Sin Ming Autocare

Singapore 575721

Tel : 6453 2151; Fax : 6456 3060

email: jinhuat1951@gmail.com

Co. Reg. No: 020403/00C

Quotation

To: Boh Tuan Jew
56 Mariam Walk
Singapore 507131

Date : 26 December 2018

Pages : 1 of 1

Vehicle No: SKE 2637 T
Model: Mercedes E250
Insurer: Tokio Marine Insurance Singapore Pte Ltd

*Not Notch
C/Lup 81700p
Resurvey After Paint
2 days*

We are pleased to quote you as follows:

Items	Description	Qty	Unit	Unit Price	Total Price
Accident Details:					
	Date of Accident : 24 December 2018				
	T/P claim against Vehicle No. FBE 3104 P				
	insured with Sompo Insurance Singapore Pte Ltd				
Parts:					
1)	Rear bumper <i>Red/Bm</i>	1	pc	\$ 1,235.00	\$ 1,235.00 ✓
2)	Rear lower diffuser <i>Re Form</i>	1	pc	\$ 395.00	\$ 395.00 ✓
3)	Rear bumper bracket	2	pc	\$ 48.00	\$ 96.00 X
Labour: <i>10%</i>					
4)	Repair & replace rear bumper	1	lot	\$ 400.00	\$ 400.00 <i>30cl</i>
5)	Spray painting.	1	lot	\$ 450.00	\$ 450.00 <i>35cl</i>
TOTAL PRICE					\$ 2,576.00

JIN HUAT & CO

Alice Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18023175/KSBN2

Date: 03/01/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D17MTMC01002578
Claimant Vehicle No :	SKE2637T	Insured Vehicle No :	FBE3104P
Date of Loss:	24/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805664

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE2637T	Engine No:	27186030376977
Make & Model:	MERCEDES-BENZ E250, 2.0 (A)	Chassis No:	WDD2120472A547123
Reg. Date:	21/02/2012 (Man. Year: 2011)	Odometer:	122599 km
Colour:	Metallic Grey		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R17	Rear Tyre Size:	245/40R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,726.00	1,467.00	259.00	15.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	650.00	200.00	23.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,576.00	2,117.00	459.00	17.82
Approved Total (Overridden) (\$\$)		1,700.00		
Nett Amount (\$\$)	2,576.00	1,700.00	876.00	34.01

INSPECTION

Date of Assignment:	27/12/2018	
Date Inspected:	28/12/2018 Inspected At:	Jin Huat & Co (HQ) 176 SIN MING DRIVE #05-01, SIN MING AUTOCARE Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
Parts: 143	MERCEDES-BENZ E250 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKE2637T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Buckled	1,235.00 F	*1,235.00 FL
2	1		*REAR LOWER DIFFUSER	Deformed	395.00 F	*395.00 FL
3	2		*REAR BUMPER BRACKET	Serviceable	96.00 F	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					1,726.00	1,630.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	163.00
Total Parts (\$\$)					1,726.00	1,467.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR & REPLACE REAR BUMPER	New	400.00	300.00
2	SPRAY PAINTING	New	450.00	350.00
Gross Labour Cost (\$\$)			850.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >