

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG18023177/K1ES3Q2

**Date:** 07/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507688

**Claimant**  
**Vehicle No :** SHC7042Y **Insured Vehicle No :** SJB8662H

Date of Loss: 25/12/2018 Nature of Claim: TP Claim No: 3491272485SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7042Y	Engine No:	D4FDDU395096
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU085493
Reg. Date:	04/03/2016 (Man. Year: 2015)	Odometer:	410047 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Triangle 7 mm	Rear Left Side:	Triangle 7 mm
Front Right Side:	Triangle 7 mm	Rear Right Side:	Triangle 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,688.42	2,054.00	5,634.42	73.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	1,960.00	1,450.00	42.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>11,098.42</b>	<b>4,014.00</b>	<b>7,084.42</b>	<b>63.83</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	776.89	280.98	495.91	63.83
<b>Nett Amount (\$\$)</b>	<b>11,875.31</b>	<b>4,294.98</b>	<b>7,580.33</b>	<b>63.83</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (\$\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$115.00/day) (\$\$)</b>		460.00		
		<b>(S\$)</b>	<b>4,954.98</b>	
<b>Liabile Amount (80.00%) (\$\$)</b>		<b>3,963.98</b>		
<b>+ Doc/Search Fee (\$\$)</b>		7.49		
<b>Nett Liability (\$\$)</b>		<b>3,971.47</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>4,000.00</b>		

### INSPECTION

Date of Assignment: 27/12/2018

Date Inspected: 27/12/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	2,174.90 FL	*- FL
2	1		*BOOT LID RUBBER	Serviceable	96.50 FL	*- FL
3	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
4	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
5	1		*BOOT LID LAMP (LH)	Cracked	565.60 FL	*565.60 FL
6	1		*BOOTLID MOULDING	Cut	85.00 FL	*85.00 FL
7	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
8	1		*BOOTLID LOWER GARNISH	Cracked	227.90 FL	*227.90 FL
9	1		*REAR BUMPER	Deformed	553.00 FL	*553.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Serviceable	428.40 FL	*- FL
11	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Serviceable	160.60 FL	*- FL
12	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
13	1		*REAR BUMPER BRACKET (LH)	Cracked	35.60 FL	*35.60 FL
14	1		*REAR BUMPER SPONGE	Serviceable	103.50 FL	*- FL
15	1		*REAR BUMPER UNDER COVER	Cracked	228.00 FL	*228.00 FL
16	1		*REAR BUMPER REFLECTOR LAMP (LH)	Cracked	30.60 FL	*30.60 FL
17	1		*TAIL LAMP (LH)	Cracked	697.80 FL	*697.80 FL
18	1		*TAIL LAMP QUARTER PANEL (LH)	Repair	226.50 FL	*- FL
19	1		*REAR PANEL	Repair	526.70 FL	*- FL
20	1		*REAR PANEL GARNISH	Serviceable	57.70 FL	*- FL
21	1		*REAR PANEL LOWER PANEL	Repair	495.50 FL	*- FL
22	1		*REAR FENDER (LH)	Repair	2,171.40 FL	*- FL
23	1		*REAR FENDER INNER LINING (LH)	Serviceable	169.30 FL	*- FL
24	1		*REAR FENDER AIR-DUCT (LH)	Serviceable	51.60 FL	*- FL
25	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.30 FL	*- FL
26	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS
27	1		*REAR BUMPER REVERSE SENSOR	Serviceable	135.70 FS	*- FS
28	1		*REAR BUMPER ADVERTISEMENT LOGO	Not Necessary	50.00 FS	*- FS
29	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
30	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 9,532.60 2,560.00  
**- List Item Discount on L Items 20.00/20.00% (\$\$)** 1,844.18 506.00

**Total Parts (\$\$)** 7,688.42 2,054.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING (REPAIR)	New	1,600.00	800.00
2	SPRAY PAINTING CHARGE	New	1,250.00	1,000.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	100.00	30.00
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	50.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
7	REMOVE /REFIX REVERSE SENSOR	New	80.00	0.00
8	TOWING	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,410.00</b>	<b>1,960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >