



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 2015366H

3RD PARTY CLAIM ESTIMATION

AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way

#08-16

Singapore(079120)

Vehicle number	SKT5775D
Make / Model	NISSAN ELGRAND
Chassis number	JN1TBAE52Z0802379
Accident date	12-Dec-18
Reference	1812-27

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER <i>distorted</i>	1794.00 3449.88 ✓
1	REAR BUMPER SPONGE <i>torn</i>	167.25 ✓
1	REAR BUMPER REINFORCEMENT <i>Dented</i>	720.50 900.63 ✓
1	REAR END PANEL - INNER <i>HH</i>	1351.50 X
1	REAR END PANEL - OUTER <i>Dented</i>	841.00 1051.25 ✓
1	TAILGATE <i>Dented</i>	2706.60 3382.00 ✓
1	REAR LH CORNER PANEL <i>SVC</i>	1938.25 X
1	REAR RH CORNER PANEL <i>SVC</i>	1938.25 X
1	REAR RH FENDER INNER TRIM <i>SVC</i>	531.44 X
1	FRONT BUMPER <i>cut</i>	2735.90 3435.90 ✓
		17816.35
Less 30%		5344.90
Subtotal		12471.45
Balance C/F		12471.45
1	REAR RH INNER LAMP <i>monument broken</i>	310.50 ✓
2	REAR REINFORCEMENT BRACKET <i>req</i>	401.50 X
1	TAILGATE EMBLEM <i>Hec</i>	65.63 ✓
1	FRONT RH SIDE RETAINER <i>SVC</i>	48.00 X
2	REAR BUMPER RETAINER <i>SVC</i>	83.00 X
2	REAR BUMPER REFLECTOR <i>HH</i>	119.76 X
1	REAR LOCK SENSOR <i>broken</i>	92.63 ✓
1	TAILGATE WEATHERSTRIP <i>deformed</i>	183.25 ✓
1	REAR END PANEL TOP GARNISH COVER <i>monument deformed</i>	301.50 376.88 ✓
		1681.15
Less 10 %		167.80
Subtotal		1513.35
Balance C/F		13984.80
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
Balance B/F		13984.80
1	REAR NUMBER PLATE <i>HH</i>	80.00 X
1 SET	REAR BUMPER CLIP <i>Hec</i>	40.00 301-
1 SET	REAR REVERSE SENSOR <i>Dem</i>	400.00 2201-

8964.25

6274.97

953.51

858.15

1	WINDSCREEN SEALANT <i>huc</i>		150.00	<i>40/-</i>
1	JOINT SEALANT <i>huc</i>		150.00	<i>40/-</i>
1 BOT	BRAKE FULID <i>huc</i>	330.00	50.00	<i>x</i>
1 BOT	COOLANT <i>huc</i>		50.00	<i>x</i>
		Subtotal	920.00	
		Balance C/F	14904.80	
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
		Balance B/F	14904.80	
1	CHECK REAR WIRING AND LIGHTNING SYSTEM		70.00	<i>30/-</i>
4	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH		200.00	<i>80/-</i>
5	REMOVE AND RENEW REAR REVERSE SENSOR		150.00	<i>40/-</i>
6	REMOVE AND RENEW FLOOR INSULATOR	1930.00	150.00	<i>huc</i>
7	REMOVE AND REFIT REAR WINDSCREEN		150.00	<i>80/-</i>
12	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW		200.00	<i>60/-</i>
14	PANEL BEATING ON AFFECTED AREAS		2000.00	<i>800/-</i>
15	SPRAY PAINTING ON AFFECTED AREAS		1800.00	<i>800/-</i>
16	APPLY ANTI RUST ON AFFECTED AREAS		150.00	<i>40/-</i>
		Subtotal	4870.00	
		Grand total	19774.80	

27/12/2018 @ 1100hrs

9393.12

Not Attached

L/S 7500/-

L/Sum 15⁶ days.

ryan

Pending/Subject
consistency
check on
front bumper
damage.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto

Check part prices.