

ASS. REC. BY:

REF es/FCI18023184/71fd3n2

Special Instruction:

Supervisor  
CWS

Taufik

ASSIGNMENT (Office)

From (Person): Irene Jer

of FCI

Date/Time: 2:34pm @ 27/12/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 2790Z

Insured: SHD 7129B

at Workshop m/s: Prime Auto

Tel: 68610908

of: G Benoi place

Policy No:

Claim No: D19000028MP&H

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 25/12/2018

CA / REV / REP. / REV 24 HRS 'DS

H.O.D. Endorsement:

Date/Time: 3:22pm @ 27/12/18

Person Contacted: pei yee

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 2790Z - NN/DAI/1018928/h4 Jan. 6/10/2014
	SHD 7129B - CS/FCI/18021893/Ksb02 Jan. 30/11/2018
28/12 @ 4:05pm	Revised via email preli advise.

No photo upload 28/12

SYDNEY

Tanpin

REF: FA

ASSIGNMENT

From: \_\_\_\_\_ Date: 27/12/2018

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 2790Z

at Workshop n/s Prime Auto

of 6 Bendu Place

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No


GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: SHD 2790Z

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Prius Hybrid C.C. 1792

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZUV 301609086

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Air / S/Rim / STD Air/Rim or

Tyre Size: F: 185/65R15 R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or 18mm Goodridge

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 27/12/18

Survey held at Prime Auto

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/3/8000, 8 days. Battery week.

Lump Sum \$8000 (cred: 4420.61: 35%)

RECEIVED 09 JAN 2019

Date/Time, File Pass to?  : Preli. Report  : Final Report

Days Of Repair: 8 Resurvey No. of Trip: 1

Date/Time, File Return to? \_\_\_\_\_

Add Fee:  Site Insp (\$ )  Interview (\$ )  Tech. Invs (\$ )  Weekend (\$ )

Survey Fee: \_\_\_\_\_ Transportation: \_\_\_\_\_ Photos: \_\_\_\_\_ Others: \_\_\_\_\_

Report Format : Lump Sum / I.B.I. (\$) 8000

2x15 = 30
170+30
50
50
85
<b>385</b>

TOTAL



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000028MFSH

Date: 28/12/2018

Our Ref: CS/FCI18023184/T1td3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 2790Z

Please be informed that we had conducted the inspection of the abovementioned vehicle 27/12/2018 at the premises of M/s Prime Auto have the following to report: -

Workshop Estimate Amount	: S\$ <u>12,420.61</u>
Revised Estimate Amount	: S\$ <u>10,003.63</u>
"Check" Items Amount	: S\$ <u>1,716.98</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the front and rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Taufikh  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

Date	26-12-2018	Our Ref No. D19000028MFSH
Accident Date	25-12-2018	Claim Type. Third Party
Insured Vehicle	SHD7129B	Third Party Vehicle. SHD2790Z
Survey Location	6 BENOI PLACE	
Contact Person.	PEI YEE	
Contact No.	68610908/ 0	Fax No. 65152948
Survey Type	WITHOUT PREJUDICE; NO EST. PROVIDED (WE ADMIT LIABILITY QUANTUM TO BE AGREED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	PRIME AUTO CLAIMS SERVICE PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 28 December 2018 4:05 PM  
**To:** Admin-D (LKKAuto); 'CWS Motor Claims'; assignments  
**Cc:** 'Karen Tan'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19000055MFSH/1  
**Attachments:** PRELI ADVISED SHD 2790Z.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 2790Z**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 28 December 2018 2:51 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Karen Tan' <[karentan@msfirstcapital.com.sg](mailto:karentan@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19000055MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 31/12/2018.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 28 December 2018 2:05 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6293Z
Vehicle Details	
Vehicle No.:	SHD2790Z
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8L A
Primary Colour:	Brown
Manufacturing Year:	2012
Engine No.:	2ZR5555004
Chassis No.:	ZVW301609046
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$26,146.00
Original Registration Date:	26 Jun 2013
First Registration Date:	26 Jun 2013
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2021
PARF Rebate Amount:	\$3,500.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$52,036.00
COE Rebate Amount:	\$16,223.00
<b>Total Rebate Amount:</b>	<b>\$19,723.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Dec 2018

OK



# Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M  
 6 Benoi Place Singapore 629927  
 Tel: 6861 0908 Fax: 6515 2948

*Handwritten:* 3/12/18  
 Tan Kah 97495749

Date: 26.12.2018

MS First Capital Insurance Ltd  
 36 Robinson Road #16-01  
 City House  
 Singapore 068877

Attn: Motor Claims Dept

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Handwritten:* WP  
 27/12/18 @ 145 pm  
 Resurvey after repair  
 surel/maintenance  
 8 days

## RE: COST OF REPAIR TO VEHICLE SHD2790Z TOYOTA PRIUS HYBRID 1.8L A (2012)

### To Supply

1 )	1pc	Rear bumper	\$ de	1,218.00
2 )	1pc	Rear bumper left side retainer	\$ re	122.25
3 )	1pc	Rear bumper right side retainer	\$ we	122.25
4 )	1set	Rear bumper clip	\$ we	30.00
5 )	1pc	Rear bumper left bracket	\$ ?	132.10 x un
6 )	1pc	Dash panel No.1 insulator pad	\$ ?	217.50 x un
7 )	1pc	No. 2 floor mat	\$ ?	255.60 x un
8 )	1pc	Rear end panel	\$ bt	782.00
9 )	1pc	Rear end panel top garnish <i>* check price</i>	\$ <del>over</del> we	562.00 382.
10 )	1set	Rear end panel top garnish clip	\$ we	40.00
11 )	1pc	Tail gate	\$ bc	1,450.00
12 )	1pc	Tail gate weatherstrip	\$ cut	284.00
13 )	1pc	Tail gate lock	\$ bt	289.90
14 )	1pc	Tail gate "Toyota" emblem	\$ re	62.00
15 )	1pc	Tail gate "Prius" emblem	\$ we	72.00
16 )	1pc	Tail gate "Hybrid Synergy Drive" emblem	\$ we	51.00
17 )	1pc	Rear floor panel	\$ <del>bu</del> re	972.85
18 )	1pc	Exhaust tail pipe & silencer	\$ bl	382.92550
19 )	1pc	Right main muffler heat insulator	\$ bt	107.82
20 )	1pc	Right tail lamp	\$ ?	680.00 x un
21 )	1pc	Front bumper	\$ de	1,230.00
22 )	1set	Front bumper clip	\$ we	30.00
23 )	1pc	Front bumper lower grille	\$ cut	320.85
24 )	1set	Front bumper sponge	\$ ?	150.00 x un
25 )	1pc	Front bumper reinforcement	\$ ?	290.00 x un
26 )	1pc	Front no plate garnish	\$ de	102.00
27 )	1pc	Front radiator grille	\$ ?	324.10 x un
28 )	1pc	Front grille 'Toyota' emblem	\$ mis	80.00

29 )	1set	Front grille clip	\$	? 40.00 <i>Xnn</i>
30 )	1pc	Right front tow hook cover	\$	<i>ms</i> 45.00

Sub total parts	\$	10,446.14
Less: 25% discount	\$	2,611.53
	\$	7,834.61

To Supply S.Nett Parts

1 )	2tube	Rear glass sealant	@\$45.00	\$	<i>nl</i> 90.00
2 )	1pc	Floor panel sealant		\$	150.00 <i>Xny</i>
3 )	2pcs	Tail gate lower glass moulding (2pcs)		\$	<i>nl</i> 60.00
4 )	1set	Tail gate glass moulding (3pcs)		\$	<i>nl</i> 240.00
5 )	1pc	"Prime taxi" sticker		\$	<i>nl</i> 55.00
6 )	1pc	"Dial-A-Cab" sticker		\$	<i>nl</i> 55.00
7 )	1pc	Rear bumper advertisement sticker		\$	<i>nl</i> 100.00
8 )	1pc	Tail gate advertisement sticker		\$	<i>nl</i> 100.00
9 )	1pc	Left rear fender advertisement sticker		\$	<i>nl</i> 200.00
10 )	1pc	Right rear fender advertisement sticker		\$	<i>nl</i> 200.00
11 )	1set	Reverse sensor		\$	<i>nl</i> 250.00 <i>200</i>
12 )	1pc	Front license plate no.		\$	<i>nl</i> 38.00
13 )	1pc	Rear license plate no.		\$	<i>nl</i> 38.00


Sub total S.Nett Parts	\$	1,576.00
------------------------	----	----------

L/charge

1 )	Towing charges (using king-dolley)	\$	<i>✓</i> 80.00
2 )	To tuff kote	\$	<i>50</i> 80.00
3 )	To remove & refit reverse sensor. Check wiring	\$	<i>30</i> 50.00
4 )	To cut / welding rear end panel & floor panel, remove rear bumper, tail gate & replace the above parts. Straighten right wheel house panel. Align & adjust rear bumper & tail gate	\$	<i>900</i> 1,000.00
5 )	To putty, respray painting rear end panel, floor panel, rear bumper & tail gate inlet & outer right wheel house panel.	\$	<i>900</i> 1,100.00
6 )	To remove front bumper, front radiator grille, front bumper lower grille & etc. Replace the above parts. Align front bumper & front grille	\$	<i>200</i> 400.00
7 )	To putty, respray painting front bumper & right front tow hook cover. To polish	\$	<i>200</i> 300.00

Sub total L/charges	\$	3,010.00
Estimated Grand Total	\$	12,420.61

12545.91



# ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@ymail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1204534

Date: 25/12/10

24 HOURS

HOTLINE: 9182 8211

M/S: Home

Vehicle No: SM D27907 Model: T/Plus

From: Changi Airport 73 Time Start: 11.00pm

To: G Bena Pl Time End: 1.25pm

Remarks: \_\_\_\_\_

Change Tyres / Jump Start

Accident

Use Car Carrier

Basement / Multi Carpark

Crane Up / Winch Out

Open Door

Using King Dolly

Dismantle Shaft / Brake

Loaded

AMOUNT S\$ 80

GST S\$ 5.60

TOTAL S\$ 85.60

**bizSAFE<sub>3</sub>**

*S. J. Tan*

Received By \_\_\_\_\_

Important Note:

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18023184/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-01-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 7129B	Veh. Inspected	SHD 2790Z
Policy No.		Coverage (\$)	0.00
Claim No.	D19000028MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	27/12/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	ZVW301609046	Colour	ORANGE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	GOODRIDE	6 mm
L/H Front Tyre	185/65 R15	GOODRIDE	6 mm
R/H Rear Tyre	185/65 R15	GOODRIDE	6 mm
L/H Rear Tyre	185/65 R15	GOODRIDE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/12/2018	Inspection Date	27/12/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2790Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DEFORMED	1,218.00	1,218.00
1	REAR BUMPER LEFT SIDE RETAINER	NECESSARY	122.25	122.25
1	REAR BUMPER RIGHT SIDE RETAINER	NECESSARY	122.25	122.25
1	SET REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR BUMPER LEFT BRACKET	NOT NECESSARY	132.10	-
1	DASH PANEL NO.1 INSULATOR PAD	NOT NECESSARY	217.50	-
1	NO 2 FLOOR MAT	NOT NECESSARY	255.60	-
1	REAR END PANEL	BENT	782.00	782.00
1	REAR END PANEL TOP GARNISH	CRACKED	562.00	382.00
1	SET REAR END PANEL TOP GARNISH CLIP	NECESSARY	40.00	40.00
1	TAIL GATE	BENT	1,450.00	1,450.00
1	TAIL GATE WEATHERSTRIP	CUT	284.00	284.00
1	TAIL GATE LOCK	BENT	289.90	289.90
1	TAIL GATE "TOYOTA" EMBLEM	NECESSARY	62.00	62.00
1	TAIL GATE "PRIUS" EMBLEM	NECESSARY	72.00	72.00
1	TAIL GATE "HYBRID SYNERGY DRIVE" EMBLEM	NECESSARY	51.00	51.00
1	REAR FLOOR PANEL	BUCKLED	972.85	972.85
1	EXHAUST TAIL PIPE & SILENCER	BENT	550.00	550.00
1	RIGHT MAIN MUFFLER HEAT INSULATOR	BENT	107.82	107.82
1	RIGHT TAIL LAMP	NOT NECESSARY	680.00	-
1	FRONT BUMPER	DEFORMED	1,230.00	1,230.00
1	SET FRONT BUMPER CLIP	NECESSARY	30.00	30.00
1	FRONT BUMPER LOWER GRILLE	CUT	320.85	320.85
1	SET FRONT BUMPER SPONGE	NOT NECESSARY	150.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	290.00	-
1	FRONT NO PLATE GARNISH	DEFORMED	102.00	102.00
1	FRONT RADIATOR GRILLE	NOT NECESSARY	324.10	-
1	FRONT RADIATOR "TOYOTA" EMBLEM	MISSING	80.00	80.00
1	SET FRONT RADIATOR CLIP	NOT NECESSARY	40.00	-
1	RIGHT FRONT TOW HOOK COVER	MISSING	45.00	45.00

Report Ref No. CS/FC118023184/T1td3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,653.31	-2,085.98
			7,959.91	6,257.94
	<b><u>SPECIAL NETT ITEMS</u></b>			
2	TUBE REAR GLASS SEALANT (SN)	NECESSARY	90.00	90.00
1	FLOOR PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
2	TAIL GATE LOWER GLASS MOULDING (2PCS)(SN)	NECESSARY	60.00	60.00
1	SET TAIL GATE GLASS MOULDING (3PCS)(SN)	NECESSARY	240.00	240.00
1	"PRIME TAXI" STICKER (SN)	NECESSARY	55.00	55.00
1	"DIAL-A-CAB" STICKER (SN)	NECESSARY	55.00	55.00
1	REAR BUMPER ADVERTISEMENT STICKER (SN)	NECESSARY	100.00	100.00
1	TAIL GATE ADVERTISEMENT STICKER (SN)	NECESSARY	100.00	100.00
1	LEFT REAR FENDER ADVERTISEMENT STICKER (SN)	NECESSARY	200.00	200.00
1	RIGHT REAR FENDER ADVERTISEMENT STICKER (SN)	NECESSARY	200.00	200.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
1	FRONT LICENSE PLATE NO (SN)	CRACKED	38.00	38.00
1	REAR LICENSE PLATE NO (SN)	CRACKED	38.00	38.00
			1,576.00	1,376.00
	<b><u>LABOUR</u></b>			
	TOWING CHARGES (USING KING-DOLLEY).		80.00	80.00
	TO TUFF KOTE.		80.00	50.00
	TO REMOVE & REFIT REVERSE SENSOR.CHECK WIRING.		50.00	30.00
	TO CUT/WELDING REAR END PANEL & FLOOR PANEL,REMOVE REAR BUMPER,TAIL GATE & REPLACE THE ABOVE PARTS.STRAIGHTEN RIGHT WHEEL HOUSE PANEL.ALIGN & ADJUST REAR BUMPER & TAIL GATE.		1,000.00	900.00
	TO PUTTY,RESPRAY PAINTING REAR END PANEL,FLOOR PANEL,REAR BUMPER & TAIL GATE INLET & OUTER RIGHT WHEEL HOUSE PANEL.		1,100.00	900.00
	TO REMOVE FRONT BUMPER,FRONT RADIATOR GRILLE,FRONT BUMPER LOWER GRILLE & ETC.REPLACE THE ABOVE PARTS.ALIGN FRONT BUMPER & FRONT GRILLE.		400.00	200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY,RESPRAY PAINTING FRONT BUMPER & RIGHT FRONT TOW HOOK COVER.TO POLISH.		300.00	200.00
			3,010.00	2,360.00
<b>GRAND TOTAL</b>			<b>12,545.91</b>	<b>9,993.94</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,000.00</b>

Report Ref No. CS/FCI18023184/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.