

12/01/2002

ASS. REC. BY:

REF: 03/CT118023186/Gcd3

Special Instruction:

Surveyor: Quo Cidng

ASSIGNMENT (Office)

From (Person): Catherine Thia

of CTI

Date/Time: 27/12/18 @ 2:54pm

Estimated Cost:

Bill to:

OD WS/TP RES / OD RES / EVA / INV / MY/CS

To Inspect Vehicle No: SKW 6766H

Insured: SGT 3452X

at Workshop in/s: Ngai Hong Auto

Tel: 6453 1712

of 160 Sir Ming Drive #06-08

Policy No:

Claim No: SNM18D05877C02

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 19/12/2018

CA / REV / REP. / REV 24 HRS ^{up}

07/01/2018
H.O.D. Endorsement:

Date/Time: 3:56pm @ 27/12/18

Person Contacted: Mr. Teo

Vehicle-IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKW 6766H - NA/INC17017080/h4 4/08071071/VA/H9979 WKS DVA: 27/12/2018
	SGT 3452X - NA/CT118023186/24 DVA: 19/12/2018
	Dismantle: 8/1/2019

Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Thursday, 27 December 2018 2:54 PM
To: Admin A; 'assignments'
Cc: boo@kurupnboo.com.sg
Subject: snm18D05877C02 (new PRI assignment)
Attachments: SNM18D05877-2.pdf

Dear LKK oic

Please assist to contact Mr Teo from workshop on new PRI assignment

We will create in Merimen shortly

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

KURUP & BOO

UEN 53130914B
ADVOCATE & SOLICITOR
COMMISSIONER FOR OATHS
NOTARY PUBLIC

111 North Bridge Road
#15-03 Peninsula Plaza
Singapore 179098
Tel. No. 6223 3343
6221 8623
Fax. No. 6225 7248
Writer's e-mail :
boo@kurupnboo.com.sg
kurup@singnet.com.sg

Our Ref : BMC.3251.18.sa
Your Ref : Insured vehicle no. SGT 3452X
21 December 2018

18/5877/2
URGENT

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Via fax (6222 1033)
and **BY HAND**

Dear Sirs

ACCIDENT INVOLVING VEHICLE NOS. SKW 6766H, SGT 3452X AND SGZ 7047A AT BUKIT HO SWEE ON 19 December 2018

We act for Mr. Tan Cheng Kwang, the owner of the vehicle no. SKW 6766H which was involved in the above accident.


We attach a copy of our client's Singapore Accident Statement for your immediate attention.

By way of notice, we hereby inform you that our client damaged vehicle is now in the following workshop:

Ngai Hong Auto Services
160 Sin Ming Drive
#06-08 Sin Ming AutoCity
Singapore 575722
Tel : 6453 1712 Fax: 6266 6402

We hereby give you **two days'** notice for your representative to go the above workshop to inspect our client's damaged vehicle. Kindly contact Mr. Teo Yew Haw at cell phone no. 9677-9434 prior to going to the workshop for the survey.

Yours faithfully


BOO MOH CHEH
enc
cc Ngai Hong Auto Services

26 DEC 2018

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4454F
Vehicle Details	
Vehicle No.:	SKW6766H
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRX536022
Chassis No.:	MR053REH104540679
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,589.00
Original Registration Date:	11 Nov 2015
First Registration Date:	11 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$19,589.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Nov 2025
PARF Rebate Amount:	\$14,691.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,301.00
COE Rebate Amount:	\$39,187.00
Total Rebate Amount:	\$53,878.00

The information contained herein is correct as at 08 Jan 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2018		08 Jan 2019 17:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	TAN CHENG KWANG		
Vehicle Reg. No.:	SKW6766H	Date of Loss:	19/12/2018 00:00 - :59 [37 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05877C02	Policy/Cover Note No.:	DMPCSN3017131804
Vehicle Reg. No. (Insured):	SGT3452X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ngai Hong Auto Services (HQ) 160 SIN MING DRIVE #06-08, SIN MING AUTO CITY, 575722 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/01/2019]		
Adj Asg. Remarks:	PRI ALREADY ASSIGN VIA EMAIL ON 27/12/2018		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKW6766H (SNM18D05877C02)**
[SGT3452X]
TP
TAN CHENG KWANG
Dec 19 2018 12:00AM
[-]
Ngai Hong Auto Services

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
2	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
3	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
4	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
5	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
6	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/01/19 11:28	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	14/01/19 11:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118023186/GCD3S2
Date: 21/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3017131804
 Claimant Vehicle No: SKW6766H Insured Vehicle No: SGT3452X
 Date of Loss: 19/12/2018 Nature of Claim: TP Claim No: SNM18D05877C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW6766H**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZRX536022
 Reg. Date: 11/11/2015 (Man. Year: 2015) Chassis No: MR053REH104540679
 Colour: Silver Odometer: 124420 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/01/2019
 Date Inspected: 07/01/2019 Inspected At: 160 SIN MING DRIVE# 06-08
 Estimated Period of Repair: 5.0 days Repairer: Ngai Hong Auto Services

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jan 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW6766H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >