



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 26-12-2018

VEHICLE NO. : SJN1633A
ACCIDENT DATE : 25-12-2018 19:00
THIRD PARTY REF. : SJZ8134P

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SJN1633A MERCEDES-BENZ B180

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BUMPER / ee	1100.00 983
2	1	REAR BUMPER LOWER / ee	285.00 /
3	1	REAR BUMPER TOP CHROME / ac	175.00 /
4	2	REAR BUMPER CHROME @\$85.00 / 3 ac	170.00 /
5	10	REAR BUMPER CLIP @\$5.00 /	50.00
			1,780.00 1663
LESS 10 %			178.00
TOTAL (A)			1,602.00
			1496.7
LABOUR CHARGES			
1	1	TO CHECK WIRING SYSTEM	20 30.00
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	240 450.00
3	1	SPRAYPAINTING CHARGES	200 400.00 420
TOTAL (D)			880.00
ESTIMATE TOTAL			2,482.00

2 Days.
put by pet.
before paint photos.
Gino Qianf.
24/1/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1916.7