

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7489

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0760/18

DATE : 24-DEC-2018

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : WONG KOK GHAY
ADDRESS : BLK 225C COMPASSVALE WALK
#07-351
S(543225)
TELEPHONE NO : 90401613

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100494646-02
VEHICLE NO : SLJ6811S
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2303143A
CHASSIS NO : SJNFEAJ11U1711379
MILEAGE : 40500 KM
DATE IN : 24/12/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 23/12/2018

-9645 0084 elmer@tanchoy.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLJ68115

| S/NO | JOB CODE | NATURE OF JOB | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|---|-------------------|---------------------------|
| 1 | ZZ/001 | LABOR CHARGES TO REPAIR BOTH RR FENDER & HATCHBACK DOOR, RENEW RR END PANEL & RR BUMPER | 3120.00 | 780 |
| 2 | ZZ/002 | CHARGES TO SPRAY PAINTING SAME | 1250.00 | 500 |
| 3 | ZZ/003 | APPLY SEALANT TO RR END PANEL | 100.00 | ? |
| 4 | ZZ/004 | RENEW REVERSE SENSOR 4 POINT | 110.00 | / |
| 5 | ZZ/005 | SUPPLY RR LICENSE PLATE | | |
| 6 | ZZ/006 | REMOVE AND INSTALL BOTH RR COMBINATION LAMP TO FACILITATE RR BUMPER REPLACEMENT | 48.00 | / |
| TOTAL LABOUR CHARGES | | | 4628.00 | |

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLJ6811S

| S/NO | PARTS DESCRIPTION | PARTS NUMBER | DAMAGED PARTS & PRICES | | |
|---|--|--------------|------------------------|------|-----------------|
| | | | NETT | LIST | S/NETT REMARKS |
| 1 | REAR LICENCE PLATE <i>X NN</i> | RLP | | | 60.00 |
| 2 | SUNDRIES <i>/ mcl</i> | NPN | | | 50.00 <i>20</i> |
| 3 | REAR END PANEL <i>?</i> | G9110-4EAMA | 482.60 | | |
| 4 | LH REFLECTOR RR BUMPER <i>X</i> | 26565-JJ90A | 55.00 | | |
| 5 | RH REFLECTOR RR BUMPER <i>X</i> | 26560-JJ90A | 55.00 | | |
| 6 | LH STAY RR BUMPER <i>?</i> | H5211-4EAMA | 126.00 | | |
| 7 | RH STAY RR BUMPER <i>?</i> | H5210-4EAMA | 126.00 | | |
| 8 | REINFORCEMENT RR BUMPER <i>?</i> | H5030-4EAMA | 619.20 | | |
| 9 | ENERGY ABSORBER RR BUMPER <i>?</i> | 85090-4EA0B | 126.40 | | |
| 10 | SENSOR-REVERSE 4 POINT <i>/ DM</i> | SENSOR | | | 250.00 |
| 11 | LH SIDE BRACKET RR BUMPER <i>?</i> | 85221-4EA0A | 35.90 | | |
| 12 | RH SIDE BRACKET RR BUMPER <i>?</i> | 85220-4EA0A | 35.90 | | |
| 13 | CLIP RR BUMPER @ SGD \$ 1.20 EACH <i>/ mcl</i> | 01553-05933 | 7.20 | | |
| 14 | TOW HOOK COVER RR BUMPER <i>X NN</i> | 85071-4EA0A | 16.80 | | |
| 15 | REAR BUMPER <i>/ SGD RE</i> | 85022-4EA0H | 717.00 | | |
| SUB TOTAL | | | 2403.00 | 0.00 | 360.00 |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) | | | 480.60 | 0.00 | 0.00 |
| GRAND TOTAL | | | 1922.40 | 0.00 | 360.00 |
| OVERALL TOTAL | | | 2282.40 | | |

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLJ68115

| | |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES | 4628.00 |
| TOTAL SPARE PARTS CHARGES | 2282.40 |
| GRAND TOTAL | 6910.40 * |

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

Amo Qiang - 82880282

4 days.

28/12/18

before paint photos.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: